

**OWNER:** METRO HOLDINGS AUSTRALIA PTY LTD  
**ADDRESS:** 28 DROVER ROAD  
BANKSTOWN AIRPORT NSW 2200

**OPERATOR:** AIR LINK PTY. LIMITED  
**ADDRESS:** 650 DROVER ROAD BANKSTOWN  
AIRPORT  
SYDNEY NSW 2200

**OPERATOR:** AIRMED AUSTRALIA PTY LTD  
**ADDRESS:** PO BOX 222  
GEORGES HALL NT 2198

**PHONE:** +61 414 279 897  
**FAX:**

**PHONE:**  
**FAX:**

**PHONE:** +61 2 8700 0680  
**FAX:** +61 2 8700 0661

**ANALYST:** ROHIT CHAUHAN - (DIRECT)  
**EMAIL:** ROHITKUMAR.CHAUHAN@CAMPSYSTEMS.COM +91-40-30275000 (OFFICE)  
.COM WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

**AIRCRAFT SERIAL/REGNO:** 1314/VH-AL4      **MODEL:** PC-12/47E      **MANUFACTURER:** PILATUS AIRCRAFT LTDX

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	29-NOV-2011	7141.5 A/C HRS	as of 30-APR-2025	A/C HRS	as of ___/___/___
		6241 AFL	as of 30-APR-2025	AFL	as of ___/___/___
		188 ACH	as of 05-OCT-2023	ACH	as of ___/___/___
		5783 FLTS	as of 30-APR-2025	FLTS	as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** PCE-RY0331/3072955-01      **MODEL:** PT6A-67P      **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 03-DEC-2021		LAST ACTUALS		CURRENT ACTUAL	
4881 ENG. HRS	5543.33 A/C HRS	6380.42 ENG. HRS	as of 30-APR-2025	ENG. HRS	as of ___/___/___
4090 ENC		5487 ENC	as of 30-APR-2025	ENC	as of ___/___/___

**PROPELLER NOSERIAL/PART:** KX1388/HC-E4A-3D      **MODEL:** HC-E4A-3      **MANUFACTURER:** HARTZELL PROPELLER LLC

INSTALLED ON 23-DEC-2021		LAST ACTUALS		CURRENT ACTUAL	
3302.25 PROP HRS	5683.17 A/C HRS	4790.83 PROP HRS	as of 30-APR-2025	PROP HRS	as of ___/___/___

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - AD - 1314/VH-AL4</b>							
CAA UK G-2021-0010-E PARA (1)	INSPECT EACH FUEL CYLINDER WHERE AN AFFECTED PART AND REMOVE THE CYLINDER FROM SERVICE, IAW PARA (2) (IF ANY LEAKAGE IS DETECTED)	MOS HRS/MSC - AFL					NOT APPLICABLE - NOT EQUIPPED
CAA UK G-2021-0010-E PARA (4)	DO NOT INSTALL AN AFFECTED PART ON ANY CYLINDER	MOS HRS/MSC - AFL				MANDATORY	NOT APPLICABLE - NOT EQUIPPED
CAA UK G-2021-0010-E PARA (5)	MODIFY EACH CYLINDER BY REPLACING THE P/N CB437 ISSUE F QSO FLANGED ADAPTOR, WITH A P/N CB437 ISSUE G (OR LATER ISSUE) QSO FLANGED ADAPTOR OR BY REPLACING THE QSO VALVE ASSY WITH A HANDWHEEL VALVE PART NO CB0824-0001 (THIS PART HAS A REGO-TYPE HOSE CONNECTION)	MOS HRS/MSC - AFL					NOT APPLICABLE - NOT EQUIPPED
EASA 2008-0163	NEW LIFE LIMIT OF 10,000 FLIGHT HOURS, FOR THE PITCH TRIM ACTUATOR ATTACHMENT PARTS	MOS HRS/MSC - AFL		31-JAN-2012 5 5		MANDATORY	NOT APPLICABLE - BY A/C MODEL
EASA 2009-0028-E	EMERGENCY AD - NAVIGATION - INCORRECT INFORMATION OF THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) - POH TEMPORARY REVISION	MOS HRS/MSC - AFL		21-MAY-2014		SUPERSEDED	- SUPERSEDED BY EASA AD 2009-0080-E
13-FEB-2009							
EASA 2009-0040	ATA 27 - ELEVATOR AND TAB - STICK-PUSHER SERVO-CABLES - INSPECTION	DAYS HRS/MSC - AFL		30-NOV-2011 0 0		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
01-MAR-2009							
EASA 2009-0060	ATA 32 - NOSE GEAR - TORQUE TUBE OF THE NOSE WHEEL STEERING - REPLACEMENT / LIMITATIONS	DAYS HRS/MSC - AFL		30-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
25-MAR-2009							
EASA 2009-0060 PARA (2)	REPLACE ATA 32 - NOSE GEAR - TORQUE TUBE OF THE NOSE WHEEL STEERING - REPLACEMENT / LIMITATIONS NOSE LANDING GEAR STEERING TORQUE TUBE	MOS HRS/MSC - AFL		29-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
25-MAR-2009							
EASA 2009-0060 PARA (3)	AMEND ATA 32 - NOSE GEAR - TORQUE TUBE OF THE NOSE WHEEL STEERING - REPLACEMENT / LIMITATIONS MAINTENANCE DOCUMENTATION TO INCORPORATE THE STRUCTURAL, COMPONENT AND MISCELLANEOUS LIMITATIONS	DAYS HRS/MSC - AFL		29-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
25-MAR-2009							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2009-0080-E	EMERGENCY AD - NAVIGATION - AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) - PILOT'S OPERATING HANDBOOK (POH) TEMPORARY REVISION (SUPERSEDED BY EASA 2009-0249)					SUPERSEDED	- SUPERSEDED BY EASA AD 2009-0249
07-APR-2009		MOS HRS/MSC - AFL		21-MAY-2014			
EASA 2009-0086	NOSE LANDING GEAR - RIGHT HAND UPPER DRAG LINK - INSPECTION / LIFE LIMITATION						NOT APPLICABLE - BY MSN EFFECTIVITY
28-APR-2009		MOS HRS/MSC - AFL		29-NOV-2011			
EASA 2009-0086 PARA (1)	AMEND NOSE LANDING GEAR - RIGHT HAND UPPER DRAG LINK - INSPECTION / LIFE LIMITATION APPROVED AIRCRAFT MAINTENANCE PROGRAMME					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		DAYS HRS/MSC - AFL		30-NOV-2011			
EASA 2009-0086 PARA (2)	INSPECT NOSE LANDING GEAR - RIGHT HAND UPPER DRAG LINK - INSPECTION / LIFE LIMITATION NLG RH UPPER DRAG LINK					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS HRS/MSC 300 (s) AFL 400		29-NOV-2011 0 0			
EASA 2009-0086 PARA (3)	REPLACE NOSE LANDING GEAR - RIGHT HAND UPPER DRAG LINK - INSPECTION / LIFE LIMITATION NLG RH UPPER DRAG LINK WITH NEW DESIGN, P/N 532.20.12.296					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS HRS/MSC - AFL		29-NOV-2011			
EASA 2009-0249	NAVIGATION - AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) - MODIFICATION/REPLACEMENT					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		DAYS HRS/MSC - AFL		21-MAY-2014			
EASA 2010-0093	ENGINE CONTROLS - POWER CONTROL LEVER REVERSE THRUST LATCH - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
27-JUL-2011		MOS HRS/MSC - AFL		21-MAY-2014			
EASA 2010-0093 PARA (1)	INSPECT ENGINE CONTROLS - POWER CONTROL LEVER REVERSE THRUST LATCH - INSPECTION / MODIFICATION THE PCL REVERSE THRUST LATCH HANDLE					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS HRS/MSC - AFL		21-MAY-2014			
EASA 2010-0093 PARA (2.1)	INSERT ENGINE CONTROLS - POWER CONTROL LEVER REVERSE THRUST LATCH - INSPECTION / MODIFICATION TEMPORARY REVISION (TR) NO. 12 INTO AIRCRAFT FLIGHT MANUAL (AFM)					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS HRS/MSC - AFL		21-MAY-2014			
EASA 2010-0093 PARA (2.2)	MODIFY ENGINE CONTROLS - POWER CONTROL LEVER REVERSE THRUST LATCH - INSPECTION / MODIFICATION THE ENGINE CONTROL CONSOLE ASSEMBLY					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS HRS/MSC - AFL		21-MAY-2014			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2012-0099	TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATION SECTION - AMENDMENT / IMPLEMENTATION (SUPERSEDED BY EASA AD 2013-0031)						- SUPERSEDED BY EASA AD 2013-0031
22-JUN-2012		MOS HRS/MSC - AFL		15-JUL-2012 51.58 42			
EASA 2013-0031	TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATION SECTION - AMENDMENT / IMPLEMENTATION (THIS AD WAS SUPERSEDED BY 2014-0170, DATED JULY 17, 2014)					MANDATORY	- SUPERSEDED BY EASA AD 2014-0170
		MOS HRS/MSC - AFL		28-FEB-2013			
EASA 2013-0114	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT SYSTEM / POWER RETURN WIRES - MODIFICATION					MANDATORY	COMPLIED WITH - SEE SB 34-038
11-JUN-2013		MOS HRS/MSC - AFL		04-AUG-2013 595.25 470			
EASA 2014-0170	TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATION SECTION - AMENDMENT / IMPLEMENTATION (SUPERSEDED BY EASA AD 2016-0083)					MANDATORY	COMPLIED WITH - SUPERSEDED BY EASA AD 2016-0083
31-JUL-2014		MOS HRS/MSC - AFL					
EASA 2014-0170 PARA (1.1)	REPLACE EACH COMPONENT BEFORE EXCEEDING THE APPLICABLE LIFE LIMIT					MANDATORY	COMPLIED WITH - SUPERSEDED BY EASA AD 2016-0083
31-JUL-2014		MOS HRS/MSC A/R AFL					
EASA 2014-0170 PARA (1.2)	WITHIN THE THRESHOLDS AND INTERVALS, ACCOMPLISH ALL APPLICABLE MAINTENANCE TASKS. THE NEXT INSPECTION OF THE INBOARD FLAP DRIVE ARMS MUST BE ACCOMPLISHED WITHIN 150 FLIGHT HOURS OR WITHIN THREE MONTHS, WHICHEVER OCCURS FIRST AFTER THE EFFECTIVE DATE OF THIS AD					MANDATORY	COMPLIED WITH - SUPERSEDED BY EASA AD 2016-0083
31-JUL-2014		MOS HRS/MSC - AFL					
EASA 2014-0170 PARA (2)	IN CASE OF FINDING DISCREPANCIES ACCOMPLISH THE APPLICABLE MAINTENANCE PROCEDURES FOR CORRECTIVE ACTIONS IN ACCORDANCE WITH THE APPROVED MAINTENANCE DOCUMENTATION					MANDATORY	COMPLIED WITH - SUPERSEDED BY EASA AD 2016-0083
31-JUL-2014		MOS HRS/MSC BF/F AFL					
EASA 2014-0170 PARA (3.1)	REVISING AS FOLLOWS THE APPROVED AIRCRAFT MAINTENANCE PROGRAMME AND STANDARD PRACTICES ON THE BASIS OF WHICH THE OPERATOR OR THE OWNER ENSURES THE CONTINUING AIRWORTHINESS OF EACH OPERATED AEROPLANE: INCORPORATE ALL APPLICABLE MAINTENANCE INSTRUCTIONS AND ASSOCIATED AIRWORTHINESS LIMITATIONS SPECIFIED IN CHAPTER 4 OF AMM REPORT 02049 ISSUE 28 OR AMM REPORT 02300 ISSUE 11, DATED 31 MAY 2014					MANDATORY	COMPLIED WITH - SUPERSEDED BY EASA AD 2016-0083
31-JUL-2014		MOS HRS/MSC - AFL					
EASA 2014-0170 PARA (3.2)	COMPLYING WITH THE APPROVED AIRCRAFT MAINTENANCE PROGRAMME DESCRIBED IN PARAGRAPH (3.1) OF THIS AD					MANDATORY	COMPLIED WITH - SUPERSEDED BY EASA AD 2016-0083
31-JUL-2014		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2015-0060	FLIGHT CONTROLS - AILERON CONTROL SYSTEM / TAB COUNTER BALANCE WEIGHT - REPLACEMENT					MANDATORY	COMPLIED WITH - SEE SB 27-021
24-APR-2015		MOS HRS/MSC - AFL		14-AUG-2015 1734.75 1416			
EASA 2015-0060 PARA (1)	REPLACE THE AILERON TAB COUNTER BALANCE WEIGHT AND RE-IDENTIFY THE AILERON TRIM TAB ASSEMBLY (FOR AEROPLANES EQUIPPED WITH A PART IDENTIFIED BY PART NUMBER (P/N) IN TABLE 1 OF THIS AD).					MANDATORY	COMPLIED WITH - SEE SB 27-021
24-APR-2015		MOS HRS/MSC - AFL		14-AUG-2015 1734.75 1416			
EASA 2015-0060 PARA (2)	DO NOT INSTALL ON ANY AEROPLANE AN AILERON TRIM TAB ASSEMBLY HAVING A P/N AS IDENTIFIED IN TABLE 1 OF THIS AD					MANDATORY	COMPLIED WITH - SEE SB 27-021
24-APR-2015		MOS HRS/MSC - AFL		14-AUG-2015 1734.75 1416			
EASA 2015-0060 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, IT IS ALLOWED TO INSTALL ON AN AEROPLANE AN AILERON ASSEMBLY, HAVING A P/N AS IDENTIFIED IN TABLE 1 OF THIS AD, PROVIDED THAT IT IS DETERMINED THAT THIS DOES NOT HAVE AN AILERON TRIM TAB ASSEMBLY INSTALLED, HAVING A P/N AS IDENTIFIED IN TABLE 1 OF THIS AD.					MANDATORY	COMPLIED WITH - SEE SB 27-021
24-APR-2015		MOS HRS/MSC - AFL		14-AUG-2015 1734.75 1416			
EASA 2015-0111	FLIGHT CONTROLS – AILERON CONTROL SYSTEM / UNIVERSAL JOINTS – REPLACEMENT					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY (NO REPLACEMENT OF THE UNIVERSAL JOINTS P/N: 944.61.73.012 - 527.10.12.195 AND NO INSTALLATION KIT P/N 500.50.12.314)
30-JUN-2015		MOS HRS/MSC - AFL		18-JUN-2015			
EASA 2015-0111 PARA (1)	WITHIN THE COMPLIANCE TIME DEFINED IN TABLE 1 OF THIS AD, AS APPLICABLE, REPLACE EACH AFFECTED UNIVERSAL JOINT P/N 944.61.73.012 OR P/N 527.10.12.195 WITH A NEW UNIVERSAL JOINT P/N 527.10.12.195 (PURCHASED AFTER 01 MARCH 2015 AND MARKED WITH A PLACARD "RT IO") IN ACCORDANCE WITH THE INSTRUCTIONS OF PILATUS AIRCRAFT LTD. SB NO. 27-022.					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY (NO REPLACEMENT OF THE UNIVERSAL JOINTS P/N: 944.61.73.012 - 527.10.12.195 AND NO INSTALLATION KIT P/N 500.50.12.314)
30-JUN-2015		MOS HRS/MSC - AFL		18-JUN-2015			
EASA 2015-0111 PARA (2)	DO NOT INSTALL ON ANY AEROPLANE A UNIVERSAL JOINT P/N 944.61.73.012 OR P/N 527.10.12.195 195 (EXCEPT ONE MARKED WITH A PLACARD "RT IO") OR AN INSPECTION KIT P/N 500.50.12.314 PURCHASED BETWEEN 01 MARCH 2014 AND 28 FEBRUARY 2015, AS SPECIFIED IN PARAGRAPH (2.1) OR (2.2) OF THIS AD, AS APPLICABLE.					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY (NO REPLACEMENT OF THE UNIVERSAL JOINTS P/N: 944.61.73.012 - 527.10.12.195 AND NO INSTALLATION KIT P/N 500.50.12.314)
30-JUN-2015		MOS HRS/MSC - AFL		18-JUN-2015			
EASA 2016-0037	WINGS - WING-TO-FUSELAGE ATTACHMENT TORLON PLATES - INSPECTION					MANDATORY	COMPLIED WITH - EASA 2016-0037 PARA (5)
11-MAR-2016		MOS HRS/MSC - AFL		29-APR-2022 5874.75 5116			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0037 PARA (1)	DETERMINE WHETHER A WING WAS REMOVED AND REINSTALLED, OR REPLACED, BETWEEN JUNE 2007 AND THE EFFECTIVE DATE OF THIS AD.					MANDATORY	NOT APPLICABLE - N/A
11-MAR-2016		MOS		29-APR-2022			
		HRS/MSC -		5874.75			
		AFL		5116			
EASA 2016-0037 PARA (2)(LH)	INSPECT THE TORLON PLATES IN THE FORWARD LOWER WING-TO-FUSELAGE ATTACHMENTS (IF, DURING THE DETERMINATION, AS REQUIRED BY PARA (1), IT IS FOUND THAT A WING WAS REMOVED AND REINSTALLED, OR REPLACED, BETWEEN JUNE 2007 AND THE EFFECTIVE DATE OF THIS AD)					MANDATORY	NOT APPLICABLE - N/A
11-MAR-2016		MOS		29-APR-2022			
		HRS/MSC -		5874.75			
		AFL		5116			
EASA 2016-0037 PARA (2)(RH)	INSPECT THE TORLON PLATES IN THE FORWARD LOWER WING-TO-FUSELAGE ATTACHMENTS (IF, DURING THE DETERMINATION, AS REQUIRED BY PARA (1), IT IS FOUND THAT A WING WAS REMOVED AND REINSTALLED, OR REPLACED, BETWEEN JUNE 2007 AND THE EFFECTIVE DATE OF THIS AD)					MANDATORY	NOT APPLICABLE - N/A
11-MAR-2016		MOS		29-APR-2022			
		HRS/MSC -		5874.75			
		AFL		5116			
EASA 2016-0037 PARA (3)	INSPECT THE TORLON PLATES AND THE AFFECTED LUGS, AND REINSTALL THE TORLON PLATES IN THE CORRECT SEQUENCE (IF, DURING THE INSPECTION, AS REQUIRED BY PARAGRAPH (2) OF THIS AD, AN INCORRECT INSTALLATION OF TORLON PLATES IS FOUND, REMOVE THE AFFECTED TORLON PLATES)					MANDATORY	NOT APPLICABLE - N/A
11-MAR-2016		MOS		29-APR-2022			
		HRS/MSC -		5874.75			
		AFL		5116			
EASA 2016-0037 PARA (4)	CONTACT PILATUS AIRCRAFT LTD. (IF, DURING THE INSPECTION OF THE TORLON PLATES AND LUGS, AS REQUIRED BY PARA (3), ANY DAMAGE IS FOUND)					MANDATORY	NOT APPLICABLE - N/A
11-MAR-2016		MOS		29-APR-2022			
		HRS/MSC - (s)		5874.75			
		AFL		5116			
EASA 2016-0037 PARA (5)	FROM 11 MAR, 2016, IT IS ALLOWED TO INSTALL/RE-INSTALL A WING ON AN AEROPLANE, PROVIDED THAT, CONCURRENTLY WITH WING INSTALLATION, THE TORLON PLATES OF THE FWD LOWER WING-TO-FUSELAGE ATTACHMENT (BOTH LH & RH SIDES) OF THAT AEROPLANE PASS AN INSPECTION IAW THE INSTRUCTIONS OF PARA 3.B. OF SB NO.57-007. INSTALLING A WING ON AN AEROPLANE IAW THE INSTRUCTIONS OF PILATUS AMM 02049, R28 / LATER, OR AMM 02300, R11 / LATER, IS AN ACCEPTABLE ALTERNATIVE METHOD TO COMPLY WITH THIS INSPECTION REQUIREMENT.					MANDATORY	COMPLIED WITH - COMPLIED WITH
11-MAR-2016		MOS		29-APR-2022			
		HRS/MSC -		5874.75			
		AFL		5112			
EASA 2016-0081	POWER PLANT – ENGINE MOUNTING FRAME / SWAGED TUBE ENDS – INSPECTION					MANDATORY	- *A/S WAS SOLD, NO LONGER IN THE FLEET* APPLICABLE AT NEXT ANNUAL INSPECTION (MAX DUE 11000 FH OR 13500FC WHATEVER COMES FIRST)
02-MAY-2016		MOS					
		HRS/MSC -			11000 M		
		AFL			13500 M		
EASA 2016-0081 PARA (1)	INSPECT THE AEROPLANE TO DETERMINE WHETHER AN AFFECTED EMF, HAVING A SERIAL NUMBER (S/N), AS LISTED IN TABLE 2 IS INSTALLED.					MANDATORY	
02-MAY-2016		MOS		(EFF)			
		HRS/MSC	11000		11000 M		
		AFL	13500		13500 M		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0083	TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATION SECTION - AMENDMENT / IMPLEMENTATION					MANDATORY	COMPLIED WITH - SEE AMP 7.11
12-MAY-2016		MOS HRS/MSC - AFL		19-DEC-2023			
EASA 2017-0024	AIRCRAFT FLIGHT MANUAL - SECTION LIMITATIONS / PRIMUS APEX BUILD 10 OR 10.9 - AMENDMENT					MANDATORY	COMPLIED WITH - TR-38 INSERT INTO POH
27-FEB-2017		DAYS HRS/MSC - AFL		14-FEB-2017			
EASA 2019-0032	LANDING GEAR - MAIN LANDING GEAR SPRING PACK ASSEMBLIES - REPLACEMENT					MANDATORY	NOT APPLICABLE - By Effectivity: n/a by acft msn
01-MAR-2019		MOS HRS/MSC - AFL ACH FLTS					
EASA 2019-0129	STABILIZERS - HORIZONTAL STABILIZER REAR ATTACHMENT BOLTS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY BATCH NUMBER FITTED.
20-JUN-2019		MOS HRS/MSC - AFL		04-JUL-2019 4174.5 3567			
EASA 2019-0231	FLIGHT CONTROLS - FLAP DRIVE SYSTEM / FLAP FAIRINGS AND FRONT INBOARD TENSION RODS - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - By Effectivity: BY ACFT MSN
27-SEP-2019		MOS HRS/MSC - AFL ACH FLTS					
EASA 2020-0229	FUEL - FUEL TRANSFER EJECTOR - REPLACEMENT					MANDATORY	NOT APPLICABLE - BY PART: P/N :968.84.71.112 NOT INSTALLED
03-NOV-2020		MOS HRS/MSC - AFL		22-OCT-2020			
EASA 2021-0005	TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - AMENDMENT					MANDATORY	COMPLIED WITH - TAKE IN ACCOUNT IN JFL AMP
21-JAN-2021		MOS HRS/MSC - AFL		21-JAN-2021			
EASA 2021-0005 PARA (1) & (2)	REPLACE EACH COMPONENT BEFORE EXCEEDING THE APPLICABLE LIFE LIMIT, AND WITHIN THE THRESHOLDS AND INTERVALS (SEE NOTE 1 OF THIS AD), ACCOMPLISH ALL APPLICABLE MAINTENANCE TASKS; IN CASE OF FINDING DISCREPANCIES, WITHIN THE COMPLIANCE TIME SPECIFIED IN THE APPLICABLE ALS, ACCOMPLISH THE APPLICABLE CORRECTIVE ACTION(S) ANF . IF NO COMPLIANCE TIME IS IDENTIFIED IN THE APPLICABLE ALS, ACCOMPLISH THE APPLICABLE CORRECTIVE ACTION(S) BEFORE NEXT FLIGHT.					MANDATORY	NOT APPLICABLE - BOLTS REPLACED SEE TASK 32-30/518
21-JAN-2021		MOS HRS/MSC - AFL		07-JAN-2021			
EASA 2021-0005 PARA (3)	AMP REVISION: REVISE THE APPROVED AMP BY INCORPORATING THE LIMITATIONS, TASKS AND ASSOCIATED THRESHOLDS AND INTERVALS DESCRIBED IN THE APPLICABLE ALS, DEPENDING ON AEROPLANE CONFIGURATION.					MANDATORY	NOT APPLICABLE - BOLTS REPLACED SEE TASK 32-30/518
21-JAN-2021		MOS HRS/MSC - AFL		21-JAN-2021			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2021-0010	FUEL - INWARD VENT VALVE - MODIFICATION					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
25-JAN-2021		MOS HRS/MSC - AFL		14-JAN-2021			
EASA 2021-0110	LANDING GEAR - NOSE LANDING GEAR FORK ASSEMBLY - INSPECTION / REPLACEMENT					MANDATORY	- CANCELLED
05-MAY-2021		MOS HRS/MSC - AFL		22-APR-2021			
EASA 2021-0110-CN	ATA 32 - CANCELLED: LANDING GEAR - NOSE LANDING GEAR FORK ASSEMBLY - INSPECTION / REPLACEMENT					CANCELLED	- CANCELLED
03-NOV-2021		MOS HRS/MSC - AFL		(EFF)			
EASA 2021-0214	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - AMENDMENT					MANDATORY	COMPLIED WITH - INFORMATIONAL ONLY: TAKE IN ACCOUNT IN JETFLY AMP
01-OCT-2021		MOS HRS/MSC - AFL		20-SEP-2021			
EASA 2021-0214 PARA (1) & (2)	REPLACE EACH COMPONENT BEFORE EXCEEDING THE APPLICABLE LIFE LIMIT, AND WITHIN THE THRESHOLDS AND INTERVALS (SEE NOTE 1 OF THIS AD), ACCOMPLISH ALL APPLICABLE MAINTENANCE TASKS; IN CASE OF FINDING DISCREPANCIES, WITHIN THE COMPLIANCE TIME SPECIFIED IN THE APPLICABLE ALS, ACCOMPLISH THE APPLICABLE CORRECTIVE ACTION(S) ANF . IF NO COMPLIANCE TIME IS IDENTIFIED IN THE APPLICABLE ALS, ACCOMPLISH THE APPLICABLE CORRECTIVE ACTION(S) BEFORE NEXT FLIGHT.					MANDATORY	COMPLIED WITH - INFORMATIONAL ONLY: TAKE IN ACCOUNT IN JETFLY AMP
01-OCT-2021		MOS HRS/MSC - AFL		20-SEP-2021			
EASA 2021-0214 PARA (3)	REVISE THE APPROVED AMP BY INCORPORATING THE LIMITATIONS, TASKS AND ASSOCIATED THRESHOLDS AND INTERVALS DESCRIBED IN THE APPLICABLE ALS, AS APPLICABLE TO AEROPLANE MODEL AND DEPENDING ON AEROPLANE CONFIGURATION					MANDATORY	COMPLIED WITH - INFORMATIONAL ONLY: TAKE IN ACCOUNT IN JETFLY AMP
01-OCT-2021		MOS HRS/MSC - AFL		20-SEP-2021			
EASA 2022-0103	TIME LIMITS/MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - AMENDMENT					MANDATORY	COMPLIED WITH - INCORPORATED IN AMP - LEGACY 2.2 NG NCO AMP 7.7 NG CAT 1.2 AND NGX 1.6
23-JUN-2022		MOS HRS/MSC - AFL		13-JUN-2022			
EASA 2022-0158	LANDING GEAR - NOSE AND MAIN LANDING GEAR ACTUATORS - REPLACEMENT					MANDATORY	NOT APPLICABLE - By Effectivity- PC-12/47E Applicable to group 1 Aeroplanes MSN 1300, 1451 to 1663
18-AUG-2022		MOS HRS/MSC AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2022-0212	AIR CONDITIONING - VAPOUR CYCLE COOLING SYSTEM / COMPRESSOR CONDENSER CABLES - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: "N/A BY A/C MSN O2 BOTTLE FITTED 957.12.12.212 - LH REAR FUSELAGE - 2022-09-16"
01-NOV-2022		MOS HRS/MSC - AFL			24-OCT-2022		
EASA 2022-0212 PARA (1)	ONE-TIME INSPECTION OF THE POWER RETURN AND CHASSIS GROUNDING CABLE ATTACHMENT POINTS AT FRAME 37, INCLUDING ATTACHMENT PARTS					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: "N/A BY A/C MSN O2 BOTTLE FITTED 957.12.12.212 - LH REAR FUSELAGE - 2022-09-16"
01-NOV-2022		MOS HRS/MSC - AFL			25-OCT-2022		
EASA 2022-0212 PARA (3)	MODIFY THE INSTALLATION OF THE VCCS COMPRESSOR/CONDENSER POWER RETURN CABLES AND INSTALL AN ADDITIONAL ISOLATED VCCS CHASSIS GROUND CABLE					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: "N/A BY A/C MSN O2 BOTTLE FITTED 957.12.12.212 - LH REAR FUSELAGE - 2022-09-16"
01-NOV-2022		MOS HRS/MSC - AFL			25-OCT-2022		
EASA 2022-0245	LANDING GEAR - NOSE AND MAIN LANDING GEAR ACTUATORS - REPLACEMENT					MANDATORY	NOT APPLICABLE - BY SERIAL: NOT FITTED WITH ELDG, THESE ACTUATORS ARE NOT FITTED
26-DEC-2022		MOS HRS/MSC - AFL			13-DEC-2022		
EASA 2023-0184	TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS SECTION - AMENDMENT					MANDATORY	COMPLIED WITH
02-NOV-2023		MOS HRS/MSC - AFL			19-DEC-2023		
FAA 2009-05-07	ATA 27 - INSPECTION OF THE STICK-PUSHER SERVO-CABLES INSTALLATION AND ADJUSTMENT OF THE STICK-PUSHER CABLE TENSION, AS NECESSARY					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS HRS/MSC - AFL			31-JAN-2012 5 5		
FAA 2009-08-10	INCORPORATE PILATUS AIRCRAFT LTD. TEMPORARY REVISION NO. 11 TO PC-12/47E PILOT'S OPERATING HANDBOOK, INTO THE PILATUS PC-12/47E POH, AND REMOVE THE INFORMATION AND/OR THE COPY OF AD 2009-04-14 REQUIRED BY AD 2009-04-14 TO BE INSERTED IN THE POH					MANDATORY	NOT APPLICABLE - SUPERSEDED
20-APR-2009		MOS HRS/MSC - AFL			31-JAN-2012 5 5		
FAA 2009-14-13	MANDATE THE IMPLEMENTATION OF THE LATEST REVISION OF THE PC-12 AIRCRAFT MAINTENANCE MANUAL (AMM) CHAPTER 4 - AIRWORTHINESS LIMITATIONS SECTION-BY ESTABLISHING REPETITIVE INSPECTIONS FOR THE NLG RH UPPER DRAG LINKS P/N 532.20.12.140 AND P/N 532.20.12.289 (SUPERSEDED BY FAA AD 2012-26-16)					MANDATORY	NOT APPLICABLE - BY A/C SERIAL NUMBER
19-AUG-2009		MOS HRS/MSC - AFL			31-JAN-2012 5 5		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2009-14-13 PARA (1)	INSERT MANDATE THE IMPLEMENTATION OF THE LATEST REVISION OF THE PC-12 AIRCRAFT MAINTENANCE MANUAL (AMM) CHAPTER 4 - AIRWORTHINESS LIMITATIONS SECTION-BY ESTABLISHING REPETITIVE INSPECTIONS FOR THE NLG RH UPPER DRAG LINKS P/N 532.20.12.140 AND P/N 532.20.12.289 (SUPERSEDED BY FAA AD 2012-26-16) CHAPTER 04 "LIMITATIONS" INTO THE AIRCRAFT MAINTENANCE MANUAL					MANDATORY	NOT APPLICABLE - BY A/C SERIAL NUMBER
19-AUG-2009		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		AFL		5			
FAA 2009-14-13 PARA (2)	REPLACE MANDATE THE IMPLEMENTATION OF THE LATEST REVISION OF THE PC-12 AIRCRAFT MAINTENANCE MANUAL (AMM) CHAPTER 4 - AIRWORTHINESS LIMITATIONS SECTION-BY ESTABLISHING REPETITIVE INSPECTIONS FOR THE NLG RH UPPER DRAG LINKS P/N 532.20.12.140 AND P/N 532.20.12.289 (SUPERSEDED BY FAA AD 2012-26-16) TORQUE TUBE					MANDATORY	NOT APPLICABLE - BY A/C SERIAL NUMBER
19-AUG-2009		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		AFL		5			
FAA 2010-05-02	NAVIGATION - AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) - MODIFICATION/REPLACEMENT					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
01-APR-2010		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		AFL		5			
FAA 2010-17-09	INSPECT AND MODIFY POWER CONTROL LEVER REVERSE THRUST LATCH HANDLE					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
22-SEP-2010		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		AFL		5			
FAA 2010-17-09 PARA (F)(1)	INSPECT INSPECT AND MODIFY POWER CONTROL LEVER REVERSE THRUST LATCH HANDLE THE POWER CONTROL LEVER REVERSE THRUST LATCH HANDLE FOR FREE MOVEMENT					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
22-SEP-2010		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		AFL		5			
FAA 2010-17-09 PARA (F)(2)(I)	INSERT INSPECT AND MODIFY POWER CONTROL LEVER REVERSE THRUST LATCH HANDLE TEMPORARY REVISION NO. 12 TO POH					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
22-SEP-2010		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		AFL		5			
FAA 2010-17-09 PARA (F)(2)(II)	MODIFY INSPECT AND MODIFY POWER CONTROL LEVER REVERSE THRUST LATCH HANDLE THE ENGINE CONTROL CONSOLE ASSEMBLY, IF REQUIRED					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
22-SEP-2010		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		AFL		5			
FAA 2013-19-10	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) RETURN WIRE GROUND CONNECTION - MODIFICATION					MANDATORY	COMPLIED WITH - SEE SB 34-038
		MOS		29-NOV-2014			
		HRS/MSC	-(s)	1340.08			
		AFL		1076			
FAA 2014-22-01	TIME LIMITS/MAINTENANCE CHECKS - INCORPORATE NEW REVISIONS INTO THE LIMITATIONS SECTION CHAPTER 4, OF THE FAA-APPROVED MAINTENANCE PROGRAM (SUPERSEDED BY FAA AD 2016-26-08)					MANDATORY	COMPLIED WITH - SEE AIRCRAFT MAINTENANCE PROGRAM PC12 47E NG ED 5 AMDT 0
18-DEC-2014		MOS		29-NOV-2014			
		HRS/MSC	-(s)	1340.08			
		AFL		1076			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2014-22-01 PARA (F)(1)	INSERT DATA MODULE CODE 12-A-04-00-00-00A-000A-A, 12-B-04-00-00-00A-000A-A OF THE PILATUS AMM INTO THE LIMITATIONS SECTION OF THE FAA-APPROVED MAINTENANCE PROGRAM					MANDATORY	COMPLIED WITH - SEE AIRCRAFT MAINTENANCE PROGRAM PC12 47E NG ED 5 AMDT 0
18-DEC-2014		MOS HRS/MSC - (s) AFL		29-NOV-2014 1340.08 1076			
FAA 2014-22-01 PARA (F)(5)	INSPECT THE INBOARD FLAP DRIVE ARMS FOR CRACKS AND TAKE ALL NECESSARY CORRECTIVE ACTIONS.					MANDATORY	COMPLIED WITH - SEE AIRCRAFT MAINTENANCE PROGRAM PC12 47E NG ED 5 AMDT 0
18-DEC-2014		MOS HRS/MSC - (s) AFL		29-NOV-2014 1340.08 1076			
FAA 2015-14-10	FLIGHT CONTROLS - REPLACE THE AILERON TAB COUNTER BALANCE WEIGHT AND RE-IDENTIFY THE AILERON TRIM TAB ASSEMBLY					MANDATORY	COMPLIED WITH - SEE SB 27-021
20-AUG-2015		MOS HRS/MSC - (s) AFL		14-AUG-2015 1734.75 1416			
FAA 2015-19-15	FLIGHT CONTROLS - REPLACE WITH A NEW UNIVERSAL JOINT P/N 527.10.12.195 PURCHASED AFTER MARCH 1, 2015, AND MARKED WITH A PLACARD "RT IO" FOR AIRPLANES EQUIPPED WITH AILERON CONTROL SYSTEM UNIVERSAL JOINTS PART NUMBER (P/N) 944.61.73.012 OR P/N 527.10.12.195 OR UNIVERSAL JOINTS INSTALLED IN SERVICE THROUGH AN AILERON CONTROL SYSTEM INSPECTION KIT P/N 500.50.12.314, PURCHASED BETWEEN MARCH 1, 2014, AND FEBRUARY 28, 2015					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY ( NO REPLACEMENT OF THE UNIVERSAL JOINTS P/N : 944.61.73.012 - 527.10.12.195 AND NO INSTALLATION KIT P/N 500.50.12.314 )
03-NOV-2015		MOS HRS/MSC - (s) AFL		03-OCT-2015 1831.25 1487			
FAA 2016-12-01	WINGS - ACTIONS TO ADDRESS THE UNSAFE CONDITION AS INCORRECT INSTALLATION INSTRUCTIONS OF THE TORLON PLATES IN THE AIRPLANE MAINTENANCE MANUAL RESULTING IN THE INCORRECT INSTALLATION OF THE TORLON PLATES IN THE FORWARD WING-TO-FUSELAGE ATTACHMENT					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
15-JUL-2016		MOS HRS/MSC - AFL		16-JUN-2016			
FAA 2016-12-01 PARA (F)(1)(LH)	INSPECT THE TORLON PLATES IN THE FORWARD LOWER WING-TO-FUSELAGE ATTACHMENTS					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
15-JUL-2016		MOS HRS/MSC - AFL		16-JUN-2016			
FAA 2016-12-01 PARA (F)(1)(RH)	INSPECT THE TORLON PLATES IN THE FORWARD LOWER WING-TO-FUSELAGE ATTACHMENTS					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
15-JUL-2016		MOS HRS/MSC - AFL		16-JUN-2016			
FAA 2016-12-01 PARA (F)(2)	REMOVE THE AFFECTED TORLON PLATES, VISUALLY INSPECT THE TORLON PLATES AND THE AFFECTED LUGS USING A MIRROR AND LIGHT SOURCE (IF NECESSARY) FOR ANY DAMAGE, AND REINSTALL THE TORLON PLATES IN THE CORRECT SEQUENCE (IF AN INCORRECT INSTALLATION OF THE TORLON PLATES IS FOUND DURING THE INSPECTION REQUIRED IN PARA (F)(1)) (FOR ANY AIRPLANE THAT HAS HAD A WING REMOVED AND REINSTALLED OR REPLACED, BETWEEN JUNE 2007 AND JULY 15, 2016)					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
15-JUL-2016		MOS HRS/MSC - AFL		16-JUN-2016			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2016-12-01 PARA (F)(3)	CONTACT PILATUS (IF ANY DAMAGE IS FOUND DURING THE INSPECTION OF THE TORLON PLATES AND LUGS REQUIRED IN PARA (F)(2)) (FOR ANY AIRPLANE THAT HAS HAD A WING REMOVED AND REINSTALLED OR REPLACED, BETWEEN JUNE 2007 AND JULY 15, 2016)					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
15-JUL-2016		MOS HRS/MSC - (s) AFL		16-JUN-2016			
FAA 2016-12-01 PARA (F)(4)	AS OF JULY 15, 2016, DO NOT INSTALL OR REINSTALL A WING ON ANY AIRPLANE, UNLESS CONCURRENT WITH THE WING INSTALLATION, THE TORLON PLATES OF THE FORWARD LOWER WING-TO-FUSELAGE ATTACHMENT (BOTH LH AND RH SIDES) OF THE AIRPLANE ARE INSPECTED AND FOUND TO BE INSTALLED CORRECTLY IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS IN PARAGRAPH 3.B. OF PILATUS AIRCRAFT LTD. PC-12 SERVICE BULLETIN NO. 57-007, DATED SEPTEMBER 29, 2015					MANDATORY	COMPLIED WITH - SEE JFS-SM1-22 WC 57.040
15-JUL-2016		MOS HRS/MSC - AFL		29-APR-2022 5874.75 5116			
FAA 2016-18-05 PARA (F)(1)	ACCOMPLISH AN ULTRASONIC INSPECTION OF THE SWAGED ENGINE MOUNTING TUBE ENDS OF THE AFFECTED EMF					MANDATORY	
06-OCT-2016		MOS HRS/MSC 11000 AFL 13500			11000 13500		
FAA 2016-26-08	TIME LIMITS - THE LIMITATIONS WERE REVISED TO INCLUDE REPETITIVE INSPECTIONS OF THE MAIN LANDING GEAR (MLG) ATTACHMENT BOLTS					MANDATORY	COMPLIED WITH - SEE EASA AD 2016-0083 INCLUDED IN THE JETFLY P.E EDITION 5 AMENDMENT 4 IAW AMM PILATUS REPORT 02300 ISSUE 11.
09-FEB-2017		MOS HRS/MSC - AFL		15-JAN-2017 2568.42 2189			
FAA 2016-26-08 PARA (F)(1)	INSERT THE DATA MODULE CODE 12-A-04-00-00A-000A-A, 12-B-04-00-00A-000A-A OF THE PILATUS AMM INTO THE LIMITATIONS SECTION OF THE FAA-APPROVED MAINTENANCE PROGRAM					MANDATORY	COMPLIED WITH - SEE EASA AD 2016-0083 INCLUDED IN THE JETFLY P.E EDITION 5 AMENDMENT 4 IAW AMM PILATUS REPORT 02300 ISSUE 11.
09-FEB-2017		MOS HRS/MSC - AFL		15-JAN-2017 2568.42 2189			
FAA 2016-26-08 PARA (F)(5)	CONTACT PILATUS (IF A DISCREPANCY IS FOUND)					MANDATORY	COMPLIED WITH - SEE EASA AD 2016-0083 INCLUDED IN THE JETFLY P.E EDITION 5 AMENDMENT 4 IAW AMM PILATUS REPORT 02300 ISSUE 11.
09-FEB-2017		MOS HRS/MSC - AFL		15-JAN-2017 2568.42 2189			
FAA 2016-26-08 PARA (F)(6)	INSPECT THE MLG ATTACHMENT BOLTS FOR CRACKS AND CORROSION AND TAKE ALL NECESSARY CORRECTIVE ACTIONS					MANDATORY	COMPLIED WITH - SEE TASK 32-10/438 AND SEE WORK ORDER PC12-081-16 R3
09-FEB-2017		MOS HRS/MSC - AFL		08-APR-2016 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-04-06	CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016					MANDATORY	NOT APPLICABLE - Mfg Date
07-APR-2017		MOS HRS/MSC - (s) AFL ACH FLTS					
FAA 2017-11-16	NAVIGATION - INSERT TEMPORARY REVISION NO. 38 TO PC-12/47E PILOT'S OPERATING HANDBOOK, AIRPLANE FLIGHT MANUAL 02277, SECTION 2-LIMITATIONS, REPORT NO: 02277, DATED FEBRUARY 8, 2017					MANDATORY	COMPLIED WITH - TR-38 PUT INTO THE POH
13-JUL-2017		MOS HRS/MSC - AFL		14-FEB-2017			
FAA 2018-21-14 PARA (G)	REQUIRED ACTIONS					MANDATORY	NOT APPLICABLE - By Part: BY HARNESS P/N
		MOS HRS/MSC - AFL ACH FLTS					
FAA 2020-21-23	HORIZONTAL STABILIZER REAR ATTACHMENT BOLT REPLACEMENT					MANDATORY	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: COMPLIED WITH IAW SB 55-004
07-DEC-2020		MOS HRS/MSC - AFL		03-NOV-2020			
FAA 2020-22-05	MLG SPRING PACK ASSEMBLY REPLACEMENT					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: AIRCRAF S/N
07-DEC-2020		MOS HRS/MSC - AFL		04-NOV-2020			
FAA 2021-02-04	FLIGHT CONTROLS - FLAP DRIVE SYSTEM / FLAP FAIRINGS AND FRONT INBOARD TENSION RODS - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN IAW SB 27-026
30-MAR-2021		MOS HRS/MSC - AFL		26-FEB-2021			
FAA 2021-02-04 PARA (F) (1)	INSPECT THE LEFT-HAND (LH) AND RIGHT-HAND (RH) IFFAS FOR CORRECT SHAPE AND CLEARANCE WITH THE LH AND RH TENSION RODS AND ACCOMPLISH ALL APPLICABLE CORRECTIVE ACTIONS					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN IAW SB 27-026
30-MAR-2021		MOS HRS/MSC - AFL		26-FEB-2021			
FAA 2021-02-04 PARA (F) (2)	INSPECT THE FRONT INBOARD LH AND RH TENSION RODS FOR CHAFING AND REPLACE THE TENSION ROD, IF THE LH OR RH TENSION ROD HAS ANY CHAFING					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN IAW SB 27-026
30-MAR-2021		MOS HRS/MSC - AFL		26-FEB-2021			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-24-01	FUSELAGE - STRAKE ATTACHMENT BRACKETS AND SURROUNDING STRUCTURE - INSPECT/REPLACE					MANDATORY	NOT APPLICABLE - Not Equipped- Supplemental Type Certificate No. SA00634DE. Not installed
13-JAN-2022		MOS HRS/MSC AFL ACH FLTS					
FAA 2022-07-04	FUEL - INWARD VENT VALVES - MODIFICATION					MANDATORY	NOT APPLICABLE - By Effectivity- BY AIRCRAFT SERIAL NUMBER
09-MAY-2022		MOS HRS/MSC AFL ACH FLTS					
FAA 2022-10-01	FUEL TRANSFER EJECTOR REMOVE/REPLACE					MANDATORY	NOT APPLICABLE - By Effectivity- FOR PC-12/47E MSN 2001 AND LARGER
24-JUN-2022		MOS HRS/MSC AFL ACH FLTS		23-MAY-2022			
FAA 2022-19-03	REVISE THE ALS SECTION OF THE EXISTING AMM OR INSTRUCTIONS FOR CONTINUED AIRWORTHINES					MANDATORY	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: REFER TO EASA AD 2021-0005 MLG BOTTOM ATTACHMENT BOLT (VLG) AND AD 2021-0214 RUDDER BELLCRANK.
27-OCT-2022		MOS HRS/MSC - AFL		27-SEP-2022			
FAA 2023-07-08	LANDING GEAR - CORROSION ON THE ACTUATOR ATTACHMENT LUG AREAS UNDERNEATH THE ANTI-ROTATION PADS OF THE MAIN LANDING GEAR (MLG) AND NOSE LANDING GEAR (NLG)					MANDATORY	NOT APPLICABLE - BY SERIAL: BY A/C MSN (NOT FITTED W/ ELDG, THESE ACTUATORS ARE NOT FITTED)
FAA 39-22410 19-MAY-2023		MOS HRS/MSC - AFL		17-APR-2023			
FAA 2023-07-08 PARA (H)(1)(I)	REPLACE EACH AFFECTED PART AS DEFINED IN PARAGRAPH (F)(1) OF THIS AD WITH A SERVICEABLE PART..					MANDATORY	NOT APPLICABLE - BY SERIAL: BY A/C MSN (NOT FITTED W/ ELDG, THESE ACTUATORS ARE NOT FITTED)
19-MAY-2023		MOS HRS/MSC - AFL		17-APR-2023			
FAA 2023-07-08 PARA (H)(1)(II)	REPLACE EACH AFFECTED PART AS DEFINED IN PARAGRAPH (F)(1) OF THIS AD					MANDATORY	NOT APPLICABLE - BY SERIAL: BY A/C MSN (NOT FITTED W/ ELDG, THESE ACTUATORS ARE NOT FITTED)
19-MAY-2023		MOS HRS/MSC - AFL		17-APR-2023			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2023-07-08 PARA (H)(1)(III)	REPLACE EACH AFFECTED PART AS DEFINED IN PARAGRAPH (F)(1) OF THIS AD					MANDATORY	NOT APPLICABLE - BY SERIAL: BY A/C MSN (NOT FITTED W/ ELDG, THESE ACTUATORS ARE NOT FITTED)
19-MAY-2023		MOS HRS/MSC - AFL		17-APR-2023			
FAA 2023-09-12	INSPECTION OF AIR CONDITIONING SYSTEM WIRING					MANDATORY	NOT APPLICABLE - BY SERIAL: N/A BY A/C MSN - MODEL PC-12, PC-12/45, PC-12/47, AND PC-12/47E MSN 466, 467, 725, 861, 1032, 1052, 1082, 1115, 1232, 1411, 1428, 1439, 1530,1541, 1663, 1725, AND 1802
39-22435 05-JUL-2023		MOS HRS/MSC - AFL		01-JUN-2023			
FAA 2023-09-12 PARA (G)(1)	INSPECT THE POWER RETURN AND CHASSIS GROUNDING CABLE ATTACHMENT POINTS AT FRAME 37					MANDATORY	NOT APPLICABLE - BY SERIAL: N/A BY A/C MSN - MODEL PC-12, PC-12/45, PC-12/47, AND PC-12/47E MSN 466, 467, 725, 861, 1032, 1052, 1082, 1115, 1232, 1411, 1428, 1439, 1530,1541, 1663, 1725, AND 1802
39-22435 05-JUL-2023		MOS HRS/MSC - AFL		01-JUN-2023			
FAA 2023-09-12 PARA (G)(3)	MODIFY THE INSTALLATION OF THE VCCS COMPRESSOR/CONDENSER POWER RETURN CABLES AND INSTALL AN ADDITIONAL ISOLATED VCCS CHASSIS GROUND CABLE					MANDATORY	NOT APPLICABLE - BY SERIAL: N/A BY A/C MSN - MODEL PC-12, PC-12/45, PC-12/47, AND PC-12/47E MSN 466, 467, 725, 861, 1032, 1052, 1082, 1115, 1232, 1411, 1428, 1439, 1530,1541, 1663, 1725, AND 1802
39-22435 05-JUL-2023		MOS HRS/MSC - AFL		01-JUN-2023			
FAA 2023-12-17	HORIZONTAL STABILIZER - SPAR/RIB - REVISING THE AIRWORTHINESS LIMITATIONS SECTION (ALS) OF THE EXISTING AIRCRAFT MAINTENANCE MANUAL (AMM)					MANDATORY	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: INCORPORATED IN AMP - LEGACY 2.2 NG NCO AMP 7.6 NG CAT 1.1 AND NGX 1.5
39-22475 07-AUG-2023		MOS HRS/MSC - AFL		05-JUL-2023			
FOCA HB-2007-390	TORQUE OIL PRESSURE PIPE & HOSE ASSEMBLIES - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - BY MODEL
		MOS HRS/MSC A/R AFL					
FOCA HB-2008-301	NEW LIFE LIMIT OF 10,000 FLIGHT HOURS, FOR THE PITCH TRIM ACTUATOR ATTACHMENT PARTS					MANDATORY	NOT APPLICABLE - BY A/C MODEL
		MOS HRS/MSC - AFL		31-JAN-2012 5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>APPLIANCE - 1314/VH-AL4</b>							
CAA IL ISR-I-53-2019-12-6	APPLIANCE AD - FUSELAGE - LOADING RESTRICTIONS DUE TO 9G BARRIER MANUFACTURING NON COMPLIANCE					MANDATORY	NOT APPLICABLE - By Effectivity: APPLIES TO 737-300, 737-400 and 737-700 airplanes
12-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
CAA UK G-2022-0011	APPLIANCE AD - ATA 25 - EQUIPMENT / FURNISHINGS - PILOT & CO-PILOT SEATS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - By Part- BY PART NUMBER
23-JUN-2022		MOS HRS/MSC - AFL ACH FLTS		13-JUN-2022			
CAA UK G-2022-0011 PARA (1)	INSPECT ANY AFFECTED SPRING OF EACH AFFECTED SEAT IN ACCORDANCE WITH THE INSTRUCTIONS OF THE INSPECTION SB (SB 063-25-14)					MANDATORY	NOT APPLICABLE - By Part- BY PART NUMBER
23-JUN-2022		MOS HRS/MSC AFL ACH FLTS					
CAA UK G-2022-0011 PARA (2)	REPLACE BOTH SPRINGS IN ACCORDANCE WITH THE INSTRUCTIONS OF THE INSPECTION SB (SB 063-25-14)					MANDATORY	NOT APPLICABLE - By Part- BY PART NUMBER
23-JUN-2022		MOS HRS/MSC - AFL ACH FLTS					
CAA UK G-2022-0011 PARA (4)	MODIFY AND RE-IDENTIFY EACH AFFECTED SEAT					MANDATORY	NOT APPLICABLE - By Part- BY PART NUMBER
23-JUN-2022		MOS HRS/MSC AFL ACH FLTS					
EASA 2007-0256-CN	APPLIANCE AD - ATA 25 - CANCELLED: EQUIPMENT / FURNISHINGS - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE - CANCELLED
		MOS HRS/MSC - AFL		12-MAY-2021			
EASA 2009-0251-E	APPLIANCE/EMERGENCY AD - FIRE PROTECTION - PORTABLE FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY EXTINGUISHER SERIAL NUMBER
26-NOV-2009		MOS HRS/MSC - AFL		29-NOV-2011 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2009-0251-E PARA (1)	IDENTIFY FIRE PROTECTION - PORTABLE FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT FG NUMBER AND SERIAL NUMBER					MANDATORY	NOT APPLICABLE - BY EXTINGUISHER SERIAL NUMBER
26-NOV-2009		DAYS		30-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
EASA 2009-0251-E PARA (2)	REPLACE FIRE PROTECTION - PORTABLE FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT AFFECTED SERIAL NUMBER PORTABLE FIRE EXTINGUISHERS					MANDATORY	NOT APPLICABLE - BY EXTINGUISHER SERIAL NUMBER
26-NOV-2009		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
EASA 2009-0262	APPLIANCE AD - FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT					SUPERSEDED	NOT APPLICABLE - N/A BY FIRE EXTINGUISHER SERIAL NUMBER
29-DEC-2009		DAYS					
		HRS/MSC -		0			
		AFL		0			
EASA 2009-0262 R01	APPLIANCE AD - FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY EXTINGUISHER SERIAL NUMBER
10-FEB-2010		DAYS		30-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION					MANDATORY	NOT APPLICABLE - BY PART NUMBER
14-OCT-2014		MOS					
		HRS/MSC -					
		AFL					
EASA 2010-0003 R02 PARA (1)	VERIFY AIRCRAFT TYPE MODE STRAPPING CODE S SET TO '0' (ZERO) OR '1', AS DEFINED IN ROCKWELL-COLLINS SERVICE LETTER TDR-94( ) SIL 07-2.					MANDATORY	NOT APPLICABLE - BY PART NUMBER
14-OCT-2014		MOS		(EFF)			
		HRS/MSC -					
		AFL					
EASA 2010-0003 R02 PARA (2)	EXEMPTIONS: DASSAULT AEROPLANES					MANDATORY	NOT APPLICABLE - BY PART NUMBER
14-OCT-2014		MOS					
		HRS/MSC -					
		AFL					
EASA 2010-0003 R02 PARA (3)	EXEMPTIONS: ATR 42 AND ATR 72 AEROPLANES					MANDATORY	NOT APPLICABLE - BY PART NUMBER
14-OCT-2014		MOS					
		HRS/MSC -					
		AFL					
EASA 2010-0003 R02 PARA (4)	EXEMPTIONS: SAAB 2000 AEROPLANES					MANDATORY	NOT APPLICABLE - BY PART NUMBER
14-OCT-2014		MOS					
		HRS/MSC -					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2010-0003 R02 PARA (5)	EXEMPTIONS: BOMBARDIER AEROSPACE (CANADAIR) AEROPLANES: CL-600-2B16 (604 VARIANT) AND CL-600-2B19 (RJ100 AND RJ200)					MANDATORY	NOT APPLICABLE - BY PART NUMBER
14-OCT-2014		MOS	HRS/MSC -	AFL			
EASA 2010-0003 R02 PARA (6)	EXEMPTIONS: CESSNA AIRCRAFT COMPANY AEROPLANES: CESSNA MODEL 525, 525A, 525B; AND CESSNA MODEL 525, 525A, 525B, 560; 560XL					MANDATORY	NOT APPLICABLE - BY PART NUMBER
14-OCT-2014		MOS	HRS/MSC -	AFL			
EASA 2010-0003 R02 PARA (7)	EXEMPTIONS: PIAGGIO AERO INDUSTRIES AEROPLANES: P.180 (AVANTI) AND P.180 (AVANTI II)					MANDATORY	NOT APPLICABLE - BY PART NUMBER
14-OCT-2014		MOS	HRS/MSC -	AFL			
EASA 2010-0062	APPLIANCE AD - FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT					SUPERSEDED	NOT APPLICABLE - BY EXTINGUISHER SERIAL NUMBER
14-APR-2010		MOS	HRS/MSC -	AFL	29-NOV-2011 0 0		
EASA 2010-0062 R01	APPLIANCE AD - FIRE PROTECTION - HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY EXTINGUISHER SERIAL NUMBER
31-MAY-2010		MOS	HRS/MSC -	AFL	29-NOV-2011 0 0		
EASA 2012-0254 R01	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY PART NUMBER
21-DEC-2012		MOS	HRS/MSC -	AFL	22-JUL-2016		
EASA 2012-0254 R01 PARA (1)	INSPECT EACH FLIGHT CREW OXYGEN MASK REGULATOR TO IDENTIFY THE P/N AND S/N					MANDATORY	NOT APPLICABLE - BY PART NUMBER
21-DEC-2012		DAYS	HRS/MSC -	AFL	22-JUL-2016		
EASA 2012-0254 R01 PARA (2.1)	REPLACE EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - BY PART NUMBER
21-DEC-2012		DAYS	HRS/MSC -	AFL	22-JUL-2016		
EASA 2012-0254 R01 PARA (2.2)	AMEND THE AIRCRAFT FLIGHT MANUAL (AFM) AND INSTALL A PLACARD					MANDATORY	NOT APPLICABLE - BY PART NUMBER
21-DEC-2012		DAYS	HRS/MSC -	AFL	22-JUL-2016		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2012-0254 R01 PARA (3)	REPLACE EACH AFFECTED FLIGHT CREW OXYGEN MASK REGULATOR					MANDATORY	NOT APPLICABLE - BY PART NUMBER
21-DEC-2012		MOS HRS/MSC - AFL		22-JUL-2016			
EASA 2013-0020 R01	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - IA BY A/C TYPE (ONIY FOR PC-1 2/45/47)
12-MAR-2013		MOS HRS/MSC - AFL		11-APR-2013 399.58 323			
EASA 2013-0020 R01 PARA (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - IA BY A/C TYPE (ONIY FOR PC-1 2/45/47)
12-MAR-2013		MOS HRS/MSC - AFL		11-APR-2013 399.58 323			
EASA 2013-0020 R01 PARA (2)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - IA BY A/C TYPE (ONIY FOR PC-1 2/45/47)
12-MAR-2013		MOS HRS/MSC - (s) AFL		11-APR-2013 399.58 323			
EASA 2013-0020 R01 PARA (3)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - IA BY A/C TYPE (ONIY FOR PC-1 2/45/47)
12-MAR-2013		MOS HRS/MSC - (s) AFL		11-APR-2013 399.58 323			
EASA 2013-0020 R01 PARA (4)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD.					MANDATORY	NOT APPLICABLE - IA BY A/C TYPE (ONIY FOR PC-1 2/45/47)
12-MAR-2013		MOS HRS/MSC - AFL		11-APR-2013 399.58 323			
EASA 2013-0020 R02	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY A/C TYPE.
11-JUL-2013		MOS HRS/MSC - AFL		09-AUG-2013 595.92 471			
EASA 2013-0020 R02 PARA (1)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - BY A/C TYPE.
11-JUL-2013		MOS HRS/MSC - AFL		09-AUG-2013 595.92 471			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R02 PARA (2)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - BY A/C TYPE.
11-JUL-2013		MOS		09-AUG-2013			
		HRS/MSC - (s)		595.92			
		AFL		471			
EASA 2013-0020 R02 PARA (3)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - BY A/C TYPE.
11-JUL-2013		MOS		09-AUG-2013			
		HRS/MSC - (s)		595.92			
		AFL		471			
EASA 2013-0020 R02 PARA (4)	EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - BY A/C TYPE.
11-JUL-2013		MOS		09-AUG-2013			
		HRS/MSC -		595.92			
		AFL		471			
EASA 2013-0020 R03	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NO EVOLUTION WITH R2
28-MAR-2014		MOS		02-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0020 R03 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - NO EVOLUTION WITH R2
28-MAR-2014		MOS		02-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0020 R03 PARA (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - NO EVOLUTION WITH R2
28-MAR-2014		MOS		02-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0020 R03 PARA (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - NO EVOLUTION WITH R2
28-MAR-2014		MOS		02-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0020 R03 PARA (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - NO EVOLUTION WITH R2
28-MAR-2014		MOS		02-APR-2014			
		HRS/MSC -					
		AFL					
EASA 2013-0020 R04	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NO REPAIR OR MODIFICATION PERFORMED ON SAFETY BELT ORIGINAL SAFETY BELT INSTALLED
11-JUL-2014		MOS		09-JUL-2014			
		HRS/MSC - (s)					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2013-0020 R04 PARA (1)	INSPECT THE MARKINGS OF SAFETY BELTS AND/OR TORSO RESTRAINT SYSTEMS, TO DETERMINE IF THEY HAVE BEEN MAINTAINED OR REPAIRED BY ORGANISATIONS OTHER THAN THE DESIGN APPROVAL HOLDER					MANDATORY	NOT APPLICABLE - NO REPAIR OR MODIFICATION PERFORMED ON SAFETY BELT ORIGINAL SAFETY BELT INSTALLED
11-JUL-2014		MOS HRS/MSC - (s) AFL		09-JUL-2014			
EASA 2013-0020 R04 PARA (2)	VERIFY IF THE ORGANISATION IS LISTED AMONG THE AUTHORIZED MAINTENANCE OR REPAIR ORGANISATION REFERENCE DOCUMENTS QUOTED IN THE REF. PUBLICATIONS SECTION OF THIS AD					MANDATORY	NOT APPLICABLE - NO REPAIR OR MODIFICATION PERFORMED ON SAFETY BELT ORIGINAL SAFETY BELT INSTALLED
11-JUL-2014		MOS HRS/MSC - (s) AFL		09-JUL-2014			
EASA 2013-0020 R04 PARA (3)	REMOVE AND REPLACE BELTS NOT MEETING THE CERTIFICATION REQUIREMENTS OR MAKE RELEVANT SEAT INOPERATIVE					MANDATORY	NOT APPLICABLE - NO REPAIR OR MODIFICATION PERFORMED ON SAFETY BELT ORIGINAL SAFETY BELT INSTALLED
11-JUL-2014		MOS HRS/MSC - (s) AFL		09-JUL-2014			
EASA 2013-0020 R04 PARA (4)	AFTER 14 FEBRUARY 2013 [THE EFFECTIVE DATE OF THE ORIGINAL ISSUE OF THIS AD], DO NOT INSTALL SAFETY BELTS OR TORSO RESTRAINT SYSTEMS ON ANY AIRCRAFT, UNLESS INSPECTED AND CORRECTED IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - NO REPAIR OR MODIFICATION PERFORMED ON SAFETY BELT ORIGINAL SAFETY BELT INSTALLED
11-JUL-2014		MOS HRS/MSC - (s) AFL		09-JUL-2014			
EASA 2014-0019	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT (SUPERSEDED BY EASA 2014-0095)					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY EQUIPMENT
31-JAN-2014		MOS HRS/MSC - AFL		17-FEB-2014			
EASA 2014-0019 PARA (1)	AMEND THE AFM OF THE AFFECTED AIRCRAFT					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY EQUIPMENT
31-JAN-2014		DAYS HRS/MSC - AFL		17-FEB-2014			
EASA 2014-0019 PARA (2)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() OR 503-42-()					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY EQUIPMENT
31-JAN-2014		MOS HRS/MSC - AFL		17-FEB-2014			
EASA 2014-0019 PARA (3)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() OR P/N 503-42-(), EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A, OR 503-24-()-A, OR 503-24-G, OR 503-24-()-G, OR 503-42-A OR 503-42-()-A OR 503-42-G OR 503-42-()-G, ON AN AIRCRAFT, UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY EQUIPMENT
31-JAN-2014		MOS HRS/MSC - AFL		17-FEB-2014			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0019 PARA (4)	REMOVE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY EQUIPMENT
31-JAN-2014		MOS HRS/MSC - AFL		17-FEB-2014			
EASA 2014-0088	APPLIANCE AD - COMMUNICATIONS - COCKPIT VOICE RECORDER - REPLACEMENT					MANDATORY	NOT APPLICABLE - BY PART NUMBER
29-APR-2014		MOS HRS/MSC - AFL		30-APR-2014			
EASA 2014-0088 PARA (1)	REMOVE THE TEAM CVR P/N AP71232101 OR P/N AP71231101, AS APPLICABLE, FROM THE AIRCRAFT AND, DEPENDING ON OPERATIONAL REGULATIONS, INSTALL A SERVICEABLE CVR IN ACCORDANCE WITH APPROVED AIRCRAFT MODIFICATION INSTRUCTIONS					MANDATORY	NOT APPLICABLE - BY PART NUMBER
29-APR-2014		MOS HRS/MSC - AFL		30-APR-2014			
EASA 2014-0088 PARA (2)	DO NOT INSTALL ON ANY AIRCRAFT A TEAM CVR P/N AP71232101 OR P/N AP71231101, AS REQUIRED BY PARAGRAPH (2.1) OR (2.2) OF THIS AD, AS APPLICABLE					MANDATORY	NOT APPLICABLE - BY PART NUMBER
29-APR-2014		MOS HRS/MSC - AFL		30-APR-2014			
EASA 2014-0095	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT					MANDATORY	NOT APPLICABLE - NOT EQUIPED
07-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0095 PARA (1)	INSTALL A PLACARD "DO NOT USE TRANSMIT OVER WATER" NEXT TO THE CPI CONTROL PANEL/AMEND THE AFM OF THE AIRCRAFT					MANDATORY	NOT APPLICABLE - NOT EQUIPED
07-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0095 PARA (2)	INCORPORATION OF APPENDIX A OF THIS AD INTO THE EMERGENCY PROCEDURES SECTION OF THE AFM OF THE AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1.2) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
07-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0095 PARA (3)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) WITH AN IMPROVED PART P/N 503-24-A, OR P/N 503-24-()-A, OR P/N 503-24-G, OR P/N 503-24-()-G, OR P/N 503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G (THAT INCORPORATES AUTOMATIC CPI DEPLOYMENT AFTER MANUAL ACTIVATION) IN ACCORDANCE WITH AN APPROVED AIRCRAFT MAINTENANCE INSTRUCTION					MANDATORY	NOT APPLICABLE - NOT EQUIPED
07-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0095 PARA (4)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A OR P/N 503-24-()-A OR P/N 503-24-G OR P/N 503-24-()-G OR P/N 503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G ON AN AIRCRAFT UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
07-MAY-2014		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0095 PARA (5)	REMOVE THE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
07-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
EASA 2014-0095 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT					MANDATORY	NOT APPLICABLE - NOT EQUIPED
12-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
EASA 2014-0095 R01 PARA (1)	INSTALL A PLACARD "DO NOT USE TRANSMIT OVER WATER" NEXT TO THE CPI CONTROL PANEL/AMEND THE AFM OF THE AIRCRAFT					MANDATORY	NOT APPLICABLE - NOT EQUIPED
12-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
EASA 2014-0095 R01 PARA (2)	INCORPORATION OF APPENDIX A OF THIS AD INTO THE EMERGENCY PROCEDURES SECTION OF THE AFM OF THE AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1.2) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
12-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
EASA 2014-0095 R01 PARA (3)	REPLACE THE SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) WITH AN IMPROVED PART P/N 503-24-A, OR P/N 503-24-()-A, OR P/N 503-24-G, OR P/N 503-24-()-G, OR P/N 503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G (THAT INCORPORATES AUTOMATIC CPI DEPLOYMENT AFTER MANUAL ACTIVATION) IN ACCORDANCE WITH AN APPROVED AIRCRAFT MAINTENANCE INSTRUCTION					MANDATORY	NOT APPLICABLE - NOT EQUIPED
12-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
EASA 2014-0095 R01 PARA (4)	DO NOT INSTALL A HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134 OR 15-503-134-1 EQUIPPED WITH CONTROL PANEL P/N 503-22-(), BEACON RELEASE UNIT P/N 503-21 AND SYSTEM INTERFACE UNIT P/N 503-24-() (INCLUDING 503-24) OR P/N 503-42-() (INCLUDING 503-42) EXCLUDING SYSTEM INTERFACE UNIT P/N 503-24-A OR P/N 503-24-()-A OR P/N 503-24-G OR P/N 503-24-()-G OR P/N 503-42-A OR P/N 503-42-()-A OR P/N 503-42-G OR P/N 503-42-()-G ON AN AIRCRAFT UNLESS IN COMPLIANCE WITH THE REQUIREMENTS OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
12-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
EASA 2014-0095 R01 PARA (5)	REMOVE THE AFM AMENDMENT AND PLACARD AS REQUIRED BY PARAGRAPH (1) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
12-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
EASA 2014-0125	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR SYSTEM - REPLACEMENT; AIRCRAFT FLIGHT MANUAL - AMENDMENT					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					
EASA 2014-0125 PARA (1)	AMEND THE AFM OF AFFECTED AIRCRAFT TO INCORPORATE TEMPORARY CPI SIU OPERATING PROCEDURES BY INSERTING A COPY OF APPENDIX 1 OF THIS AD (OR ITS TEXT) INTO THE APPLICABLE NORMAL PROCEDURES SECTION OF THE AFM					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAY-2014		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0125 PARA (2)	ACCOMPLISH THE COMPLETE START-UP PROCEDURE/APPLICABLE START-UP PROCEDURE/SHUTDOWN PROCEDURE					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0125 PARA (3)	COMPLIANCE WITH THE REQUIREMENTS OF PARAGRAPH (2) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0125 PARA (4)	REPLACE THE CPI SIU HAVING P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 WITH AN IMPROVED UNIT P/N 503-24G OR P/N 503-24-2G OR P/N 503-24-6G IN ACCORDANCE WITH THE APPLICABLE AIRCRAFT DESIGN APPROVAL HOLDER SERVICE INSTRUCTIONS AND, CONCURRENTLY, REMOVE THE TEMPORARY AFM PROCEDURE AS REQUIRED BY PARAGRAPH (2) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0125 PARA (5)	MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (4) OF THIS AD CONSTITUTES TERMINATING ACTION FOR ACCOMPLISHMENT OF THE PROCEDURES AS REQUIRED BY PARAGRAPH (2) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0125 PARA (6)	FROM THE EFFECTIVE DATE OF THIS AD, INSTALLATION ON AN AIRCRAFT OF AN HR SMITH (TECHNICAL DEVELOPMENTS) CPI SYSTEM SERIES 15-503-134-1 EQUIPPED WITH BRU P/N 503-21-1 AND SIU P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 IS ALLOWED, PROVIDED THE AIRCRAFT IS OPERATED IN COMPLIANCE WITH THE PROCEDURES AS REQUIRED BY THIS AD					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0125 PARA (7)	AFTER REPLACEMENT OF THE CPI SIU ON AN AIRCRAFT AS REQUIRED BY PARAGRAPH (4) OF THIS AD, DO NOT INSTALL AN SIU P/N 503-24 OR P/N 503-24-2 OR P/N 503-24-6 ON THE CPI SYSTEM OF THAT AIRCRAFT					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAY-2014		MOS HRS/MSC - AFL					
EASA 2014-0142	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY PART NUMBER
18-JUN-2014		MOS HRS/MSC - AFL		05-JUN-2014			
EASA 2014-0142 PARA (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445952 WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS					MANDATORY	NOT APPLICABLE - BY PART NUMBER
18-JUN-2014		MOS HRS/MSC - AFL		05-JUN-2014			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0142 PARA (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD	MOS			05-JUN-2014	MANDATORY	NOT APPLICABLE - BY PART NUMBER
18-JUN-2014		HRS/MSC - AFL					
EASA 2014-0142 PARA (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD.	MOS			05-JUN-2014	MANDATORY	NOT APPLICABLE - BY PART NUMBER
18-JUN-2014		HRS/MSC - AFL					
EASA 2014-0142 R01	APPLIANCE AD - OXYGEN – OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE – IDENTIFICATION / REPLACEMENT	MOS			20-JUN-2014	MANDATORY	NOT APPLICABLE - BY PART NUMBER
18-JUN-2014		HRS/MSC - AFL					
EASA 2014-0142 R01 PARA (1)	ACCOMPLISH ACCOMPLISH THE ACTIONS AS SPECIFIED IN PARAGRAPHS (1.1) AND (1.2) OF THIS AD - DETERMINE THE DATE OF MANUFACTURING / REPLACE THE HARNESS INFLATION HOSE P/N 445186 OR P/N 445952, AS APPLICABLE, WITH A SERVICEABLE PART, OR REMOVE THE INFLATABLE HARNESS FROM THE MASK REGULATOR AND REPLACE IT WITH A SERVICEABLE HARNESS	MOS			20-JUN-2014	MANDATORY	NOT APPLICABLE - BY PART NUMBER
18-JUN-2014		HRS/MSC - AFL					
EASA 2014-0142 R01 PARA (2)	ACCOMPLISH AN OXYGEN MASK REGULATOR EQUIPPED WITH A P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS HAVING A DMF CODE OF NOVEMBER 2008 (0845-S OR 08/45-S) OR EARLIER, AND THOSE WITH A DMF OF JANUARY 2011 (1101-S OR 11/01-S) OR LATER, IS EXCLUDED FROM THE INSPECTION AND REPLACEMENT REQUIREMENTS OF PARAGRAPH (1) OF THIS AD	MOS			20-JUN-2014	MANDATORY	NOT APPLICABLE - BY PART NUMBER
18-JUN-2014		HRS/MSC - AFL					
EASA 2014-0142 R01 PARA (3)	ACCOMPLISH IT IS ALLOWED TO INSTALL ON AN AEROPLANE A FLIGHT CREW OXYGEN MASK REGULATOR, HAVING A P/N AS IDENTIFIED IN SECTION 1.A.(1) OF ZODIAC AEROTECHNICS SB MC10-35-274, PROVIDED IT HAS BEEN DETERMINED THAT A P/N MXH21-31 INFLATABLE HARNESS IS INSTALLED, OR THAT THE P/N MXH20-1 OR P/N MXH21-1 INFLATABLE HARNESS INSTALLED ON THAT FLIGHT CREW OXYGEN MASK REGULATOR HAS BEEN CORRECTED, AS REQUIRED BY THIS AD	MOS			20-JUN-2014	MANDATORY	NOT APPLICABLE - BY PART NUMBER
18-JUN-2014		HRS/MSC - AFL					
EASA 2014-0187	APPLIANCE AD - EQUIPMENT & FURNISHINGS – SAFETY BELT ATTACHMENT BOLTS – INSPECTION / REPLACEMENT	MOS				MANDATORY	NOT APPLICABLE - BY PART NUMBER
03-SEP-2014		HRS/MSC - AFL					
EASA 2014-0187 PARA (1)	INSPECT THE SAFETY BELT ATTACHMENT BOLTS	MOS				MANDATORY	NOT APPLICABLE - BY PART NUMBER
03-SEP-2014		HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2014-0187 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DETACHED OR LOOSENED SAFETY BELT ATTACHMENT BOLTS ARE FOUND, BEFORE NEXT FLIGHT, RE-TORQUE THE AFFECTED BOLTS TO THE VALUE AS DEFINED IN, AND IN ACCORDANCE WITH THE INSTRUCTIONS OF, GEVEN SB NO. D103-25-004 REVISION 2.					MANDATORY	NOT APPLICABLE - BY PART NUMBER
03-SEP-2014		MOS HRS/MSC - AFL					
EASA 2014-0187 PARA (3)	FOR SPECIFIC D1-03 SEAT ASSEMBLIES (P/N AS IDENTIFIED IN TABLE 1.1.1 OF GEVEN SB NO. D103-25-004 REVISION 2, EFF CODE FROM AAA TO AUC), WITHIN 6 MONTHS AFTER THE EFFECTIVE DATE OF THIS AD, MODIFY THE SEAT BELT ATTACHMENT ASSEMBLY ON THE AISLE SIDE SPREADER OF STANDARD AND LAST ROW SEATS IN ACCORDANCE WITH THE INSTRUCTIONS OF GEVEN SB NO. D103-25-004 REVISION 2.					MANDATORY	NOT APPLICABLE - BY PART NUMBER
03-SEP-2014		MOS HRS/MSC - AFL					
EASA 2014-0187 PARA (4)	AS AN ALTERNATIVE TO THE CORRECTIVE ACTIONS AS REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, BEFORE NEXT FLIGHT, BLOCK EACH AFFECTED SEAT FOR OCCUPANCY, PENDING ACCOMPLISHMENT OF THE APPLICABLE CORRECTIVE ACTION(S).					MANDATORY	NOT APPLICABLE - BY PART NUMBER
03-SEP-2014		MOS HRS/MSC - AFL					
EASA 2014-0279	APPLIANCE AD - EQUIPMENT / FURNISHING - RESTRAINT SYSTEM ROTARY BUCKLE SUBASSEMBLY - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY MANUFACTURER
02-JAN-2015		MOS HRS/MSC - AFL		13-FEB-2015			
EASA 2014-0279 PARA (1)	INSPECT THE LABEL OF THE ROTARY BUCKLE SUB-ASSEMBLY TO DETERMINE ITS PART NUMBER (P/N) AND SERIAL NUMBER (S/N)					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY MANUFACTURER
02-JAN-2015		MOS HRS/MSC - AFL		13-FEB-2015			
EASA 2014-0279 PARA (1.1)	REPLACE THE ROTARY BUCKLE SUB-ASSEMBLY WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY MANUFACTURER
02-JAN-2015		MOS HRS/MSC - AFL		13-FEB-2015			
EASA 2014-0279 PARA (1.2)	MARK THE SEAT AS "INOPERATIVE" UNTIL REPLACEMENT OF THE ROTARY BUCKLE SUB-ASSEMBLY AS REQUIRED BY PARAGRAPH (2) OF THIS AD					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY MANUFACTURER
02-JAN-2015		MOS HRS/MSC - AFL		13-FEB-2015			
EASA 2014-0279 PARA (2)	REPLACE EACH ROTARY BUCKLE SUB-ASSEMBLY HAVING A P/N AND S/N AS SPECIFIED IN ROMTEX ANJOU AERONAUTIQUE SB 358SB-14-101 WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY MANUFACTURER
02-JAN-2015		MOS HRS/MSC - AFL		13-FEB-2015			
EASA 2014-0279 PARA (3)	DO NOT INSTALL: - ON ANY RESTRAINT SYSTEM A SPARE ROTARY BUCKLE SUB-ASSEMBLY, OR - ON ANY AIRCRAFT A RESTRAINT SYSTEM EQUIPPED WITH A ROTARY BUCKLE SUB-ASSEMBLY HAVING A P/N AND A S/N LISTED IN ROMTEX ANJOU AERONAUTIQUE SB 358SB-14-101, UNLESS THE SUB-ASSEMBLY HAS BEEN REPAIRED,					MANDATORY	NOT APPLICABLE - NOT CONCERNED BY MANUFACTURER
02-JAN-2015		MOS HRS/MSC - AFL		13-FEB-2015			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2015-0093	APPLIANCE AD - NAVIGATION - ATTITUDE HEADING REFERENCE SYSTEM - MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - BY AHRS INSTALLED (KSG 7200 INSTALLED)
10-JUN-2015		MOS HRS/MSC - AFL		08-JUN-2015			
EASA 2015-0093 PARA (1)	AMEND THE AFM OF THE AIRCRAFT BY INSERTING A TEMPORARY REVISION (TR) TO THE AFM (SUPPLEMENT)					MANDATORY	NOT APPLICABLE - BY AHRS INSTALLED (KSG 7200 INSTALLED)
10-JUN-2015		DAYS HRS/MSC - AFL		08-JUN-2015			
EASA 2015-0093 PARA (2)	MODIFY THE AIRCRAFT BY REPLACING EACH AHRS UNIT HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 2 OF THIS AD WITH A MODIFIED UNIT, HAVING A P/N SPECIFIED AS 'NEW' IN TABLE 2 OF THIS AD					MANDATORY	NOT APPLICABLE - BY AHRS INSTALLED (KSG 7200 INSTALLED)
10-JUN-2015		MOS HRS/MSC - AFL		08-JUN-2015			
EASA 2015-0093 PARA (3)	CONCURRENT WITH MODIFICATION OF AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, THE AFM CHANGE, IF REQUIRED BY PARAGRAPH (1) OF THIS AD (SEE NOTE 1 OF THIS AD), CAN BE REMOVED FROM THAT AIRCRAFT					MANDATORY	NOT APPLICABLE - BY AHRS INSTALLED (KSG 7200 INSTALLED)
10-JUN-2015		MOS HRS/MSC - AFL		08-JUN-2015			
EASA 2015-0093 PARA (4)	DO NOT INSTALL ON ANY AIRCRAFT A LCR-100 AHRS UNIT, HAVING A P/N SPECIFIED AS 'OLD' IN TABLE 1 OF THIS AD					MANDATORY	NOT APPLICABLE - BY AHRS INSTALLED (KSG 7200 INSTALLED)
10-JUN-2015		MOS HRS/MSC - AFL		08-JUN-2015			
EASA 2016-0024	APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT EQUIPED
01-FEB-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0024 PARA (1)	INSPECT EACH SIEMENS SMOKE DETECTOR TO DETERMINE WHETHER IT IS AN AFFECTED PART					MANDATORY	NOT APPLICABLE - NOT EQUIPED
01-FEB-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0024 PARA (2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 1 OR TABLE 2					MANDATORY	NOT APPLICABLE - NOT EQUIPED
01-FEB-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0024 PARA (2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER ON BOARD LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (1), IN ACCORDANCE WITH TABLE 3					MANDATORY	NOT APPLICABLE - NOT EQUIPED
01-FEB-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0024 PARA (2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN APPENDIX 1					MANDATORY	NOT APPLICABLE - NOT EQUIPED
01-FEB-2016		MOS HRS/MSC - (s) AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0024 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL ON ANY AEROPLANE AN AFFECTED P/N SMOKE DETECTOR UNLESS THE UNIT (GMC ONLY) IS MARKED 'SIL PMC-26-002'					MANDATORY	NOT APPLICABLE - NOT EQUIPED
01-FEB-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0044	APPLIANCE AD - ATA 26 - FIRE PROTECTION - ENGINE AND AUXILIARY POWER UNIT AUTOMATIC FIRE EXTINGUISHERS - INSPECTION/OVERHAUL					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAR-2016		MOS HRS/MSC - AFL		(EFF)			
EASA 2016-0044 PARA (1)	INSPECT EACH FIRE EXTINGUISHER, EXCEPT THOSE HAVING P/N 57333 SERIES, INSTALLED ON BAE146 AND RJ AEROPLANES, AND THOSE HAVING P/N 57183 SERIES, INSTALLED ON ATP AEROPLANES, AND DEPENDING ON FINDINGS, ACCOMPLISH CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAR-2016		MOS HRS/MSC - AFL					
EASA 2016-0044 PARA (2)	ACCOMPLISHMENT OF AN OVERHAUL (SEE NOTE 2 OF THIS AD) OF A FIRE EXTINGUISHER BY KIDDE GRAVINER OR HUGEN, OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH KG CMM 26-21-40 REVISION 14 OR LATER OR KG CMM 26-21-52 REVISION 13 OR LATER (AS APPLICABLE TO FIRE EXTINGUISHER P/N) IS ACCEPTABLE TO COMPLY WITH THE REQUIREMENT OF PARAGRAPH (1).					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAR-2016		MOS HRS/MSC - AFL					
EASA 2016-0044 PARA (3)	FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED FIRE EXTINGUISHER, UNLESS IT IS NEW, OR HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SB 26-080 REVISION 1, OR IT HAS BEEN OVERHAULED (SEE NOTE 2) BY KG, OR BY HUGEN OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG SIL 01-10 OR IN ACCORDANCE WITH THE INSTRUCTIONS OF KG CMM 26-21-40 REVISION 14, OR OF KG CMM 26-21-52 REVISION 13, AS APPLICABLE TO FIRE EXTINGUISHER P/N					MANDATORY	NOT APPLICABLE - NOT EQUIPED
22-MAR-2016		MOS HRS/MSC - AFL					
EASA 2016-0163	APPLIANCE AD - EQUIPMENT / FURNISHINGS – CABIN ATTENDANT SEAT – MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - Not Equipped:
24-AUG-2016		MOS HRS/MSC - (s) AFL ACH FLTS					
EASA 2016-0163 PARA (1)	MODIFY AND RE-IDENTIFY EACH AFFECTED CABIN ATTENDANT SEAT					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED:
24-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0163 PARA (2)	DO NOT INSTALL AN AFFECTED CABIN ATTENDANT SEAT ON ANY AEROPLANE					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED:
24-AUG-2016		MOS HRS/MSC - (s) AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0164	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION (SUPERSEDED BY EASA AD 2017-0001)					MANDATORY	- SUPERSEDED BY EASA AD 2017-0001
24-AUG-2016		MOS HRS/MSC - (s) AFL ACH FLTS					
EASA 2016-0164 PARA (1)	VISUAL INSPECTION OF EACH AFFECTED CABIN ATTENDANT SEAT						- : SUPERSEDED BY EASA AD 2017-0001
24-AUG-2016		MOS HRS/MSC - AFL					
EASA 2016-0164 PARA (2)	REPLACE THE SEAT PAN OF THE AFFECTED SEAT (IF DURING ANY INSPECTION AS REQUIRED BY PARA (1) OF THIS AD, ANY DAMAGED SEAT PAN IS FOUND)					MANDATORY	- : SUPERSEDED BY EASA AD 2017-0001
24-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0164 PARA (3)	REPLACEMENT OF A SEAT PAN ON A SEAT, AS REQUIRED BY PARA (2) OF THIS AD, DOES NOT CONSTITUTE TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS REQUIRED BY PARA (1) OF THIS AD FOR THAT SEAT					MANDATORY	- : SUPERSEDED BY EASA AD 2017-0001
24-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0164 PARA (4)	TEMPORARILY STOWING AND SECURING AN ATTENDANT SEAT IN RETRACTED POSITION TO PREVENT OCCUPANCY, IN ACCORDANCE WITH THE PROVISIONS AND LIMITATIONS OF THE APPLICABLE MASTER MINIMUM EQUIPMENT LIST ITEM, IS AN ACCEPTABLE ALTERNATIVE METHOD TO DEFER COMPLIANCE WITH THE REQUIREMENTS OF PARA (1) OR (2) OF THIS AD					MANDATORY	- : SUPERSEDED BY EASA AD 2017-0001
24-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0164 PARA (5)	FROM THE EFFECTIVE DATE OF THIS AD, IT IS ALLOWED TO INSTALL ON ANY AEROPLANE AN AFFECTED SEAT, HAVING ACCUMULATED MORE THAN 2,500 FC SINCE FIRST INSTALLATION ON AN AEROPLANE, PROVIDED THAT, BEFORE INSTALLATION, THE SEAT HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF ZODIAC SB 536-25-003					MANDATORY	- : SUPERSEDED BY EASA AD 2017-0001
24-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0167	APPLIANCE AD - ATA 25 - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - BY TYPE OR P/N
31-AUG-2016		MOS HRS/MSC - (s) AFL ACH FLTS					
EASA 2016-0167 PARA (1)	REMOVE SEAT FROM THE AEROPLANE AND ACCOMPLISH A DETAILED VISUAL INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 2, SUBPART B OF ZODIAC SEATS FRANCE SB NO. 536-25-002					MANDATORY	NOT APPLICABLE - : BY TYPE OR P/N
31-AUG-2016		MOS HRS/MSC - (s) AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0167 PARA (2)	WITHIN 3 MONTHS AFTER THE INSPECTION AS REQUIRED BY PARAGRAPH (1) AND THEREAFTER AT INTERVALS NOT TO EXCEED 3 MONTHS, ACCOMPLISH A DETAILED VISUAL INSPECTION (DVI) IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 2 OF ZODIAC SEATS FRANCE SB NO. 536-25-002.					MANDATORY	NOT APPLICABLE - : BY TYPE OR P/N
31-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0167 PARA (3)	IF DURING ANY INSPECTION REQUIRED BY PARAGRAPH (1) OR (2) OF THIS AD, AS APPLICABLE, CORROSION OR ANY OTHER DAMAGE IS FOUND, BEFORE NEXT FLIGHT, OR BEFORE REINSTALLATION OF THE SEAT ON AN AEROPLANE, AS APPLICABLE, ACCOMPLISH THE APPLICABLE TEMPORARY CORRECTIVE ACTIONS IN ACCORDANCE WITH THE INSTRUCTIONS OF ZODIAC SEATS FRANCE SB NO. 536-25-002 SECTION 2 SUBPART B AND C,					MANDATORY	NOT APPLICABLE - : BY TYPE OR P/N
31-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0167 PARA (4)	TEMPORARILY STOWING AND SECURING A DAMAGED ATTENDANT SEAT IN RETRACTED POSITION TO PREVENT OCCUPANCY, IN ACCORDANCE WITH THE PROVISIONS AND LIMITATIONS OF THE APPLICABLE MASTER MINIMUM EQUIPMENT LIST ITEM, IS AN ACCEPTABLE ALTERNATIVE METHOD TO DEFER COMPLIANCE WITH THE REQUIREMENTS OF PARAGRAPH (3) OF THIS AD.					MANDATORY	NOT APPLICABLE - : BY TYPE OR P/N
31-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0167 PARA (5)	FROM THE EFFECTIVE DATE OF THIS AD, IT IS ALLOWED TO INSTALL (SEE NOTE OF THIS AD) ON ANY AEROPLANE AN AFFECTED SEAT, HAVING ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON AN AEROPLANE, PROVIDED THAT, BEFORE (RE)INSTALLATION, IT HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 2, SUBPART B, OF ZODIAC SEATS FRANCE SB NO. 536-25-002.					MANDATORY	NOT APPLICABLE - : BY TYPE OR P/N
31-AUG-2016		MOS HRS/MSC - (s) AFL					
EASA 2016-0167 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - NOT EQUIPPED
02-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2016-0167 R01 (CORR)	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - By Part: not concerned on FLEET
02-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2016-0167 R01 PARA (1)	REMOVE SEAT FROM THE AEROPLANE AND ACCOMPLISH A DETAILED VISUAL INSPECTION (DVI)					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
02-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0167 R01 PARA (2)	DETAILED VISUAL INSPECTION (DVI)					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
02-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2016-0167 R01 PARA (3)	ACCOMPLISH THE APPLICABLE TEMPORARY CORRECTIVE ACTIONS (IF, DURING ANY INSPECTION AS REQUIRED BY PARAS (1) OR (2) OF THIS AD, AS APPLICABLE, CORROSION OR OTHER DAMAGE IS FOUND)					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
02-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2016-0167 R01 PARA (4)	TEMPORARILY STOWING AND SECURING A DAMAGED ATTENDANT SEAT IN RETRACTED POSITION TO PREVENT OCCUPANCY, IN ACCORDANCE WITH THE PROVISIONS AND LIMITATIONS OF THE APPLICABLE MASTER MINIMUM EQUIPMENT LIST ITEM, IS AN ACCEPTABLE ALTERNATIVE METHOD TO DEFER COMPLIANCE WITH THE REQUIREMENTS OF PARA (3) OF THIS AD.					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
02-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2016-0167 R01 PARA (5)	IT IS ALLOWED TO INSTALL (SEE NOTE 2 OF THIS AD) ON ANY AEROPLANE AN AFFECTED SEAT, HAVING ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON AN AEROPLANE, PROVIDED THAT, BEFORE (RE)INSTALLATION, IT HAS PASSED AN INSPECTION IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 2, SUBPART B, OF ZODIAC SEATS FRANCE SB NO. 536-25-002					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
02-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2016-0167 R01 PARA (6)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE INSTRUCTIONS OF ZODIAC SEATS FRANCE SB NO. 536-25-004 CONSTITUTE TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AS REQUIRED BY PARAS (1) AND (2) OF THIS AD FOR THAT SEAT					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
02-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2016-0210	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT					MANDATORY	NOT APPLICABLE - by manufacturer
07-NOV-2016		MOS HRS/MSC - (s) AFL ACH FLTS					
EASA 2016-0210 PARA (1)	REPLACE THE EA ASSEMBLIES ON EACH AFFECTED SEAT WITH SERVICEABLE ASSEMBLIES IN ACCORDANCE WITH THE INSTRUCTIONS OF B/E AEROSPACE FISCHER SB 9911-001					MANDATORY	NOT APPLICABLE - : BY MANUFACTURER
07-NOV-2016		DAYS HRS/MSC - (s) AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2016-0210 PARA (2)	INSTALLATION OF AN AFFECTED SEAT ON AN AIRCRAFT IS ALLOWED, PROVIDED THAT, PRIOR TO INSTALLATION, IT IS DETERMINED THAT THE EA ASSEMBLIES HAVE BEEN REPLACED IN ACCORDANCE WITH THE INSTRUCTIONS OF B/E AEROSPACE FISCHER SB 9911-001					MANDATORY	NOT APPLICABLE - : BY MANUFACTURER
07-NOV-2016		MOS	HRS/MSC - (s)	AFL			
EASA 2016-0256	APPLIANCE AD - EQUIPMENT / FURNISHINGS - PILOT AND CO-PILOT SEATS - MODIFICATION (SUPERSEDED BY EASA AD 2018-0262)					MANDATORY	NOT APPLICABLE - By Part: NOT CONCERNED
30-DEC-2016		MOS	HRS/MSC -	AFL			
				ACH			
				FLTS			
EASA 2016-0256 PARA (1)	MODIFY AND RE-IDENTIFY EACH AFFECTED SEAT					MANDATORY	NOT APPLICABLE - : BY PART: NOT CONCERNED
30-DEC-2016		MOS	HRS/MSC -	AFL			
EASA 2016-0256 PARA (2)	DO NOT INSTALL AN AFFECTED SEAT ON ANY AEROPLANE					MANDATORY	NOT APPLICABLE - : BY PART: NOT CONCERNED
30-DEC-2016		MOS	HRS/MSC -	AFL			
EASA 2017-0001	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION					MANDATORY	NOT APPLICABLE - NOT EQUIPPED
20-JAN-2017		MOS	HRS/MSC - (s)	AFL			
				ACH			
				FLTS			
EASA 2017-0001 PARA (1)	VISUAL INSPECTION OF EACH GROUP 1 CABIN ATTENDANT SEAT					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
20-JAN-2017		MOS	HRS/MSC - (s)	AFL			
EASA 2017-0001 PARA (2)	REPLACE THE AFFECTED SEAT PAN WITH A PRE MOD SEAT PAN P/N F0433453 OR MODIFY THE SEAT BY INSTALLING A REINFORCED SEAT PAN P/N F0511530					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
20-JAN-2017		MOS	HRS/MSC - (s)	AFL			
EASA 2017-0001 PARA (3)	TEMPORARILY STOWING AND SECURING AN ATTENDANT SEAT IN RETRACTED POSITION TO PREVENT OCCUPANCY, IN ACCORDANCE WITH THE PROVISIONS AND LIMITATIONS OF THE APPLICABLE MASTER MINIMUM EQUIPMENT LIST ITEM, IS AN ACCEPTABLE ALTERNATIVE METHOD TO DEFER COMPLIANCE WITH THE REQUIREMENTS OF PARA (1) OR (2) OF THIS AD					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
20-JAN-2017		MOS	HRS/MSC - (s)	AFL			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2017-0001 PARA (4)	REPLACEMENT OF A SEAT PAN WITH A PRE-MOD SEAT PAN P/N F0433453 DOES NOT CONSTITUTE TERMINATING ACTION FOR THE REPETATIVE INSPECTIONS REQUIRED BY PARA (1). IF A NEW PRE-MOD SEAT PAN P/N F0433453 IS INSTALLED ON A SEAT THE NEXT VISUAL INSPECTION REQUIRED BY PARA (1) MAY BE DEFERRED UNTIL 2500 FC AT THAT INSTALLATION					MANDATORY	NOT APPLICABLE - :NOT EQUIPPED
20-JAN-2017		MOS HRS/MSC - (s) AFL					
EASA 2017-0001 PARA (5)	MODIFICATION OF A SEAT BY INSTALLING A REINFORCED SEAT PAN P/N F0511530 AND UPDATING THE SEAT P/N CONSTITUTES TERMINATING ACTION FOR THE REPETATIVE INSPECTIONS REQUIRED BY PARA (1)					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
20-JAN-2017		MOS HRS/MSC - (s) AFL					
EASA 2017-0001 PARA (6)	IT IS ALLOWED TO INSTALL (SEE NOTE 2) ON ANY AEROPLANE A GROUP 1 CABIN ATTENDANT SEAT (SEE NOTE 1) HAVING ACCUMULATED MORE THAN 2500 FC SINCE FIRST INSTALLATION ON AN AEROPLANE PROVIDED THAT, BEFORE INSTALLATION, THE SEAT HAS PASSED AN INSPECTION IAW ZODIAC SEATS FRANCE SB 536-25-003					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
20-JAN-2017		MOS HRS/MSC - (s) AFL					
EASA 2017-0001 PARA (7)	FOR GROUP 2 CABIN ATTENDANT SEATS, FROM THE EFFECTIVE DATE OF THIS AD DO NOT INSTALL A PRE-MOD SEAT PAN P/N F0433453					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
20-JAN-2017		MOS HRS/MSC - (s) AFL					
EASA 2017-0192	APPLIANCE AD - EQUIPMENT AND FURNISHING - PASSENGER SEATS - MODIFICATION					MANDATORY	NOT APPLICABLE - NOT EQUIPPED WITH RECARO AIRCRAFT SEAT
12-OCT-2017		MOS HRS/MSC - (s) AFL ACH FLTS					
EASA 2017-0192 PARA (1)	MODIFY AND RE-IDENTIFY EACH AFFECTED PASSENGER SEAT					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED WITH RECARO AIRCRAFT SEAT
12-OCT-2017		MOS HRS/MSC - (s) AFL					
EASA 2017-0192 PARA (2)	DO NOT INSTALL (SEE NOTE 2 OF THIS AD) AN AFFECTED PASSENGER SEAT ON ANY AEROPLANE, AS REQUIRED BY PARAGRAPH (2.1) OR (2.2) OF THIS AD, AS APPLICABLE					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED WITH RECARO AIRCRAFT SEAT
12-OCT-2017		MOS HRS/MSC - (s) AFL					
EASA 2017-0225	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT RESTRAINT SYSTEMS - AFM AMENDMENT / MODIFICATION					MANDATORY	NOT APPLICABLE - Not Equipped:
01-DEC-2017		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2017-0225 PARA (1)	INSTALL A PLACARD AS SPECIFIED IN TABLE 1 OF THIS AD IN FULL VIEW OF THE PILOT(S), AMEND THE APPLICABLE AFM, INFORM ALL FLIGHT CREWS AND, THEREAFTER, OPERATE THE AIRCRAFT ACCORDINGLY					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
01-DEC-2017		DAYS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2017-0225 PARA (3)	DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT THAT, ACCORDING TO THE APPLICABLE AFM, IS CERTIFICATED IN THE AEROBATIC CATEGORY, AS REQUIRED BY PARAGRAPH (3.1) OR (3.2) OF THIS AD, AS APPLICABLE					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
01-DEC-2017		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2018-0195	APPLIANCE AD - EQUIPMENT / FURNISHINGS - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REMOVAL FROM SERVICE					MANDATORY	NOT APPLICABLE - Not Equipped: NOT EQUIPPED ANJOU TORSO RESTRAINT
18-SEP-2018		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2018-0223	APPLIANCE AD - EQUIPMENT / FURNISHING - SEAT ENERGY ABSORBER ASSEMBLY - MODIFICATION					MANDATORY	NOT APPLICABLE - BY P/N AND TYPE
31-OCT-2018		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2018-0247	APPLIANCE AD - NAVIGATION - TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - BY XPDR TYPE
27-NOV-2018		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2018-0247 PARA (1)	INSPECT THE INSTALLATION OF THE AFFECTED PART ON THE AIRCRAFT					MANDATORY	NOT APPLICABLE - BY XPDR TYPE
27-NOV-2018		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2018-0247 PARA (2)	IF, DURING THE INSPECTION AS REQUIRED BY PARAGRAPH (1) OF THIS AD, IT IS DETERMINED THAT THE INSTALLATION IS NOT A CONVENTIONAL INSTALLATION, AS DEFINED IN THIS AD, BEFORE NEXT FLIGHT, REMOVE THE TRANSPONDER FROM SERVICE FOR IN-SHOP MODIFICATION.					MANDATORY	NOT APPLICABLE - BY XPDR TYPE
27-NOV-2018		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2018-0247 PARA (3)	RETURNING AN AFFECTED PART, REMOVED FROM AN AIRCRAFT AS REQUIRED BY PARAGRAPH (2) OF THIS AD, TO TRIG AVIONICS FOR MODIFICATION, AND RE-INSTALLATION OF THAT MODIFIED TRANSPONDER ON THAT AIRCRAFT IS AN ACCEPTABLE METHOD TO COMPLY WITH THE REQUIREMENTS OF THIS AD FOR THAT AIRCRAFT					MANDATORY	NOT APPLICABLE - BY XPDR TYPE
27-NOV-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
EASA 2018-0247 PARA (4)	FROM THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT, UNLESS THE INSTALLATION IS CONVENTIONAL, AS DEFINED IN THIS AD					MANDATORY	NOT APPLICABLE - BY XPDR TYPE
27-NOV-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
EASA 2018-0259	APPLIANCE AD - INFORMATION SYSTEMS - ELECTRONIC FLIGHT BAG UNIVERSAL SERIAL BUS RECEPTACLE - MODIFICATION					MANDATORY	NOT APPLICABLE - By Effectivity: STC NOT INSTALLED
14-DEC-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
EASA 2018-0259 PARA (1)	MODIFY EACH AFFECTED PART IN ACCORDANCE WITH THE INSTRUCTIONS OF THE APPLICABLE SB/EB						NOT APPLICABLE - By Effectivity: STC NOT INSTALLED
14-DEC-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
EASA 2018-0259 PARA (2)	AFTER MODIFICATION OF AN AEROPLANE AS REQUIRED BY PARAGRAPH (1) OF THIS AD, DO NOT INSTALL AN AFFECTED PART ON THAT AEROPLANE.					MANDATORY	NOT APPLICABLE - By Effectivity: STC NOT INSTALLED
14-DEC-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
EASA 2018-0262	APPLIANCE AD - EQUIPMENT / FURNISHINGS - PILOT AND CO-PILOTS SEATS - MODIFICATION / INSPECTION					MANDATORY	NOT APPLICABLE - By Part: PART NUMBER
20-DEC-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
EASA 2018-0262 PARA (1)	MODIFY AND RE-IDENTIFY EACH PRE-MOD SEAT (FOR GROUP 1 AEROPLANES) (RESTATEMENT OF EASA AD 2016-0256 (1))					MANDATORY	NOT APPLICABLE - By Part: PART NUMBER
20-DEC-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2018-0262 PARA (2)	DO NOT INSTALL A PRE-MOD SEAT ON ANY AEROPLANE (RESTATEMENT OF EASA AD 2016-0256 PARA (2))					MANDATORY	NOT APPLICABLE - By Part: PART NUMBER
20-DEC-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2018-0262 PARA (3)	INSPECT ANY AFFECTED SPRING OF EACH SEAT; REPLACE BOTH SPRINGS (IF, DURING ANY INSPECTION ANY DAMAGE OR INCORRECT INSTALLATION OF AN EFFECTED SPING IS FOUND)					MANDATORY	NOT APPLICABLE - By Part: PART NUMBER
20-DEC-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2018-0262 PARA (5)	IT IS ALLOWED TO DEFER ACCOMPLISHMENT OF CORRECTIVE ACTIONS REQUIRED BT PARA (4) OF THIS AD FOR THAT SEAT, PROVIDED A COPY OF THE ATR OEB IS INCLUDED IN THE APPLICABLE AFM, PILOTS ARE INFORMED, AND THE AEROPLANE IS OPERATED IAW THE INSTRUCTIONS OF THAT OEB (IF, DURING ANY INSPECTION AS REQ BY PARA (3) OF THIS AD, ANY DAMAGE OR INCORRECT INSTALLATION OF ONLY ONE AFFECTED SPRING IS FOUND ON THE PILOT OR CO-PILOT SEAT) (FOR ATR AEROPLANES)					MANDATORY	NOT APPLICABLE - By Part: PART NUMBER
20-DEC-2018		DAYS HRS/MSC - AFL ACH FLTS					
EASA 2018-0262 PARA (8)	IT IS ALLOWED TO INSTALL AN AFFECTED SPRING ON A SEAT INSTALLED ON AN AEROPLANE PROVIDED THAT, AFTER INSTALLATION, THAT SPRING PASSES AN INSPECTION (NO DEFECT FOUND)						NOT APPLICABLE - By Part: PART NUMBER
20-DEC-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2018-0262 PARA (9) & (10)	REPORTING					MANDATORY	NOT APPLICABLE - By Part: PART NUMBER
20-DEC-2018		DAYS HRS/MSC - AFL ACH FLTS					
EASA 2018-0264	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION					MANDATORY	NOT APPLICABLE - By Part: BY PART NUMBER
21-DEC-2018		MOS HRS/MSC - AFL ACH FLTS					
EASA 2018-0264 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION					MANDATORY	NOT APPLICABLE - BY MANUFACTURER
04-APR-2019		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0004	APPLIANCE AD - NAVIGATION - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS					MANDATORY	NOT APPLICABLE - Not Equipped: BY OEM
25-JAN-2019		DAYS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2019-0010	APPLIANCE AD - EQUIPMENT/FURNINSHING - LIFE JACKET - REMOVAL/REPAIR					MANDATORY	NOT APPLICABLE - By Effectivity: N/A BY OEM
06-FEB-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2019-0010 PARA (1)	REMOVE EACH AFFECTED PART FROM SERVICE AND REPLACE IT WITH A SERVICEABLE PART					MANDATORY	NOT APPLICABLE - By Effectivity: N/A BY OEM
06-FEB-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2019-0010 PARA (2)	DO NOT INSTALL AN AFFECTED PART ON ANY AIRCRAFT					MANDATORY	NOT APPLICABLE - By Effectivity: N/A BY OEM
06-FEB-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2019-0010 PARA (3)	DO NOT RELEASE TO SERVICE ANY AFFECTED PART, UNLESS IT HAS BEEN REPAIRED AND RE-IDENTIFIED					MANDATORY	NOT APPLICABLE - By Effectivity: N/A BY OEM
06-FEB-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2019-0179	APPLIANCE AD - NAVIGATION – AIRBORNE COLLISION AVOIDANCE SYSTEM DISPLAY SOFTWARE – UPDATE					MANDATORY	NOT APPLICABLE - Not Equipped: N/A BY TC HOLDER INSTALLED
31-JUL-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
EASA 2019-0179 PARA (1)	AMEND THE APPLICABLE AFM(S) IN ACCORNDANCE WITH THE OPSB AND INSTALL THE APPROPRIATE PLACARD; VERIFY THAT A PRESSURE ALTITUDE REPORTING TRANSPONDER IS INSTALLED AND INTRODUCE PRE-FLIGHT CHECKS					MANDATORY	NOT APPLICABLE - Not Equipped: N/A BY TC HOLDER INSTALLED
31-JUL-2019		DAYS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0179 PARA (2)	MODIFY THE AEROPLANE BY INSTALLING A SOFTWARE UPDATE THAT RECTIFIES THE UNSAFE CONDITION ADDRESSED BY THIS AD; BEFORE NEXT FLIGHT AFTER MODIFICATION REMOVE THE AFM CHANGES AND PLACARD AND CONCURRENT WITH REMOVAL OF THE AFM(S) CHANGE AND PLACARD INSERT THE APPLICABLE POST-SB MTB 34-02 AFM TC					MANDATORY	NOT APPLICABLE - Not Equipped: N/A BY TC HOLDER INSTALLED
31-JUL-2019		MOS HRS/MSC - AFL ACH FLTS					
EASA 2019-0179 R01	APPLIANCE AD - NAVIGATION - AIRBORNE COLLISION AVOIDANCE SYSTEM DISPLAY SOFTWARE - UPDATE					MANDATORY	NOT APPLICABLE - Not Equipped: WITH FDSA-6500
24-APR-2020		MOS HRS/MSC - AFL ACH FLTS					
EASA 2019-0179 R01 PARA (1)	AMEND THE APPLICABLE AFM(S) IAW THE OPSB AND INSTALL THE APPROPRIATE PLACARD; VERIFY THAT A PRESSURE ALTITUDE REPORTING TRANSPONDER IS INSTALLED; AND INTRODUCE PRE-FLIGHT CHECKS					MANDATORY	NOT APPLICABLE - Not Equipped: WITH FDSA-6500
24-APR-2020		DAYS HRS/MSC AFL ACH FLTS					
EASA 2019-0179 R01 PARA (2) & (4)	MODIFY THE AEROPLANE BY INSTALLING A SOFTWARE UPDATE THAT RECTIFIES THE UNSAFE CONDITION THEN REMOVE THE AFM(S) CHANGES AND PLACARD, AS REQUIRED BY PARA (1) OF THIS AD. CONCURRENTLY, FOR CERTAIN TEXTRON AVIATION AEROPLANES, INSERT THE THE APPLICABLE POST-SB MTB-34-02 AFM TC OR POST-MOD AFMS, AS IDENTIFIED IN APPENDIX 2 OF THIS AD					MANDATORY	NOT APPLICABLE - Not Equipped: WITH FDSA-6500
24-APR-2020		MOS HRS/MSC AFL ACH FLTS					
EASA 2019-0235	APPLIANCE AD - EQUIPMENT / FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER - INSPECTION / MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - By Part: N/A BY PART NUMBER
04-OCT-2019		MOS HRS/MSC - AFL ACH FLTS					
EASA 2019-0235 PARA (1) THRU (4)	CONCURRENTLY ACCOMPLISH PARAS (1.1) AND (1.2) OF THIS AD AND ACCOMPLISH APPLICABLE CORRECTIVE ACTION(S) (IF, DISCREPANCIES ARE DETECTED, AS IDENTIFIED IN THE SIL); OPERATORS MAY CONTINUE TO USE ELTS WITH THE ORIGINAL G-SWITCHES BY REDUCING THE INTERVAL OF THE G-SWITCH TESTING, AS REQUIRED BY PARA (1.1)					MANDATORY	NOT APPLICABLE - By Part: N/A BY PART NUMBER
04-OCT-2019		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2019-0235 PARA (5)	REMOVE THE AFFECTED PART FROM SERVICE IAW THE INSTRUCTIONS OF SECTION 7 OF THE SB FOR THE PURPOSE OF IN-SHOP MODIFICATION					MANDATORY	NOT APPLICABLE - By Part: N/A BY PART NUMBER
04-OCT-2019		MOS HRS/MSC - AFL ACH FLTS					
EASA 2019-0235 PARA (6)	IN-SHOP CORRECTION OF AN AFFECTED PART OR MODIFICATION INTO A SERVICEABLE PART IAW THE INSTRUCTIONS OF THE SB CONSTITUTES TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS AND TESTING AS REQUIRED BY THIS AD FOR THAT PART					MANDATORY	NOT APPLICABLE - By Part: N/A BY PART NUMBER
04-OCT-2019		MOS HRS/MSC - AFL ACH FLTS					
EASA 2019-0235 PARA (9)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED PART THAT HAS ACCUMULATED 10 YEAR TIS OR MORE					MANDATORY	NOT APPLICABLE - By Part: N/A BY PART NUMBER
04-OCT-2019		MOS HRS/MSC - AFL ACH FLTS					
EASA 2020-0272	APPLIANCE AD - EQUIPMENT / FURNISHINGS - BUCKLE - MODIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH 4 POINT HARNESS RESTRAINT SYSTEMS SCHROTH SAFETY PRODUCTS CORP
23-DEC-2020		MOS HRS/MSC - AFL		17-DEC-2020			
EASA 2020-0272 PARA (1)	MODIFY EACH AFFECTED BUCKLE OR REPLACE THE AFFECTED BUCKLE WITH A SERVICEABLE BUCKLE					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH 4 POINT HARNESS RESTRAINT SYSTEMS SCHROTH SAFETY PRODUCTS CORP
23-DEC-2020		MOS HRS/MSC - AFL		17-DEC-2020			
EASA 2020-0272 PARA (2)	REPLACE EACH AFFECTED BUCKLE WITH A SERVICEABLE BUCKLE (IF POST-MODIFICATION AND PRE-REPLACEMENT PER PARA (1))					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH 4 POINT HARNESS RESTRAINT SYSTEMS SCHROTH SAFETY PRODUCTS CORP
23-DEC-2020		MOS HRS/MSC - AFL		17-DEC-2020			
EASA 2021-0185 R01	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT						NOT APPLICABLE - By Part: BY PART NUMBER
19-AUG-2021		DAYS HRS/MSC AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
EASA 2024-0024	APPLIANCE AD - NAVIGATION - DIGITAL AIR DATA COMPUTER - REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: EQUIPMENT NOT FITTED - PC12 NG ARE EQUIPPED WITH HONEYWELL KSG 7200 ADAHRS
07-FEB-2024		MOS HRS/MSC - AFL		26-JAN-2024			
FAA 2005-18-20	APPLIANCE AD - PROPELLERS - INSPECTION, REPAIR, OR REPLACEMENT OF THOSE "FASTPROP" PROPELLER DE-ICERS THAT FAIL DAILY VISUAL CHECKS						NOT APPLICABLE - SEE AD/SB PILATUS DELIVERY REPORT
		MOS HRS/MSC - (s) AFL		14-OCT-2005			
FAA 2010-01-03	APPLIANCE AD - REPLACE PORTABLE HALON 1211 (BCF) FIRE EXTINGUISHERS MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH SERVICEABLE FIRE EXTINGUISHERS					MANDATORY	NOT APPLICABLE - SEE DOC LINKED
20-JAN-2010		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
FAA 2010-09-04	APPLIANCE AD - TO PROVIDE THE FLIGHTCREW WITH PROCEDURES TO RECOVER FROM OR WORK AROUND SOFTWARE ANOMALIES DURING FLIGHT RELATED TO PRIMUS APEX FMS P/N EB7037248-00103, WITH NZ7.1 VAR12 FMS SOFTWARE, WHICH COULD LEAD TO AN AIRPLANE DEPARTING FROM ITS SCHEDULED FLIGHT PATH, AND RESULT IN POSSIBLE COLLISION WITH OTHER AIRCRAFT OR TERRAIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
14-MAY-2010		DAYS HRS/MSC - AFL		30-NOV-2011			
FAA 2012-14-15	APPLIANCE AD - AMEND AFM, FABRICATE AND INSTALL PLACARD TO ADDRESS LIMITATIONS ON LNAV/VNAV APPROACHES					MANDATORY	COMPLIED WITH - SEE WO PC12-213-12 R1 AND WR RUAG 213159
19-JUL-2012		MOS HRS/MSC - AFL		15-AUG-2012 99.08 78			
FAA 2012-14-15 PARA (G)	AMEND AMEND AFM, FABRICATE AND INSTALL PLACARD TO ADDRESS LIMITATIONS ON LNAV/VNAV APPROACHES					MANDATORY	COMPLIED WITH - SEE WO PC12-213-12 R1 AND WR RUAG 213159
19-JUL-2012		MOS HRS/MSC - AFL		15-AUG-2012 99.08 78			
FAA 2012-14-15 PARA (H)	FABRICATE AMEND AFM, FABRICATE AND INSTALL PLACARD TO ADDRESS LIMITATIONS ON LNAV/VNAV APPROACHES AND INSTALL A PLACARD					MANDATORY	COMPLIED WITH - SEE WO PC12-213-12 R1 AND WR RUAG 213159
19-JUL-2012		DAYS HRS/MSC - AFL		15-AUG-2012 99.08 78			
FAA 2012-26-15 R01	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)					MANDATORY	NOT APPLICABLE - BY S/N ADAHRS IN ACCORDING THE TABLE 12 OF HONEYWELL SB 34-A01
03-DEC-2014		MOS HRS/MSC - AFL		02-DEC-2014			
FAA 2014-05-27	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION					MANDATORY	NOT APPLICABLE - NOT APPLICABLE BY PART NUMBER
		MOS HRS/MSC - AFL		10-APR-2014			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2014-17-02	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING DISCREPANCIES - HONEYWELL ASCA INC					MANDATORY	NOT APPLICABLE - BY ELT MODEL
09-SEP-2014		MOS HRS/MSC - (s) AFL					
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - BY MANUFACTURER
14-OCT-2014		MOS HRS/MSC - AFL		(EFF)			
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES					MANDATORY	COMPLIED WITH - IN ACCORDANCE WITH AD EASA 2011-0090 R1
16-JUN-2015		MOS HRS/MSC - AFL		07-JUN-2015 1588.17 1296			
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011					MANDATORY	COMPLIED WITH - IN ACCORDANCE WITH AD EASA 2011-0090 R1
16-JUN-2015		MOS HRS/MSC - AFL		07-JUN-2015 1588.17 1296			
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES					MANDATORY	COMPLIED WITH - IN ACCORDANCE WITH AD EASA 2011-0090 R1
16-JUN-2015		MOS HRS/MSC - AFL		07-JUN-2015 1588.17 1296			
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE - BY PART NUMBER
12-JUN-2015		MOS HRS/MSC - (s) AFL					
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2					MANDATORY	NOT APPLICABLE - BY PART NUMBER
12-JUN-2015		MOS HRS/MSC - (s) AFL					
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK					MANDATORY	NOT APPLICABLE - BY PART NUMBER
12-JUN-2015		MOS HRS/MSC - (s) AFL					
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS					MANDATORY	NOT APPLICABLE - BY PART NUMBER
12-JUN-2015		MOS HRS/MSC - (s) AFL					
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS					MANDATORY	NOT APPLICABLE - BY SYSTEM INSTALLED ON AIRCRAFT (HONEYWELL SYSTEM)
01-JUL-2015		MOS HRS/MSC - AFL		22-JUL-2015			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.					MANDATORY	NOT APPLICABLE - NOT EQUIPED
18-MAY-2015		MOS HRS/MSC - AFL					
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - Not Equipped:
15-JUL-2016		MOS HRS/MSC - (s) AFL ACH FLTS					
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV. 000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED:
15-JUL-2016		MOS HRS/MSC - (s) AFL					
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED:
15-JUL-2016		MOS HRS/MSC - (s) AFL					
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED:
15-JUL-2016		MOS HRS/MSC - (s) AFL					
FAA 2017-06-03	APPLIANCE AD - HEATING SYSTEM - ACCOMPLISH REPETATIVE DETAILED INSPECTIONS AND PRESSURE DECAY TESTS OF THE COMBUSTION HEATER AND DISABLE / REMOVE IF NECESSARY						NOT APPLICABLE - NOT EQUIPPED : EQUIPMENT NOT FITTED
05-MAY-2017		MOS HRS/MSC - AFL					
FAA 2017-06-03	APPLIANCE AD - HEATING SYSTEM - ACCOMPLISH REPETATIVE DETAILED INSPECTIONS AND PRESSURE DECAY TESTS OF THE COMBUSTION HEATER AND DISABLE / REMOVE IF NECESSARY					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: EQUIPMENT NOT FITTED
05-MAY-2017		MOS HRS/MSC - (s) AFL ACH FLTS					
FAA 2017-06-03 PARA (G)	PERFORM INSPECTIONS AND PRESSURE DECAY TEST (PDT) OF THE COMBUSTION HEATER					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED: EQUIPMENT NOT FITTED
05-MAY-2017		MOS HRS/MSC - (s) AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-06-03 PARA (K)	DISABLE OR REMOVE COMBUSTION HEATER					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED: EQUIPMENT NOT FITTED
05-MAY-2017		DAYS					
		HRS/MSC	- (s)				
		AFL					
FAA 2017-09-09	APPLIANCE AD - PASSENGER COMPARTMENT EQUIPMENT - REPLACEMENT OF ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS					MANDATORY	NOT APPLICABLE - Not Equipped: not concerned by seat model
28-JUN-2017		MOS					
		HRS/MSC	- (s)				
		AFL					
		ACH					
		FLTS					
FAA 2017-11-11	APPLIANCE AD - NAVWORX, INC. AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS - REMOVE, DISABLE, OR REVISE SOFTWARE TO BROADCAST A SIL OF 0					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
11-JUL-2017		MOS					
		HRS/MSC	- (s)				
		AFL					
		ACH					
		FLTS					
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS					MANDATORY	NOT APPLICABLE - N/A BY EQUIPMENT MANUFACTURER
24-OCT-2017		MOS					
		HRS/MSC	- (s)				
		AFL					
		ACH					
		FLTS					
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - : N/A BY EQUIPMENT MANUFACTURER
24-OCT-2017		MOS					
		HRS/MSC	- (s)				
		AFL					
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT					MANDATORY	NOT APPLICABLE - : N/A BY EQUIPMENT MANUFACTURER
24-OCT-2017		MOS					
		HRS/MSC	- (s)				
		AFL					
FAA 2017-16-04	APPLIANCE AD - ROMTEX ANJOU AERONAUTIQUE (ROMTEX) TORSO RESTRAINT SYSTEMS ROTARY BUCKLE ASSEMBLY INSPECTION AND REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: BY EQUIPMENT MANUFACTURER
22-SEP-2017		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
FAA 2017-16-04 PARA (E.1)	INSPECT EACH RESTRAINT SYSTEM FOR CORRECT OPERATION					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED: BY EQUIPMENT MANUFACTURER
22-SEP-2017		MOS					
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-16-04 PARA (E.1.I) & (E.1.II)	REPLACE THE BUCKLE ASSEMBLY WITH A BUCKLE ASSEMBLY NOT IDENTIFIED IN PARAGRAPH (A) OF THIS AD AND PLACARD THE SEAT AS INOPERATIVE IF THE STRAPS DO NOT RELEASE FROM BUCKLE ASSEMBLY					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED: BY EQUIPMENT MANUFACTURER
22-SEP-2017		MOS HRS/MSC - AFL					
FAA 2017-16-04 PARA (E.2)	DO NOT INSTALL A RESTRAINT SYSTEM WITH A BUCKLE ASSEMBLY IDENTIFIED IN PARAGRAPH (A) OF THIS AD ON ANY HELICOPTER					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED: BY EQUIPMENT MANUFACTURER
22-SEP-2017		MOS HRS/MSC - AFL					
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: NOT EQUIPPED
16-OCT-2017		MOS HRS/MSC - (s) AFL ACH FLTS					
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED: NOT EQUIPPED
16-OCT-2017		MOS HRS/MSC - (s) AFL					
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED: NOT EQUIPPED
16-OCT-2017		MOS HRS/MSC - (s) AFL					
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED: NOT EQUIPPED
16-OCT-2017		MOS HRS/MSC - (s) AFL					
FAA 2017-19-05	APPLIANCE AD - APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
31-OCT-2017		MOS HRS/MSC - (s) AFL ACH FLTS					
FAA 2017-19-05 PARA (F)(1)	INSPECT EACH SIEMENS SMOKE DETECTOR, OR REVIEW YOUR MAINTENANCE RECORDS, TO DETERMINE IF AN AFFECTED DETECTOR IS INSTALLED					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED:
31-OCT-2017		DAYS HRS/MSC - (s) AFL					
FAA 2017-19-05 PARA (F)(2.1)	REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURES 2 AND 3					MANDATORY	NOT APPLICABLE - : NOT EQUIPPED:
31-OCT-2017		MOS HRS/MSC - (s) AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-19-05 PARA (F)(2.2)	REPLACE PASSENGER, CABIN OR ANY OTHER LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURE 4	MOS				MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
31-OCT-2017		HRS/MSC - (s)					
		AFL					
FAA 2017-19-05 PARA (F)(2.3)	REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN PARAGRAPH (C)(2), SPECIFIED FIGURE 1	MOS				MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
31-OCT-2017		HRS/MSC - (s)					
		AFL					
FAA 2017-19-05 PARA (G)	DO NOT INSTALL ON ANY AIRPLANE A SMOKE DETECTOR WITH A MANUFACTURING DATE AND P/N LISTED IN FIGURE 2 OR 3 OR LISTED IN FIGURE 4 TO PARAGRAPH (F) OF THIS AD UNLESS THE DETECTOR IS MARKED "SIL PMC-26-002"	MOS				MANDATORY	NOT APPLICABLE - : NOT EQUIPPED
31-OCT-2017		HRS/MSC - (s)					
		AFL					
FAA 2017-22-02	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS	MOS				MANDATORY	NOT APPLICABLE - Not Equipped: N/A NOT EQUIPPED
12-DEC-2017		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILANCE SYSTEM PROCESSING UNITS	MOS				MANDATORY	NOT APPLICABLE - Not Equipped: N/A BY EQUIPMENT
20-DEC-2017		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
FAA 2018-03-04	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC	MOS				MANDATORY	NOT APPLICABLE - Not Equipped: BY OEM
16-MAR-2018		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
FAA 2018-03-04 PARA (G)	DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED	DAYS				MANDATORY	NOT APPLICABLE - Not Equipped: BY OEM
16-MAR-2018		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
FAA 2018-03-04 PARA (H)(1)	REPLACE AFFECTED PITOT PROBES	MOS				MANDATORY	NOT APPLICABLE - Not Equipped: BY OEM
16-MAR-2018		HRS/MSC -					
		AFL					
		ACH					
		FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-03-04 PARA (H)(2)	DO NOT INSTALL ON ANY AIRPLANE A PITOT PROBE HAVING A SERIAL NUMBER LISTED IN PARA (C)(1) OF THIS AD, UNLESS IT HAS BEEN PROPERLY REPAIRED, AND IF REPAIRED BY CSI AEROSPACE, INC., HAS A REPAIR DATE OF AUGUST 1, 2014, OR LATER					MANDATORY	NOT APPLICABLE - Not Equipped: BY OEM
16-MAR-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-16-01	APPLIANCE AD - APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT					MANDATORY	NOT APPLICABLE - Not Equipped: no b/e aerospace fischer attendant and pilot seats fitted
31-AUG-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-16-01 PARA (G)	REVIEW EACH AFFECTED ATTENDANT SEAT NG AND PILOT SEAT 120/335, REMOVE AND REPLACE THE EA ASSEMBLIES ON EACH AFFECTED PILOT SEAT, AND REMOVE EACH AFFECTED ATTENDANT SEAT AND REPLACE WITH A REWORKED SEAT IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016					MANDATORY	NOT APPLICABLE - Not Equipped: no b/e aerospace fischer attendant and pilot seats fitted
31-AUG-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-16-01 PARA (H)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED SEAT ON AN AIRCRAFT UNLESS, PRIOR TO INSTALLATION, THE EA ASSEMBLIES ON THE SEAT HAVE BEEN REPLACED IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016					MANDATORY	NOT APPLICABLE - Not Equipped: no b/e aerospace fischer attendant and pilot seats fitted
31-AUG-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-16-13	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECT THE SAFETY BELT WEBBING, AND MODIFY AND RE-MARKING EACH AFFECTED CABIN ATTENDANT SEAT					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
26-OCT-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-16-13 PARA (G)	INSPECT SAFETY BELT WEBBING, MODIFY AND RE-MARK EACH AFFECTED CABIN ATTENDANT SEAT USING ZODIAC SEATS FRANCE SERVICE INFORMATION LETTER 537-01					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
26-OCT-2018		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-16-13 PARA (H)	DO NOT INSTALL ANY AFFECTED ZODIAC SEATS FRANCE CABIN ATTENDANT SEAT ON ANY AIRCRAFT					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
26-OCT-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-19-15	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / TORQUE VERIFICATION / MODIFICATION					MANDATORY	NOT APPLICABLE - Not Equipped: EQUIPMENT NOT INSTALLED
14-NOV-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - By Part: BY HARNESS P/N
27-MAR-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-21-14 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD					MANDATORY	NOT APPLICABLE - By Part: BY HARNESS P/N
27-MAR-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-23-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION AND REPLACEMENT					MANDATORY	NOT APPLICABLE - Not Equipped: no zodiac Cabin Attendant Seats
28-DEC-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-23-01 PARA (G)	INSPECT THE SEAT PAN STRUCTURE IN BOTH DEPLOYED AND STOWED POSITIONS (IF CRACKS ARE FOUND, REPLACE WITH REINFORCED SEAT PAN P/N F0511530 AND REMARK THE SEAT) (IF NO CRACKS ARE FOUND, REMARK THE SEAT AND REINSPECT OR REPLACE THE SEAT PAN WITH REINFORCED SEAT PAN P/N F0511530)					MANDATORY	NOT APPLICABLE - Not Equipped: no zodiac Cabin Attendant Seats
28-DEC-2018		MOS HRS/MSC - AFL ACH FLTS					
FAA 2018-23-01 PARA (H)	INSTALLATION OF A REINFORCED SEAT PAN, P/N F0511530, USING PARAGRAPH 2.B., ACCOMPLISHMENT INSTRUCTIONS, OF ZODIAC SEATS FRANCE SB NO. 536-25-003, REV. 3, DATED JUNE 2, 2017, IS TERMINATING ACTION TO THIS AD					MANDATORY	NOT APPLICABLE - Not Equipped: no zodiac Cabin Attendant Seats
28-DEC-2018		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2018-23-12	APPLIANCE AD - EQUIPMENT / FURNISHINGS - INSPECTION AND REPLACEMENT OF ZODIAC AERO (ALSO KNOWN AS AIR CRUISERS COMPANY) EVACUATION SYSTEMS FUSIBLE PLUGS					MANDATORY	NOT APPLICABLE - Not Equipped: BY LIFERAFT P/N
28-DEC-2018		MOS	HRS/MSC -	AFL	ACH	FLTS	
FAA 2018-23-12 PARA (G)	ACCOMPLISH AN INSPECTION TO DETERMINE IF ANY PLUG HAS PART NUMBER (P/N) B13984-3, STAMPED WITH LOT PA-21 OR PA-22					MANDATORY	NOT APPLICABLE - Not Equipped: BY LIFERAFT P/N
28-DEC-2018		MOS	HRS/MSC -	AFL	ACH	FLTS	
FAA 2018-23-12 PARA (H)	REPLACE FUSIBLE PLUG WITH A SERVICEABLE FUSIBLE PLUG P/N B13984-3 THAT IS NOT STAMPED WITH LOT PA-21 OR PA-22					MANDATORY	NOT APPLICABLE - Not Equipped: BY LIFERAFT P/N
28-DEC-2018		MOS	HRS/MSC -	AFL	ACH	FLTS	
FAA 2018-23-12 PARA (I)	NO PERSON SHAL INSTALL ON ANY AIRPLANE ANY FUSIBLE PLUG HAVING P/N B13984-3, STAMPED WITH LOT PA-21 OR PA-22					MANDATORY	NOT APPLICABLE - Not Equipped: BY LIFERAFT P/N
28-DEC-2018		MOS	HRS/MSC -	AFL	ACH	FLTS	
FAA 2019-01-02	APPLIANCE AD - NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN - AIRPLANE FLIGHT MANUAL SUPPLEMENT (AFMS) - DISABLE / REVISE					MANDATORY	NOT APPLICABLE - Not Equipped: EQUIPMENT NOT FITTED
07-FEB-2019		MOS	HRS/MSC -	AFL	ACH	FLTS	
FAA 2019-01-02 PARA (G)(1)	DISABLE THE AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) IN FUNCTION IN EACH UNIT					MANDATORY	NOT APPLICABLE - Not Equipped: EQUIPMENT NOT FITTED
07-FEB-2019		MOS	HRS/MSC -	AFL	ACH	FLTS	
FAA 2019-01-02 PARA (G)(2)	REVISE THE AIRPLANE FLIGHT MANUAL SUPPLEMENT IN ACCORDANCE WITH PARAGRAPH 5.2.C OF SB2018-01					MANDATORY	NOT APPLICABLE - Not Equipped: EQUIPMENT NOT FITTED
07-FEB-2019		MOS	HRS/MSC -	AFL	ACH	FLTS	

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-07-03	APPLIANCE AD - EQUIPMENT / FURNISHINGS - REAR CABIN ATTENDANT SEAT - INSPECTION / REPAIR					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
16-MAY-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-07-03 PARA (G)	REMOVE THE SEAT FROM THE AIRCRAFT AND PERFORM A DETAILED VISUAL INSPECTION; IF CORROSION OR OTHER DAMAGE IS FOUND, BEFORE NEXT FLIGHT OR BEFORE (RE)INSTALLATION OF THE SEAT ON AN AIRCRAFT, AS APPLICABLE, REPAIR THE SEAT					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
16-MAY-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-07-03 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN AFFECTED ZODIAC SEATS FRANCE 536-SERIES CABIN ATTENDANT SEAT THAT HAS ACCUMULATED MORE THAN 14 MONTHS SINCE FIRST INSTALLATION ON ANY AIRCRAFT, UNLESS IT HAS PASSED AN INSPECTION IAW THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.B., OF ZODIAC SEATS FRANCE SB NO. 536-25-002, REVISION 3, DATED NOVEMBER 2, 2016					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
16-MAY-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-07-03 PARA (I)	MODIFICATION AND RE-IDENTIFICATION (P/N CHANGE) OF A SEAT IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2.A., OF ZODIAC SEATS FRANCE SB NO. 536-25-004, REV. 0, DATED OCTOBER 19, 2017, CONSTITUTES A TERMINATING ACTION FOR THE REPETITIVE INSPECTIONS					MANDATORY	NOT APPLICABLE - Not Equipped: not equipped
16-MAY-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-07-10	APPLIANCE AD - NAVIGATION - LITEF ATTITUDE HEADING AND REFERENCE SYSTEM (AHRS) - REMOVAL					MANDATORY	NOT APPLICABLE - By Part: BY OEM EQUIPMENT
29-MAY-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-07-10 PARA (F)(1)	REMOVE THE AHRS UNIT FROM SERVICE					MANDATORY	NOT APPLICABLE - By Part: BY OEM EQUIPMENT
29-MAY-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-07-10 PARA (F)(2)	REMOVAL FROM SERVICE OF P/N 145130-7100 TERMINATES THE REQUIREMENTS OF AD 2010-26-09 (75 FR 81424, DECEMBER 28, 2010)					MANDATORY	NOT APPLICABLE - By Part: BY OEM EQUIPMENT
29-MAY-2019		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-07-10 PARA (F)(3)	DO NOT INSTALL AN AHRS UNIT P/N 145130-2000, 145130-2001, 145130-7000, 145130-7001, OR 145130-7100 ON ANY AIRCRAFT					MANDATORY	NOT APPLICABLE - By Part: BY OEM EQUIPMENT
29-MAY-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
FAA 2019-08-01	APPLIANCE AD - EQUIPEMENT AND FURNISHINGS - MODIFICATION AND RE-IDENTIFICATION OF ALL AFFECTED RECARO AIRCRAFT SEATING GMBH & CO. KG MODEL PASSENGER SEATS					MANDATORY	NOT APPLICABLE - Not Equipped: n/a by oem
21-MAY-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
FAA 2019-08-01 PARA (G)	MODIFY THE AFFECTED PASSENGER SEAT AND RE-IDENTIFY EACH MODIFIED PASSENGER SEAT					MANDATORY	NOT APPLICABLE - Not Equipped: n/a by oem
21-MAY-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
FAA 2019-08-01 PARA (H)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED RECARO MODEL PASSENGER SEAT ON ANY AIRCRAFT, UNLESS THE SEAT HAS BEEN MODIFIED AND RE-IDENTIFIED IN ACCORDANCE WITH PARAGRAPH (G)(2), (3), OR (4) OF THIS AD					MANDATORY	NOT APPLICABLE - Not Equipped: n/a by oem
21-MAY-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
FAA 2019-12-09	APPLIANCE AD - NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)					MANDATORY	NOT APPLICABLE - Not Equipped: No Rockwell Collins FDSA-600 Fitted
23-JUL-2019		DAYS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
FAA 2019-13-03	APPLIANCE AD - TRIG AVIONICS LTD. - NAVIGATION - TRANSPONDERS INSTALLATION - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - Not Equipped: BY OEM
27-AUG-2019		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
FAA 2019-13-03 PARA (G)	INSPECT THE TRANSPONDER INSTALLATION TO DETERMINE IF THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK					MANDATORY	NOT APPLICABLE - Not Equipped: BY OEM
27-AUG-2019		DAYS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-13-03 PARA (H)	DO NOT INSTALL AN AFFECTED TRANSPONDER ON ANY AIRCRAFT, UNLESS THE TRANSPONDER IS INSTALLED IN A CONVENTIONAL AFT-FACING AVIONICS RACK AS DEFINED IN THIS AD					MANDATORY	NOT APPLICABLE - Not Equipped: BY OEM
27-AUG-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-14-05	APPLIANCE AD - EQUIPMENT / FURNISHING - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT					MANDATORY	NOT APPLICABLE - Not Equipped: N/A BY OEM
03-SEP-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-14-05 PARA (G)	REVIEW EACH AFFECTED B/E AEROSPACE FISCHER COMMON SEAT TO DETERMINE IF REWORK HAS ALREADY BEEN PERFORMED. IF THE REWORK HAS NOT BEEN PERFORMED REWORK THE AFFECTED SEATS AND MARK THE SEAT BY INSTALLING A PLACARD					MANDATORY	NOT APPLICABLE - Not Equipped: N/A BY OEM
03-SEP-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-14-05 PARA (H)	DO NOT INSTALL ANY SEAT AFFECTED BY THIS AD ONTO ANY AIRCRAFT UNLESS THE SEAT IS MARKED WITH A PLACARD STATING COMPLETION OF B/E AEROSPACE FISCHER ASB NO. SB0718-004, ISSUE A, DATED JUNE 26, 2018					MANDATORY	NOT APPLICABLE - Not Equipped: N/A BY OEM
03-SEP-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR					MANDATORY	NOT APPLICABLE - By Part: N/A BY P/N
19-SEP-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION					MANDATORY	NOT APPLICABLE - By Part: N/A BY P/N
19-SEP-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-15-10 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA					MANDATORY	NOT APPLICABLE - By Part: N/A BY P/N
19-SEP-2019		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-21-06	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS					MANDATORY	NOT APPLICABLE - By Part: BY PART NUMBER
13-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-21-06 PARA (G)(1)	MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT (RESTATEMENT OF FAA 2017-22-02)					MANDATORY	NOT APPLICABLE - By Part: BY PART NUMBER
13-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-21-06 PARA (G)(2)	INSPECT ANY AFFECTED SPRING OF EACH SEAT; REPLACE BOTH SPRINGS (IF, DURING ANY INSPECTION ANY DAMAGE OR INCORRECT INSTALLATION OF AN EFFECTED SPING IS FOUND)					MANDATORY	NOT APPLICABLE - By Part: BY PART NUMBER
13-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-21-06 PARA (G)(3)	SEND THE INSPECTION RESULTS, INCLUDING NO FINDINGS, TO IPECO AT TECHNICALSUPPORT@IPECO.COM					MANDATORY	NOT APPLICABLE - By Part: BY PART NUMBER
13-DEC-2019		DAYS HRS/MSC - AFL ACH FLTS					
FAA 2019-21-06 PARA (H)	DO NOT INSTALL ANY PILOT OR CO-PILOT SEAT IDENTIFIED IN PARAGRAPH (C)(1)(I) OF THIS AD UNLESS THE SEAT IS MODIFIED AND RE-IDENTIFIED AS SPECIFIED IN PARAGRAPH (G)(1) OF THIS AD					MANDATORY	NOT APPLICABLE - By Part: BY PART NUMBER
13-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-21-09	APPLIANCE AD - EQUIPMENT / FURNISHINGS - LIFE VEST POUCH - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - Not Equipped: NOT EQUIPPED
18-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2019-21-09 PARA (G)	INSPECT THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY; IF, DURING THE INSPECTION A LIFE VEST POUCH VELCRO STRIP IS FOUND DAMAGED OR WORN OR A LIFE VEST POUCH INSTALLATION IS NOT FOUND ACCEPTABLE, BEFORE FURTHER FLIGHT, REMOVE THE LIFE VEST POUCH FROM SERVICE AND REPLACE IT WITH A PART ELIGIBLE FOR INSTALLATION					MANDATORY	NOT APPLICABLE - Not Equipped: NOT EQUIPPED
18-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2019-21-09 PARA (I)	AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AVIOINTERIORS CENTAURUS ECONOMY CLASS PASSENGER SEAT WITH A P/N IDENTIFIED IN PARAGRAPH (C) OF THIS AD UNLESS THE AFFECTED SEAT LIFE VEST POUCH ASSEMBLY HAS BEEN INSPECTED IN ACCORDANCE WITH PARAGRAPH (G)(1) OF THIS AD					MANDATORY	NOT APPLICABLE - Not Equipped: NOT EQUIPPED
18-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
FAA 2020-08-02	APPLIANCE AD - NAVIGATION - THALES AVS FRANCE SAS - GLOBAL NAVIGATION SATELLITE SYSTEM - OPERATIONAL LIMITATIONS					MANDATORY	NOT APPLICABLE - Not Equipped: NOT EQUIPPED
19-MAY-2020		MOS HRS/MSC - AFL ACH FLTS					
FAA 2020-09-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ANJOU AERONAUTIQUE - RESTRAINT SYSTEMS ROTARY BUCKLE SUB ASSEMBLY - REPLACEMENT					MANDATORY	NOT APPLICABLE - Not Equipped: N/A, Romrex Anjou Aeronautique model 358 torso restraint system not installed (inst.on, but not limited to Airbus helicopters EC130T2,AS350B2 and B3
29-MAY-2020		MOS HRS/MSC - AFL ACH FLTS					
FAA 2020-09-02 PARA (G)(1)	INSPECT EACH RESTRAINT SYSTEM FOR PROPER RELEASE OF THE STRAPS FROM THE RESTRAINT SYSTEM AND, DEPENDING IF THE STRAPS RELEASE, PLACARD THE SEAT AS INOPERATIVE AND REMOVE AND REPLACE THE ROTARY BUCKLE SUB-ASSEMBLY (FOR THE RESTRAINT SYSTEMS LISTED IN THE EFFECTIVITY OF ANJOU AERO SB 358SB-14-101 R01, EXCEPT FOR S/NS 1038-1048 (INCLUSIVE), 1050-1055 (INCLUSIVE), AND 1062-1073 (INCLUSIVE))					MANDATORY	NOT APPLICABLE - Not Equipped: N/A, Romrex Anjou Aeronautique model 358 torso restraint system not installed (inst.on, but not limited to Airbus helicopters EC130T2,AS350B2 and B3
29-MAY-2020		MOS HRS/MSC AFL ACH FLTS					
FAA 2020-09-02 PARA (G)(2)	INSPECT EACH RESTRAINT SYSTEM FOR PROPER RELEASE OF THE STRAPS FROM THE RESTRAINT SYSTEM AND, DEPENDING IF THE STRAPS RELEASE, PLACARD THE SEAT AS INOPERATIVE AND REMOVE AND REPLACE THE RESTRAINT SYSTEM FROM SERVICE (FOR RESTRAINT SYSTEMS, P/N 358XX-XXX-YY-ZZZ (WHERE 358XX-XXX-YY-ZZZ CAN BE ANY COMBINATION OF NUMBERS AND/OR LETTERS), HAVING S/NS 738-1619 (INCLUSIVE))					MANDATORY	NOT APPLICABLE - Not Equipped: N/A, Romrex Anjou Aeronautique model 358 torso restraint system not installed (inst.on, but not limited to Airbus helicopters EC130T2,AS350B2 and B3
29-MAY-2020		MOS HRS/MSC AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-09-02 PARA (H)	DO NOT INSTALL ON ANY AIRCRAFT AN ANJOU AERONAUTIQUE RESTRAINT SYSTEM, P/N 358XX-XXX-YY-ZZZ, HAVING S/NS 738-1619 (INCLUSIVE), EVEN IF THE RESTRAINT SYSTEM IS LABELED IN COMPLIANCE WITH ANJOU AERO SB 358SB-14-101 R01, DATED DECEMBER 12, 2014					MANDATORY	NOT APPLICABLE - Not Equipped: N/A, Romrex Anjou Aeronautique model 358 torso restraint system not installed (inst.on, but not limited to Airbus helicopters EC130T2,AS350B2 and B3
29-MAY-2020		MOS HRS/MSC - AFL ACH FLTS					
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS
24-JUN-2020		MOS HRS/MSC - AFL		12-FEB-2021			
FAA 2020-16-08	APPLIANCE AD - ASPEN AVIONICS, INC. - EFD1000 FLIGHT DISPLAY SYSTEMS - AIRPLANE FLIGHT MANUAL - REVISION					MANDATORY	NOT APPLICABLE - Not Equipped: NO ASPEN AVIONICS FITTED
17-AUG-2020		MOS HRS/MSC - AFL ACH FLTS					
FAA 2020-18-51	APPLIANCE AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT					MANDATORY	NOT APPLICABLE - Not Equipped: NOT EQUIPPED WITH SANDIA AEROSPACE
28-SEP-2020		MOS HRS/MSC - AFL ACH FLTS					
FAA 2020-18-51-E	APPLIANCE/EMERGENCY AD - SANDIA AEROSPACE - AIRPLANE FLIGHT MANUAL - SECTION LIMITATIONS - AMENDMENT					MANDATORY	NOT APPLICABLE - Not Equipped: NOT EQUIPPED
31-AUG-2020		MOS HRS/MSC - AFL ACH FLTS					
FAA 2020-21-02	APPLIANCE AD - FIRE PROTECTION - KIDDE AEROSPACE & DEFENSE CARGO FIRE EXTINGUISHER HALON BOTTLES - REPLACEMENT					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: NO KIDDE AEROSPACE EXTINGUISHER INSTALLED
19-NOV-2020		MOS HRS/MSC - AFL		19-OCT-2020			
FAA 2020-21-02 PARA (H) & (I)	DO AN INSPECTION TO DETERMINE THE PART NUMBER AND SERIAL NUMBER OF THE CARGO FIRE EXTINGUISHER HALON BOTTLES INSTALLED IN THE CARGO COMPARTMENT AND REPLACE WITH A SERVICEABLE PART AS REQUIRED					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: NO KIDDE AEROSPACE EXTINGUISHER INSTALLED
		MOS HRS/MSC - AFL		20-OCT-2020			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2020-21-02 PARA (J)	NO PERSON MAY INSTALL ON ANY AIRPLANE AN AFFECTED PART AS IDENTIFIED IN PARAGRAPH (G)(3) OF THIS AD UNLESS THAT PART HAS A CIRCLED LETTER "G" STAMPED AT A DISTANCE 8 OF APPROXIMATELY ONE INCH FROM THE LEFT EDGE OF THE PLACARD, INDICATING THAT THE CARGO FIRE EXTINGUISHER HALON BOTTLE HAS BEEN TESTED AND REFILLED	MOS HRS/MSC - AFL		20-OCT-2020		MANDATORY	NOT APPLICABLE - NOT EQUIPPED: NO KIDDE AEROSPACE EXTINGUISHER INSTALLED
FAA 2021-05-17	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITIATIONS / SOFTWARE UPGRADE	MOS HRS/MSC - AFL		06-APR-2021		MANDATORY	NOT APPLICABLE - NOT EQUIPPED: NO FDSA-6500 INSTALLED
29-APR-2021							
FAA 2021-05-17 PARA (G)(1) & (G)(2)	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)	MOS HRS/MSC - AFL		06-APR-2021		MANDATORY	NOT APPLICABLE - NOT EQUIPPED: NO FDSA-6500 INSTALLED
29-APR-2021							
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE	MOS HRS/MSC - AFL		06-APR-2021		MANDATORY	NOT APPLICABLE - NOT EQUIPPED: NO FDSA-6500 INSTALLED
29-APR-2021							
FAA 2021-05-17 PARA (G)(5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE	MOS HRS/MSC - AFL		06-APR-2021		MANDATORY	NOT APPLICABLE - NOT EQUIPPED: NO FDSA-6500 INSTALLED
29-APR-2021							
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	MOS HRS/MSC - AFL		12-APR-2021		MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE
11-MAY-2021							
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	MOS HRS/MSC - AFL		12-APR-2021		MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE
11-MAY-2021							
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	MOS HRS/MSC - AFL		12-APR-2021		MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE
11-MAY-2021							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH PACIFIC SCIENTIFIC COMPANY ROTARY BUCKLE
11-MAY-2021		MOS HRS/MSC - AFL		12-APR-2021			
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: WITH ROCKWELL COLLINS GPS-4000S
12-MAY-2021		MOS HRS/MSC - AFL		12-APR-2021			
FAA 2021-08-15	APPLIANCE AD - NAVIGATION - GARMIN INTERNATIONAL GMN-00962 GTS PROCESSOR UNITS, PART NUMBER 011-02571-0() - SOFTWARE UPATE					MANDATORY	NOT APPLICABLE - NOT EQUIPPED: GTS825,GTS855 OR GTS8000 NOT INSTALLED
17-MAY-2021		MOS HRS/MSC AFL ACH FLTS		19-APR-2021			
FAA 2021-22-07	APPLIANCE AD - FIRE PROTECTION - HAND-OPERATED FIRE EXTINGUISHERS - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - By Part: BY P/N
18-NOV-2021		DAYS HRS/MSC AFL ACH FLTS					
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	NOT APPLICABLE - NOT ELIGIBLE BY ADOPTION BY EASA AT THIS TIME
09-DEC-2021		MOS HRS/MSC - AFL					
FAA 2022-01-03	APPLIANCE AD - FIRE PROTECTION - HAND-HELD FIRE EXTINGUISHERS - REPLACEMENT					MANDATORY	NOT APPLICABLE - By Part- BY PART NUMBER
07-MAR-2022		MOS HRS/MSC AFL ACH FLTS					
FAA 2022-04-09	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECT / REPLACE					MANDATORY	NOT APPLICABLE - Not Equipped- Part not installed on the A/C
04-APR-2022		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2022-04-09 PARA (H) & (I)	INSPECT THE OXYGEN VALVE ASSEMBLIES, AND OXYGEN CYLINDER AND VALVE ASSEMBLIES, TO DETERMINE IF AN EFFECTED PART INSTALLED; IF INSTALLED, BEFORE FURTHER FLIGHT, DO A DETAILED INSPECTION FOR CORRECT SPACING OF THE GAP BETWEEN THE BOTTOM OF THE PACKING RETAINER AND TOP OF THE VALVE BODY AND PERFORM CORRECTIVE ACTIONS	MOS HRS/MSC AFL ACH FLTS				MANDATORY	NOT APPLICABLE - Not Equipped- Part not installed on the A/C
04-APR-2022							
FAA 2022-04-09 PARA (J)	REPORT THE RESULTS OF THE INSPECTION	MOS HRS/MSC AFL ACH FLTS				MANDATORY	NOT APPLICABLE - Not Equipped- Part not installed on the A/C
04-APR-2022							
FAA 2022-05-10	APPLIANCE AD - CABIN EQUIPMENT/FURNISHINGS - GOODRICH HOIST ASSEMBLY - INSPECT/REPLACE	MOS HRS/MSC - AFL ACH FLTS				MANDATORY	NOT APPLICABLE - NOT EQUIPPED - HELICOPTERS EXTERNALLY MOUNTED HOIST ASSEMBLIES
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION	MOS HRS/MSC - AFL			05-JUN-2023	MANDATORY	NOT APPLICABLE - N/A FOR A/C THAT DO NOT OPERATE IN US AIR SPACE OR CONTIGUOUS US
26-MAY-2023							
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE- 2023 - SATISFIED BY FAA 2021-23-12)	MOS HRS/MSC - AFL			05-JUN-2023	MANDATORY	NOT APPLICABLE - N/A FOR A/C THAT DO NOT OPERATE IN US AIR SPACE OR CONTIGUOUS US
26-MAY-2023							
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	MOS HRS/MSC - AFL			05-JUN-2023	MANDATORY	NOT APPLICABLE - N/A FOR A/C THAT DO NOT OPERATE IN US AIR SPACE OR CONTIGUOUS US
26-MAY-2023							
FAA 2023-13-11	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES / OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECTION/REPLACEMENT	MOS HRS/MSC - AFL			07-AUG-2023	MANDATORY	NOT APPLICABLE - BY PART: OXYGEN SYSTEM NOT EQUIPPED WITH THE AFFECTED P/NS. CURRENT AVOX P/N INSTALLED: VENDOR PN: 895-06077 (PILATUS PN: 957.12.12.212 )
39-22496 05-SEP-2023							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2023-13-11 PARA (H)	INSPECT THE OXYGEN VALVE ASSEMBLIES AND OXYGEN CYLINDER AND VALVE ASSEMBLIES					MANDATORY	NOT APPLICABLE - BY PART: OXYGEN SYSTEM NOT EQUIPPED WITH THE AFFECTED P/NS. CURRENT AVOX P/N INSTALLED: VENDOR PN: 895-06077 (PILATUS PN: 957.12.12.212 )
39-22496 05-SEP-2023		MOS HRS/MSC - AFL			07-AUG-2023		
FAA 2023-13-11 PARA (J)	REPORT THE RESULTS OF THE INSPECTION AND RETURN PARTS (AS REQUIRED)					MANDATORY	NOT APPLICABLE - BY PART: OXYGEN SYSTEM NOT EQUIPPED WITH THE AFFECTED P/NS. CURRENT AVOX P/N INSTALLED: VENDOR PN: 895-06077 (PILATUS PN: 957.12.12.212 )
39-22496 05-SEP-2023		MOS HRS/MSC - AFL			07-AUG-2023		
FAA 2023-14-10	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LIMITED (IPECO) PILOT AND CO-PILOT SEATS - INSPECTION/MODIFICATION					MANDATORY	NOT APPLICABLE - BY PART: JETFLY FLEET IS NOT EQUIPPED WITH THE AFFECTED PNS OF THE IPECO SEATS
39-22510 07-SEP-2023		MOS HRS/MSC - AFL			14-AUG-2023		
FAA 2023-14-10 PARA (G)(1)	MODIFY AND RE-IDENTIFY EACH AFFECTED PILOT AND CO-PILOT SEAT (SEATS THAT HAVE NOT INSTALLED THE TRACK LOCK SPRING MODIFICATION KIT)					MANDATORY	NOT APPLICABLE - BY PART: JETFLY FLEET IS NOT EQUIPPED WITH THE AFFECTED PNS OF THE IPECO SEATS
07-SEP-2023		MOS HRS/MSC - AFL			14-AUG-2023		
FAA 2023-14-10 PARA (G)(2)	INSPECT THE TRACK LOCK SPRING OF EACH SEAT					MANDATORY	NOT APPLICABLE - BY PART: JETFLY FLEET IS NOT EQUIPPED WITH THE AFFECTED PNS OF THE IPECO SEATS
07-SEP-2023		MOS HRS/MSC - AFL			14-AUG-2023		
FAA 2023-14-10 PARA (G)(3)	SEND THE INSPECTION RESULTS, INCLUDING NO FINDINGS, TO IPECO					MANDATORY	NOT APPLICABLE - BY PART: JETFLY FLEET IS NOT EQUIPPED WITH THE AFFECTED PNS OF THE IPECO SEATS
07-SEP-2023		MOS HRS/MSC - AFL			14-AUG-2023		
FAA 2023-14-10 PARA (H)	MODIFY AND RE-IDENTIFY EACH AFFECTED SEAT					MANDATORY	NOT APPLICABLE - BY PART: JETFLY FLEET IS NOT EQUIPPED WITH THE AFFECTED PNS OF THE IPECO SEATS
07-SEP-2023		MOS HRS/MSC - AFL			14-AUG-2023		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2023-46	APPLIANCE AD - NAVIGATION - AEROPLANE - PROHIBITION OF OPERATIONS REQUIRING RADIO ALTIMETER WHEN OPERATING IN THE CONTIGUOUS UNITED STATES DUE TO 5G C-BAND WIRELESS BROADBAND INTERFERENCE					MANDATORY	NOT APPLICABLE - N/A BY STATE OF REGISTRY - THIS AD IS APPLICABLE TO CANADIAN-REGISTERED A/C, EXCEPT CANADIAN REGISTERED A/C WHICH ARE U.S. STATE OF DESIGN, WHEN OPERATING IN CONTIGUOUS U.S. AIRSPACE.
30-JUN-2023		MOS HRS/MSC - AFL			04-JUL-2023		
TCCA CF-2023-46 PART II	AIRPLANE/AIRCRAFT FLIGHT MANUAL (AFM) REVISION UNTIL 30 JUNE 2023					MANDATORY	NOT APPLICABLE - N/A BY STATE OF REGISTRY - THIS AD IS APPLICABLE TO CANADIAN-REGISTERED A/C, EXCEPT CANADIAN REGISTERED A/C WHICH ARE U.S. STATE OF DESIGN, WHEN OPERATING IN CONTIGUOUS U.S. AIRSPACE.
30-JUN-2023		MOS HRS/MSC - AFL			04-JUL-2023		
TCCA CF-2023-46 PART III	AFM REVISION AFTER 30 JUNE 2023					MANDATORY	NOT APPLICABLE - N/A BY STATE OF REGISTRY - THIS AD IS APPLICABLE TO CANADIAN-REGISTERED A/C, EXCEPT CANADIAN REGISTERED A/C WHICH ARE U.S. STATE OF DESIGN, WHEN OPERATING IN CONTIGUOUS U.S. AIRSPACE.
30-JUN-2023		MOS HRS/MSC - AFL			04-JUL-2023		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - SB - 1314/VH-AL4</b>							
SB 04-001	CONVERSION OF PC-12 TO PC-12/45, SERVICE BULLETIN						NOT APPLICABLE
	25-MAR-1997	MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 04-001 R01	CONVERSION OF THE PC-12 TO A PC12/45 VARIANT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
	31-OCT-2006	MOS HRS/MSC - AFL		30-NOV-2011			
SB 04-002 R03	CANADIAN REGISTRATION OF PC-12 AND PC-12/45, SERVICE BULLETIN						NOT APPLICABLE
	07-APR-1998	MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 04-002 R04	CANADIAN REGISTRATION OF PC-12 AND PC-12/45, SERVICE BULLETIN						NOT APPLICABLE - BY REGISTRATION COUNTRY
	09-MAR-2006	MOS HRS/MSC - AFL		30-NOV-2011			
SB 04-003 R01	BRAZILIAN REGISTRATION OF THE PC-12 AND PC-12/45, SERVICE BULLETIN						NOT APPLICABLE
	29-JUN-2000	MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 04-003 R02	BRAZILIAN REGISTRATION OF THE PC-12, PC-12/45 AND PC-12/47 AIRCRAFT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY REGISTRATION COUNTRY
	26-MAY-2008	MOS HRS/MSC - AFL		30-NOV-2011			
SB 04-004	ARGENTINEAN REGISTRATION OF THE PC-12 AND PC12/45, SERVICE BULLETIN						NOT APPLICABLE
	04-DEC-1997	MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 04-004 R01	ARGENTINEAN REGISTRATION OF THE PC-12, PC-12/45 AND PC-12/47 AIRCRAFT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY REGISTRATION COUNTRY
	23-JUN-2008	MOS HRS/MSC - AFL		30-NOV-2011			
SB 04-005 R01	FRENCH REGISTRATION OF THE PC-12, SERVICE BULLETIN						NOT APPLICABLE
	12-SEP-2001	MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 04-005 R02	FRENCH REGISTRATION OF THE PC-12, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY REGISTRATION COUNTRY
	27-MAY-2008	MOS HRS/MSC - AFL		30-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 04-006 R01	NETHERLAND CERTIFICATION PC-12 AND PC-12/45, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
18-JUN-2001		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 04-006 R02	AIRWORTHINESS LIMITATIONS PC-12 AND PC-12/45 AIRCRAFT-NETHERLANDS CERTIFICATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY REGISTRATION COUNTRY
27-JUN-2008		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
SB 04-007	AIRWORTHINESS LIMITATIONS-PC12 AND PC12/45 A/C-CIS CERTIFICATION, SERVICE BULLETIN						NOT APPLICABLE
20-AUG-2004		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 04-007 R01	AIRWORTHINESS LIMITATIONS PC-12, PC12/45 AND PC12/47 AIRCRAFT - CIS CERTIFICATION, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
28-SEP-2006		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 04-007 R02	AIRWORTHINESS LIMITATIONS PC-12, PC-12/45 AND PC-12/47 AIRCRAFT - CIS CERTIFICATION, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
13-AUG-2007		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 04-007 R03	AIRWORTHINESS LIMITATIONS PC-12, PC-12/45 AND PC-12/47 AIRCRAFT - CIS CERTIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY REGISTRATION COUNTRY
25-AUG-2008		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
SB 04-008	AIRWORTHINESS LIMITATIONS - CONVERSION OF PC-12/45 AIRCRAFT MSN 684, MSN 710, MSN 723, MSN728 AND MSN 745 TO PC-12/47 AIRCRAFT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
15-DEC-2006		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
SB 04-009	AIRWORTHINESS LIMITATIONS - LIFE EXTENSION TO 25,000 FLIGHT HOURS OR 30,000 FLIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - DUE TO SERIAL NUMBER
31-MAR-2008		MOS		13-MAY-2014			
		HRS/MSC -		1028.67			
		AFL		824			
SB 04-009 R01	AIRWORTHINESS LIMITATIONS - LIFE EXTENSION TO 25,000 FLYING HOURS OR 30,000 LANDINGS, SERVICE BULLETIN					OPTIONAL	DECLINED - ALL AIRCRAFT WILL BE SOLD BEFORE THEIR 10TH YEAR.
28-JUL-2010		MOS		13-MAY-2014			
		HRS/MSC -		1028.67			
		AFL		824			
SB 04-009 R05	AIRWORTHINESS LIMITATIONS - LIFE EXTENSION TO 25,000 FLIGHT HOURS OR 30,000 LANDINGS (AVAILABLE ON REQUEST ONLY), SERVICE BULLETIN						DECLINED - ALL AIRCRAFT WILL BE SOLD BEFORE THEIR 10TH YEAR.
01-JUL-2016		MOS					
		HRS/MSC - (s)					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 04-010 R01	CANADIAN REGISTRATION OF PC-12/47E AIRCRAFT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY REGISTRATION COUNTRY
		MOS		31-JAN-2012			
		HRS/MSC	A/R	5			
		AFL		5			
SB 04-010 R02	CANADIAN REGISTRATION OF PC-12/47E AIRCRAFT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY REGISTRATION COUNTRY
24-JUL-2020		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
SB 04-011 R02	FOR THE INTERSTATE AVIATION COMMITTEE AVIATION REGISTER (IAC AR) CERTIFIED PC-12/47E AIRPLANES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - n/a by aircraft registration
14-DEC-2017		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
SB 04-012	AIRWORTHINESS LIMITATIONS - LIFE EXTENSION TO 27,500 FLIGHT HOURS OR 33,000 FLIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
22-JUN-2009		MOS		30-NOV-2011			
		HRS/MSC	-				
		AFL					
SB 04-013	AIRWORTHINESS LIMITATIONS - GENERAL - PEOPLE'S REPUBLIC OF CHINA (PRC) CERTIFICATION STANDARD PC-12 SERIES AIRCRAFT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
06-NOV-2009		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		AFL		5			
SB 04-013 R01	AIRWORTHINESS LIMITATIONS - GENERAL - PEOPLE'S REPUBLIC OF CHINA (PRC) CERTIFICATION STANDARD PC-12 SERIES AIRCRAFT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY REGISTRATION COUNTRY
14-NOV-2011		MOS		29-NOV-2011			
		HRS/MSC	-	0			
		AFL		0			
SB 04-014	AIRWORTHINESS LIMITATIONS - GENERAL - LIFE EXTENSION TO 30,000 FLIGHT HOURS OR 36,000 LANDINGS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
17-AUG-2010		MOS		30-NOV-2011			
		HRS/MSC	-				
		AFL					
SB 04-015	AIRWORTHINESS LIMITATIONS - GENERAL NEW ZEALAND CERTIFICATION STANDARD PC-12 SERIES AIRCRAFT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - DUE TO COUNTRY REGISTRATION
20-FEB-2014		MOS		13-MAY-2014			
		HRS/MSC	-	1028.67			
		AFL		824			
SB 04-016	AIRWORTHINESS LIMITATIONS - GENERAL DEPARTMENT OF CIVIL AVIATION, MALAYSIA CERTIFICATION STANDARD PC-12 SERIES AIRCRAFT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - DUE TO COUNTRY REGISTRATION
07-MAY-2014		MOS		15-MAY-2014			
		HRS/MSC	-	1034.25			
		AFL		834			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 04-017	AIRWORTHINESS LIMITATIONS - GENERAL - AIRWORTHINESS LIMITATIONS - GENERAL - FEDERAL AVIATION OFFICE, GERMANY - CERTIFICATION STANDARD PC-12/47E AIRCRAFT (MSN 1461 ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
03-NOV-2014		MOS		29-NOV-2011			
		HRS/MSC	-	0			
		AFL		0			
SB 04-017 R01	AIRWORTHINESS LIMITATIONS - GENERAL FEDERAL AVIATION OFFICE, GERMANY - CERTIFICATION STANDARD PC-12/47E AIRCRAFT, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - INFORMATIONAL ONLY: NOT CONCERNED BY REGISTRATION COUNTRY
10-DEC-2018		MOS		12-DEC-2018			
		HRS/MSC	-	3869.75			
		AFL		3283			
SB 04-018	AIRWORTHINESS LIMITATIONS - GENERAL COLOMBIA UNIDAD ADMINISTRATIVA ESPECIAL DE AERONAUTICA CERTIFICATION STANDARD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY COUNTRY REGISTRATION
17-JUL-2015		MOS		11-AUG-2015			
		HRS/MSC	-				
		AFL					
SB 04-019	AIRWORTHINESS LIMITATIONS - GENERAL CIVIL AVIATION AUTHORITY OF PERU CERTIFICATION STANDARD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY COUNTRY REGISTRATION
23-JUL-2015		MOS		11-AUG-2015			
		HRS/MSC	-				
		AFL					
SB 04-020	AIRWORTHINESS LIMITATIONS - GENERAL - UNITED ARAB EMIRATES (UAE) GENERAL CIVIL AVIATION AUTHORITY CERTIFICATION STANDARD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY GCAA OF THE UNITED ARAB EMIRATES CERTIFICATION STANDARD
02-AUG-2016		MOS		17-AUG-2016			
		HRS/MSC	-				
		AFL					
SB 04-022	AIRWORTHINESS LIMITATIONS - GENERAL - JAPAN CIVIL AVIATION BUREAU CERTIFICATION STANDARD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - By Effectivity- PC-12/47E Series aircraft MSN 1001 and Up registered in Japan.
18-FEB-2022		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
SB 04-022 R01	AIRWORTHINESS LIMITATIONS - GENERAL - JAPAN CIVIL AVIATION BUREAU CERTIFICATION STANDARD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - N/A TO THE JETFLY FLEET. ALL JETFLY FLEET A/C ARE REGISTERED IN LUXEMBOURG
15-SEP-2022		MOS		29-NOV-2022			
		HRS/MSC	-				
		AFL					
SB 11-001	TAKE-OFF/LANDING WEIGHT AND SPEED PLACARD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
24-FEB-1995		MOS		30-NOV-2011			
		HRS/MSC	-				
		AFL					
SB 11-002	REPLACEMENT OF FLAP PLACARD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
20-NOV-2001		MOS		30-NOV-2011			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 11-003	POSSIBLE INCORRECT OPERATIONAL LIMITATIONS PLACARD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
16-SEP-2002		MOS HRS/MSC - (s) AFL		30-NOV-2011			
SB 11-004	PLACARDS AND MARKINGS - INTERNAL PLACARDS FLIGHT COMPARTMENT - REPLACE THE VFE/VO KIAS PLACARD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
02-AUG-2010		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 11-004 R01	PLACARDS AND MARKINGS - INTERNAL PLACARDS FLIGHT COMPARTMENT- REPLACE THE VFENO KIAS PLACARD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
26-NOV-2010		MOS HRS/MSC - AFL		30-NOV-2011			
SB 11-005	PLACARDS AND MARKINGS - EXTERNAL PLACARDS REPLACE THE FUEL FILLER PLACARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
01-MAR-2012		MOS HRS/MSC - AFL		15-AUG-2012 99.08 78			
SB 11-006	PLACARDS AND MARKINGS - EXTERNAL PLACARDS - REPLACE THE ENGINE OIL AND OXYGEN CHARGING PRESSURE PLACARDS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
01-MAR-2012		MOS HRS/MSC - AFL		15-AUG-2012 99.08 78			
SB 21-001 R01	PRESSURE CONTROL SYSTEM INSTALLATION - SOLENOID VALVE, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
03-MAR-1997		MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 21-002	MODIFICATION OF CABIN HEATING, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
17-FEB-1998		MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 21-003 R01	MODIFICATION OF ECS PIPING AND TEMPERATURE CONTROL VALVE, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
21-JUL-2000		MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 21-004	INSTALLATION OF COCKPIT FOOTWARMER HEATER, SERVICE BULLETIN						NOT APPLICABLE
11-SEP-1998		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 21-004 R01	AIR CONDITIONING - FOOT HEATER INSTALLATION OF FOOT HEATER AND DUCTS FOR THE PILOT AND COPILOT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
08-SEP-2008		MOS HRS/MSC - AFL		29-NOV-2011 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 21-004 R01A	AIR CONDITIONING - FOOT HEATER - INSTALLATION OF FOOT HEATER AND DUCTS FOR THE PILOT AND COPILOT - NO LONGER AVAILABLE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - This Service Bulletin is therefore no longer available.
17-NOV-2021		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 21-005	INSTALLATION OF ECS REFRIGERATION PACK VIBRATION INSULATORS, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
08-DEC-1999		MOS		29-NOV-2011			
		HRS/MSC - (s)		0			
		AFL		0			
SB 21-006 REV A	INSTALLATION OF A COVER OVER THE ECS TEMPERATURE CONTROL VALVE, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
30-JUN-2000		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 21-007	AIR CONDITIONING-TEMPERATURE CONTROL-CHANGE THE CABLE ROUTING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 21-008	AIR CONDITIONING - VAPOR-CYCLE COOLING SYSTEM MODIFICATION TO THE HOUR METER WIRING ON THE COMPRESSOR/CONDENSER MODULE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
31-AUG-2007		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 21-008 R01	AIR CONDITIONING - VAPOR-CYCLE COOLING SYSTEM MODIFICATION TO THE HOUR METER WIRING ON THE COMPRESSOR/CONDENSER MODULE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
06-JUN-2008		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 21-009 PART A	AIR CONDITIONING - PRESSURIZATION CONTROL CABIN PRESSURE SWITCHES - MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
23-NOV-2007		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 21-009 PART B	AIR CONDITIONING - PRESSURIZATION CONTROL CABIN PRESSURE SWITCHES - MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
23-NOV-2007		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 21-009 R01	AIR CONDITIONING - PRESSURIZATION CONTROL CABIN PRESSURE SWITCHES - MODIFICATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
23-DEC-2010		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 21-009 R01 PART A	- AIR CONDITIONING - PRESSURIZATION CONTROL CABIN PRESSURE SWITCHES - MODIFICATION, SERVICE BULLETIN FOR THE CABIN PRESSURE SWITCH					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
23-DEC-2010		MOS		29-NOV-2011			
		HRS/MSC - (s)		0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 21-009 R01 PART B	- AIR CONDITIONING - PRESSURIZATION CONTROL CABIN PRESSURE SWITCHES - MODIFICATION, SERVICE BULLETIN FOR THE CABIN DIFFERENTIAL PRESSURE SWITCH					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
23-DEC-2010		MOS		29-NOV-2011			
		HRS/MSC - (s)		0			
		AFL		0			
SB 21-010	AIR CONDITIONING - TEMPERATURE CONTROL REPLACEMENT OF THE INTEGRATED ENVIRONMENTAL-CONTROL-SYSTEM CONTROLLER (IEC), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
12-JAN-2009		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 21-011	AIR CONDITIONING - PRESSURIZATION CONTROL INTRODUCTION OF CABIN PRESSURE CONTROL UNIT P/N 959.90.91.143, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
22-OCT-2009		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 21-012	AIR CONDITIONING - COMPRESSOR CONDENSER ASSEMBLY - REPLACE INCORRECT BINARY PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY S/N : 1243 (COMPRESSOR MODULE)
29-APR-2013		MOS		18-MAY-2013			
		HRS/MSC -		460.67			
		AFL		372			
SB 21-012 R01	AIR CONDITIONING - COMPRESSOR CONDENSER ASSEMBLY - REPLACE INCORRECT BINARY PRESSURE SWITCH, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY S/N COMPRESSOR CONDENSER
26-AUG-2014		MOS		11-SEP-2014			
		HRS/MSC -					
		AFL					
SB 21-013	AIR CONDITIONING - COMPRESSOR CONDENSER ASSEMBLY - REPLACEMENT OF THE IDENTIFICATION PLATE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY COMPRESSOR CONDENSER MODULE S/N
11-JUL-2016		MOS		10-AUG-2016			
		HRS/MSC -					
		AFL					
SB 21-014	AIR CONDITIONING - COOLING - VCCS COMPRESSOR CONDENSER MODULE IMPROVEMENTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY P/N
31-MAY-2017		MOS		28-AUG-2018			
		HRS/MSC -					
		AFL					
SB 21-015	AIR CONDITIONING - COMPRESSOR CONDENSER MODULE - INSPECT THE COMPRESSOR CONDENSER MODULE FAN BLADE, SERVICE BULLETIN					RECOMMENDED	- SUPERSEDED BY R01
30-JUL-2018		MOS					
		HRS/MSC -					
		AFL					
SB 21-015 R01	AIR CONDITIONING - COMPRESSOR CONDENSER MODULE - INSPECT THE COMPRESSOR CONDENSER MODULE FAN BLADE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY S/N LISTED ON SB ENVIRO 18-101
18-DEC-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 21-015 R02	AIR CONDITIONING - COMPRESSOR CONDENSER MODULE - INSPECT THE COMPRESSOR CONDENSER MODULE FAN BLADE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - By Part: P/N 1134400-13 INSTALLED
10-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
SB 21-016	AIR CONDITIONING - COMPRESSOR CONDENSER MODULE - MODIFICATION TO THE COMPRESSOR/CONDENSER BONDING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL: VCCS AND LARGE O2 BOTTLE FITTED PN 957.12.12.212 -1965 LTR - BUT O2 BOTTLE FITTED IN THE LH REAR FUSELAGE - 2022-09-16
15-AUG-2022		MOS HRS/MSC - AFL		21-SEP-2022			
SB 21-017	AIR CONDITIONING - COMPRESSOR CONDENSER MODULE MODIFICATION TO THE COMPRESSOR/CONDENSER BONDING, SERVICE BULLETIN						
17-JAN-2023		MOS HRS/MSC 1200 AFL	12	(EFF)	17-JAN-2024 ?	RECURRING ?	
SB 21-018	AIR CONDITIONING - HEATING - INTRODUCTION OF A NEW ECS OVER-TEMPERATURE SWITCH AND DUCT OVER-TEMPERATURE SWITCH, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY A/C MSN - PC-12 SERIES AIRCRAFT MSN 101 THRU MSN 888.
20-JAN-2023		MOS HRS/MSC - AFL		16-OCT-2023			
SB 21-018 PART 1	ACCOMPLISH AIR CONDITIONING - HEATING - INTRODUCTION OF A NEW ECS OVER-TEMPERATURE SWITCH AND DUCT OVER-TEMPERATURE SWITCH, SERVICE BULLETIN REPLACES THE ECS OVER-TEMPERATURE SWITCH					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY A/C MSN - PC-12 SERIES AIRCRAFT MSN 101 THRU MSN 888.
20-JAN-2023		MOS HRS/MSC - AFL		16-OCT-2023			
SB 21-018 PART 2	ACCOMPLISH AIR CONDITIONING - HEATING - INTRODUCTION OF A NEW ECS OVER-TEMPERATURE SWITCH AND DUCT OVER-TEMPERATURE SWITCH, SERVICE BULLETIN REPLACES THE DUCT OVER-TEMPERATURE SWITCH					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY A/C MSN - PC-12 SERIES AIRCRAFT MSN 101 THRU MSN 888.
20-JAN-2023		MOS HRS/MSC - AFL		16-OCT-2023			
SB 22-001	REPLACE EPROM IC (I236) IN THE FLIGHT CONTROL SYSTEM, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
15-DEC-1994		MOS HRS/MSC - AFL		30-NOV-2011			
SB 22-002	MODIFICATION OF ANGLE OF ATTACK (AOA) TRANSMITTER MOUNTINGS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
24-OCT-1997		MOS HRS/MSC - AFL		30-NOV-2011			
SB 22-003	ADJUSTMENT OF OUTPUT TORQUE OF STICK PUSHER ACTUATOR AND CAPSTAN CLUTCH, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
24-JUN-1999		MOS HRS/MSC - AFL		30-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 22-004 R01	AUTOPILOT-PITCH ACTUATOR-REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		30-NOV-2011			
	15-JUN-2005	HRS/MSC -					
		AFL					
SB 22-005	AUTOFLIGHT - AUTOPILOT REPLACEMENT OF THE FLIGHT GUIDANCE PANEL (FGP), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT MSN
		MOS		18-DEC-2014			
		HRS/MSC -		1340.08			
		AFL		1076			
SB 22-007	AUTO FLIGHT - STICK PUSHER COMPUTER - REPLACEMENT OF THE STICK PUSHER COMPUTER, SERVICE BULLETIN					OPTIONAL	- NO FUTHER ACTION - SUPERSEDED BY R01 IN CASE OF FAILURE OF STICK PUSHER COMPUTER P/N 975.44.23.104, REPLACE WITH NEW PN 975.44.23.106
		MOS		(EFF)			
	25-FEB-2020	HRS/MSC -					
		AFL					
SB 22-007 R01	AUTO FLIGHT - STICK PUSHER COMPUTER - REPLACEMENT OF THE STICK PUSHER COMPUTER, SERVICE BULLETIN					OPTIONAL	- APPLICABLE - WAITING FOR EXECUTIVE MANAGER DECISION - IN CASE OF FAILURE OF STICK PUSHER COMPUTER P/N 975.44.23.104, REPLACE WITH NEW PN 975.44.23.106
		MOS					
	13-MAY-2024	HRS/MSC -					
		AFL					
SB 23-001	INSTALLATION OF IMPROVED STATIC DISCHARGERS, SERVICE BULLETIN						NOT APPLICABLE
		MOS		29-NOV-2011			
	24-OCT-1997	HRS/MSC -		0			
		AFL		0			
SB 23-001 R01	COMMUNICATIONS - INSTALLATION OF IMPROVED STATIC DISCHARGERS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	23-FEB-2012	HRS/MSC -		0			
		AFL		0			
SB 23-002	REPLACEMENT OF VHF/COMM 2 TRANSCEIVERS, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	04-SEP-2000	HRS/MSC -		5			
		AFL		5			
SB 23-002 R01	COMMUNICATIONS - VHF NAV/COMM 1 AND NAV/COMM 2 KX155A1KX165A (25KHZ) TRANSCEIVERS - REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	06-JUN-2008	HRS/MSC -		0			
		AFL		0			
SB 23-003	REPLACEMENT OF VHF/COMM 2 TRANSCEIVERS, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	17-NOV-2000	HRS/MSC -		0			
		AFL		0			
SB 23-004	INTRODUCTION OF MICROPHONE SELECTOR SWITCH AND OXYGEN MASK CONNECTION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		31-JAN-2012			
	08-MAY-2003	HRS/MSC -		5			
		AFL		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 23-004 R01	COMMUNICATION - AUDIO INTEGRATING - INTRODUCTION OF A MICROPHONE SELECTOR SWITCH AND CONNECTION FOR THE OXYGEN MASK MICROPHONE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
27-SEP-2011		MOS		29-NOV-2011			
		HRS/MSC	-	0			
		AFL		0			
SB 23-005	COMMUNICATIONS - VHF COMMUNICATION SYSTEM 1 AND 2 TRANSCEIVER - REPLACEMENT OF MMDR KTR2280 RADIOS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
11-JUN-2008		MOS		29-NOV-2011			
		HRS/MSC	-	0			
		AFL		0			
SB 23-006	COMMUNICATIONS - STATIC DISCHARGING IMPROVEMENTS TO THE AIRFRAME ELECTRICAL BONDING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-DEC-2009		MOS		29-NOV-2011			
		HRS/MSC	-	0			
		AFL		0			
SB 23-006 R01	COMMUNICATIONS - STATIC DISCHARGING IMPROVEMENTS TO THE AIRFRAME ELECTRICAL BONDING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
22-NOV-2012		MOS		15-MAY-2014			
		HRS/MSC	-	1034.25			
		AFL		834			
SB 23-007	COMMUNICATIONS - AUDIO SYSTEM - OXYGEN MASK MICROPHONE SOCKET WIRING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
21-SEP-2011		MOS		29-NOV-2011			
		HRS/MSC	-	0			
		AFL		0			
SB 23-008	COMMUNICATIONS - AUDIO SYSTEM - OXYGEN MASK MICROPHONE SOCKET WIRING, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
28-SEP-2011		MOS		29-NOV-2011			
		HRS/MSC	-	0			
		AFL		0			
SB 23-009	COMMUNICATION - SPEECH COMMUNICATION UPGRADE OF HONEYWELL KTR 2280 MULTI MODE DIGITAL RADIO SOFTWARE, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED BY 23-009 R1
17-OCT-2012		MOS		15-MAY-2014			
		HRS/MSC	-	1034.25			
		AFL		834			
SB 23-009 R01	COMMUNICATION - SPEECH COMMUNICATION. UPGRADE OF HONEYWELL KTR 2280 MULTI MODE DIGITAL RADIO SOFTWARE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
07-NOV-2012		MOS		05-MAR-2013			
		HRS/MSC	-	306.58			
		AFL		243			
SB 23-010 R01	COMMUNICATIONS - AEROWAVE 100 SATCOM SYSTEM - INSTALLATION, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
28-AUG-2017		MOS		04-SEP-2018			
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
SB 23-010 R02	COMMUNICATIONS - AEROWAVE 100 SATCOM SYSTEM - INSTALLATION, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
15-MAR-2022		MOS		(EFF)			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 23-011	COMMUNICATIONS - AUDIO INTEGRATING - INTRODUCTION OF HAND MICROPHONE P/N 984.22.11.303, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		04-APR-2017			
		26-JAN-2017	HRS/MSC -				
			AFL				
SB 23-013	COMMUNICATIONS - AEROWAVE 100 SATCOM SYSTEM - HARDWARE AND SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - Not Equipped: NO SATCOM FITTED
		MOS					
		01-MAY-2019	HRS/MSC -				
			AFL				
			ACH				
			FLTS				
SB 23-014	COMMUNICATIONS - AEROWAVE 100 SATCOM SYSTEM - INSTALLATION OF AN ON/OFF SWITCH IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - Not Equipped: NO SATCOM INSTALLED
		MOS					
		19-SEP-2019	HRS/MSC -				
			AFL				
			ACH				
			FLTS				
SB 23-014 R01	COMMUNICATIONS - AEROWAVE 100 SATCOM SYSTEM - INSTALLATION OF AN ON/OFF SWITCH IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - Not Equipped: NO SATCOM INSTALLED
		MOS					
		09-JUL-2020	HRS/MSC -				
			AFL				
			ACH				
			FLTS				
SB 23-014 R02	COMMUNICATIONS - AEROWAVE 100 SATCOM SYSTEM - INSTALLATION OF AN ON/OFF SWITCH IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		(EFF)			
		29-SEP-2020	HRS/MSC -				
			AFL				
SB 23-015	COMMUNICATIONS - AUDIO INTEGRATING SYSTEM AUDIO CONTROL PANEL (KMA-29A), SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		(EFF)			
		08-JUN-2021	HRS/MSC -				
			AFL				
SB 23-016	COMMUNICATIONS - AEROWAVE 100 SATCOM SYSTEM - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY SERIAL: A/C MSN
		MOS		23-JAN-2023			
		13-JAN-2023	HRS/MSC - (s)				
			AFL				
SB 24-001	REPLACEMENT OF GENERATOR 2 DRIVE HOUSING, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
		27-SEP-1996	HRS/MSC -	0			
			AFL	0			
SB 24-002 R01	RE-ROUTING OF THE GENERATOR 1 AND 2 POWER RETURN CABLES, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
		20-SEP-1996	HRS/MSC -	0			
			AFL	0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 24-003 R01	REWIRING OF THE AUTOMATIC DISCONNECT CIRCUIT, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	18-SEP-1996	HRS/MSC -		0			
		AFL		0			
SB 24-004	STARTER DELAY RELAY REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	03-JUN-1997	HRS/MSC -		0			
		AFL		0			
SB 24-005	CB211 BUS TIE GEN 1 UNCONTROLLED OPENING, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	24-OCT-1997	HRS/MSC -		0			
		AFL		0			
SB 24-006	INSTALLATION OF A CABLE TIE ATTACHMENT AT FRAME 40, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	12-FEB-1998	HRS/MSC -		0			
		AFL		0			
SB 24-007	INSTALLATION OF TWO CIRCUIT BREAKERS AT FRAME 19, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	04-FEB-1998	HRS/MSC -		0			
		AFL		0			
SB 24-008 R02	INSTALLATION OF EXTERNAL POWER CONTROL UNIT, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	30-AUG-2002	HRS/MSC -		0			
		AFL		0			
SB 24-009	INSTALLATION OF GEN 2 CUT-OUT RELAY, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	28-SEP-1998	HRS/MSC -		0			
		AFL		0			
SB 24-010 R01	REPLACEMENT OF GEN 2, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	06-OCT-2003	HRS/MSC -		5			
		AFL		5			
SB 24-010 R02	REPLACEMENT OF GENERATOR 2, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	01-JUL-2005	HRS/MSC -		0			
		AFL		0			
SB 24-011	INSTALLATION OF GEN 1 VOLT AND AMP INDICATION SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	28-JUN-2001	HRS/MSC -		0			
		AFL		0			
SB 24-012	MODIFICATION OF GEN 2 EXCITATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	19-FEB-1999	HRS/MSC -		0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 24-013	CHECK AND/OR REPLACEMENT OF BATTERY CONNECTOR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
23-AUG-1999		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 24-014	REPLACE THE SUPPRESSION FILTER (A250), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
27-OCT-1999		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 24-015	INSTALLATION OF PROTECTIVE COVER OVER VOLTAGE CONTROL UNIT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
09-AUG-2000		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 24-016 R01	REPLACEMENT OF GEN 2 BRUSH HOLDER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
15-NOV-2001		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 24-016 R02	ELECTRICAL POWER - BRUSH HOLDER IN SECOND GENERATOR - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
05-JUN-2008		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 24-017 R04	ELECTRICAL POWER - DC GENERATION - REPLACEMENT OF NICKEL CADMIUM BATTERIES WITH LEAD ACID BATTERIES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - DUE TO SERIAL NUMBER
29-FEB-2016		MOS		23-SEP-2016			
		HRS/MSC -					
		AFL					
SB 24-017 R05	ELECTRICAL POWER - DC GENERATION - REPLACEMENT OF NICKEL CADMIUM BATTERIES WITH LEAD ACID BATTERIES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - LEAD ACID BATTERIES ALREADY FITTED
03-NOV-2020		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 24-017 R06	ELECTRICAL POWER - DC GENERATION - REPLACEMENT OF NICKEL CADMIUM BATTERIES WITH LEAD ACID BATTERIES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - LEAD ACID BATTERIES INSTALLED PIL. PN 976.11.26.120 VENDOR PN RG-380E/44
18-JUN-2021		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 24-019 R01	REPLACEMENT OF SECOND GENERATOR CONTROL UNIT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
06-JUN-2003		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 24-020	CHANGE LDG LIGHT RH CIRCUIT BREAKER TO GENERATOR 1 BUS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		31-JAN-2012			
	23-OCT-2003	HRS/MSC -		5			
		AFL		5			
SB 24-020 R01	ELECTRICAL POWER - DC ELECTRICAL LOAD DISTRIBUTION CHANGE LDG LIGHT RH CIRCUIT - BREAKER FROM NON ESSENTIAL BUS TO GENERATOR BUS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	30-JUN-2008	HRS/MSC -		0			
		AFL		0			
SB 24-021	GENERATOR 1 GROUND SENSING LEAD, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	06-JUN-2003	HRS/MSC -		0			
		AFL		0			
SB 24-022	REPLACEMENT OF 2ND GENERATOR CONTROL UNIT WITH 2ND BATTERY INSTALLED, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
	13-JUN-2003	HRS/MSC -		0			
		AFL		0			
SB 24-023	DC GENERATION SYSTEM-SECOND GENERATOR WIRING MOD, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	15-FEB-2005	HRS/MSC -		5			
		AFL		5			
SB 24-023 R01	DC GENERATION SYSTEM-SECOND GENERATOR WIRING MOD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	18-AUG-2005	HRS/MSC -		0			
		AFL		0			
SB 24-024	AC GENERATION SYSTEM STATIC INVERTERS - REPLACEMENT, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	23-NOV-2005	HRS/MSC -		5			
		AFL		5			
SB 24-024 R01	ELECTRICAL POWER - AC GENERATION SYSTEM STATIC INVERTERS - REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
		HRS/MSC A/R		0			
		AFL		0			
SB 24-025	ELECTRICAL POWER - EXTERNAL POWER INTRODUCTION OF BATTERY AND EXTERNAL POWER JUNCTION BOX P/N 974.03.38.142, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	24-SEP-2009	HRS/MSC -		0			
		AFL		0			
SB 24-026	ELECTRICAL POWER - GENERAL INSPECTION OF THE CLAMPING BANDS ON PLUGS PB361 AND PB362, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	21-SEP-2010	HRS/MSC -		0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 24-027	ELECTRICAL POWER - DC POWER DISTRIBUTION - LEFT HAND POWER JUNCTION BOX - INSPECT THE GAP BETWEEN CURRENT SENSOR AND BUSBAR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
08-JUN-2011		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 24-028	ELECTRICAL POWER - DC GENERATION - INSTALLATION OF WATER PROTECTION FOR ELECTRICAL EQUIPMENT PANEL ON FRAME 10, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
20-JUL-2011		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 24-029	ELECTRICAL POWER - BATTERY INSTALLATION - INSTALLATION OF NICKEL CADMIUM BATTERIES IN LIEU SEALED LEAD ACID BATTERIES, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
30-SEP-2011		MOS		22-JUN-2015			
		HRS/MSC -					
		AFL					
SB 24-029 R01	ELECTRICAL POWER - BATTERY INSTALLATION - INSTALLATION OF NICKEL CADMIUM BATTERIES IN LIEU OF SEALED LEAD ACID BATTERIES, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
02-JUN-2017		MOS		04-SEP-2018			
		HRS/MSC -					
		AFL					
SB 24-029 R02	ELECTRICAL POWER - BATTERY INSTALLATION - INSTALLATION OF NICKEL CADMIUM BATTERIES IN LIEU OF SEALED LEAD ACID BATTERIES, SERVICE BULLETIN					OPTIONAL	DECLINED - APPLICABLE - WAITING FOR EXECUTIVE MANAGER DECISION LEAD BATTERIES INSTALLED PN ON RG-380E/44
06-JUL-2023		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 24-030	ELECTRICAL POWER - DISTRIBUTION - RE-ROUTING AND PROTECTION OF WIRE LOOMS IN THE WING ROOT FAIRING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
08-MAR-2012		MOS		12-APR-2012			
		HRS/MSC -					
		AFL					
SB 24-031	ELECTRICAL POWER - DISTRIBUTION - INSPECTION OF THE CLEARANCE BETWEEN THE REAR FUSELAGE POWER CABLE INSTALLATION AND THE LARGE OXYGEN SYSTEM PIPES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
17-APR-2012		MOS		20-NOV-2012			
		HRS/MSC -		209.25			
		AFL		168			
SB 24-032	ELECTRICAL POWER - DISTRIBUTION JUNCTION BOX RH, EXCHANGE OF TYPE PLATE DUE TO FAILURE ON HARDWARE MODIFICATION BY ESTERLINE-LEACH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-APR-2012		MOS		25-FEB-2013			
		HRS/MSC -		301.83			
		AFL		239			
SB 24-032 R01	ELECTRICAL POWER - DISTRIBUTION - JUNCTION BOX RH, EXCHANGE OF TYPE PLATE DUE TO FAILURE ON HARDWARE MODIFICATION BY ESTERLINE-LEACH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
04-JUN-2012		MOS		25-FEB-2013			
		HRS/MSC -		301.83			
		AFL		239			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 24-033 R01	ELECTRICAL POWER - DISTRIBUTION PC-12 GENERATOR COMMON SPARES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - N/A DUE TO SERIAL NUMBER
15-OCT-2013		MOS HRS/MSC - AFL		13-MAY-2014 1028.67 824			
SB 24-035	ELECTRICAL POWER - ELECTRICAL HARNESS PROTECTION OF THE ENGINE BAY ELECTRICAL HARNESS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
23-NOV-2012		MOS HRS/MSC - AFL		13-MAY-2014 1028.67 824			
SB 24-036	ELECTRICAL POWER - DC DISTRIBUTION EXTERNAL POWER CONNECTOR PROTECTION, SERVICE BULLETIN					OPTIONAL	DEFERRED - SEE FORM F-19 SB 24-036
04-FEB-2015		MOS HRS/MSC - AFL					
SB 24-038	ELECTRICAL POWER - DC GENERATION - INTRODUCTION OF NI-CAD BATTERIES WITH IN-FLIGHT HEATING, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY TYPE OF BATTERIES INSTALLED (LEAD ACID BATTERIES INSTALLED)
28-JAN-2016		MOS HRS/MSC - AFL		09-FEB-2016			
SB 24-038 R01	ELECTRICAL POWER - DC GENERATION - INTRODUCTION OF NI-CAD BATTERIES WITH IN-FLIGHT HEATING, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - Not Equipped: NO NICAD BATTERIES
30-MAY-2018		MOS HRS/MSC - AFL ACH FLTS					
SB 24-039	ELECTRICAL POWER - DC GENERATION - REPLACE LEAD ACID BATTERIES WITH NI-CAD BATTERIES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
11-MAR-2016		MOS HRS/MSC - AFL		06-APR-2016			
SB 24-040	ELECTRICAL POWER - EXTERNAL POWER - BATTERY AND EXTERNAL POWER JUNCTION BOX - CHECK OF CB LUG INCLINATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY S/N BATTERY AND EXTERNAL POWER JUNCTION BOX INSTALLED
25-JAN-2016		MOS HRS/MSC - AFL		29-JAN-2016			
SB 24-041	ELECTRICAL POWER - DC GENERATION - INTRODUCTION OF NI-CAD BATTERIES WITH IN FLIGHT HEATING, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - N/A BY AIRCRAFT MODEL
20-APR-2017		MOS HRS/MSC - AFL					
SB 24-042	ELECTRICAL POWER - GENERAL IMPROVEMENTS TO THE ELECTRICAL HARNESS INSTALLATION , SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
03-FEB-2021		MOS HRS/MSC - AFL		25-FEB-2021			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 25-001	MODIFICATION OF THE AIRCRAFT CREW SEATS ADJUSTMENT MECHANISM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
24-SEP-1997		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-002 R01	INSTALLATION OF BATTERY AND ENGINE HEATING SYSTEMS (SUPERSEDED BY 25-002 R2), SERVICE BULLETIN						NOT APPLICABLE
13-OCT-1998		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 25-002 R02	INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM FOR EXTREME COLD TEMPERATURES (SUPERSEDED BY 25-002 R3), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
01-APR-1998		MOS HRS/MSC A/R AFL		31-JAN-2012 5 5			
SB 25-002 R03	INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM FOR EXTREME COLD TEMPERATURES (SUPERSEDED BY 25-002 R4), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
06-SEP-2006		MOS HRS/MSC - (s) AFL		31-JAN-2012 5 5			
SB 25-002 R04	INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM FOR EXTREME COLD TEMPERATURES (SUPERSEDED BY SB 25-040 R01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
30-JUN-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-003 R01	HIC MODIFICATIONS TO THE EXECUTIVE CABIN LAYOUT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
07-APR-1998		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-004	EXECUTIVE TOILET WIRING MOD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
24-OCT-1997		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-005 R01	INSTALLATION OF LUGGAGE RESTRAINT BAR, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY INSTALLATION OF PAX SEATS
27-FEB-1998		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-005 R02	EQUIPMENT/FURNISHINGS - GENERAL - INSTALLATION OF PAX SEAT LUGGAGE RESTRAINT BAR, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - DECLINED BY EXECUTIVE MANAGER DECISION
28-JAN-2020		MOS HRS/MSC - AFL		19-NOV-2020			
SB 25-006	HIC MODIFICATIONS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY INSTALLATION OF PAX SEATS
07-APR-1998		MOS HRS/MSC - AFL		29-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 25-008	INTRODUCTION OF PASSENGER DOOR THERMAL BLANKET, SERVICE BULLETIN					OPTIONAL	DECLINED - SB 25-008 REV 0 NO LONGER AVAILABLE
06-JUL-1998		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-009	CREW SEAT LAP STRAPS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
17-JUN-1998		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-010	INTRODUCTION OF LARGER BAGGAGE NET, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - SUPERSEDED BY 25-010 R1
05-MAR-1999		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 25-010 R01	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT NEW BAGGAGE NET INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY INSTALLATION CABIN CONFIGURATION ( 6 PAX OR 8 PAX ) NO CORPORATE COMMUTER 9 PAX
29-MAY-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-010 R01A	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT NEW BAGGAGE NET INSTALLATION (NO LONGER AVAILABLE), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - NFA - PUB CANCELLED
28-FEB-2024		MOS HRS/MSC - AFL		20-MAR-2024			
SB 25-012 R01	INSTALLATION OF NEW PASSENGER COMPARTMENT INSULATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
24-NOV-2000		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-012 R02	EQUIPMENT AND FURNISHINGS - PASSENGER CABIN INSTALLATION OF NEW INSULATION AND PART NUMBERS UPDATE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
06-FEB-2012		MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 25-013 R01	INSTALLATION OF NEW PASSENGER COMPARTMENT UNDERFLOOR INSULATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
05-APR-2000		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-013 R03	EQUIPMENT AND FURNISHINGS - CABIN UNDERFLOOR INSULATION AND DRAINAGE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
23-JAN-2014		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 25-014 R01	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT INSTALLATION OF A 3-BENCH SEAT TO THE EXECUTIVE MODEL, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
22-OCT-2007		MOS HRS/MSC A/R AFL		26-JUN-2015			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 25-014 R01A	EQUIPMENT/FURNISHINGS - GENERAL - INSTALLATION OF A 3-BENCH SEAT TO THE EXECUTIVE MODEL (NO LONGER REQUIRED), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - SERVICE BULLETIN IS NO LONGER REQUIRED
07-JAN-2021		MOS HRS/MSC - AFL		21-JAN-2021			
SB 25-015	MODIFICATION OF THE CREW SEATS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY PART NUMBER OF PILOT AND COPILOT
27-APR-1999		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-016 R01	INTERIOR PLACARDS IDENTIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
27-SEP-2000		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-017 R01	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT BAGGAGE HOLD CURTAIN - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
01-JUL-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-019	BAGGAGE NET LIMITATIONS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
27-SEP-2000		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-020	INSTALLATION OF ELT 910 REMOTE CONTROL PANEL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY ELT PART NUMBER ( 406 AF INSTALLED )
26-FEB-2001		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-021	KANNAD ELT 406 AF AS A REPLACEMENT FOR 121 AF, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
14-MAR-2002		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 25-021 R01	EQUIPMENT/FURNISHINGS-EMERGENCY EQUIPMENT INTRODUCTION OF THE KANNAD 406 AF EMERGENCY LOCATOR TRANSMITTER AS A REPLACEMENT FOR THE KANNAD 121 AF EMERGENCY LOCATOR TRANSMITTER, SERVICE BULLETIN						NOT APPLICABLE - BY MSN AIRCRAFT
15-SEP-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-022	KANNAD ELT 406 AF AS A REPLACEMENT FOR NARCO ELT 910, SERVICE BULLETIN					SUPERSEDED	DECLINED - SB SUPERSEDED BY SB 25-028 REV 0
01-FEB-2002		MOS HRS/MSC - AFL		29-NOV-2011			
SB 25-023	APPLICATION OF ADHESIVE TAPE TO FIRE-WALL INSULATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
05-JUL-2001		MOS HRS/MSC - AFL		31-JAN-2012 5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 25-023 R01	EQUIPMENT AND FURNISHINGS - INSULATION FIRE - WALL INSULATION - APPLY ADHESIVE TAPE, SERVICE BULLETIN	MOS		29-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
27-MAY-2005		HRS/MSC - (s)					
		AFL					
SB 25-024	MSN 321 AND 401-500. SMALLER ELT REMOTE CONTROL PANEL, SERVICE BULLETIN	MOS		29-NOV-2011		OPTIONAL	DECLINED - SB SUPERSEDED BY SB 25-027 REV 1
15-AUG-2002		HRS/MSC -					
		AFL					
SB 25-025	INSPECTION OF EXECUTIVE SEAT P/N AND PEDESTAL LEG ASSEMBLY, SERVICE BULLETIN	MOS		29-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
27-SEP-2002		HRS/MSC -					
		AFL					
SB 25-026 REV A	EQUIPMENT AND FURNISHINGS - FLIGHT COMPARTMENT - PILOTS RELIEF TUBE - INSTALLATION (NO LONGER AVAILABLE), SERVICE BULLETIN	MOS		29-NOV-2011		CANCELLED	DECLINED - SB 25-026 REV A NO LONGER AVAILABLE
08-JUL-2005		HRS/MSC -					
		AFL					
SB 25-027 R01	ELT CONTROL PANEL REPLACEMENT WITH SMALLER PANEL, SERVICE BULLETIN	MOS		29-NOV-2011		OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
21-APR-2004		HRS/MSC -					
		AFL					
SB 25-028	KANNAD ELT 406 AF REPLACEMENT FOR NARCO 910, SERVICE BULLETIN	MOS		29-NOV-2011		OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
08-JAN-2004		HRS/MSC -					
		AFL					
SB 25-029	INSTALLATION OF ELT SMART CONNECTOR, SERVICE BULLETIN	MOS		29-NOV-2011		OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
17-FEB-2004		HRS/MSC -					
		AFL					
SB 25-030 R01	INSTALLATION OF ELT NAVIGATION INTERFACE, SERVICE BULLETIN	MOS		31-JAN-2012		OPTIONAL	NOT APPLICABLE
17-FEB-2004		HRS/MSC -		5			
		AFL		5			
SB 25-030 R02	EQUIPMENT FURNISHINGS - EMERGENCY EQUIPMENT INTRODUCTION OF AN EMERGENCY - LOCATOR - TRANSMITTER GPS NAVIGATION INTERFACE INSTALLATION, SERVICE BULLETIN	MOS		29-NOV-2011		OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
30-JUN-2008		HRS/MSC -					
		AFL					
SB 25-031	FLIGHT COMPARTMENT-CREW SEATS-INSPECTION OF CREW SEATS BACKREST, SERVICE BULLETIN	MOS		29-NOV-2011		MANDATORY	NOT APPLICABLE - BY SEAT'S PART NUMBER
21-JUL-2004		HRS/MSC -					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 25-032	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT EXECUTIVE SEAT LEGS - REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY PART NUMBER VENDOR & SERIAL NUMBER
		MOS		29-NOV-2011			
		HRS/MSC - (s)					
		AFL					
02-OCT-2006							
SB 25-033	EQUIPMENT/FURNISHINGS-INTRODUCTION OF COVERS TO PREVENT WATER INGRESS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
13-JUL-2007							
SB 25-034	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (110 V AC) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - SUPERSEDED BY 25-034R1
		MOS		13-MAY-2014			
		HRS/MSC -		1028.67			
		AFL		824			
22-OCT-2009							
SB 25-034 R01	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (110 V AC) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		26-JUN-2015			
		HRS/MSC -					
		AFL					
SB 25-035	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (230 V AC) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					SUPERSEDED	- SUPERSEDED
		MOS		13-MAY-2014			
		HRS/MSC -		1028.67			
		AFL		824			
22-OCT-2009							
SB 25-035 R01	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (230 V AC) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					SUPERSEDED	- SEE SB 25-035R2
		MOS		13-MAY-2014			
		HRS/MSC -		1028.67			
		AFL		824			
12-MAY-2010							
SB 25-035 R02	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (230 V AC) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		26-JUN-2015			
		HRS/MSC -					
		AFL					
SB 25-035 R02A	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (230 V AC) FOR EXTREME COLD TEMPERATURES (NO LONGER REQUIRED, SUPERSEDED BY SB 25-042), SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - INFORMATIONAL ONLY: THIS SERVICE BULLETIN IS SUPERSEDED BY SB 25-042
		MOS		24-FEB-2021			
		HRS/MSC -					
		AFL					
04-JAN-2021							
SB 25-036	EQUIPMENT AND FURNISHINGS - CABIN - CABIN CONFIGURATION MSN 1209 (AVAILABLE FOR FACTORY MODIFICATION ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
12-NOV-2012							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 25-037	EQUIPMENT AND FURNISHINGS - CABIN - CABIN CONFIGURATION MSN 1390 (AVAILABLE FOR FACTORY MODIFICATION ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
23-JAN-2014		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 25-038	EQUIPMENT AND FURNISHINGS - CABIN - CABIN CONFIGURATION MSN 1467 (AVAILABLE FOR FACTORY MODIFICATION ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
20-NOV-2014		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 25-039	EQUIPMENT AND FURNISHINGS - CABIN - CABIN CONFIGURATION MSN 1515 (AVAILABLE FOR FACTORY MODIFICATION ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
07-JAN-2015		MOS		04-MAR-2015			
		HRS/MSC -					
		AFL					
SB 25-039 R01	EQUIPMENT AND FURNISHINGS - CABIN - CABIN CONFIGURATION MSN 1515 (AVAILABLE FOR FACTORY MODIFICATION ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		22-JUN-2015			
		HRS/MSC -					
		AFL					
SB 25-040	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (115 VAC/60 HZ) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER. SUPERSEDED BY R01
08-JUN-2017		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 25-040 R01	EQUIPMENT/FURNISHINGS - GENERAL - INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (115 VAC/60 HZ) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT SERIAL NUMBER. SUPERSEDED BY R02
25-FEB-2021		MOS		12-MAR-2021			
		HRS/MSC -					
		AFL					
SB 25-040 R02	EQUIPMENT AND FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (115 VAC/60 HZ) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT SERIAL NUMBER.
06-JUL-2023		MOS		18-AUG-2023			
		HRS/MSC -					
		AFL					
SB 25-041	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (115 VAC/60 HZ) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
02-SEP-2016		MOS		24-JAN-2018			
		HRS/MSC -					
		AFL					
SB 25-041 R01	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (115 VAC/60 HZ) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
13-JAN-2021		MOS		(EFF)			
		HRS/MSC -					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 25-042	EQUIPMENT/FURNISHINGS - GENERAL INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (230 VAC) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
06-DEC-2017		MOS		04-SEP-2018			
		HRS/MSC -					
		AFL					
SB 25-042 R01	EQUIPMENT/FURNISHINGS - GENERAL - INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (230 VAC) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
13-JAN-2021		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 25-043	EQUIPMENT AND FURNISHINGS - CONNECTOR CONVERSION FOR THE ENGINE COLD WEATHER PREHEATER SYSTEM, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
06-DEC-2017		MOS		04-SEP-2018			
		HRS/MSC -					
		AFL					
SB 25-044 R03	EQUIPMENT AND FURNISHINGS - FLIGHT COMPARTMENT - INTRODUCTION OF DUAL USB - CHARGING PORTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - C/W DURING JFS-007-21
06-AUG-2020		MOS		23-JUL-2021			
		HRS/MSC -		5312.33			
		AFL		4590			
SB 25-045	EQUIPMENT AND FURNISHINGS - FLIGHT COMPARTMENT - INTRODUCTION OF HEADSET HOLDERS ON THE COCKPIT SIDEWALLS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EXECUTIVE MANGER DECISION
28-FEB-2018		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 25-046	EQUIPMENT AND FURNISHINGS - PASSENGER COMPARTMENT - REPLACEMENT OF THE EXECUTIVE PASSENGER SEAT BRACKET, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - By Effectivity: BY ACFT MSN
18-APR-2019		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 25-047	EQUIPMENT/FURNISHINGS - GENERAL - INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (115 VAC/60 HZ) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
03-MAR-2021		MOS		12-MAR-2021			
		HRS/MSC -					
		AFL					
SB 25-048	EQUIPMENT/FURNISHINGS - GENERAL - INSTALLATION OF A SUPPLEMENTARY AIRCRAFT HEATING SYSTEM (230 VAC) FOR EXTREME COLD TEMPERATURES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
03-MAR-2021		MOS		12-MAR-2021			
		HRS/MSC -					
		AFL					
SB 25-050	EQUIPMENT AND FURNISHINGS - FLIGHT COMPARTMENT MODIFICATION TO PERMIT INSTALLATION OF REPLACEMENT CREW SEATS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
28-JAN-2021		MOS		25-FEB-2021			
		HRS/MSC -					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 25-051	EQUIPMENT AND FURNISHINGS - FLIGHT COMPARTMENT INSTALLATION OF STORAGE BOX ON LEFT BULKHEAD, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
14-JAN-2021		MOS HRS/MSC - AFL		25-FEB-2021			
SB 25-053	EQUIPMENT AND FURNISHINGS - FLIGHT COMPARTMENT - INTRODUCTION OF PILOT AND COPILOT TABLET MOUNTS, SERVICE BULLETIN					OPTIONAL	- SUPERSEDED BY R01
28-JAN-2021		MOS HRS/MSC - AFL		(EFF)			
SB 25-053 R01	EQUIPMENT AND FURNISHINGS - FLIGHT COMPARTMENT - INTRODUCTION OF PILOT AND COPILOT TABLET MOUNTS, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
04-MAY-2021		MOS HRS/MSC - AFL		(EFF)			
SB 25-054	EQUIPMENT AND FURNISHINGS - GENERAL - RETROFIT OF PLISSE CURTAINS IN THE FLIGHT COMPARTMENT AND THE BAGGAGE COMPARTMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY A/C MSN
03-FEB-2022		MOS HRS/MSC - (s) AFL		03-NOV-2022			
SB 26-001	FIRE PROTECTION - EXTINGUISHING TO PROVIDE AN ALTERNATIVE COCKPIT FIRE EXTINGUISHER, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
12-APR-2010		MOS HRS/MSC - AFL		26-JUN-2015			
SB 26-001 REV A	FIRE PROTECTION - EXTINGUISHING - TO PROVIDE AN ALTERNATIVE COCKPIT FIRE EXTINGUISHER (NO LONGER REQUIRED), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - NO LONGER REQUIRED
01-SEP-2020		MOS HRS/MSC - AFL ACH FLTS					
SB 26-002	FIRE PROTECTION - EXTINGUISHING - TO PROVIDE A HALON-ALTERNATIVE FLIGHT COMPARTMENT FIRE EXTINGUISHER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - C/W IAW SB26-002 EXTINGUISHER REPLACED
24-OCT-2019		MOS HRS/MSC - AFL		10-NOV-2021 5642.08 4839			
SB 26-002 R01	FIRE PROTECTION - EXTINGUISHING TO PROVIDE A HALON-ALTERNATIVE FLIGHT COMPARTMENT FIRE EXTINGUISHER, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
29-SEP-2020		MOS HRS/MSC - AFL		10-NOV-2021 5642.08 4839			
SB 27-001	MODIFICATION OF AILERON TIE-ROD ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
25-MAR-1997		MOS HRS/MSC - AFL		29-NOV-2011 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 27-002	MODIFICATION OF FLAP POSITION TRANSMITTER, SERVICE BULLETIN					OPERATING TIME LIMIT	NOT APPLICABLE - BY MSN AIRCRAFT
	03-JAN-1998	MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 27-003	REPLACEMENT OF FLAP DRIVE SHAFTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
	08-MAR-1999	MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 27-004	REMOVAL OF ALTERNATE FLAP SYSTEM, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
	15-SEP-1998	MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 27-005	CHECK OF FLAP ACTUATORS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
	18-NOV-1998	MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 27-006 R01	INSTALLATION OF NEW FLAP RESET SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
	14-AUG-2001	MOS HRS/MSC - (s) AFL		29-NOV-2011 0 0			
SB 27-006 R01A	FLIGHT CONTROLS - FLAPS - INSTALLATION OF A NEW FLAP RESET SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
	10-AUG-2001	MOS HRS/MSC - AFL		04-JAN-2016			
SB 27-007	LIMITED SERVICE LIFE FLAP ACTUATORS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
	26-JAN-1999	MOS HRS/MSC - (s) AFL		31-JAN-2012 5 5			
SB 27-007 R01	FLIGHT CONTROLS - FLAPS - CONTROL OF LIMITED SERVICE LIFE FLAP SCREW ACTUATORS (REVISION 1 NOT ISSUED - EDITORIAL ONLY), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
	26-JAN-1999	MOS HRS/MSC - (s) AFL		29-NOV-2011 0 0			
SB 27-008 R02	REPLACEMENT OF THE FCWU AND MODIFICATIONS TO THE SYSTEM, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
	13-SEP-2000	MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 27-009	MODIFICATION OF THE FLAP LIMIT MICROSWITCHES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
	23-SEP-1999	MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 27-010	MODIFICATION OF THE AILERON CONTROL INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
	31-MAR-2000	MOS HRS/MSC - AFL		29-NOV-2011 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 27-011 R01	MODIFICATION OF THE FLAP CONTROL WIRING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	26-JAN-2001	HRS/MSC -		0			
		AFL		0			
SB 27-012	FCWU REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	13-SEP-2000	HRS/MSC -		0			
		AFL		0			
SB 27-013	FLIGHT CONTROLS - FLAPS INTRODUCTION OF A NEW POWER DRIVE UNIT (PDU), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		31-JAN-2012			
	02-APR-2001	HRS/MSC -		5			
		AFL		5			
SB 27-013 R03	FLIGHT CONTROLS - FLAPS INTRODUCTION OF A NEW POWER DRIVE UNIT (PDU), SERVICE BULLETIN					DISCRETIONARY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	12-MAY-2010	HRS/MSC -		0			
		AFL		0			
SB 27-014	INSTALLATION OF NEW FLAP MOTOR RELAY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	29-JUN-2001	HRS/MSC -		0			
		AFL		0			
SB 27-015 REV A	REPLACEMENT OF INBOARD FLAP DRIVE SHAFTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	13-NOV-2003	HRS/MSC -		0			
		AFL		0			
SB 27-016	FLAPS-POWER DRIVE UNIT-REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	04-FEB-2004	HRS/MSC -		0			
		AFL		0			
SB 27-017 R01	FLIGHT CONTROLS - FLAPS - MODIFICATION TO THE WIRING CIRCUIT OF THE FLAP POWER DRIVE UNIT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
	20-DEC-2006	HRS/MSC -		0			
		AFL		0			
SB 27-018	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM REPLACE THE BOLTS ON THE CABLE CLAMPS FOR THE STICK-PUSHER SERVO-CABLES (SUPERSEDED BY 27-020), SERVICE BULLETIN					SUPERSEDED	DECLINED - SB SUPERSEDED BY SB 27-020 REV 1
		MOS		29-NOV-2011			
	27-NOV-2007	HRS/MSC - (s)		0			
		AFL		0			
SB 27-019	FLIGHT CONTROLS - FLAPS - FLAP CONTROL AND WARNING UNIT - CHANGE TO WIRING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
		MOS		29-NOV-2011			
	10-JUL-2009	HRS/MSC -		0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 27-020 R01	FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM DO A CHECK OF THE TENSION ON THE STICK-PUSHER SERVO-CABLES, SERVICE BULLETIN	MOS HRS/MSC - AFL		29-NOV-2011 0 0		MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
SB 27-022	FLIGHT CONTROLS - AILERON CONTROL SYSTEM REPLACEMENT OF THE UNIVERSAL JOINTS IN THE FLIGHT CONTROLS, SERVICE BULLETIN	MOS HRS/MSC - AFL		23-MAR-2015		MANDATORY	NOT APPLICABLE - BY EFFECTIVITY ( NO REPLACEMENT OF THE UNIVERSAL JOINTS P/N : 944.61.73.012 - 527.10.12.195 AND NO INSTALLATION KIT P/N 500.50.12.314 )
SB 27-023	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM - REPLACEMENT OF THE MANUAL PITCH TRIM RELAY, SERVICE BULLETIN	MOS HRS/MSC - AFL		25-OCT-2020 5078.92 4389	07-MAY-2019	OPTIONAL	COMPLIED WITH - REPLACEMENT OF HORIZONTAL STABILISER MANUAL PITCH TRIM RELAY SEE JFS-007-20
SB 27-023 R01	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM - REPLACEMENT OF THE MANUAL PITCH TRIM RELAY, SERVICE BULLETIN	MOS HRS/MSC - AFL		25-OCT-2020	12-OCT-2020	OPTIONAL	COMPLIED WITH - SEE WO JFS-007-20
SB 27-023 R02	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM - REPLACEMENT OF THE MANUAL PITCH TRIM RELAY, SERVICE BULLETIN	MOS HRS/MSC - AFL		19-JUL-2023	07-JUL-2023	RECOMMENDED	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: NFA - REFER TO WO JFS-007-20 2020-10-25
SB 27-024	FLIGHT CONTROLS - HORIZONTAL STABILIZER TRIM - REPLACEMENT OF THE TRIM ADAPTER UNIT, SERVICE BULLETIN	MOS HRS/MSC - AFL		11-OCT-2019 4392.25 3753	04-MAR-2019	OPTIONAL	COMPLIED WITH - SB PERFORMED DUE TO REPLACEMENT OF TRIM ADAPTER UNIT
SB 27-025	AILERONS - FUSELAGE BELLCRANKS - CHECK FOR INSTALLATION OF THE WASHER P/N 527.10.12.112, SERVICE BULLETIN	MOS HRS/MSC - AFL ACH FLTS			12-JUL-2019	RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
SB 27-026	FLIGHT CONTROLS - FLAP DRIVE SYSTEM - INSPECTION OF THE INBOARD FLAP FAIRINGS AFT AND THE FRONT INBOARD TENSION RODS, SERVICE BULLETIN	MOS HRS/MSC - AFL ACH FLTS				MANDATORY	NOT APPLICABLE - By Effectivity: BY ACFT MSN

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 28-001	INSTALLATION OF CHECK VALVES IN THE WING FUEL SYSTEM, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
22-NOV-1996		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-002	MODIFICATION OF FUEL FIREWALL SHUT-OFF VALVE CONTROL LEVER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
19-JUL-1996		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-003 R01	MODIFICATION OF FUEL TANK INWARD VENT VALVES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
30-SEP-1997		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-004	FUEL - STORAGE - MODIFICATION OF FUEL FILLER CAPS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
27-MAR-1998		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-005	MODIFICATION OF FUEL VENT VALVES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
04-MAY-1998		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-006	MODIFICATION OF DELIVERY JET PUMPS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
04-MAY-1998		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-007	REPLACEMENT OF FUEL FILTER O-RINGS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN AIRCRAFT
09-AUG-1999		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-008	INSPECTION OF BOOSTER PUMPS ARMATURE END PLAY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
19-JUN-2001		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-009	TORQUE CHECK OF ENGINE DRIVEN FUEL PUMP RELIEF VALVE SCREWS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
10-AUG-2001		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-010	EDP REPLACEMENT OF RELIEF VALVE BODY HOUSING AND SEALS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
16-SEP-2002		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-011 R01	DAMAGE TO FUEL BOOSTER PUMP WIRES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
11-JUL-2003		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 28-012	FUEL -INDICATION SYSTEMS REPLACEMENT OF THE FUEL CONTROL MONITORING-UNIT (FCMU), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
	04-SEP-2008	MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 28-013	FUEL - DISTRIBUTION MODIFICATION TO INTRODUCE THE NEW DELIVERY EJECTOR PUMPS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY ACFT MSN
	15-SEP-2020	MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 28-015	FUEL - STORAGE APPLICATION OF CHROMATE CONVERSION COATING TO INWARD VENT VALVE, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: BY ACFT MSN
	12-OCT-2020	MOS		20-OCT-2020			
		HRS/MSC -					
		AFL					
SB 29-001	MODIFICATION OF THE HYDRAULIC HAND PUMP HANDLE, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	01-JUL-1996	MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 29-002	HYDRAULIC POWER PACK MOTOR DRIVE SHAFT SEEPAGE DRAIN, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
	12-AUG-1997	MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 29-003	INSTALLATION OF A FILTER SCREEN TO HYDRAULIC SELECTOR VALVE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
	02-SEP-1997	MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 30-001	MODIFICATION OF THE ANTI AND DEICE SYSTEMS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
	20-DEC-1995	MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 30-002	REPLACE THE PROPELLER DE-ICING CONTROLLER (PDIC) (P/N: 968.29.13.223), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	16-SEP-1996	MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 30-003	REPLACE THE AOA PLATE (TEMPERATURE) CONTROLLER (P/N: 975.44.21.417), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	16-SEP-1996	MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 30-004	INSTALLATION OF THE NEW PROPELLER DE-ICING TIMER UNIT AND BRUSH PACK, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
	18-SEP-1998	MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 30-005	MODIFICATION OF THE WINDSHIELD WIRES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	24-JUN-1999	MOS HRS/MSC - AFL		29-NOV-2011			
SB 30-006	MODIFICATION OF WINDSHIELD WIRES AND CIRCUIT BREAKERS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	22-MAY-2000	MOS HRS/MSC - AFL		29-NOV-2011			
SB 30-007 R03	ICE AND RAIN PROTECTION - WINDSHIELD REPLACEMENT OF THE OLD TYPE WINDSHIELDS WITH THE NEW TYPE WINDSHIELDS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
	04-MAR-2010	MOS HRS/MSC - AFL		29-NOV-2011			
SB 30-008	POSSIBLE WRONG PITOT/STATIC/AOA CURRENT SENSORS INSTALLED, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	21-AUG-2003	MOS HRS/MSC - AFL		29-NOV-2011			
SB 30-009	WINDSHIELD DEICE SYSTEM WIRING-INSPECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	25-JAN-2005	MOS HRS/MSC - AFL		29-NOV-2011			
SB 30-010	ICE AND RAIN PROTECTION - PROPELLER DEICE SYSTEM MODIFICATION TO THE OUTSIDE AIR TEMPERATURE (OAT) SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS HRS/MSC - AFL		29-NOV-2011			
SB 30-011	ICE AND RAIN PROTECTION - AIRFOIL DEICE SYSTEM INSTALLATION OF AN OVERBOARD VENT FOR THE PRESSURE REGULATOR, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	09-JUL-2008	MOS HRS/MSC - (s) AFL		29-NOV-2011			
SB 30-012	ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - PARTIALLY C/W - SUPERSEDED BY SB 30-012 R1
	29-MAY-2017	MOS HRS/MSC - AFL					
SB 30-012 PART A	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - LH WING INBOARD DE-ICE BOOT					OPTIONAL	COMPLIED WITH - REFER TO WO JFS-002-18 2018-01-29
	29-MAY-2017	MOS HRS/MSC - AFL		29-JAN-2018 3254.67 2785			
SB 30-012 PART B	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - LH WING OUTBOARD DE-ICE BOOT					OPTIONAL	NOT APPLICABLE - SUPERSEDED BY SB 30-012 R1
	29-MAY-2017	MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 30-012 PART C	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - RH WING INBOARD DE-ICE BOOT					OPTIONAL	COMPLIED WITH - REFER TO WO JFS-005-22 2022-04-27 - W&B AMENDED
29-MAY-2017		MOS HRS/MSC - AFL		27-MAY-2022 5922.17 5164			
SB 30-012 PART D	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - RH WING OUTBOARD DE-ICE BOOT					OPTIONAL	NOT APPLICABLE - SUPERSEDED BY SB 30-012 R1
29-MAY-2017		MOS HRS/MSC - AFL					
SB 30-012 PART E	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - LH HORIZONTAL STABILIZER DE-ICE BOOT					OPTIONAL	COMPLIED WITH - SEE WORK ORDER JFS-011-18 R1 AND SEE WORK REPORT JG AVIATION FS020518
29-MAY-2017		MOS HRS/MSC - AFL		16-MAY-2018 3443.17 2934			
SB 30-012 PART F	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - RH HORIZONTAL STABILIZER DE-ICE BOOT					OPTIONAL	COMPLIED WITH - REFER TO WO JFS-007-19 R1 2019-07-04 - RH HORIZ STAB REPLACED IAW 12-B-30-16-01-00A-920A-A
29-MAY-2017		MOS HRS/MSC - AFL		04-JUL-2019 4174.5 3567			
SB 30-012 R01	ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN					OPTIONAL	- TO BE PERFORMED AT NEXT EXCHANGE BOOTS
26-OCT-2017		MOS HRS/MSC - AFL		(EFF)			
SB 30-012 R01 PART A	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - LH WING INBOARD DE-ICE BOOT					OPTIONAL	COMPLIED WITH - PCW - REFER TO WO JFS-002-18 2018-01-29
26-OCT-2017		MOS HRS/MSC - AFL		29-JAN-2018 3254.67 2785			
SB 30-012 R01 PART B	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - LH WING OUTBOARD DE-ICE BOOT					OPTIONAL	- TO BE PERFORMED AT NEXT EXCHANGE BOOT
26-OCT-2017		MOS HRS/MSC - AFL		(EFF)			
SB 30-012 R01 PART C	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - RH WING INBOARD DE-ICE BOOT					OPTIONAL	COMPLIED WITH - PCW - SEE WO JFS-005-22 AND SEE WR BASL 012477/22
26-OCT-2017		MOS HRS/MSC - AFL		27-JUL-2022			
SB 30-012 R01 PART D	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - RH WING OUTBOARD DE-ICE BOOT					OPTIONAL	- TO BE PERFORMED AT NEXT EXCHANGE BOOT
26-OCT-2017		MOS HRS/MSC - AFL		(EFF)			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 30-012 R01 PART E	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - LH HORIZONTAL STABILIZER DE-ICE BOOT					OPTIONAL	COMPLIED WITH - PCW - SEE WO JFS-011-18 R1 AND SEE WORK REPORT JG AVIATION FS020518
26-OCT-2017		MOS HRS/MSC - AFL		16-MAY-2018 3443.17 2934			
SB 30-012 R01 PART F	ACCOMPLISH ICE AND RAIN PROTECTION -AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF INCREASED THICKNESS DE-ICE BOOTS, SERVICE BULLETIN MODIFICATION - RH HORIZONTAL STABILIZER DE-ICE BOOT					OPTIONAL	COMPLIED WITH - PCW - REFER TO WO JFS-007-19 R1 2019-07-04 - RH HORIZ STAB DE-ICE BOOT IAW 12-B-30-16-01-00A-920A-A
26-OCT-2017		MOS HRS/MSC - AFL		04-JUL-2019			
SB 30-013 R01	ICE AND RAIN PROTECTION - AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF A WIRING MODIFICATION TO SUPPORT REPLACEMENT OF A NEW AIRFOIL DE-ICE SYSTEM DWELL TIMER WITH INHIBIT FUNCTION, SERVICE BULLETIN					OPTIONAL	- SUPERSEDED BY SB 30-013 R2
05-MAR-2018		MOS HRS/MSC - AFL		18-OCT-2018 3800.33 3208			
SB 30-013 R02	ICE AND RAIN PROTECTION - AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF A WIRING MODIFICATION TO SUPPORT REPLACEMENT OF A NEW AIRFOIL DE-ICE SYSTEM DWELL TIMER WITH INHIBIT FUNCTION, SERVICE BULLETIN					OPTIONAL	- TO BE APPLIED IN CASE OF FAILURE OR REPLACEMENT OF AIRFOIL DE-ICE TIMER
09-NOV-2020		MOS HRS/MSC - AFL		(EFF)			
SB 30-014 R01	ICE AND RAIN PROTECTION - AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF A WIRING MODIFICATION TO SUPPORT - REPLACEMENT OF A NEW AIRFOIL DE-ICE SYSTEM TIMER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: ACFT MSN
06-SEP-2018		MOS HRS/MSC - AFL ACH FLTS					
SB 30-014 R02	ICE AND RAIN PROTECTION - AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF A WIRING MODIFICATION TO SUPPORT REPLACEMENT OF A NEW AIRFOIL DE-ICE SYSTEM TIMER, SERVICE BULLETIN					OPTIONAL	- AT NEXT TIMER EXCHANGE
30-NOV-2018		MOS HRS/MSC - AFL ACH FLTS					
SB 30-014 R03	ICE AND RAIN PROTECTION - AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF A WIRING MODIFICATION TO SUPPORT REPLACEMENT OF A NEW AIRFOIL DE-ICE SYSTEM TIMER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY ACFT MSN
03-AUG-2021		MOS HRS/MSC - AFL ACH FLTS					
SB 30-015	ICE AND RAIN PROTECTION - AIRFOIL DE-ICE SYSTEM - INTRODUCTION OF A WIRING MODIFICATION TO SUPPORT REPLACEMENT OF A NEW AIRFOIL DE-ICE SYSTEM TIMER, SERVICE BULLETIN					OPTIONAL	- THIS SB WILL BE EMBODIED DURING NEXT TROUBLE DE-ICE TIMER
09-MAR-2018		MOS HRS/MSC - AFL		18-OCT-2018 3800.33 3208			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 30-016	ICE AND RAIN PROTECTION - AIRFOIL - RELOCATION OF AIRFOIL DE-ICE BOOTS PRESSURE SWITCHES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - C/W DURING JFS-007-21
26-JUL-2019		MOS HRS/MSC - AFL		23-JUL-2021 5312.33 4590			
SB 31-002	INTRODUCTION OF A NEW GLARESHIELD, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
12-OCT-2000		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-003	REPLACEMENT OF SWITCH CAPS ON THE OVERHEAD PANEL, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
27-SEP-2002		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-004 REV A	MODIFICATION TO THE CAWS, SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
05-FEB-2003		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-005	REPLACEMENT OF THE CAWS CACU, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
10-FEB-2003		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-006	REMOVAL OF THE JUMPER WIRE FROM CONNECTOR J992, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
27-JUN-2005		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-007 R01	INDICATING/RECORDING SYSTEMS CENTRAL ADVISORY AND WARNING SYSTEM (CAWS) - CHANGE TO THE CAWS DISPLAY WIRING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
06-AUG-2009		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-008	INDICATING / RECORDING SYSTEMS - INSTRUMENT AND CONTROL PANELS MODIFICATION TO THE SYSTEMS THAT ARE CONTROLLED BY THE OVER HEAD PANEL, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
22-SEP-2009		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-008 R01	INDICATING / RECORDING SYSTEMS - INSTRUMENT AND CONTROL PANELS MODIFICATION TO THE SYSTEMS THAT ARE CONTROLLED BY THE OVER HEAD PANEL, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
18-JAN-2010		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-008 R02	INDICATING / RECORDING SYSTEMS - INSTRUMENT AND CONTROL PANELS MODIFICATION TO THE SYSTEMS THAT ARE CONTROLLED BY THE OVER HEAD PANEL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
26-MAR-2010		MOS HRS/MSC - AFL		29-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 31-008 R03	INDICATING / RECORDING SYSTEMS - INSTRUMENT AND CONTROL PANELS - MODIFICATION TO THE SYSTEMS THAT ARE CONTROLLED BY THE OVER HEAD PANEL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
13-MAY-2011		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 31-008 R04	INDICATING / RECORDING SYSTEMS - INSTRUMENT AND CONTROL PANELS MODIFICATION TO THE SYSTEMS THAT ARE CONTROLLED BY THE OVERHEAD PANEL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
03-OCT-2012		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 31-009	INDICATING / RECORDING SYSTEMS - INSTRUMENT AND CONTROL PANELS MODIFICATION OF THE OVERHEAD CONTROL PANEL PUSH BUTTON SWITCHES, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
26-NOV-2010		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 31-010	INDICATING AND RECORDING SYSTEMS - CENTRAL DISPLAY SYSTEMS INTRODUCTION OF AN APEX VIDEO INPUT SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - SUPERSEDED
18-JAN-2011		MOS		13-MAY-2014			
		HRS/MSC -		1028.67			
		AFL		824			
SB 31-010 R01	INDICATING AND RECORDING SYSTEMS - CENTRAL DISPLAY SYSTEMS INTRODUCTION OF AN APEX VIDEO INPUT SYSTEM, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
09-MAR-2011		MOS		26-JUN-2015			
		HRS/MSC -					
		AFL					
SB 31-011	INDICATING AND RECORDING SYSTEMS - CENTRAL COMPUTERS INTRODUCTION OF ADVANCED GRAPHICS MODULE P/N 985.99.12.222, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
22-DEC-2010		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 31-012	INDICATING AND RECORDING SYSTEMS - RECORDERS - INTRODUCTION OF A COCKPIT VOICE AND FLIGHT DATA RECORDER, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED BY 31-012 R1
18-JAN-2011		MOS		15-MAY-2014			
		HRS/MSC -		1034.25			
		AFL		834			
SB 31-012 R01	INDICATING AND RECORDING SYSTEMS - RECORDERS - INTRODUCTION OF A COCKPIT VOICE AND FLIGHT DATA RECORDER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
23-FEB-2011		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 31-012 R02	INDICATING AND RECORDING SYSTEMS - RECORDERS INTRODUCTION OF A COCKPIT VOICE AND FLIGHT DATA RECORDER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - DUE TO SERIAL NUMBER
04-JUL-2012		MOS		15-MAY-2014			
		HRS/MSC -		1034.25			
		AFL		834			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 31-012 R03	INDICATING AND RECORDING SYSTEMS - RECORDERS INTRODUCTION OF A COCKPIT VOICE AND FLIGHT DATA RECORDER, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
14-APR-2014		MOS HRS/MSC - AFL		02-SEP-2015			
SB 31-012 R03 PART A	INSTALL INDICATING AND RECORDING SYSTEMS - RECORDERS INTRODUCTION OF A COCKPIT VOICE AND FLIGHT DATA RECORDER, SERVICE BULLETIN THE CVFDR AND DO THE WIRING MODIFICATION					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
14-APR-2014		MOS HRS/MSC - AFL		02-SEP-2015			
SB 31-012 R03 PART B	WIRING INDICATING AND RECORDING SYSTEMS - RECORDERS INTRODUCTION OF A COCKPIT VOICE AND FLIGHT DATA RECORDER, SERVICE BULLETIN MODIFICATION WHEN A CVFDR IS ALREADY INSTALLED					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
14-APR-2014		MOS HRS/MSC - AFL		02-SEP-2015			
SB 31-012 R04	INDICATING AND RECORDING SYSTEMS - RECORDERS - INTRODUCTION OF A LIGHTWEIGHT DATA RECORDER (LDR), SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
04-MAR-2016		MOS HRS/MSC - AFL					
SB 31-012 R04 PART A	ACCOMPLISH INDICATING AND RECORDING SYSTEMS - RECORDERS - INTRODUCTION OF A LIGHTWEIGHT DATA RECORDER (LDR), SERVICE BULLETIN INSTALL THE CVFDR AND DO THE WIRING MODIFICATION					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
04-MAR-2016		MOS HRS/MSC - AFL					
SB 31-012 R04 PART B	ACCOMPLISH INDICATING AND RECORDING SYSTEMS - RECORDERS - INTRODUCTION OF A LIGHTWEIGHT DATA RECORDER (LDR), SERVICE BULLETIN WIRING MODIFICATION WHEN A CVFDR IS ALREADY INSTALLED					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
04-MAR-2016		MOS HRS/MSC - AFL					
SB 31-013	INDICATING / RECORDING SYSTEMS - INSTRUMENT AND CONTROL PANELS REPLACEMENT OF THE OVERHEAD CONTROL PANEL BUS-TIE CIRCUIT BREAKER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
15-SEP-2011		MOS HRS/MSC - AFL		29-NOV-2011			
SB 31-014	INDICATING / RECORDING SYSTEMS - INSTRUMENT AND CONTROL PANELS BATTERY REPLACEMENT THOMMEN CHRONOGRAPH Q15-948.22.05.1.AA, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY PART NUMBER
09-DEC-2011		MOS HRS/MSC - AFL		20-FEB-2012			
SB 31-015	INDICATING / RECORDING SYSTEMS - INDEPENDENT INSTRUMENTS WIRING CHANGE TO CLOCK POWER SUPPLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
09-DEC-2011		MOS HRS/MSC - AFL		23-APR-2012 5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 31-015 R01	INDICATING / RECORDING SYSTEMS - INDEPENDENT INSTRUMENTS WIRING CHANGE TO CLOCK POWER SUPPLY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-JAN-2012		MOS HRS/MSC - AFL		23-APR-2012 5 5			
SB 31-015 R02	INDICATING / RECORDING SYSTEMS - INDEPENDENT INSTRUMENTS WIRING CHANGE TO CLOCK POWER SUPPLY, SERVICE BULLETIN					RECOMMENDED	DECLINED - BY EXECUTIVE MANAGER DECISION
08-MAR-2012		MOS HRS/MSC - AFL		26-JUN-2015			
SB 31-016	INDICATING / RECORDING SYSTEMS - INDEPENDENT INSTRUMENTS REPLACE THOMMEN DIGITAL CLOCK WITH DAVTRON DIGITAL CLOCK, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY CLOCK INSTALLED
08-MAR-2012		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 31-018	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - INSTALLATION OF NEW MODULAR AVIONICS UNIT GIO AND CSIO MODULES IN CONJUNCTION WITH SB 46-004, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - INSTALLATION OF NEW GIO AND CSIO
09-AUG-2013		MOS HRS/MSC - AFL		18-DEC-2014 1340.08 1076			
SB 31-019	INDICATING / RECORDING SYSTEMS - OVERHEAD CONTROL PANEL - REPLACEMENT OF THE MASTER POWER SWITCH GUARD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN
02-NOV-2016		MOS HRS/MSC - AFL		07-MAR-2017			
SB 31-020 R01	INDICATING AND RECORDING - PROVISION FOR A MICRO QUICK-ACCESS RECORDER IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
30-MAY-2018		MOS HRS/MSC - AFL		(EFF)			
SB 31-020 R02	INDICATING AND RECORDING - PROVISION FOR A MICRO QUICK-ACCESS RECORDER IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN					OPTIONAL	- IN REVIEW WAITING FOR FINAL DECISION
29-SEP-2021		MOS HRS/MSC - AFL ACH FLTS		(EFF)			
SB 31-021	INDICATING AND RECORDING - INSTALLATION OF A MICRO QUICK-ACCESS RECORDER IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
18-MAY-2018		MOS HRS/MSC - AFL		(EFF)			
SB 31-021 R01	INDICATING AND RECORDING - INSTALLATION OF A MICRO QUICK-ACCESS RECORDER IN THE FLIGHT COMPARTMENT, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
14-JAN-2022		MOS HRS/MSC - AFL		17-MAY-2022			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 31-022	INDICATING AND RECORDING - LIGHTWEIGHT DATA RECORDER - REPLACEMENT OF THE COCKPIT AREA MICROPHONE, SERVICE BULLETIN			(EFF)		OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
21-JUN-2021		MOS HRS/MSC - AFL					
SB 31-023	INDICATING AND RECORDING - RECORDING SYSTEMS - INSTALLATION OF A MICRO QUICK-ACCESS RECORDER IN THE FLIGHT DEPARTMENT, SERVICE BULLETIN				31-MAY-2023	OPTIONAL	NOT APPLICABLE - BY SERIAL: BY A/C VARIANT - PC-12/47E 2001 AND UP WHICH HAVE AN LDR INSTALLED BY FACTORY OPTION
29-SEP-2022		MOS HRS/MSC - AFL					
SB 31-024	INDICATING AND RECORDING - INDICATING SYSTEMS - REPLACEMENT OF THE FLIGHT TIME COUNTER, SERVICE BULLETIN					OPTIONAL	- SUPERSEDED BY R01
09-MAY-2022		MOS HRS/MSC - AFL					
SB 31-024 R01	INDICATING AND RECORDING - INDICATING SYSTEMS - REPLACEMENT OF THE FLIGHT TIME COUNTER, SERVICE BULLETIN			(EFF)		OPTIONAL	- SUPERSEDED BY R02
15-FEB-2023		MOS HRS/MSC - AFL					
SB 31-024 R02	INDICATING AND RECORDING - INDICATING SYSTEMS - REPLACEMENT OF THE FLIGHT TIME COUNTER, SERVICE BULLETIN			(EFF)		OPTIONAL	- APPLICABLE. TO BE PERFORMED WHEN THE A/C HAS A FLIGHT TIME COUNTER FAILURE
16-FEB-2024		MOS HRS/MSC - AFL					
SB 32-001	NOSE LANDING GEAR - CRACK INSPECTION OF THE FORGED MAIN FITTING, SERVICE BULLETIN				29-NOV-2011	MANDATORY	NOT APPLICABLE - BY MSN AIRCRAFT
15-DEC-1994		MOS HRS/MSC - AFL					
SB 32-002 R01	REPLACEMENT OF BRAKE UNIT, SERVICE BULLETIN				29-NOV-2011	RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
05-JAN-1996		MOS HRS/MSC - AFL					
SB 32-003 R01	INSTALLATION OF A SPACER RING ON THE MLG REAR TRUNNION, SERVICE BULLETIN				29-NOV-2011	MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
29-SEP-1997		MOS HRS/MSC - AFL					
SB 32-004	REPLACE BRAKE PEDAL LEVERS AND ADJUST THE MECHANISM, SERVICE BULLETIN				29-NOV-2011	RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
18-MAR-1998		MOS HRS/MSC - AFL					
SB 32-005	MODIFICATION OF MLG AXLE (SUPERSEDED BY 32-006), SERVICE BULLETIN				31-JAN-2012		NOT APPLICABLE - SUPERSEDED
07-OCT-1998		MOS HRS/MSC - AFL		5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 32-006	REPLACEMENT OF MLG AXLE (SUPERSEDED BY SB 32-009 R2), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
18-DEC-1998		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-007	INSTALLATION OF STATIC DISCHARGERS ON THE MAIN LANDING GEARS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
27-AUG-1999		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-008	MODIFICATION TO THE SEALS AND BARREL NUT OF THE NOSE LANDING GEAR, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
14-SEP-1999		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-009	REPLACEMENT OF MLG AXLE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
12-OCT-2000		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 32-009 R01	LANDING GEAR - MAIN LANDING GEAR - AXLE - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
21-DEC-2006		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-009 R02	LANDING GEAR - MAIN LANDING GEAR - AXLE REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
02-SEP-2015		MOS HRS/MSC - AFL		09-OCT-2015			
SB 32-010	MODIFICATION OF NLG MAIN FITTING, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
27-SEP-2000		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-011	INSTALLATION OF NEW NUT ON MLG SHOCK ABSORBER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN AIRCRAFT
13-NOV-2000		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-012	REPLACEMENT OF MLG SPECIAL BOLT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
18-OCT-2001		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-013	REPLACEMENT BRAKE UNITS WITH STEEL HEAT SINKS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
26-MAR-2002		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-014 R01	REPLACEMENT OF NLG RIGHT DRAG LINK, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
24-APR-2003		MOS HRS/MSC - AFL		31-JAN-2012 5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 32-014 R02	LANDING GEAR - NOSE LANDING GEAR (NLG) - REPLACEMENT OF DRAG LINK RIGHT-HAND, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
15-DEC-2009		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 32-014 R03	LANDING GEAR - NOSE LANDING GEAR (NLG) - REPLACEMENT OF DRAG LINK RIGHT-HAND, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
16-JUN-2010		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-014 R04	LANDING GEAR - NOSE LANDING GEAR (NLG) - REPLACEMENT OF DRAG LINK RIGHT-HAND, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY
24-NOV-2017		MOS HRS/MSC - AFL		12-DEC-2017			
SB 32-014 R04 PART A	ACCOMPLISH LANDING GEAR - NOSE LANDING GEAR (NLG) - REPLACEMENT OF DRAG LINK RIGHT-HAND, SERVICE BULLETIN REPLACE THE DRAG LINK RH (PART NO. 532.20.12.140) WITH A NEW ITEM (PART NO. 532.20.12.296)					OPTIONAL	NOT APPLICABLE
24-NOV-2017		MOS HRS/MSC - AFL		12-DEC-2017			
SB 32-014 R04 PART B	ACCOMPLISH LANDING GEAR - NOSE LANDING GEAR (NLG) - REPLACEMENT OF DRAG LINK RIGHT-HAND, SERVICE BULLETIN MODIFY THE DRAG LINK ASSEMBLY PART NUMBER 532.20.12.297					OPTIONAL	NOT APPLICABLE
24-NOV-2017		MOS HRS/MSC - AFL		12-DEC-2017			
SB 32-015	INSPECTION OF MLG SHOCK ABSORBER BOLTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
12-SEP-2003		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-016	INSPECTION AND REPLACEMENT OF COMPONENTS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
11-MAR-2004		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-017	MLG-ACTUATOR-REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
03-AUG-2004		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-018	INSPECTION AND REPLACEMENT SPECIAL BOLT ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
02-MAY-2005		MOS HRS/MSC - (s) AFL		29-NOV-2011			
SB 32-020	LANDING GEAR-MAIN LANDING GEAR SPECIAL BOLTS-INSPECTION AND REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
24-JUL-2007		MOS HRS/MSC - (s) AFL		31-JAN-2012 5 5			
SB 32-020 R01	LANDING GEAR - MAIN LANDING GEAR SPECIAL BOLTS - INSPECTION AND REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
22-NOV-2007		MOS HRS/MSC - (s) AFL		29-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 32-021	LANDING GEAR - NOSE WHEEL STEERING REPLACEMENT OF THE CRANK BAR ASSY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
21-NOV-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-022	LANDING GEAR - BRAKE SYSTEM - MODIFICATION TO REPLACE THE STAINLESS STEEL BRAKE LINES AND SWIVEL JOINTS WITH FLEXIBLE PRESSURE HOSES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
17-NOV-2009		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-022 R01	LANDING GEAR - BRAKE SYSTEM - MODIFICATION TO REPLACE THE STAINLESS STEEL BRAKE LINES AND SWIVEL JOINTS WITH FLEXIBLE PRESSURE HOSES, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - NOT CONCERNED BY MSN AIRCRAFT
21-JAN-2015		MOS HRS/MSC - AFL		09-FEB-2015			
SB 32-023	LANDING GEAR - NOSE WHEEL STEERING - STEERING ROD RETENTION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-DEC-2009		MOS HRS/MSC - AFL		29-NOV-2011			
SB 32-024	LANDING GEAR - EXTENSION AND RETRACTION - IMPROVEMENTS TO THE EMERGENCY GEAR EXTENSION SYSTEM (MSN 1300 ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
03-DEC-2012		MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 32-025	LANDING GEAR - EXTENSION AND RETRACTION - INTRODUCTION OF IMPROVED LANDING GEAR ACTUATORS (MSN 1300 ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
08-NOV-2013		MOS HRS/MSC - AFL		29-NOV-2011 0 0			
SB 32-026	LANDING GEAR - NOSE GEAR AND DOORS - INSPECTION OF SPRING PACK ASSEMBLY PART NUMBER 532.20.12.249, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - By Serial:
24-NOV-2017		MOS HRS/MSC - AFL ACH FLTS					
SB 32-026 R01	LANDING GEAR - NOSE GEAR AND DOORS - INSPECTION OF SPRING PACK ASSEMBLY PART NUMBER 532.20.12.249, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - N/A BY PART S/N
19-FEB-2018		MOS HRS/MSC - AFL ACH FLTS					
SB 32-027	LANDING GEAR - MAIN GEAR AND DOORS - REPLACEMENT OF SPRING PACK ASSEMBLIES, PART NUMBER 532.34.12.101, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - By Effectivity: BY ACFT MSN
07-JAN-2019		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 32-028	LANDING GEAR - EXTENSION AND RETRACTION - REPLACE EMERGENCY GEAR EXTENSION PLACARD P/N 511.32.12.524 WITH PLACARD P/N 511.32.12.531, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: ACFT MSN
12-DEC-2019		MOS HRS/MSC - AFL ACH FLTS					
SB 32-029	LANDING GEAR - NOSE LANDING GEAR - FORK ASSEMBLY - INSPECTION AND REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY NLG STRUT ASSY P/N AND S/N
08-FEB-2021		MOS HRS/MSC - AFL		26-FEB-2021			
SB 32-029 R01	LANDING GEAR - NOSE LANDING GEAR - FORK ASSEMBLY - INSPECTION, REPAIR AND REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - By Part: BY NLG STRUT ASSY P/N AND S/N
06-AUG-2021		MOS HRS/MSC AFL ACH FLTS					
SB 32-030	LANDING GEAR - EXTENSION AND RETRACTION ELECTRO-MECHANICAL ACTUATOR CORROSION PROTECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - By Effectivity- PC-12/47E aircraft MSN 1300 and 1451 thru 1663
27-JUN-2022		MOS HRS/MSC AFL ACH FLTS		29-JUN-2022			
SB 32-030 R01	LANDING GEAR - EXTENSION AND RETRACTION ELECTRO-MECHANICAL ACTUATOR CORROSION PROTECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL: PC-12/47E AIRCRAFT MSN 1300 AND 1451 THRU 1663
12-SEP-2022		MOS HRS/MSC - AFL		15-SEP-2022			
SB 32-030 R02	LANDING GEAR - EXTENSION AND RETRACTION - ELECTRO-MECHANICAL ACTUATOR CORROSION PROTECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY SERIAL: BY A/C MSN (NOT FITTED W/ ELDG, THESE ACTUATORS ARE NOT FITTED)
07-OCT-2022		MOS HRS/MSC - AFL		20-OCT-2022			
SB 33-001	INSTALLATION OF OPTIONAL RECOGNITION LIGHTS, SERVICE BULLETIN						NOT APPLICABLE
16-FEB-1999		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 33-001 R01	INSTALLATION OF OPTIONAL RECOGNITION LIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 33-001 R02	LIGHTS - EXTERIOR RECOGNITION LIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
30-JUN-2008		MOS HRS/MSC - AFL		31-JAN-2012 5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 33-001 R03	LIGHTS - EXTERIOR RECOGNITION LIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
16-FEB-2009		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-002	INSTALLATION OF OPTIONAL RED ANTI-COLLISION BEACONS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
15-JAN-1999		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 33-002 R01	LIGHTS - EXTERIOR - RED ANTI-COLLISION BEACONS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
30-JUN-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-003	INSTALLATION OF OPTIONAL LOGO LIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
25-NOV-1999		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 33-003 R01	LIGHTS - EXTERIOR INSTALLATION OF LOGO LIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
30-JUN-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-004	REPLACEMENT OF THE DIMMER UNIT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
10-MAY-1999		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-005	INSTALLATION OF NEW ANTI-COLLISION LIGHTS AND POWER SUPPLY UNITS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
02-FEB-2001		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-006 R01	INSTALLATION OF A NEW DIODE IN THE CABIN FLOOD LIGHTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
14-FEB-2003		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-007	INSTALLATION OF AN OPTIONAL BAGGAGE COMPARTMENT LIGHT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
12-AUG-2002		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-008	DIODE REMOVAL AND WIRING ROUTING CHANGE TO CABIN FLOOD LIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
28-NOV-2002		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-009	OPTIONAL DUAL FILAMENT NAVIGATION LIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
17-APR-2003		MOS HRS/MSC - AFL		29-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 33-010	LIGHTS - EXTERIOR MODIFICATION TO THE LED NAVIGATION LIGHTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
08-SEP-2006		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 33-010 R01	LIGHTS - EXTERIOR - MODIFICATION TO THE LED NAVIGATION LIGHTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
20-DEC-2006		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-011	LIGHTS - INTERIOR LIGHTS - REPLACE INCANDESCENT CABIN SIGNS WITH LED CABIN SIGNS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
15-JUL-2011		MOS HRS/MSC - AFL		29-NOV-2011			
SB 33-011 R01	LIGHTS - INTERIOR LIGHTS - REPLACE INCANDESCENT CABIN SIGNS WITH LED CABIN SIGNS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
28-MAR-2012		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 33-011 R02	LIGHTS - INTERIOR LIGHTS - REPLACE INCANDESCENT CABIN SIGNS WITH LED CABIN SIGNS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY AIRCRAFT SERIAL NUMBER
26-OCT-2021		MOS HRS/MSC - AFL ACH FLTS					
SB 33-012	EXTERNAL LIGHTS - REPLACE INCANDESCENT LANDING AND TAXI LIGHTS WITH LED LIGHTS (SUPERSEDED BY 33-012 R1), SERVICE BULLETIN					OPTIONAL	- SUPERSEDED BY SB 33-012 REV 1
10-APR-2014		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 33-012 R01	LIGHTS - EXTERNAL LIGHTS - REPLACE INCANDESCENT LANDING AND TAXI LIGHTS WITH LED LIGHTS (SUPERSEDED BY 33-012 R2), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SB PERFORMED IAW 33-012R1
14-AUG-2014		MOS HRS/MSC - AFL		24-OCT-2014 1296.17 1035			
SB 33-012 R02	LIGHTS - EXTERNAL LIGHTS - REPLACE INCANDESCENT LANDING AND TAXI LIGHTS WITH LED LIGHTS (SUPERSEDED BY 33-012 R03), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - R1 PERFORMED NO FURTHER WORK IS REQUIRED IF THE SB HAS BEEN INCORPORATED AT AN EARLIER REVISIO
26-MAY-2015		MOS HRS/MSC - AFL		09-NOV-2015 1878.67 1533			
SB 33-012 R03	LIGHTS - EXTERNAL LIGHTS - REPLACE INCANDESCENT LANDING AND TAXI LIGHTS WITH LED LIGHTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - already performed see r1
02-JUN-2017		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 33-013	LIGHTS - EXTERNAL LIGHTS - REPLACE INCANDESCENT LANDING AND TAXI LIGHTS WITH LED LIGHTS (MSN 1300 ONLY), SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
SB 33-015	LIGHTS - EXTERNAL LIGHTS - MOISTURE INGRESS TO LED LANDING AND TAXI LIGHTS, SERVICE BULLETIN					RECOMMENDED	DEFERRED - SEE FORM 19 - SB 33-015 REV 0
		MOS		24-JUN-2016			
		HRS/MSC -					
		AFL					
SB 33-016	LIGHTS - CABIN FLOOD LIGHTS - INTRODUCTION OF REDUCED INTENSITY CABIN FLOOD LIGHTS, SERVICE BULLETIN					OPTIONAL	DEFERRED - SEE FORM 19 - SB 33-016 REV 0
		MOS		25-DEC-2015			
		HRS/MSC - (s)					
		AFL					
SB 33-016 R01	LIGHTS - CABIN FLOOD LIGHTS - INTRODUCTION OF REDUCED INTENSITY CABIN FLOOD LIGHTS, SERVICE BULLETIN					OPTIONAL	DEFERRED - SEE FORM 19 - SB 33-016 REV 1
		MOS		24-JUN-2016			
		HRS/MSC -					
		AFL					
SB 33-017	LIGHTS - EXTERNAL LIGHTS - INTRODUCTION OF STROBE LIGHTS POWER FROM THE MAIN BUS, SERVICE BULLETIN					OPTIONAL	DEFERRED - SEE FORM 19 - SB 33-017 REV 0
		MOS		10-OCT-2016			
		HRS/MSC -					
		AFL					
SB 33-018	LIGHTS - FLIGHT COMPARTMENT - INTRODUCTION OF MAP LIGHTS POWERED FROM THE STANDBY BUS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SEE ANALYSIS FORM 19
		MOS		07-MAR-2017			
		HRS/MSC -					
		AFL					
SB 33-019	LIGHTS - PASSENGER COMPARTMENT - REPLACE THE TABLE/READING LIGHT SWITCH, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY SERIAL: APPLICABLE TO MSN 101 THRU 544, 546 THRU 888
		MOS		23-JAN-2023			
		HRS/MSC - (s)					
		AFL					
SB 34-002	INSTALLATION OF A SECOND AHRS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 34-002 R02	NAVIGATION - ATTITUDE AND DIRECTION - INSTALLATION OF A SECOND ATTITUDE AND HEADING REFERENCE SYSTEM (AHRS 2), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY A/C MSN
		MOS		13-MAR-2024			
		HRS/MSC -					
		AFL					
SB 34-003	MODIFICATION OF LITEF LCR-92 AHRS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-003 R01	MODIFICATION ON LITEF LCR-92 AHRS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
08-SEP-2008		HRS/MSC -					
		AFL					
SB 34-004	INSTALLTION OF A YAW RATE GYRO, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		31-JAN-2012			
01-APR-1997		HRS/MSC -		5			
		AFL		5			
SB 34-004 R01	INSTALLATION OF THE YAW RATE GYRO (KRG 332), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
08-SEP-2008		HRS/MSC -					
		AFL					
SB 34-005	INSTALLATION OF A RADAR ALTIMETER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		31-JAN-2012			
03-JUN-1997		HRS/MSC -		5			
		AFL		5			
SB 34-005 R01	INSTALLATION OF THE RADAR ALTIMETER (KRA 405), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
08-SEP-2008		HRS/MSC -					
		AFL					
SB 34-006	INTRODUCTION OF NEW STANDBY COMPASS SWING PROCEDURE, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
03-SEP-1998		HRS/MSC -					
		AFL					
SB 34-007	REPLACEMENT OF PITOT HEAD ELECTRICAL CABLES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
28-MAR-2000		HRS/MSC -					
		AFL					
SB 34-009	DEPENDANT POSITION DETERMINING-MODE S TRANSPONDER-INSTALLATION, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
19-JAN-2005		HRS/MSC -		5			
		AFL		5			
SB 34-009 R01	NAVIGATION - DEPENDENT POSITION DETERMINING MODE S TRANSPONDER GTX330D - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC - (s)		5			
		AFL		5			
SB 34-009 R02	NAVIGATION - DEPENDENT POSITION DETERMINING MODE S TRANSPONDER GTX330D - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		31-JAN-2012			
18-JUN-2007		HRS/MSC -		5			
		AFL		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-009 R03	NAVIGATION- DEPENDENT POSITION DETERMINING MODE S TRANSPONDER GTX330D - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
30-JUN-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-010	DEPENDANT POSITION DETERMINING-DUAL MODE S TRANSPONDER CTX330D-INSTALLATION, SERVICE BULLETIN						NOT APPLICABLE - BY MSN EFFECTIVITY
21-JUL-2004		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-011	DEPENDANT POSITION DETERMINING-DUAL MODE S TRANSPONDER-INSTALLATION, SERVICE BULLETIN						NOT APPLICABLE
19-APR-2005		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 34-011 R01	DEPENDANT POSITION DETERMINING DUAL MODE S TRANSPONDER-INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
07-JUL-2005		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 34-011 R02	NAVIGATION - DEPENDANT POSITION DETERMINING DUAL MODE S TRANSPONDER GTX330D - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 34-011 R03	NAVIGATION - DEPENDANT POSITION DETERMINING DUAL MODE S TRANSPONDER GTX330D - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
30-JUN-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-012	DEPENDANT POSITION DETERMINING-DUAL MODE S TRANSPONDER-INSTALLATION SERVICE BULLETIN, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
18-NOV-2004		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-013	NAVIGATION - AIRSPEED INDICATOR OVERSPEED WARNING - PREVENTION DURING ENGINE START, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
13-OCT-2006		MOS HRS/MSC - (s) AFL		29-NOV-2011			
SB 34-014	NAVIGATION - WEATHER RADAR REMOVE THE CONNECTION BETWEEN THE WEATHER RADAR AND THE WEIGHT-ON-WHEELS (WOW) SWITCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE -
05-DEC-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-015	NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) UNIT, SERVICE BULLETIN					OPTIONAL	DECLINED - SB SUPERSEDED BY SB 34-018 REV 0
13-NOV-2008		MOS HRS/MSC - AFL		29-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-016	NAVIGATION - INDEPENDENT POSITION DETERMINING EGPWS - REMOVE THE AUTOPILOT ENGAGED SIGNAL FROM THE EGPWS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
16-DEC-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-017	NAVIGATION - GLOBAL POSITIONING SYSTEM (GPS) MOOIFICATION TO THE GPS WIRING, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
15-DEC-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-018	NAVIGATION-ATTITUDE AND DIRECTION UPGRADE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) TO .192 STANDARD, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE -
09-JAN-2009		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-019	NAVIGATION - ATTITUDE AND DIRECTION - INSTALLATION AND REMOVAL OF A PLATE ON THE ADAHRS SHELF, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
04-MAR-2009		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-020	NAVIGATION - DEPENDENT POSITIONING DETERMINING - INSTALL A GPS RECEIVER THAT IS WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
22-OCT-2009		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 34-020 R01	NAVIGATION - DEPENDENT POSITIONING DETERMINING - INSTALL A GPS RECEIVER THAT IS WIDE AREA AUGMENTATION SYSTEM (WAAS) CAPABLE, SERVICE BULLETIN					OPTIONAL	DECLINED - SB 34-020 REV 1 NO LONGER AVAILABLE
05-JUL-2010		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 34-021	NAVIGATION - INDEPENDENT POSITIONING DETERMINING - INSTALLATION OF A HEADING/TRACK OVERRIDE SWITCH, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
09-OCT-2009		MOS HRS/MSC - AFL		20-AUG-2015			
SB 34-022	NAVIGATION - ATTITUDE AND DIRECTION - UPGRADE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) TO -205 STANDARD, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - AT MANUFACTURE
		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-023	NAVIGATION - INDEPENDENT POSITIONING DETERMINING - INSTALLATION OF A SECOND GLOBAL POSITIONING SYSTEM, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
21-OCT-2009		MOS HRS/MSC - AFL		29-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-023 R01	NAVIGATION - INDEPENDENT POSITIONING DETERMINING - INSTALLATION OF A SECOND GLOBAL POSITIONING SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - DUE TO SERIAL NUMBER
05-JUL-2010		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 34-023 R02	NAVIGATION - INDEPENDENT POSITIONING DETERMINING - INSTALLATION OF A SECOND GLOBAL POSITIONING SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY CONFIGURATION INSTALLED ( DUAL KGS 200 )
29-AUG-2011		MOS HRS/MSC - AFL		29-NOV-2011			
SB 34-024	NAVIGATION - WEATHER RADARINSTALLATION OF XM SATELLITE WEATHER SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - NO SATELLITE WEATHER SYSTEM - ONLY UNITED STATE OF AMERICA
21-OCT-2009		MOS HRS/MSC - (s) AFL		15-MAY-2014 1034.25 834			
SB 34-024 R01	NAVIGATION - WEATHER RADAR - INSTALLATION OF XM SATELLITE WEATHER SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - NO XM SATELLITE WEATHER SYSTEM - ONLY UNITED STATE OF AMERICA
03-FEB-2016		MOS HRS/MSC - AFL		06-APR-2016			
SB 34-024 R02	NAVIGATION - WEATHER RADAR - INSTALLATION OF XM SATELLITE WEATHER SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - Not Equipped: NO XM SATELLITE WEATHER SYSTEM – ONLY UNITED STATE OF AMERICA
04-FEB-2020		MOS HRS/MSC - AFL ACH FLTS					
SB 34-026 R01	NAVIGATION - DEPENDENT POSITIONING DETERMINING - INTRODUCTION OF A HONEYWELL SATELLITE BASE AUGMENTATION SYSTEM (SBAS) GLOBAL NAVIGATION SYSTEM SENSOR UNIT (GNSSU), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
20-JUL-2010		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 34-026 R02	NAVIGATION - DEPENDENT POSITIONING DETERMINING - INTRODUCTION OF A HONEYWELL SATELLITE BASE AUGMENTATION SYSTEM (SBAS) GLOBAL NAVIGATION SYSTEM SENSOR UNIT (GNSSU), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT MSN
		MOS HRS/MSC - AFL		18-DEC-2014 1340.08 1076			
SB 34-026 R02 PART 1	UPGRADE NAVIGATION - DEPENDENT POSITIONING DETERMINING - INTRODUCTION OF A HONEYWELL SATELLITE BASE AUGMENTATION SYSTEM (SBAS) GLOBAL NAVIGATION SYSTEM SENSOR UNIT (GNSSU), SERVICE BULLETIN THE EXISTING HONEYWELL GNSSU WITH NEW SOFTWARE					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT MSN
		MOS HRS/MSC - AFL		18-DEC-2014 1340.08 1076			
SB 34-026 R02 PART 2	REMOVE NAVIGATION - DEPENDENT POSITIONING DETERMINING - INTRODUCTION OF A HONEYWELL SATELLITE BASE AUGMENTATION SYSTEM (SBAS) GLOBAL NAVIGATION SYSTEM SENSOR UNIT (GNSSU), SERVICE BULLETIN THE EXISTING HONEYWELL GNSSU AND INSTALL SBAS GNSSUS					OPTIONAL	NOT APPLICABLE - BY AIRCRAFT MSN
		MOS HRS/MSC - AFL		18-DEC-2014 1340.08 1076			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-026 R02 PART 3	REMOVE NAVIGATION - DEPENDENT POSITIONING DETERMINING - INTRODUCTION OF A HONEYWELL SATELLITE BASE AUGMENTATION SYSTEM (SBAS) GLOBAL NAVIGATION SYSTEM SENSOR UNIT (GNSSU), SERVICE BULLETIN THE EXISTING CMC GNSSU NO.1 AND INSTALL HONEYWELL KGS 200 SBAS GNSSU (ONLY FOR AIRCRAFT THAT HAVE SERVICE BULLETIN 34-020 ACCOMPLISHED OR FACTORY OPTION GNSSU NO.1 INSTALLED). FOR GPS 2 (IF INSTALLED) REFER TO PART 1 OR PART 2 OF THIS SERVICE BULLETIN	MOS HRS/MSC - AFL		18-DEC-2014 1340.08 1076		OPTIONAL	NOT APPLICABLE - BY AIRCRAFT MSN
SB 34-026 R03	NAVIGATION - DEPENDENT POSITIONING DETERMINING - INTRODUCTION OF A HONEYWELL SATELLITE BASE AUGMENTATION SYSTEM (SBAS) GLOBAL NAVIGATION SYSTEM SENSOR UNIT (GNSSU), SERVICE BULLETIN	MOS HRS/MSC - AFL		29-NOV-2011 0 0		OPTIONAL	DECLINED - SB SUPERSEDED BY SB 34-032 REV 0
01-SEP-2011							
SB 34-027	NAVIGATION - ATTITUDE AND HEADING REFERENCE - CORRECT THE MAGNETOMETER PITCH AND ROLL OFFSETS FOR THE KGS 7200 ADAHRS, SERVICE BULLETIN	MOS HRS/MSC - AFL		29-NOV-2011		OPTIONAL	COMPLIED WITH - AT MANUFACTURE
06-JUL-2010							
SB 34-028	NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN	MOS HRS/MSC - AFL		29-NOV-2011		MANDATORY	NOT APPLICABLE
29-SEP-2010							
SB 34-028 PART A	INCORPORATE NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN TEMPORARY REVISION TR 17 INTO THE PC-12/47E AFM (REPORT NO. 02277)	MOS HRS/MSC - AFL		29-NOV-2011		MANDATORY	NOT APPLICABLE
29-SEP-2010							
SB 34-028 PART B	INSTALL NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN AN UPDATED ADAHRS KGS 7200, HONEYWELL PIN 065-00188-5103 (HW MOD 3) (PILATUS P/N 985.99.12.220)	MOS HRS/MSC - AFL		31-JAN-2012 5 5		MANDATORY	NOT APPLICABLE
29-SEP-2010							
SB 34-028 R01	NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) (THIS SB WAS SUPERSEDED BY 34-033 R1, DATED JUNE 4, 2013), SERVICE BULLETIN	MOS HRS/MSC - AFL		31-JAN-2012 5 5			DECLINED - SB SUPERSEDED BY SB 34-033 REV 1
28-NOV-2011							
SB 34-028 R01 PART A	INCORPORATE NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) (THIS SB WAS SUPERSEDED BY 34-033 R1, DATED JUNE 4, 2013), SERVICE BULLETIN THE TEMPORARY REVISION TR 17 INTO THE PC-12/47E AFM (REPORT NO. 02277)	MOS HRS/MSC - AFL		31-JAN-2012 5 5		MANDATORY	NOT APPLICABLE
28-NOV-2011							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-028 R01 PART B	REPLACE NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) (THIS SB WAS SUPERSEDED BY 34-033 R1, DATED JUNE 4, 2013), SERVICE BULLETIN AN INSTALLED ADAHRS UNIT WITH A HONEYWELL P/N 065-00188-5103 (HW MOD 3) (PILATUS P/N 985.99.12.220) UNIT	MOS		31-JAN-2012		MANDATORY	NOT APPLICABLE
28-NOV-2011		HRS/MSC -		5			
		AFL		5			
SB 34-029	NAVIGATION - EFIS SYSTEM PROTECTION OF THE EFIS DISPLAY CABLE LOOM, SERVICE BULLETIN	MOS		31-JAN-2012		RECOMMENDED	NOT APPLICABLE
30-MAR-2011		HRS/MSC -		5			
		AFL		5			
SB 34-029 R01	NAVIGATION - EFIS SYSTEM - PROTECTION OF THE EFIS DISPLAY CABLE LOOM, SERVICE BULLETIN	MOS		29-NOV-2011		RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
08-JUN-2011		HRS/MSC -					
		AFL					
SB 34-032	NAVIGATION - DEPENDENT POSITIONING DETERMINING - INTRODUCTION OF A HONEYWELL GLOBAL NAVIGATION SYSTEM UNIT (GNSSU) P/N 066-01201-0104 (PILATUS P/N 985.99.12.227), SERVICE BULLETIN	MOS		29-NOV-2011		RECOMMENDED	COMPLIED WITH
		HRS/MSC -					
		AFL					
SB 34-033	NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN	MOS		23-APR-2012			COMPLIED WITH - REPLACEMENT FOR UPGRADE BY HONEYWELL
28-NOV-2011		HRS/MSC -		5			
		AFL		5			
SB 34-033 PART A	INCORPORATE NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN THE TEMPORARY REVISION TR 17 INTO THE PC-12/47E AFM (REPORT NO. 02277) FOR MSN 545 AND MSN 1001 THRU MSN 1270 THAT ARE PRE SERVICE BULLETIN 34-028	MOS		23-APR-2012		MANDATORY	COMPLIED WITH - REPLACEMENT FOR UPGRADE BY HONEYWELL
28-NOV-2011		HRS/MSC -		5			
		AFL		5			
SB 34-033 PART B.1	REPLACE NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN THE INSTALLED ADAHRS UNIT WITH A HONEYWELL P/N 065-00188-5103 (HW MOD 4) (PILATUS P/N 985.99.12.245) UNIT FOR MSN 545 AND MSN 1001 THRU MSN 1270 THAT ARE PRE SERVICE BULLETIN 34-028	MOS		23-APR-2012		MANDATORY	COMPLIED WITH - REPLACEMENT FOR UPGRADE BY HONEYWELL
28-NOV-2011		HRS/MSC -		5			
		AFL		5			
SB 34-033 PART B.2	REPLACE NAVIGATION - ATTITUDE AND DIRECTION - REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN THE INSTALLED ADAHRS UNIT WITH A HONEYWELL P/N 065-00188-5103 (HW MOD 4) (PILATUS P/N 985.99.12.245) UNIT FOR MSN 545 AND MSN 1001 THRU MSN 1270 THAT ARE POST SERVICE BULLETIN 34-028 AND MSN 1271 THRU MSN 1340	MOS		23-APR-2012		MANDATORY	COMPLIED WITH - REPLACEMENT FOR UPGRADE BY HONEYWELL
28-NOV-2011		HRS/MSC -		5			
		AFL		5			
SB 34-033 R01	NAVIGATION - ATTITUDE AND DIRECTION REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN	MOS		15-MAY-2014		MANDATORY	DEFERRED - SEE FORM 19 - SB 34-033 REV 1 (MOD 5 INTEGRATION )
04-JUN-2013		HRS/MSC -		1034.25			
		AFL		834			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-033 R01 PART A	INCORPORATE NAVIGATION - ATTITUDE AND DIRECTION REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN THE TEMPORARY REVISION TR 17 INTO THE PC-12/47E AFM (REPORT NO. 02277) FOR MSN 545 AND MSN 1001 THRU MSN 1270 THAT ARE PRE SERVICE BULLETIN 34-028					MANDATORY	DEFERRED - SEE FORM 19 - SB 34-033 REV 1 ( MOD 5 INTEGRATION )
04-JUN-2013		MOS		15-MAY-2014			
		HRS/MSC -		1034.25			
		AFL		834			
SB 34-033 R01 PART B.1	REPLACE NAVIGATION - ATTITUDE AND DIRECTION REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN THE INSTALLED ADAHRS UNIT WITH A HONEYWELL P/N 065-00188-5103 (HW MOD 4 OR MOD 5) (PILATUS P/N 985.99.12.245) UNIT FOR MSN 545 AND MSN 1001 THRU MSN 1270 THAT ARE PRE SERVICE BULLETIN 34-028					MANDATORY	DEFERRED - SEE FORM 19 - SB 34-033 REV 1 ( MOD 5 INTEGRATION )
04-JUN-2013		MOS		15-MAY-2014			
		HRS/MSC -		1034.25			
		AFL		834			
SB 34-033 R01 PART B.2	REPLACE NAVIGATION - ATTITUDE AND DIRECTION REPLACE THE AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS), SERVICE BULLETIN THE INSTALLED ADAHRS UNIT WITH A HONEYWELL P/N 065-00188-5103 (HW MOD 4 OR MOD 5) (PILATUS P/N 985.99.12.245) UNIT FOR MSN 545 AND MSN 1001 THRU MSN 1270 THAT ARE POST SERVICE BULLETIN 34-028 AND MSN 1271 THRU MSN 1340					MANDATORY	DEFERRED - SEE FORM 19 - SB 34-033 REV 1 ( MOD 5 INTEGRATION )
04-JUN-2013		MOS		15-MAY-2014			
		HRS/MSC -		1034.25			
		AFL		834			
SB 34-034	NAVIGATION - ATTITUDE AND DIRECTION REPLACE OBSOLETE DUAL LCR-92/93 ATTITUDE AND HEADING REFERENCE SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
27-APR-2012		MOS		15-MAY-2014			
		HRS/MSC - (s)		1034.25			
		AFL		834			
SB 34-034 R01	NAVIGATION - ATTITUDE AND DIRECTION - REPLACE OBSOLETE DUAL LCR-92/93 ATTITUDE AND HEADING REFERENCE SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
06-NOV-2015		MOS		04-JAN-2016			
		HRS/MSC -					
		AFL					
SB 34-035	DEPENDENT POSITIONING DETERMINING. INTRODUCTION OF A HONEYWELL GLOBAL NAVIGATION SYSTEM SENSOR UNIT (GNSSU) P/N 066-01201-0105 (PILATUS P/N 985.99.12.253), SERVICE BULLETIN					MANDATORY	COMPLIED WITH
27-AUG-2012		MOS		08-NOV-2012			
		HRS/MSC -		198.25			
		AFL		160			
SB 34-036	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT REPLACEMENT OF THE ESIS MAGNETOMETER MOUNTING CORRECTION DATA LABEL, SERVICE BULLETIN					OPTIONAL	DEFERRED - SEE FORM 19 N*34-036
05-DEC-2012		MOS		15-MAY-2014			
		HRS/MSC -		1034.25			
		AFL		834			
SB 34-037	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) - INTRODUCTION OF EGPWS MK. VIII COMPUTER, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
11-JAN-2013		MOS		20-AUG-2015			
		HRS/MSC -					
		AFL					
SB 34-039	FLIGHT ENVIRONMENT DATA IMPROVEMENT OF THE PITOT PIPE LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SUPERSEDED BY 34-039R1
31-OCT-2013		MOS		15-MAY-2014			
		HRS/MSC -		1034.25			
		AFL		834			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-039 R01	FLIGHT ENVIRONMENT DATA - IMPROVEMENT OF THE PITOT PIPE LINE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB PERFORMED IAW SB 34-039R1
14-MAR-2014		MOS HRS/MSC - AFL		24-OCT-2014 1296.17 1035			
SB 34-041	NAVIGATION - FLIGHT ENVIRONMENT DATA IMPROVEMENT TO THE PITOT PIPE LINE (LH WING PITOT SYSTEM), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
31-OCT-2014		MOS HRS/MSC - AFL		31-DEC-2014			
SB 34-041 R01	NAVIGATION - FLIGHT ENVIRONMENT DATA IMPROVEMENT TO THE PITOT PIPE LINE (LH WING PITOT SYSTEM), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
09-APR-2015		MOS HRS/MSC - AFL		30-JUL-2015			
SB 34-042 R01	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT SYSTEM - INTRODUCTION OF L3 ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) IN LIEU OF THALES ESIS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
18-MAR-2015		MOS HRS/MSC - AFL		22-APR-2015			
SB 34-042 R02	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT SYSTEM - INTRODUCTION OF L3 ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) IN LIEU OF THALES ESIS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
22-MAR-2017		MOS HRS/MSC - AFL		10-MAY-2017			
SB 34-042 R03	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT SYSTEM INTRODUCTION OF L3 ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) IN LIEU OF THALES ESIS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
13-NOV-2020		MOS HRS/MSC - AFL		26-FEB-2021			
SB 34-043	NAVIGATION - STANDBY COMPASS SYSTEM CHECK OF THE DEVIATION CARD, SERVICE BULLETIN					RECOMMENDED	DEFERRED - SEE FORM 19 - SB 34-043 REV 0.
		MOS HRS/MSC - AFL		30-JUL-2015			
SB 34-044	NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - declined by executive manager decision
21-AUG-2017		MOS HRS/MSC - AFL ACH FLTS					
SB 34-044 PART A	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 1720, 1741 AND UP)					OPTIONAL	NOT APPLICABLE - :
21-AUG-2017		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-044 PART B	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 545, 1001 THRU 1719 AND 1721 THRU 1740)	MOS				OPTIONAL	NOT APPLICABLE - :
21-AUG-2017		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 34-044 R01	NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN	MOS				OPTIONAL	- DECLINED BY MANAGER
31-OCT-2017		HRS/MSC -					
		AFL					
SB 34-044 R01 PART A	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 1720, 1741 AND UP)	MOS				OPTIONAL	- DECLINED BY MANAGER
31-OCT-2017		HRS/MSC -					
		AFL					
SB 34-044 R01 PART B	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 545, 1001 THRU 1719 AND 1721 THRU 1740)	MOS				OPTIONAL	- DECLINED BY MANAGER
31-OCT-2017		HRS/MSC -					
		AFL					
SB 34-044 R02	NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE - declined by executive manager decision
24-AUG-2018		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 34-044 R02 PART A	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 1720, 1741 AND UP)	MOS				OPTIONAL	NOT APPLICABLE - declined by executive manager decision
24-AUG-2018		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 34-044 R02 PART B	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 545, 1001 THRU 1719 AND 1721 THRU 1740)	MOS				OPTIONAL	NOT APPLICABLE - declined by executive manager decision
24-AUG-2018		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 34-044 R03	NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN	MOS				OPTIONAL	NOT APPLICABLE - DECLINED BY EXECUTIVE MANAGER DECISION
13-NOV-2018		HRS/MSC -					
		AFL					
		ACH					
		FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-044 R03 PART A	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 1720, 1741 AND UP)	MOS HRS/MSC - AFL ACH FLTS				OPTIONAL	NOT APPLICABLE - DECLINED BY EXECUTIVE MANAGER DECISION
13-NOV-2018							
SB 34-044 R03 PART B	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 545, 1001 THRU 1719 AND 1721 THRU 1740)	MOS HRS/MSC - AFL ACH FLTS				OPTIONAL	NOT APPLICABLE - DECLINED BY EXECUTIVE MANAGER DECISION
13-NOV-2018							
SB 34-044 R04	NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN	MOS HRS/MSC - AFL		19-NOV-2020		OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
12-NOV-2020							
SB 34-044 R04 PART A	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 1741 THRU 1944)	MOS HRS/MSC - AFL ACH FLTS				OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
12-NOV-2020							
SB 34-044 R04 PART B	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 545, 1001 THRU 1719 AND 1721 THRU 1740)	MOS HRS/MSC - AFL		19-NOV-2020		OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
12-NOV-2020							
SB 34-044 R04 PART C	ACCOMPLISH NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN MODIFICATION (FOR MSN 1720, 2001 AND UP)	MOS HRS/MSC - AFL		19-NOV-2020		OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
12-NOV-2020							
SB 34-044 R05	NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN	MOS HRS/MSC - AFL		(EFF)		OPTIONAL	DECLINED - BY EXECUTIVE MANAGER ON THE PREVIOUS REVISION
03-SEP-2021							
SB 34-044 R06	NAVIGATION - WEATHER RADAR SYSTEM - REMOVE THE RDR2000 WEATHER RADAR AND INSTALL A RDR2060 WEATHER RADAR, SERVICE BULLETIN	MOS HRS/MSC - AFL		(EFF)		OPTIONAL	- IN REVIEW - RDR 2000 INSTALLED
15-MAR-2022							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 34-045	NAVIGATION - ATC TRANSPONDER - REPLACEMENT OF THE COAX SWITCH, SERVICE BULLETIN					OPTIONAL	- APPLICABLE ONLY IF THE AFFECTED P/N HAS FAILED.
		MOS		(EFF)			
		30-MAY-2018	HRS/MSC -				
			AFL				
SB 34-046	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT SYSTEM - INTRODUCTION OF EFD-750 ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) IN LIEU OF THALES ESIS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Serial- N/A
		MOS					
		30-MAY-2022	HRS/MSC -				
			AFL				
			ACH				
			FLTS				
SB 34-046 R01	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT - INTRODUCTION OF EFD-750 ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) IN LIEU OF A THALES ESIS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY A/C MSN: PC-12/47E AIRCRAFT MSN 1001 THRU MSN 1270 WITH A THALES ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) INSTALLED.
		MOS		23-MAY-2023			
		09-MAY-2023	HRS/MSC -				
			AFL				
SB 34-046 R01 PART 1	ACCOMPLISH, SERVICE BULLETIN INSTALLATION OF THE EFD-750 ESIS WITH AIRCRAFT HEADING INDICATION					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY A/C MSN: PC-12/47E AIRCRAFT MSN 1001 THRU MSN 1270 WITH A THALES ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) INSTALLED.
		MOS		23-MAY-2023			
		09-MAY-2023	HRS/MSC -				
			AFL				
SB 34-046 R01 PART 2	ACCOMPLISH, SERVICE BULLETIN INSTALLATION OF THE EFD-750 ESIS WITHOUT AIRCRAFT HEADING INDICATION					OPTIONAL	NOT APPLICABLE - BY SERIAL: BY A/C MSN: PC-12/47E AIRCRAFT MSN 1001 THRU MSN 1270 WITH A THALES ELECTRONIC STANDBY INSTRUMENT SYSTEM (ESIS) INSTALLED.
		MOS		23-MAY-2023			
		09-MAY-2023	HRS/MSC -				
			AFL				
SB 35-001 R01	INSTALLATION OF AN OXYGEN SHUT-OFF VALVE LEVER, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
		23-JAN-2003	HRS/MSC -	0			
			AFL	0			
SB 35-002	IMPROVED DISTRIBUTION OF OXYGEN TO OCCUPANTS OF REAR BENCH SEAT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
		19-DEC-2000	HRS/MSC -	0			
			AFL	0			
SB 35-003	INSTALLATION OF AN OXYGEN MASK IN THE TOILET COMPARTMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
		17-SEP-2001	HRS/MSC -	0			
			AFL	0			
SB 35-004	CHANGE ROUTING OF OXYGEN PIPES ON AIRCRAFT WITH EXECUTIVE INTERIORS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		29-NOV-2011			
		19-DEC-2003	HRS/MSC -	0			
			AFL	0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 35-005	OXYGEN - PASSENGER OXYGEN SYSTEM REPLACEMENT OF THE PRESSURE GAUGE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		15-MAY-2014			
	25-JAN-2012	HRS/MSC -		1034.25			
		AFL		834			
SB 35-006	OXYGEN - PASSENGER OXYGEN SYSTEM REPLACEMENT OF THE OXYGEN SHUT-OFF VALVE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - SUPERSEDED BY 35-006R1
		MOS		15-MAY-2014			
	06-DEC-2012	HRS/MSC -		1034.25			
		AFL		834			
SB 35-006 R01	OXYGEN - PASSENGER OXYGEN SYSTEM - REPLACEMENT OF THE OXYGEN SHUT-OFF VALVE, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		20-AUG-2015			
	16-MAY-2013	HRS/MSC -					
		AFL					
SB 35-007	OXYGEN - PASSENGER OXYGEN SYSTEM - INTRODUCTION OF A DROP - DOWN PASSENGER OXYGEN MASK SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Executive Manager Decision SEE 35-007 R1
		MOS					
	11-JUL-2016	HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 35-007 R01	OXYGEN - PASSENGER OXYGEN SYSTEM - INTRODUCTION OF A DROP-DOWN PASSENGER OXYGEN MASK SYSTEM, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		05-DEC-2016			
	21-NOV-2016	HRS/MSC -					
		AFL					
SB 35-007 R02	OXYGEN - PASSENGER OXYGEN SYSTEM - INTRODUCTION OF A DROP-DOWN PASSENGER OXYGEN MASK SYSTEM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - DECLINED BY EXECUTIVE MANAGER DECISION
		MOS					
	11-MAR-2020	HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 35-008	OXYGEN - PASSENGER OXYGEN SYSTEM - INTRODUCTION OF AN EXECUTIVE SIX SEAT TO EIGHT SEAT PASSENGER OXYGEN SYSTEM CONVERSION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY ACFT MSN
		MOS					
	18-APR-2019	HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 35-009	OXYGEN - CONTROLS - MODIFICATION TO CHANGE THE ROUTE OF CONTROL WIRE ASSEMBLY (L52-62), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: BY ACFT MSN
		MOS		19-NOV-2020			
	30-SEP-2020	HRS/MSC -					
		AFL					
SB 45-001 R01	UPGRADE THE HONEYWELL PRIMUS APEX SOFTWARE TO BUILD 5, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		31-JAN-2012			
	16-JAN-2009	HRS/MSC -		5			
		AFL		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 45-001 R02	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 5, SERVICE BULLETIN					RECOMMENDED	DECLINED - SUPERSEDED BY SB 45-002 REV 1 ( BUILD 5.3.1 )
		MOS		31-JAN-2012			
	20-JUN-2011	HRS/MSC -		5			
		AFL		5			
SB 45-002	UPGRADE THE HONEYWELL PRIMUS APEX SOFTWARE TO BUILD 5.3.1, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		31-JAN-2012			
	30-MAR-2009	HRS/MSC -		5			
		AFL		5			
SB 45-002 R01	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 5.3.1, SERVICE BULLETIN					RECOMMENDED	DECLINED - SUPERSEDED BY SB 45-003 REV 2 ( BUILD 6.0 )
		MOS		31-JAN-2012			
	27-JUN-2011	HRS/MSC -		5			
		AFL		5			
SB 45-003	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 6, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE
		MOS		31-JAN-2012			
	22-OCT-2009	HRS/MSC -		5			
		AFL		5			
SB 45-003 R01	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 6, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		31-JAN-2012			
	12-NOV-2009	HRS/MSC -		5			
		AFL		5			
SB 45-003 R02	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 6, SERVICE BULLETIN					RECOMMENDED	DECLINED - SUPERSEDED BY SB 45-005 REV 3 ( BUILD 7.0 )
		MOS		18-DEC-2014			
		HRS/MSC -		1340.08			
		AFL		1076			
SB 45-004	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS					
	18-SEP-2009	HRS/MSC -					
		AFL					
SB 45-004 R01	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS					
	05-JUL-2010	HRS/MSC -					
		AFL					
SB 45-004 R02	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - AT MANUFACTURE
		MOS		30-NOV-2011			
	18-JAN-2011	HRS/MSC - (s)					
		AFL					
SB 45-004 R06	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	- SEE FORM F-19 SB 45-004 R6
		MOS					
	08-AUG-2014	HRS/MSC - (s)					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 45-004 R08	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	DEFERRED - SEE FORM F19 SB 45-004 R8
10-MAY-2016		MOS		12-MAY-2016			
		HRS/MSC -					
		AFL					
SB 45-004 R09	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	- SEE FORM F19 SB 45-004 R9
06-JAN-2017		MOS		03-MAR-2017			
		HRS/MSC -					
		AFL					
SB 45-004 R10	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - APEX BUILD 11.1
21-AUG-2017		MOS		21-AUG-2017			
		HRS/MSC -					
		AFL					
SB 45-004 R11	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - ADSB OPTION UPGRADE CARRIED OUT
30-MAY-2018		MOS		15-JUN-2020			
		HRS/MSC -		4723.5			
		AFL		4079			
SB 45-004 R12	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: SB ALREADY DONE
03-FEB-2020		MOS		04-FEB-2020			
		HRS/MSC -					
		AFL					
SB 45-004 R14	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	- WAITING FORM MANAGEMENT DECISION
08-MAY-2023		MOS		(EFF)			
		HRS/MSC -					
		AFL					
SB 45-005	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 7, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
22-DEC-2010		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 45-005 R01	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 7, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
11-MAR-2011		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 45-005 R02	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 7, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
27-JUN-2011		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 45-005 R03	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 7, SERVICE BULLETIN					RECOMMENDED	DECLINED - SUPERSEDED BY SB 45-008 REV 0 ( BUILD 8.0 )
10-NOV-2011		MOS		18-DEC-2014			
		HRS/MSC -		1340.08			
		AFL		1076			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 45-006	CENTRAL MAINTENANCE SYSTEM - SYS 2 WIRING HARNESS - INSPECT SPLICES AND CRIMPS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
	13-MAY-2011						
SB 45-008	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 8, SERVICE BULLETIN					RECOMMENDED	DECLINED - SUPERSEDED BY SB 45-009 REV 0 ( BUILD 8.3.3 )
		MOS		23-APR-2012			
		HRS/MSC -		5			
		AFL		5			
	22-DEC-2011						
SB 45-009	UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 8.3.3, SERVICE BULLETIN					RECOMMENDED	DECLINED - SUPERSEDED BY SB 45-010 REV 0 ( BUILD 8.6 )
		MOS		23-APR-2012			
		HRS/MSC -		5			
		AFL		5			
	04-APR-2012						
SB 45-010	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 8.6, SERVICE BULLETIN					RECOMMENDED	DECLINED - SUPERSEDED BY SB 45-011 REV 0 ( BUILD 8.7 )
		MOS		26-OCT-2013			
		HRS/MSC -		713.83			
		AFL		550			
SB 45-011	CENTRAL MAINTENANCE SYSTEM - UPDATE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 8.7 (LIMITED DISTRIBUTION ONLY), SERVICE BULLETIN					RECOMMENDED	DECLINED - SUPERSEDED BY SB 45-012 REV 0 ( BUILD 8.8 )
		MOS		29-NOV-2011			
		HRS/MSC -		0			
		AFL		0			
	16-DEC-2013						
SB 45-012	CENTRAL COMPUTER - UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 8.8, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - INSTALLATION OF NEW SOFTWARE 8.8
		DAYS		18-DEC-2014			
		HRS/MSC -		1340.08			
		AFL		1076			
	03-JUL-2014						
SB 45-014	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 10.9, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - HONEYWELL PRIMUS APEX OP SOFTWARE UPGRADED TO 10.9 IAW SB 45-014
		MOS		01-JUL-2016			
		HRS/MSC -		2168.33			
		AFL		1773			
	02-MAY-2016						
SB 45-015	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 11, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SEE WO JETFLY JFS-015-17 AND SEE WR PILATUS 010818/17
		MOS		07-NOV-2017			
		HRS/MSC -		3151.92			
		AFL		2592			
	21-AUG-2017						
SB 45-015 R01	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 10.11 (BUILD 11), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SEE WO JETFLY JFS-015-17 AND SEE WR PILATUS 010818/17
		MOS		07-NOV-2017			
		HRS/MSC -		3151.92			
		AFL		2592			
	25-OCT-2017						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 45-016	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 10.14 (BUILD 11.1), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
29-MAY-2018		MOS		20-JUL-2018			
		HRS/MSC -		3591.75			
		AFL		3054			
SB 45-017	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - REPLACE THE LDI WITH A NEW REVISION (PC12_LDI_10_11_04), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - LDI SOFTWARE UPDATED
06-SEP-2019		MOS		15-JUN-2020			
		HRS/MSC -		4723.5			
		AFL		4079			
SB 45-018	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - UPGRADE THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE TO BUILD 12.6.1, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
10-DEC-2019		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 45-019	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY ACFT MSN
14-SEP-2020		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 45-019 R01	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY SERIAL: A/C MSN
12-MAY-2023		MOS		08-JUN-2023			
		HRS/MSC -					
		AFL					
SB 45-019 R02	LOAD HONEYWELL PRIMUS APEX OPTION FILE FOR VARIOUS FACTORY OPTIONS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: A/C MSN
17-MAY-2024		MOS		13-JUN-2024			
		HRS/MSC -					
		AFL					
SB 45-020	CENTRAL MAINTENANCE SYSTEM - GENERAL UPDATE THE APM SETTINGS FILE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
12-MAY-2020		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 45-021	CENTRAL MAINTENANCE SYSTEM - GENERAL UPDATE OF THE HONEYWELL PRIMUS APEX OPTION FILE TO REMOVE NUISANCE CALLOUTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
03-JUL-2020		MOS					
		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 45-023	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - ELECTRONIC CHECKLIST UPDATE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT SERIAL NUMBER
25-NOV-2020		MOS		27-JAN-2021			
		HRS/MSC -					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 45-024	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - ELECTRONIC CHECKLIST UPDATE (SUPERSEDED BY SB 45-028), SERVICE BULLETIN	MOS HRS/MSC - AFL ACH FLTS				RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
17-AUG-2021							
SB 45-024 REV A	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER ELECTRONIC CHECKLIST UPDATE (SUPERSEDED BY SB 45-028), SERVICE BULLETIN	MOS		26-SEP-2022		RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: BY A/C S/N
19-AUG-2022		HRS/MSC - AFL					
SB 45-025	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - INSTALL THE HONEYWELL PRIMUS APEX OPERATIONAL SOFTWARE BUILD 12.7.1, SERVICE BULLETIN	MOS		08-JUN-2023		RECOMMENDED	NOT APPLICABLE - BY SERIAL: A/C MSN
12-MAY-2023		HRS/MSC - AFL					
SB 45-028	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - ELECTRONIC CHECKLIST UPDATE (SUPERSEDES SB 45-024), SERVICE BULLETIN	MOS		26-SEP-2022		RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: N/A BY AC/ MSN
19-AUG-2022		HRS/MSC - AFL					
SB 45-029	CENTRAL MAINTENANCE SYSTEM - CENTRAL COMPUTER - REPLACE THE LDI WITH A NEW REVISION (PC12_LDI_12_6_19), SERVICE BULLETIN	MOS		23-DEC-2022		RECOMMENDED	NOT APPLICABLE - BY SERIAL: CONCERNS MSN 2001 THRU 2200. THIS MOD. WILL BE ACCOMPLISHED DURING PRODUCTION ON 2201 AND UP.
24-NOV-2022		HRS/MSC - (s) AFL					
SB 46-001	SYSTEMS INTEGRATION AND DISPLAY - DISPLAY REPLACE THE MULTI-FUNCTIONAL CONTROLLER (MFC), SERVICE BULLETIN	MOS		30-NOV-2011		RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
09-JAN-2009		HRS/MSC - AFL					
SB 46-003 R01	SYSTEMS INTEGRATION AND DISPLAY - DISPLAY AND CONTROL INSTALLATION OF A CURSOR CONTROL DEVICE (CCD), SERVICE BULLETIN	MOS		31-JAN-2012		OPTIONAL	NOT APPLICABLE
06-MAY-2010		HRS/MSC - AFL		5 5			
SB 46-003 R02	SYSTEMS INTEGRATION AND DISPLAY - DISPLAY AND CONTROL INSTALLATION OF A CURSOR CONTROL DEVICE (CCD), SERVICE BULLETIN	MOS		31-JAN-2012		OPTIONAL	NOT APPLICABLE
05-NOV-2010		HRS/MSC - AFL		5 5			
SB 46-003 R03	SYSTEMS INTEGRATION AND DISPLAY. DISPLAY AND CONTROL INSTALLATION OF A CURSOR CONTROL DEVICE (CCD), SERVICE BULLETIN	MOS		30-NOV-2011		OPTIONAL	COMPLIED WITH - AT MANUFACTURE -
23-DEC-2010		HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 46-004	SYSTEMS INTEGRATION AND DISPLAY - INSTALL A WIRELESS DATA LOADING/DOWNLOADING SYSTEM, SERVICE BULLETIN					OPTIONAL	- NFA - SUPERSEDED BY R01
26-APR-2013		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 46-004 R01	SYSTEMS INTEGRATION AND DISPLAY - INSTALL A WIRELESS DATA LOADING/DOWNLOADING SYSTEM, SERVICE BULLETIN					OPTIONAL	- NFA - SUPERSEDED BY R02
		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 46-004 R02	SYSTEMS INTEGRATION AND DISPLAY - INSTALL A WIRELESS DATA LOADING/DOWNLOADING SYSTEM, SERVICE BULLETIN					OPTIONAL	- NFA - SUPERSEDED BY R03
		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 46-004 R03	SYSTEMS INTEGRATION AND DISPLAY - INSTALL A WIRELESS DATA LOADING/DOWNLOADING SYSTEM, SERVICE BULLETIN					OPTIONAL	- NFA - SUPERSEDED BY R04
		MOS HRS/MSC - AFL		18-DEC-2014 1340.08 1076			
SB 46-004 R04	SYSTEMS INTEGRATION AND DISPLAY - INSTALL A WIRELESS DATA LOADING/DOWNLOADING SYSTEM, SERVICE BULLETIN					OPTIONAL	- NFA - SUPERSEDED BY R05
15-NOV-2013		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 46-004 R05	SYSTEMS INTEGRATION AND DISPLAY - INSTALL A WIRELESS DATA LOADING/DOWNLOADING SYSTEM, SERVICE BULLETIN					OPTIONAL	- NFA - SUPERSEDED BY R06
25-MAR-2014		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 46-004 R06	SYSTEMS INTEGRATION AND DISPLAY - INSTALL A WIRELESS DATA LOADING/DOWNLOADING SYSTEM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - 18/12/2014, TSN 1340.08, WO PC12-284-14
03-JUL-2014		MOS HRS/MSC - AFL		18-DEC-2014 1340.08 1076			
SB 46-004 R07	SYSTEMS INTEGRATION AND DISPLAY WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) INSTALLATION, SERVICE BULLETIN					OPTIONAL	- PCW - PREV. C/W 18/12/2014, TSN 1340.08, WO PC12-284-14 NFA - NO ADDITIONAL WORK REQUIRED
06-OCT-2015		MOS HRS/MSC - AFL		16-NOV-2015			
SB 46-004 R08	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) INSTALLATION, SERVICE BULLETIN					OPTIONAL	- PCW - PREV. C/W 18/12/2014, TSN 1340.08, WO PC12-284-14 NFA - NO ADDITIONAL WORK REQUIRED
22-MAR-2017		MOS HRS/MSC - AFL		10-MAY-2017			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 46-004 R09	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) INSTALLATION, SERVICE BULLETIN					OPTIONAL	- PCW - PREV. C/W 18/12/2014, TSN 1340.08, WO PC12-284-14 NFA - NO ADDITIONAL WORK REQUIRED
04-FEB-2020		MOS HRS/MSC - AFL		07-SEP-2020			
SB 46-004 R10	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) INSTALLATION, SERVICE BULLETIN					OPTIONAL	- NFA - SUPERSEDED BY R11
19-OCT-2021		MOS HRS/MSC - AFL		(EFF)			
SB 46-004 R11	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) INSTALLATION, SERVICE BULLETIN					OPTIONAL	- WAITING FOR EXEC DECISION
27-APR-2023		MOS HRS/MSC - AFL					
SB 46-005	SYSTEM INTEGRATION AND DISPLAY - DISPLAY AND CONTROL INTRODUCTION OF PROTECTION ON THE PILOT PFD AND MFD WIRING LOOMS, SERVICE BULLETIN					RECOMMENDED	DEFERRED - SEE FORM 19 N*46-005
28-OCT-2013		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 46-006 R01	SYSTEMS INTEGRATION AND DISPLAY WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
23-OCT-2015		MOS HRS/MSC - AFL		08-APR-2016 2018.58 1648			
SB 46-006 R02	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SEE SB 46-006 R1
19-JUN-2017		MOS HRS/MSC - AFL		29-JUL-2017 2968.17 2540			
SB 46-007	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
23-DEC-2016		MOS HRS/MSC - AFL		27-FEB-2017 2596.58 2211			
SB 46-007 R01	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - ALREADY COMPLIED WITH
04-JAN-2017		MOS HRS/MSC - AFL		27-FEB-2017			
SB 46-007 R02	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - ALREADY COMPLIED WITH
25-SEP-2017		MOS HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 46-008	SYSTEMS INTEGRATION AND DISPLAY WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - 2020-09-25, TSN 5027.16, WO JFS-007-20R1 SUPERSEDED BY R01
13-JUL-2020		MOS HRS/MSC - AFL		25-SEP-2020 5027.17 4328			
SB 46-008 R01	SYSTEMS INTEGRATION AND DISPLAY WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: 25/09/2020, 5027:10, JFS-007-20R1 DO NOT REQUIRE FUTHER REWORK
03-APR-2024		MOS HRS/MSC - AFL		11-APR-2024			
SB 46-009	SYSTEMS INTEGRATION AND DISPLAY WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY ACFT MSN
13-JUL-2020		MOS HRS/MSC - AFL ACH FLTS					
SB 46-009 R01	SYSTEMS INTEGRATION AND DISPLAY - WIRELESS DATA LOADING SYSTEM (CONNECTED FLIGHT DECK) SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: A/C MSN
22-APR-2024		MOS HRS/MSC - AFL		29-APR-2024			
SB 46-010	SYSTEMS INTEGRATION AND DISPLAY - TOUCH-SCREEN CONTROLLER - INSTALL UPDATED SOFTWARE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - By Effectivity- BY AIRCRAFT MSN
30-NOV-2021		MOS HRS/MSC - AFL ACH FLTS					
SB 52-001 R01	INSTALL IMPROVED EMERGENCY EXIT SEAL, LOCKING MECHANISM AND INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
13-OCT-1998		MOS HRS/MSC - AFL		29-NOV-2011			
SB 52-002	INSTALLATION OF NEW DOOR LOCKS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
10-OCT-1997		MOS HRS/MSC - AFL		29-NOV-2011			
SB 52-003	INSTALLATION OF IMPROVED EMERGENCY EXIT SEAL, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
29-JAN-1999		MOS HRS/MSC - AFL		29-NOV-2011			
SB 52-004 R01	INSPECTION AND INSTALLATION OF REINFORCING PLATES TO THE CARGO DOOR FRAMES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
10-SEP-2001		MOS HRS/MSC - AFL		29-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 52-005	MODIFICATION OF THE CARGO DOOR, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
09-MAY-2001		MOS HRS/MSC - AFL		29-NOV-2011			
SB 52-006	PASSENGER/CREW DOOR - ATTACHMENT OF DOOR SUPPORT BRACKETS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - DUE TO SERIAL NUMBER
22-APR-2009		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 52-006 R01	PASSENGER/CREW DOOR ATTACHMENT OF DOOR SUPPORT BRACKETS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
07-JUL-2009		MOS HRS/MSC - AFL		29-NOV-2011			
SB 52-007	PASSENGER/CREW - INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - NOT CONCERNED BY PASSENGER/CREW DOOR SERIAL NUMBERS
09-JUL-2014		MOS HRS/MSC - AFL		21-JUL-2014			
SB 52-007 PART A	INSPECT PASSENGER/CREW - INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN THE PASSENGER/CREW DOOR SERIAL NUMBER PLACARD TO DETERMINE IF THE DOOR IS POSSIBLY AFFECTED					RECOMMENDED	NOT APPLICABLE - NOT CONCERNED BY PASSENGER/CREW DOOR SERIAL NUMBERS
09-JUL-2014		MOS HRS/MSC - AFL		21-JUL-2014			
SB 52-007 PART B	IDENTIFY PASSENGER/CREW - INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN THE SHOOT BOLT FITTING MATERIAL					RECOMMENDED	NOT APPLICABLE - NOT CONCERNED BY PASSENGER/CREW DOOR SERIAL NUMBERS
09-JUL-2014		MOS HRS/MSC - AFL		21-JUL-2014			
SB 52-007 PART C	INITIAL PASSENGER/CREW - INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN DETAILED CRACK INSPECTION OF THE PASSENGER/CREW DOOR SHOOT BOLT FITTINGS FOR ALL SHOOT BOLT FITTINGS IDENTIFIED AS MANUFACTURED FROM AA 2024 T351 MATERIAL IF CRACKS ARE FOUND REPAIR IF NECESSARY					RECOMMENDED	NOT APPLICABLE - NOT CONCERNED BY PASSENGER/CREW DOOR SERIAL NUMBERS
09-JUL-2014		MOS HRS/MSC - AFL		21-JUL-2014			
SB 52-007 R01	DOORS - PASSENGER/CREW INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY PASEENGER DOOR S/N
12-AUG-2014		MOS HRS/MSC - AFL		11-SEP-2014			
SB 52-007 R01 PART A	INSPECT DOORS - PASSENGER/CREW INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN THE PASSENGER/CREW DOOR SERIAL NUMBER PLACARD TO DETERMINE IF THE DOOR IS POSSIBLY AFFECTED					RECOMMENDED	NOT APPLICABLE - BY PASEENGER DOOR S/N
12-AUG-2014		MOS HRS/MSC - AFL		11-SEP-2014			
SB 52-007 R01 PART B	IDENTIFY DOORS - PASSENGER/CREW INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN THE SHOOT BOLT FITTING MATERIAL					RECOMMENDED	NOT APPLICABLE - BY PASEENGER DOOR S/N
12-AUG-2014		MOS HRS/MSC - AFL		11-SEP-2014			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 52-007 R01 PART C	INITIAL DOORS - PASSENGER/CREW INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN DETAILED CRACK INSPECTION OF THE PASSENGER/CREW DOOR SHOOT BOLT FITTINGS FOR ALL SHOOT BOLT FITTINGS IDENTIFIED AS MANUFACTURED FROM AA 2024 T351 MATERIAL IF CRACKS ARE FOUND REPAIR IF NECESSARY	MOS		11-SEP-2014		RECOMMENDED	NOT APPLICABLE - BY PASEENGER DOOR S/N
12-AUG-2014		HRS/MSC - AFL					
SB 52-007 R02	DOORS - PASSENGER/CREW INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN	MOS		23-JAN-2015		RECOMMENDED	NOT APPLICABLE - BY SERIAL NUMBER'S DOOR (> 365)
07-JAN-2015		HRS/MSC - (s) AFL					
SB 52-007 R02 PART A	INSPECT DOORS - PASSENGER/CREW INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN THE PASSENGER/CREW DOOR SERIAL NUMBER PLACARD TO DETERMINE IF THE DOOR IS POSSIBLY AFFECTED	MOS		23-JAN-2015		RECOMMENDED	NOT APPLICABLE - SB 52-007 ISSUE 01 PART COMPLETED . DOOR SN 1106 FOUND NOT TO BE AFFECTED, NO ACTION REQUIRED
07-JAN-2015		HRS/MSC - (s) AFL					
SB 52-007 R02 PART B	IDENTIFY DOORS - PASSENGER/CREW INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN THE SHOOT BOLT FITTING MATERIAL	MOS		23-JAN-2015		RECOMMENDED	NOT APPLICABLE - BY S/N DOOR
07-JAN-2015		HRS/MSC - (s) AFL					
SB 52-007 R02 PART C	INITIAL DOORS - PASSENGER/CREW INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN DETAILED CRACK INSPECTION OF THE PASSENGER/CREW DOOR SHOOT BOLT FITTINGS	MOS		23-JAN-2015		RECOMMENDED	NOT APPLICABLE - BY S/N DOOR
07-JAN-2015		HRS/MSC - (s) AFL					
SB 52-007 R03	DOORS - PASSENGER/CREW - INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN	MOS		09-FEB-2016		RECOMMENDED	NOT APPLICABLE - BY SERIAL NUMBER'S DOOR (> 365)
28-JAN-2016		HRS/MSC - AFL					
SB 52-007 R03 PART A	INSPECT DOORS - PASSENGER/CREW - INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN THE PASSENGER/CREW DOOR SERIAL NUMBER PLACARD TO DETERMINE IF THE DOOR IS POSSIBLY AFFECTED	MOS		09-FEB-2016		RECOMMENDED	NOT APPLICABLE - SB 52-007 ISSUE 1 PART A COMPLETED.DOOR SN XXX FOUND NOT TO BE AFFECTED,NO ACTION REQUIRED
28-JAN-2016		HRS/MSC - AFL					
SB 52-007 R03 PART B	IDENTIFY DOORS - PASSENGER/CREW - INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN THE SHOOT BOLT FITTING MATERIAL	MOS		09-FEB-2016		RECOMMENDED	NOT APPLICABLE - BY S/N DOOR
28-JAN-2016		HRS/MSC - AFL					
SB 52-007 R03 PART C	INITIAL DOORS - PASSENGER/CREW - INSPECTION OF DOOR SHOOT BOLT FITTINGS, SERVICE BULLETIN DETAILED CRACK INSPECTION OF THE PASSENGER/CREW DOOR SHOOT BOLT FITTINGS	MOS		09-FEB-2016		RECOMMENDED	NOT APPLICABLE - BY S/N DOOR
28-JAN-2016		HRS/MSC - AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 52-008	DOORS - CARGO INTRODUCTION OF A NEW DOOR HANDLE SWITCH, SERVICE BULLETIN					OPTIONAL	DEFERRED - SEE FORM19 N°52-008
12-MAY-2014		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 52-008 R01	DOORS - CARGO INTRODUCTION OF A NEW DOOR HANDLE SWITCH, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
18-JUL-2014		MOS HRS/MSC - AFL		20-AUG-2015			
SB 52-009	DOORS - CARGO - REPLACEMENT OF THE CARGO DOOR DRIVE MECHANISM MOTOR, SERVICE BULLETIN					OPTIONAL	- INFORMATIONAL ONLY: SB WILL BE EMBODIED DURING NEXT CARGO DOOR MOTOR EXCHANGE
25-MAY-2018		MOS HRS/MSC - AFL					
SB 52-010	DOORS - PASSENGER/CREW - INTRODUCTION OF A NEW GAS STRUT AND MODIFICATION TO THE COUNTERBALANCE MECHANISM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: N/A BY AIRCRAFT SERIAL NUMBER
20-MAY-2019		MOS HRS/MSC - AFL		05-JAN-2021			
SB 52-010 R01	DOORS - PASSENGER/CREW - INTRODUCTION OF A NEW GAS STRUT AND MODIFICATION TO THE COUNTERBALANCE MECHANISM, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
22-DEC-2020		MOS HRS/MSC - AFL		12-MAR-2021			
SB 52-010 R01 PART A	ACCOMPLISH DOORS - PASSENGER/CREW - INTRODUCTION OF A NEW GAS STRUT AND MODIFICATION TO THE COUNTERBALANCE MECHANISM, SERVICE BULLETIN INSPECT THE BOLT AND MAKE SURE THAT IT IS INSTALLED CORRECTLY. IT ALSO GIVES THE INSTRUCTIONS TO REPLACE THE BOLT, IF NECESSARY					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
22-DEC-2020		MOS HRS/MSC - AFL		12-MAR-2021			
SB 52-010 R01 PART B	ACCOMPLISH DOORS - PASSENGER/CREW - INTRODUCTION OF A NEW GAS STRUT AND MODIFICATION TO THE COUNTERBALANCE MECHANISM, SERVICE BULLETIN INTRODUCE A NEW GAS STRUT AND MODIFY THE COUNTERBALANCE MECHANISM					OPTIONAL	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
22-DEC-2020		MOS HRS/MSC - AFL		12-MAR-2021			
SB 52-011 R01	DOORS - PASSENGER/CREW - REPLACEMENT OF THE SENSOR SUPPORT BRACKET, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY ACFT MSN
23-OCT-2019		MOS HRS/MSC - AFL ACH FLTS					
SB 52-012	DOORS - PASSENGER - STAIRS - INSTALLATION OF THE PROTECTIVE CAPS ON THE SHOCK STRUTS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY ACFT MSN
28-JAN-2020		MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 52-013	DOORS - PASSENGER/CREW - PASSENGER DOOR - REPLACEMENT OF THE DOORSTEP, SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
09-MAR-2021		HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SB 53-001	MODIFICATION OF CARGO DOOR FUSELAGE SUPPORT, SERVICE BULLETIN	MOS		29-NOV-2011		RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
06-FEB-1998		HRS/MSC -					
		AFL					
SB 53-002	REPLACEMENT OF THE PASSENGER DOOR BEARING SUPPORT ON THE FUSELAGE, SERVICE BULLETIN	MOS		29-NOV-2011		RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
12-FEB-1998		HRS/MSC -					
		AFL					
SB 53-003 R01	INSPECTION AND REPAIR OF REAR PRESSURE BULKHEAD, SERVICE BULLETIN	MOS		29-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
26-JUL-2002		HRS/MSC -					
		AFL					
SB 53-004	FUSELAGE-CENTER FUSELAGE-FR21, IN THE AREA OF THE WING UPPER- ATTACHMENT LUGS-INSPECTION, SERVICE BULLETIN	MOS		29-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		HRS/MSC - (s)					
		AFL					
SB 53-005	FUSELAGE - FORWARD FUSELAGE - FRAME 13 LIGHTENING HOLE EDGE PROTECTION - INSPECTION, SERVICE BULLETIN	MOS		29-NOV-2011		RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
10-JUL-2009		HRS/MSC -					
		AFL					
SB 53-006	FUSELAGE - CENTER FUSELAGE FRAMES INSTALL IMPROVED CHAFE PROTECTION ON FRAMES 21 AND 24, SERVICE BULLETIN	MOS		20-AUG-2015		OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
		HRS/MSC -					
		AFL					
SB 53-007	FUSELAGE - REAR FUSELAGE INSTALLATION OF AN IMPROVED MOUNTING FOR THE VHF3 ANTENNA, SERVICE BULLETIN	MOS		31-JUL-2015		OPTIONAL	NOT APPLICABLE - BY EQUIPMENT INSTALLED (NO VHF #3 INSTALLED)
		HRS/MSC - (s)					
		AFL					
SB 53-007 R01	FUSELAGE - REAR FUSELAGE INSTALLATION OF AN IMPROVED MOUNTING FOR THE VHF3 ANTENNA, SERVICE BULLETIN	MOS		17-AUG-2016		OPTIONAL	NOT APPLICABLE - BY EQUIPMENT INSTALLED (NO VHF3 INSTALLED)
29-JUL-2016		HRS/MSC -					
		AFL					
SB 53-008	FUSELAGE - CENTER FUSELAGE - INSTALL CHAFE PROTECTION TAPE ON THE FUSELAGE SKIN, SERVICE BULLETIN	MOS		07-JUN-2016		OPTIONAL	DEFERRED - SEE FORM F19 SB 53-008 R0
25-FEB-2016		HRS/MSC - (s)					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 53-008 R01	FUSELAGE - CENTER FUSELAGE - INSTALL CHAFE PROTECTION TAPE ON THE FUSELAGE SKIN, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
18-MAY-2016		MOS		24-JUN-2016			
		HRS/MSC -					
		AFL					
SB 55-001	ELEVATOR - INSPECTION AND REPAIR, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
08-NOV-1996		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
SB 55-002	VERTICAL STABILIZER - REPLACEMENT OF THE SHEAR PLATE AND STRAP, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC A/R		5			
		AFL		5			
SB 55-002 R01	VERTICAL STABILIZER REPLACEMENT OF THE SHEAR PLATE AND STRAP, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS		30-NOV-2011			
		HRS/MSC A/R					
		AFL					
SB 55-003	STABILIZERS - GENERAL - INTRODUCTION OF LIGHTWEIGHT DORSAL FIN, SERVICE BULLETIN					OPTIONAL	DECLINED - BY EXECUTIVE MANAGER DECISION
24-NOV-2017		MOS		04-SEP-2018			
		HRS/MSC -					
		AFL					
SB 55-004	STABILIZERS - HORIZONTAL STABILIZER - CHECK OF THE REAR ATTACHMENT BOLTS, SERVICE BULLETIN						COMPLIED WITH - CHECK - N/A BY BATCH NUMBER FITTED.
29-MAR-2019		MOS		04-JUL-2019			
		HRS/MSC -		4174.5			
		AFL		3567			
SB 56-001	MODIFICATION OF THE DV-WINDOW, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
19-JAN-1998		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 56-002 R01	REPLACEMENT OF THE DV WINDOW, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
23-JUN-2004		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 56-003	WINDOWS - CABIN WINDOWS - SEALS REPLACEMENT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
27-APR-2007		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 57-001	ELECTRICAL BONDING OF FUEL TANK ACCESS COVERS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
28-FEB-1997		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SB 57-002	REPLACE THE INBOARD FLAP FAIRING SUPPORT BRACKETS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
20-MAR-1998		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 57-003 R01	INSTALLATION OF NEW WING TIPS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
	01-OCT-1998	MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 57-003 R02	INSTALLATION OF IMPROVED WING TIPS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
	23-JUN-2008	MOS HRS/MSC - AFL		29-NOV-2011			
SB 57-004	MODIFICATION OF THE FLAP INBOARD ATTACHMENT FITTINGS, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	11-JUN-1999	MOS HRS/MSC - AFL		29-NOV-2011			
SB 57-005	REPLACEMENT BOLTS FOR INBOARD FLAP SUPPORT ARM ATTACHMENT BRACKETS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
	25-MAR-2002	MOS HRS/MSC - AFL		29-NOV-2011			
SB 57-006 R03	WINGS - FLAP SUPPORTS - INSPECTION OF THE FLAP SUPPORT ARM ATTACHMENTS, SERVICE BULLETIN						COMPLIED WITH - C/W DURING JFS-007-21
	08-NOV-2018	MOS HRS/MSC - AFL		23-JUL-2021 5312.33 4590			
SB 57-006 R04	WINGS - FLAP SUPPORTS - INSPECTION OF THE FLAP SUPPORT ARM ATTACHMENTS, SERVICE BULLETIN						COMPLIED WITH
	13-JUN-2019	MOS HRS/MSC - AFL		04-JUL-2019 4174.5 3567			
SB 57-006 R05	WINGS - FLAP SUPPORTS - INSPECTION OF THE FLAP SUPPORT ARM ATTACHMENTS, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: SEE WO JFS-007-19 R1
	11-FEB-2020	MOS HRS/MSC - AFL		04-SEP-2020			
SB 57-007	WINGS - WING-TO-FUSELAGE ATTACHMENTS CORRECT INSTALLATION OF TORLON PLATES, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - COMPLIED WITH
		MOS HRS/MSC - AFL		29-APR-2022 5874.75 5112			
SB 61-002	PROPELLER ASSEMBLY - REPLACE THE FIVE-BLADED PROPELLER WITH A FOUR-BLADED PROPELLER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY A/C MSN
	27-FEB-2018	MOS HRS/MSC - AFL ACH FLTS					
SB 61-002 R01	PROPELLER ASSEMBLY - REPLACE THE FIVE-BLADED PROPELLER WITH A FOUR-BLADED PROPELLER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY A/C MSN
	28-JAN-2020	MOS HRS/MSC - AFL ACH FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 61-003	PROPELLERS - CONTROLLING - MODIFICATION TO INSTALL A FEATHER INHIBIT SWITCH, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - By Effectivity: BY ACFT MSN
	31-AUG-2020	MOS HRS/MSC - AFL ACH FLTS					
SB 71-001	MODIFICATION OF OIL COOLER GUIDE VANE ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
	15-DEC-1997	MOS HRS/MSC - AFL		29-NOV-2011			
SB 71-002	MODIFICATION OF ENGINE FIRE WIRE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
	13-JAN-1998	MOS HRS/MSC - AFL		29-NOV-2011			
SB 71-003	MODIFICATION OF THE AIR INTAKE DE-ICING LIP, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
	08-DEC-1999	MOS HRS/MSC - AFL		29-NOV-2011			
SB 71-004	INSPECTION OF THE TORQUE AND PY PRESSURE PIPES, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	22-DEC-1999	MOS HRS/MSC - AFL		29-NOV-2011			
SB 71-005 R01	REPLACEMENT OF TORQUE TRANSDUCER PIPES, SERVICE BULLETIN					RECOMMENDED	DECLINED - SB SUPERSEDED BY SB 71-007 REV 0
	21-AUG-2003	MOS HRS/MSC - AFL		29-NOV-2011			
SB 71-006	CHANGES TO THE ROUTING OF THE POWERPLANT ELECTRICAL HARNESS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
	16-SEP-2002	MOS HRS/MSC - AFL		29-NOV-2011			
SB 71-007 PART I	POWERPLANT- TORQUE OIL PRESSURE PIPE AND HOSE ASSEMBLIES-INSPECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	21-AUG-2007	MOS HRS/MSC - AFL		29-NOV-2011			
SB 71-007 PART II	POWERPLANT-TORQUE OIL PRESSURE PIPE AND HOSE ASSEMBLIES- REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
	21-AUG-2007	MOS HRS/MSC - (s) AFL		29-NOV-2011			
SB 71-008	COWLING ASSEMBLY - REPLACEMENT OF PLENUM SCREEN ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	
	06-JUN-2014	MOS HRS/MSC - AFL		20-AUG-2015	9655.58 M		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 71-008 R01	POWER PLANT - COWLING ASSEMBLY - REPLACEMENT OF PLENUM SCREEN ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - declined by executive manager decision
04-JUN-2019		MOS HRS/MSC - AFL ACH FLTS					
SB 71-008 R02	POWERPLANT - COWLING ASSEMBLY - REPLACEMENT OF PLENUM SCREEN ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	- WAITING FOR EXECUTIVE MANAGEMENT DECISION
21-AUG-2023		MOS HRS/MSC - AFL		(EFF)			
SB 71-009 R02	POWER PLANT - ENGINE MOUNTING FRAME ULTRASONIC INSPECTION OF SWAGED TUBE ENDS, SERVICE BULLETIN					MANDATORY	- APPLICABLE AT "11,000 FLYING HOURS OR 13500 LANDINGS ENGINE MOUNTING FRAME SERVICE TIME, WHICHEVER COMES FIRST" IN CONJUNCTION WITH EASA AD 2016-0081
18-MAR-2016		MOS HRS/MSC AFL	11000 13500		11000 13500	RECURRING	
SB 71-011	POWER PLANT - GENERAL - IMPROVED AIRCRAFT DISPATCH CAPABILITY FOR ENGINE AND PROPELLER ELECTRONIC CONTROL SYSTEM RELATED FAULTS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ENGINE MODEL
21-JUN-2021		MOS HRS/MSC - AFL ACH FLTS					
SB 71-012	POWER PLANT - GENERAL COMPRESSOR RINSE QUICK CONNECTION, SERVICE BULLETIN						DECLINED - APPLICABLE REFERENCE ALH CAM MAN 013
17-OCT-2021		MOS HRS/MSC AFL	12 1200	(EFF)	17-OCT-2022 ?	RECURRING ?	
SB 71-013	POWER PLANT - GENERAL - INSPECTION OF COMPRESSOR BLEED VALVE ASSEMBLY (SUPERSEDED BY 71-014), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY ENGINE S/N
23-MAR-2021		MOS HRS/MSC - AFL			06-APR-2021		
SB 71-013 R01	POWER PLANT - GENERAL - INSPECTION OF COMPRESSOR BLEED VALVE ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: ENGINE MODEL
21-APR-2021		MOS HRS/MSC - AFL			26-APR-2021		
SB 71-013 R02	POWER PLANT - GENERAL INSPECTION OF COMPRESSOR BLEED VALVE ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: BY ENGINE MODEL
12-MAY-2021		MOS HRS/MSC - AFL			14-MAY-2021		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 71-013 R03	POWER PLANT - GENERAL - INSPECTION OF COMPRESSOR BLEED VALVE ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - By Effectivity: BY ENGINE MODEL
		MOS					
		HRS/MSC					
		AFL					
		ACH					
		FLTS					
SB 71-013 R04	POWER PLANT - GENERAL - INSPECTION OF COMPRESSOR BLEED VALVE ASSEMBLY, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - By Serial- N/A BY ENGINE S/N
		MOS					
		HRS/MSC					
		AFL					
		ACH					
		FLTS					
SB 71-013 R04A	POWER PLANT - GENERAL INSPECTION OF COMPRESSOR BLEED VALVE ASSEMBLY (SUPERSEDED BY SB 71-014), SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE - By Effectivity- By engine S/N
		MOS					
		HRS/MSC	-				
		AFL					
		ACH					
		FLTS					
SB 71-014	POWER PLANT - GENERAL INSTALLATION OF P3 PROBE SNORKEL (SUPERSEDES SB 71-013), SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - Not Equipped- N/A by engine type
		MOS					
		HRS/MSC					
		AFL					
		ACH					
		FLTS					
SB 71-015	POWERPLANT - GENERAL - NEW EPECS SOFTWARE V501, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: BY ENGINE VARIANT
		MOS			09-NOV-2023		
		HRS/MSC	-				
		AFL					
SB 71-015 R01	POWERPLANT - GENERAL - NEW EPECS SOFTWARE V501, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: BY ENGINE VARIANT
		MOS			13-NOV-2023		
		HRS/MSC	-				
		AFL					
SB 72-001	ENGINE TORQUE LIMITER ADJUSTMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS			30-NOV-2011		
		HRS/MSC	-				
		AFL					
SB 72-002	FUEL CONTROL UNIT REPLACEMENT, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
		MOS			30-NOV-2011		
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 72-003	ENGINE- REDUCTION GEARBOX FIRST STAGE CARRIER - REPLACE BOLTS - P&WC SERVICE BULLETIN NO. 14444, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY RANGE ACTION NO OVERHAUL NO REPAIR PERFORMED BEFORE 4TH SEPT. 2010
11-JAN-2011		MOS		30-NOV-2011			
		HRS/MSC -		0			
		AFL					
SB 72-004	ENGINE - INSPECTION OF FUEL NOZZLE ASSEMBLY - P&WC SERVICE BULLETIN NO. 14357R1, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - NOT CONCERNED BY PREFIX
		MOS		26-OCT-2013			
		HRS/MSC -		713.83			
		AFL		550			
SB 72-005	ENGINE - INSPECTION OF FUEL NOZZLE TIPS - P&WC SERVICE BULLETIN NO. 14495, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - NEW SET NOZZLE INCORPORATED WITH SB INCLUDED
18-DEC-2014		MOS		11-JUN-2015			
		HRS/MSC -		1588.17			
		AFL		1296			
SB 72-006	POWER TURBINE - SECOND STAGE - INSPECTION/REPLACEMENT OF BLADES - P&WC SERVICE BULLETIN NO. 14511, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY (ENGINE'S SERIAL NUMBER NOT CONCERNED)
07-DEC-2015		MOS		16-DEC-2015			
		HRS/MSC -					
		AFL					
SB 73-001	FUEL CONTROL UNIT REPLACEMENT AND ENGINE CONTROL RIGGING, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
20-FEB-1997		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
SB 73-002	ENGINE FUEL AND CONTROL - ELECTRONIC ENGINE CONTROL INSTALLATION OF A HARNESS SPACER ON EEC CABLES , SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT S/N
25-JAN-2021		MOS		26-FEB-2021			
		HRS/MSC -					
		AFL					
SB 74-001	RE-ROUTING OF THE IGNITION CABLES (REF. P&WC SB 14255), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
29-JAN-1998		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
SB 76-001	POWER CONTROL-INTRODUCTION OF GUARD FOR THE ENGINE CONDITION LEVER, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
03-OCT-2003		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
SB 76-002	ENGINE CONTROLS - POWER CONTROL - CHECK THE POWER CONTROL LEVER REVERSE THRUST LATCH FOR STICKING, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					
SB 76-002 PART 1	CHECK ENGINE CONTROLS - POWER CONTROL - CHECK THE POWER CONTROL LEVER REVERSE THRUST LATCH FOR STICKING, SERVICE BULLETIN REVERSE THRUST LATCH FOR STICKING					MANDATORY	NOT APPLICABLE
		MOS		30-NOV-2011			
		HRS/MSC -					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 76-002 PART 2	MODIFY ENGINE CONTROLS - POWER CONTROL - CHECK THE POWER CONTROL LEVER REVERSE THRUST LATCH FOR STICKING, SERVICE BULLETIN ENGINE CONSOLE ASSEMBLY	MOS HRS/MSC - AFL		30-NOV-2011		MANDATORY	NOT APPLICABLE
SB 76-002 R01	ENGINE CONTROLS - POWER CONTROL - CHECK THE POWER CONTROL LEVER REVERSE THRUST LATCH FOR STICKING, SERVICE BULLETIN	MOS HRS/MSC - AFL		30-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
SB 76-002 R01 PART 1	CHECK ENGINE CONTROLS - POWER CONTROL - CHECK THE POWER CONTROL LEVER REVERSE THRUST LATCH FOR STICKING, SERVICE BULLETIN THE POWER CONTROL LEVER (PCL) REVERSE THRUST LATCH FOR STICKING	MOS HRS/MSC - AFL		30-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
SB 76-002 R01 PART 2	MODIFY ENGINE CONTROLS - POWER CONTROL - CHECK THE POWER CONTROL LEVER REVERSE THRUST LATCH FOR STICKING, SERVICE BULLETIN THE POWER CONTROL LEVER ASSEMBLY	MOS HRS/MSC - AFL		30-NOV-2011		MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
SB 77-001 R01	INSTALLATION OF ENGINE TREND CHECK SYSTEM, SERVICE BULLETIN	MOS HRS/MSC - AFL		30-NOV-2011	09-MAR-1999	OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
SB 77-002 R01	EIS WIRING, SERVICE BULLETIN	MOS HRS/MSC - AFL		31-JAN-2012 5 5	01-JAN-2002	RECOMMENDED	NOT APPLICABLE
SB 77-002 R02	ENGINE - INDICATION - INSTALLATION OF AN ADDITIONAL WIRE, SERVICE BULLETIN	MOS HRS/MSC A/R AFL		30-NOV-2011		RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
SB 77-003	MODIFICATION OF THE EIS WIRING, SERVICE BULLETIN	MOS HRS/MSC - AFL		30-NOV-2011	25-NOV-1999	RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
SB 77-004	ENGINE INDICATING - INTEGRATED ENGINE INSTRUMENT SYSTEMS - REPLACE THE TORQUE TRANSDUCER ELECTRICAL CONNECTOR AND BACKSHELL, SERVICE BULLETIN	MOS HRS/MSC - AFL			07-JAN-2019	OPTIONAL	- SUPERSEDED BY R01
SB 77-004 R01	ENGINE INDICATING - INTEGRATED ENGINE INSTRUMENT SYSTEMS - REPLACE THE TORQUE TRANSDUCER ELECTRICAL CONNECTOR AND BACKSHELL, SERVICE BULLETIN	MOS HRS/MSC - AFL		(EFF)	08-NOV-2019	OPTIONAL	- THIS SB WILL BE DONE WHEN AIRCRAFT WILL BE IN AOG INDICATOR

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 77-006	ENGINE INDICATING - TORQUE LIMITER IMPROVEMENTS TO THE TORQUE LIMITER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SEE WO JFS-SM1-23R2 RTS 06/04/2023
17-FEB-2022		MOS HRS/MSC - AFL		06-APR-2023 6490.58 5656			
SB 79-001	OIL COOLER SUPPORT BRACKET - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
22-NOV-1996		MOS HRS/MSC - AFL		30-NOV-2011			
SB 79-002	MODIFICATION OF OIL COOLER SHROUD, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
13-OCT-1998		MOS HRS/MSC - AFL		30-NOV-2011			
SB 79-003 R01	REPLACEMENT OF OIL COOLER THERMAL ACTUATOR, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
18-JUN-2001		MOS HRS/MSC - AFL		30-NOV-2011			
SB 79-004 R01	REPLACEMENT OF THE OIL PRESSURE TRANSDUCER, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY MSN EFFECTIVITY
27-MAY-2002		MOS HRS/MSC - AFL		30-NOV-2011			
SB 79-005 R01	INSTALLATION OF A CHIP DETECTOR IN THE ACCESSORY GEARBOX, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
20-AUG-2001		MOS HRS/MSC - AFL		31-JAN-2012 5 5			
SB 79-005 R02	OIL - INDICATING - INTRODUCTION OF CHIP DETECTOR IN ENGINE ACCESSORY GEARBOX, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
02-JUL-2008		MOS HRS/MSC - AFL		29-NOV-2011			
SB 79-005 R03	OIL - INDICATING INTRODUCTION OF CHIP DETECTOR IN ENGINE ACCESSORY GEARBOX, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
05-DEC-2012		MOS HRS/MSC - AFL		15-MAY-2014 1034.25 834			
SB 79-006 R02	OIL - OIL DEBRIS MONITORING (ODM) SYSTEM DISABLING OR REMOVAL OF THE ODM SYSTEM, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
29-MAR-2010		MOS HRS/MSC - AFL		29-NOV-2011			
SB 79-006 R03	OIL - OIL DEBRIS MONITORING (ODM) SYSTEM - DISABLING OR REMOVAL OF THE ODM SYSTEM, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
14-MAR-2016		MOS HRS/MSC - AFL		06-APR-2016			
SB 79-007 R01	OIL - OIL DEBRIS MONITORING (ODM) SYSTEM DISABLING OR REMOVAL OF THE ODM SYSTEM, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
24-SEP-2009		MOS HRS/MSC - AFL		29-NOV-2011			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 79-007 R01 PARA I	DISABLE OIL - OIL DEBRIS MONITORING (ODM) SYSTEM DISABLING OR REMOVAL OF THE ODM SYSTEM, SERVICE BULLETIN ODM SYSTEM (REF. PARA. 3.)					RECOMMENDED	NOT APPLICABLE - BY MSN EFFECTIVITY
24-SEP-2009		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 79-007 R01 PARA II	REMOVE OIL - OIL DEBRIS MONITORING (ODM) SYSTEM DISABLING OR REMOVAL OF THE ODM SYSTEM, SERVICE BULLETIN ODM SYSTEM (REF. PARA. 4.)					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
24-SEP-2009		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 80-001	INSTALLATION OF AUTOMATIC START UNIT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
06-NOV-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SB 80-001 R01	INSTALLATION OF AUTOMATIC START UNIT, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY MSN EFFECTIVITY
03-JAN-2006		MOS		29-NOV-2011			
		HRS/MSC -					
		AFL					
SL 095	AIR CONDITIONING - AUXILIARY VOLUME TANK, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE
20-JUL-2006		MOS		29-NOV-2011			
		HRS/MSC A/R		0			
		AFL		0			
SL 119	HARTZELL PROPELLER INC. SERVICE LETTER (SL) HC-SL-30-283 REVISION 1, SERVICE LETTER					CANCELLED	NOT APPLICABLE - CANCELLED
12-APR-2008		MOS					
		HRS/MSC -					
		AFL					
SL 120	INTERTECHNIQUE SERVICE INFORMATION LETTER (SIL) 69, SERVICE LETTER					MANDATORY	NOT APPLICABLE - INFORMATION ONLY
02-JUN-2008		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SL 123	GOODRICH POWER SYSTEMS DC STARTER/GENERATOR SERVICE BULLETINS 23085025-24-1 AND 23085-024-24-01, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE
08-SEP-2008		MOS		31-JAN-2012			
		HRS/MSC -		5			
		AFL		5			
SL 165	HONEYWELL KTA 2810 TRIM ADAPTOR RELIABILITY IMPROVEMENT, SERVICE LETTER					INFORMATIONAL	COMPLIED WITH
15-JUN-2012		MOS		05-MAR-2013			
		HRS/MSC -		306.58			
		AFL		243			
SL 192	TORQUE TRANSDUCER OIL PRESSURE PIPE INSTALLATION, SERVICE LETTER						COMPLIED WITH
20-APR-2017		MOS		06-JUL-2017			
		HRS/MSC -		2886.25			
		AFL		2474			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 193	AEROWAVE 100 HIGH-SPEED DATA UNIT (HDU) UPGRADE AVAILABLE, SERVICE LETTER					RECOMMENDED	- see sb 23-010 r1
		MOS		(EFF)			
	28-AUG-2017	HRS/MSC -					
		AFL					
SL 194	ELECTRICAL LOAD ANALYSIS FOR SHOWING COMPLIANCE WITH PART 135.163(F)(2), SERVICE LETTER						NOT APPLICABLE - By Serial: N/A BY MSN
		MOS					
	01-SEP-2017	HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SL 197	PRATT & WHITNET CANADA (P&WC) SERVICE INFORMATION LETTER (SIL) NO. PT6A-239 R01, SERVICE LETTER						COMPLIED WITH - SEE WO JFS-004-18
		MOS		23-FEB-2018			
	22-JAN-2018	HRS/MSC -		3297.08			
		AFL		2817			
SL 200	REVISED MAINTENANCE PROGRAM ISSUED WITH AMM DOC. NO. 02049 REVISION 36 AND AMM DOC. NO. 02300 REVISION 19, SERVICE LETTER						COMPLIED WITH - INFORMATIONAL ONLY: TAKE INTO ACCOUNT IN JETFLY MAINTENANCE PROGRAM
		MOS		20-JUN-2018			
	14-JUN-2018	HRS/MSC -		3539			
		AFL		3014			
SL 201	INCORRECT FUSE RATINGS GIVEN IN THE ELECTRICAL LOAD ANALYSIS DOCUMENT, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
		MOS					
	25-JUN-2019	HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SL 202	INTRODUCTION OF NEW PROPELLER DE-ICE BOOTS, SERVICE LETTER						NOT APPLICABLE - By Effectivity: 4 bladed propellers.
		MOS					
	31-OCT-2019	HRS/MSC -					
		AFL					
		ACH					
		FLTS					
SL 203	CHANGE OF PROPELLER GREASE TYPE TO NYCO GN-3058, SERVICE LETTER						COMPLIED WITH - INFORMATIONAL ONLY: INFORMATION RELAYED TO SERVICE CENTER
		MOS		12-MAR-2020			
	03-FEB-2020	HRS/MSC -					
		AFL					
SL 205	REQUIREMENT TO ACCOMPLISH THE AIRCRAFT WEIGHING PROCEDURE TO CORRECT WEIGHT AND BALANCE DATA, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
		MOS					
	25-MAY-2020	HRS/MSC -					
		AFL					
		ACH					
		FLTS					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 205 R01	REQUIREMENT TO ACCOMPLISH THE AIRCRAFT WEIGHING PROCEDURE TO CORRECT WEIGHT AND BALANCE DATA, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - By Effectivity: BY ACFT MSN
08-JUN-2020		MOS HRS/MSC - AFL ACH FLTS					
SL 206	PILATUS RECOMMENDATION TO PREVENT CONTAMINATION OF THE AIRCRAFT FUEL TANKS WITH WATER AND BIOLOGICAL CONTAMINATION, SERVICE LETTER					RECOMMENDED	COMPLIED WITH - INFORMATIONAL ONLY: SL206 SEND TO FLEET MANAGER PC12 AND SERVICE CENTER PC12.
19-AUG-2020		MOS HRS/MSC - AFL		04-SEP-2020			
SL 207	INSPECTION OF THE WING AND FUSELAGE ATTACHMENT FITTINGS, SERVICE LETTER						COMPLIED WITH - COMPLIED WITH
25-NOV-2020		MOS HRS/MSC - AFL		29-APR-2022 5874.75 5112			
SL 208	NEW REPAIR FOR CABIN WINDOW SHADE ASSEMBLIES - SPRING DAMPENING, SERVICE LETTER						- NFA - FOR INFORMATION ONLY
10-DEC-2020		MOS HRS/MSC - AFL		(EFF)			
SL 209	PCL BELOW IDLE FAULT (BETA RANGE), SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - BY A/C MSN - FOR ALL PC-12/47E AIRCRAFT MSN 1720, 2001 AND UP
14-DEC-2020		MOS HRS/MSC - AFL		(EFF)			
SL 210	ENGINE AND PROPELLER ELECTRONIC CONTROL SYSTEM EXCEEDANCES, SERVICE LETTER						NOT APPLICABLE - BY EFFECTIVITY: BY AIRCRAFT MSN
17-DEC-2020		MOS HRS/MSC - AFL		04-JAN-2021			
SL 211	NOSE WHEEL - GREASE SEAL INCORRECTLY INSTALLED, SERVICE LETTER						- INFORMATION ONLY
21-JAN-2021		MOS HRS/MSC - AFL		(EFF)			
SL 212	ELECTRICAL WIRING SCHEMATIC DIAGRAM CORRECTION, SERVICE LETTER						COMPLIED WITH - INFORMATIONAL ONLY: TO ALL CUSTOMERS, OPERATORS AND SERVICE CENTERS
30-APR-2021		MOS HRS/MSC - AFL		12-MAY-2021			
SL 213	ENGINE COMPRESSOR BLEED OFF VALVE - POSSIBLE TORQUE REDUCTION, SERVICE LETTER						- INFORMATION ONLY
17-JUN-2021		MOS HRS/MSC - AFL		(EFF)			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 214	PC-12 COMPLIANCE TO CAT.OP.MPA.303: LANDING DISTANCE AT TIME OF ARRIVAL, SERVICE LETTER						- INFORMATION FOWARDED TO NPFO
	10-AUG-2021	MOS HRS/MSC - AFL		(EFF)			
SL 215	FUEL PRESSURE LOW CAUTION, SERVICE LETTER						NOT APPLICABLE - By Effectivity: BY ACFT MSN
	20-AUG-2021	MOS HRS/MSC - AFL ACH FLTS					
SL 216	HONEYWELL AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) IMPROVED RELIABILITY, SERVICE LETTER						COMPLIED WITH - INFORMATIONAL ONLY: HONEYWELL AIR DATA, ATTITUDE AND HEADING REFERENCE SYSTEM (ADAHRS) IMPROVED RELIABILITY
	20-SEP-2021	MOS HRS/MSC - AFL			23-SEP-2021		
SL 217	REPAIR OF PRODUCTS MANUFACTURED BY REVUE THOMMEN, THOMMEN AIRCRAFT EQUIPMENT AND SATHOM, SERVICE LETTER						NOT APPLICABLE - By Effectivity: NOT FOR PC1247/E
	06-OCT-2021	MOS HRS/MSC - AFL ACH FLTS					
SL 218	INTRODUCTION OF A NEW FUEL TANK DRAIN VALVE, SERVICE LETTER						- Informational Only - INFORMATION RELAYED TO SERVICE CENTER
	15-NOV-2021	MOS HRS/MSC - AFL		(EFF)			
SL 219	FORMAT AND STYLE CHANGES TO AIRCRAFT MAINTENANCE MANUAL CHAPTERS 04 AND 05, SERVICE LETTER						- Informational Only - TAKEN IN JETFLY AMP NEXT REVISION
	29-NOV-2021	MOS HRS/MSC - AFL		(EFF)			
SL 220	PILATUS RECOMMENDATION TO PREVENT CONTAMINATION OF THE AIRCRAFT FUEL TANKS WITH WATER AND BIOLOGICAL CONTAMINATION, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY SL 242. N/A BY A/C MSN
	31-AUG-2022	MOS HRS/MSC - AFL			15-SEP-2022		
SL 221	PILATUS RECOMMENDATION TO PREVENT CONTAMINATION OF THE AIRCRAFT FUEL TANKS WITH WATER AND BIOLOGICAL CONTAMINATION, SERVICE LETTER					RECOMMENDED	- INFORMATION ONLY
	31-AUG-2022	MOS HRS/MSC - AFL		(EFF)			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 222	CHANGE OF AIRCRAFT REGISTRATION (SUPERSEDES SL-177), SERVICE LETTER						- SUPERSEDED BY SL 238 INFORMATIONAL ONLY - CHANGE OF AIRCRAFT REGISTRATION
		MOS HRS/MSC - AFL		(EFF)			
27-JAN-2022							
SL 223	REPLACEMENT OF THE UPPER ENGINE PLENUM WITH LARGER ACCESS HOLES, SERVICE LETTER						DECLINED - DECLINED BY EXECUTIVE MANAGEMENT
		MOS HRS/MSC - AFL		(EFF)			
09-FEB-2022							
SL 224	EMERGENCY EXIT MARKINGS, SERVICE LETTER						- DECLINED BY EXECUTIVE MANAGER DECISION REGARDING COLOR OF PASSENGER DOOR CONTINUOUS BAND MARKING
		MOS HRS/MSC - AFL			12-SEP-2023		
22-FEB-2022							
SL 225	INFORMATION ON THE MULTI-MODE DIGITAL RADIO 2, SERVICE LETTER						NOT APPLICABLE - By Effectivity- BY ACFT MSN
		MOS HRS/MSC - AFL ACH FLTS					
25-FEB-2022							
SL 226	INFORMATION ON THE MULTI-MODE DIGITAL RADIO 2 (SUPERSEDES SL-225), SERVICE LETTER						NOT APPLICABLE - By Effectivity- Effectivity: PC-12/47E Series Aircraft MSN 1720, 2001 and Up
		MOS HRS/MSC - AFL ACH FLTS					
31-MAR-2022							
SL 227	INFORMATION ON THE MULTI-MODE DIGITAL RADIO 2 (SUPERSEDES SL-226) (SUPERSEDED BY SL 230), SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - BY SERIAL- N/A. SUPERSEDED BY SL 230
		MOS HRS/MSC - AFL ACH FLTS					
05-JUL-2022							
SL 228	IDENTIFICATION OF THE NOSE LANDING GEAR (NLG) RH DRAG LINK ASSEMBLY, SERVICE LETTER						COMPLIED WITH - INFORMATIONAL ONLY - PN FITTED 532.20.12.289 OR 532.20.12.296 (2022-09-07) - PN FITTED P/N 532.20.12.296 = 200.5 MM, REFER TO PICTURE
		MOS HRS/MSC - AFL		(EFF)			
06-JUL-2022							

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 229	OPERATION UNDER EASA PART-CAT FOR PC-12/47E AIRCRAFT WITH A CERTIFICATE OF AIRWORTHINESS ON OR AFTER 5 SEPTEMBER 2022, SERVICE LETTER						NOT APPLICABLE - BY EFFECTIVITY: APPLICABLE TO PC-12 AIRCRAFT THAT ARE FIRST ISSUED WITH AN INDIVIDUAL CERTIFICATE OF AIRWORTHINESS ON OR AFTER 5 SEPTEMBER 2022.
05-SEP-2022		MOS HRS/MSC - AFL			29-SEP-2022		
SL 230	INFORMATION ON THE MULTI-MODE DIGITAL RADIO 2 (SUPERSEDES SL-227), SERVICE LETTER						NOT APPLICABLE - BY EFFECTIVITY: N/A BY A/C MSN
15-NOV-2022		MOS HRS/MSC - (s) AFL			17-NOV-2022		
SL 231	HARTZELL PROPELLER INC. ALERT SERVICE BULLETIN (ASB) HC-ASB-61-399, SERVICE LETTER						NOT APPLICABLE - JETFLY FLEET NOT OVERHAULED BY CHINA FLYING DRAGON GENERAL AVIATION
19-DEC-2022		MOS HRS/MSC - AFL			23-DEC-2022		
SL 232	SUSTAINABLE AVIATION FUEL, SERVICE LETTER						NOT APPLICABLE - BY SERIAL: BY AIRCRAFT MSN. (PC-12 SERIES AIRCRAFT MSN 101 THRU 544, 546 THRU 888 APPLICABLE ONLY)
19-DEC-2022		MOS HRS/MSC - AFL			02-JAN-2023		
SL 233	GROUND SERVICE GUIDE, SERVICE LETTER						- INFORMATION ONLY
19-DEC-2022		MOS HRS/MSC - AFL		(EFF)			
SL 234	ICAO FLIGHT PLAN 2012 (SUPERSEDES SL 167), SERVICE LETTER						- Informational Only - SERVICE LETTER SHARED WITH FLIGHT OPERATION DEPARTMENT
28-APR-2023		MOS HRS/MSC - AFL		(EFF)			
SL 235	OPERATION UNDER EASA PART-CAT FOR PC-12/47E AIRCRAFT WITH A CERTIFICATE OF AIRWORTHINESS ON OR AFTER 5 SEPTEMBER 2022 - SUPERSEDES SL 229, SERVICE LETTER						NOT APPLICABLE - N/A - CA ISSUED BEFORE 2022-09-05 AND EQUIPMENT NOT FITTED - APEX OPERATIONAL SOFTWARE AT BUILD 10.14 (BUILD 11.1) (2023-06-12). REFER TO SB 45-016
04-MAY-2023		MOS HRS/MSC - AFL			12-JUN-2023		
SL 236	OPTION FOR ADS-B IN TRAFFIC (CDTI), SERVICE LETTER						- Informational Only - EQUIPMENT FITTED: 1. TWO MODE S XPDR ADSB OUT (EXTERNAL CDTI BENEFICIAL IN THE US)
05-MAY-2023		MOS HRS/MSC - AFL		(EFF)			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 238	CHANGE OF AIRCRAFT REGISTRATION (SUPERSEDES SL-222), SERVICE LETTER						- Informational Only - SL TO BE FOLLOWED WHEN THE CHANGE OF OPERATOR/OWNER IS PERFORMED
06-JUL-2023		MOS HRS/MSC - AFL		(EFF)			
SL 239	MULTI-MODE DIGITAL RADIO 2 - DATALINK REACTIVATION (SUPERSEDES SL-230), SERVICE LETTER						NOT APPLICABLE - BY SERIAL: BY A/C MSN - PC-12/47E SERIES AIRCRAFT MSN 1720, MSN 2001 THRU MSN 2260, AND MSN 2265 THRU MSN 2288 THAT HAVE THE VHF DATALINK FACTORY OPTION INSTALLED.
06-JUL-2023		MOS HRS/MSC - AFL			20-JUL-2023		
SL 240	MAIN LANDING GEAR YOKE FITTING OVERHAUL THRESHOLD CHANGE, SERVICE LETTER						- Informational Only - INFO ONLY - HYDRAULIC LDG FITTED - CHANGES INCORPORATED IN AMM REV.31 AND WILL BE MODIFIED IN NEXT AMP - PUBLICATION TRANSFERRED TO PPC FOR EVALUATION AND EDITION OF AMP - FH: 6753:30 AFL:5887 (CHECKED 2023-10-18)
10-AUG-2023		MOS HRS/MSC - AFL		(EFF)			
SL 241	PARKER BRAKE CONDITIONING/RECONDITIONING, SERVICE LETTER					RECOMMENDED	- Informational Only - SL FORWARDED TO PART-145, MCC AND NPFO
29-SEP-2023		MOS HRS/MSC - AFL		(EFF)			
SL 242	PILATUS RECOMMENDATION TO PREVENT CONTAMINATION OF THE AIRCRAFT FUEL TANKS WITH WATER AND BIOLOGICAL CONTAMINATION (SUPERSEDES SL 220), SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - BY EFFECTIVITY: BY A/C MSN
06-DEC-2023		MOS HRS/MSC - AFL			14-DEC-2023		
SL 243	REPLACEMENT OF CHIP DETECTOR AND SELF-CLOSING VALVE (P&WC SB 75032), SERVICE LETTER						NOT APPLICABLE - BY EFFECTIVITY: N/A BY A/C MSN
21-DEC-2023		MOS HRS/MSC - AFL			11-JAN-2024		
SL 244	PROPELLER ASSEMBLY - FAA SPECIAL AIRWORTHINESS INFORMATION BULLETIN SAIB-2023-04, SERVICE LETTER						- JETFLY PC-12 FLEET IS NOT IMPACTED AS THE JETFLY FLEET PROPELLERS, NOR THE LOANER WERE MAINTAINED OR OH AT SPECIALIZED PROPELLER SERVICES LLC.
06-FEB-2024		MOS HRS/MSC - AFL		(EFF)			
SL 245	MULTI-MODE DIGITAL RADIO 2 - DATALINK REACTIVATION (SUPERSEDES SL-239), SERVICE LETTER						NOT APPLICABLE - BY EFFECTIVITY: BY A/C MSN
06-FEB-2024		MOS HRS/MSC - AFL			19-MAR-2024		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL 246	IMPROVED ENGINE AIR INTAKE COVER, SERVICE LETTER						- Informational Only - WAITING FOR MANAGEMENT DECISION
14-FEB-2024		MOS HRS/MSC - AFL		(EFF)			
SL 247	ENGINE - 2ND STAGE POWER TURBINE (PT2) BLADE FAILURE (TCCA AD CF-2024-05), SERVICE LETTER						- Informational Only - REFER TO ENGINE TCCA AD CF-2024-05, EASA AD CF-2024-05, FAA AD 2024-04-51-E AND ASB SB A75036 AND SB A14574 FOR ACTION PERFORMED.  SL APPLIES TO PC12 EQUIPPED WITH PT6 ENGINES
16-FEB-2024		MOS HRS/MSC - AFL		(EFF)			
SL 248	WIRELESS DATA LOADING SYSTEM - CG100 AND CG200 ASPEN ROUTER UPGRADE, SERVICE LETTER						- INFORMATION ONLY
02-APR-2024		MOS HRS/MSC - AFL		(EFF)			
SL 249	U.S. REGISTERED AIRCRAFT OPERATING UNDER 14 CFR 91 OR 135, SERVICE LETTER						NOT APPLICABLE - N/A BY STATE OF REGISTRY
02-MAY-2024		MOS HRS/MSC - AFL			21-MAY-2024		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 1 - AD - PCE-RY0331/3072955-01</b>							
FAA 1997-04-12	NO. 1 ENGINE - ENGINE - COMPRESSOR BLEED-VALVES (BOV'S) - INSPECT / REPLACE						COMPLIED WITH - AT MANUFACTURE
14-MAR-1997		MOS HRS/MSC - AFL ENC		31-JAN-2012 5 5			
FAA 2024-04-51	NO. 1 ENGINE - SECOND-STAGE POWER TURBINE (PT2) BLADE FAILURE					MANDATORY	- N/A - FITTED EQUIP. IS NOT AFFECTED - PT2 BLADES ARE NOT AFFECTED AS PER SB CRITERIA. THE MCAI APPLIES TO P&WC MODEL PT6A-66T, PT6A-68B, PT6A-68C, AND PT6A-68T ENGINES, BUT THIS EMERGENCY AD DOES NOT AS THESE ENGINES ARE NOT U.S. TYPE-CERTIFICATED"
39-22694 28-MAR-2024		MOS HRS/MSC BF/F ENC AFL		(EFF)			
FAA 2024-04-51-E	NO. 1 ENGINE - EMERGENCY AD - SECOND-STAGE POWER TURBINE (PT2) BLADE FAILURE					MANDATORY	- NFA - NO FURTHER ACTION REQ'D - REQ'T FOLLOWED VIA AD CF-2024-05
16-FEB-2024		MOS HRS/MSC DUE ENC AFL		(EFF)			
TCCA CF-1996-24	NO. 1 ENGINE - COMPRESSOR BLEED-OFF VALVE COVER ASSEMBLY INSPECTION/REPLACEMENT					MANDATORY	NOT APPLICABLE
05-DEC-1996		MOS HRS/MSC - ENC		30-NOV-2011			
TCCA CF-1996-24 R01	NO. 1 ENGINE - COMPRESSOR BLEED-OFF VALVE COVER ASSEMBLY INSPECTION/ REPLACEMENT					CANCELLED	NOT APPLICABLE
13-JUN-2008		MOS HRS/MSC - ENC		30-NOV-2011			
TCCA CF-2002-04	NO. 1 ENGINE - PRATT & WHITNEY CANADA - INSPECTION OF FUEL CONTROL UNIT						NOT APPLICABLE - N/A BY P/N
28-FEB-2002		MOS HRS/MSC - ENC		30-NOV-2011			
TCCA CF-2019-05	NO. 1 ENGINE - ENGINE CONTROL - FUEL CONTROL UNIT (FCU) GALVANIC CORROSION CONTAMINATION					MANDATORY	NOT APPLICABLE - By Effectivity: BY ENGINE MODEL
19-FEB-2019		MOS HRS/MSC - ENC					
TCCA CF-2024-05-E	NO. 1 ENGINE - EMERGENCY AD - SECOND-STAGE POWER TURBINE (PT2) BLADE FAILURE					MANDATORY	- NONE OF THE AFFECTED PT2 BLADES SUSPECTED SERIAL NUMBERS ARE INSTALLED ON THIS ENGINE IAW SB PT6A-72-A14574 (C/W)
16-FEB-2024		MOS HRS/MSC - ENC AFL		(EFF)			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
TCCA CF-2024-33	NO. 1 ENGINE - ENGINE – FIRST-STAGE POWER TURBINE (PT1) BLADE FAILURE					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY: CURRENTLY INSTALLED PT1 TURBINE BLADES IDENTIFIED WITH THE FOLLOWING P/N: 3118911-01, THIS SB IS APPLICABLE TO THE PT6A-67B/P, BUT NOT APPLICABLE TO THE JFA PT6-67B/P FLEET.
30-SEP-2024		MOS HRS/MSC - ENC		(EFF)			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 1 - SB - PCE-RY0331/3072955-01</b>							
ASB PT6A-72-A14305	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
		MOS		31-JAN-2012			
13-APR-2000		HRS/MSC -		5			
		ENC		5			
ASB PT6A-72-A14305 R01	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
		MOS		01-MAR-2015			
01-AUG-2000		HRS/MSC -		1440.83			
		ENC		1182			
ASB PT6A-72-A14371	NO. 1 ENGINE - REPLACEMENT OF TURBOPROP ENGINE FUEL CONTROL UNIT, ALERT SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
15-APR-2005		HRS/MSC -		5			
		ENC		5			
ASB PT6A-72-A14371 R01	NO. 1 ENGINE - REPLACEMENT OF TURBOPROP ENGINE FUEL CONTROL UNIT, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
ASB PT6A-72-A14410	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
		MOS					
06-SEP-2007		HRS/MSC - (s)					
		ENC					
ASB PT6A-72-A14410 R01	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
		MOS					
20-SEP-2007		HRS/MSC -					
		ENC					
ASB PT6A-72-A14410 R02	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
		MOS		01-MAR-2015			
18-FEB-2014		HRS/MSC -		1440.83			
		ENC		1182			
ASB PT6A-72-A14574	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF SECOND-STAGE POWER-TURBINE BLADES, ALERT SERVICE BULLETIN					CATEGORY 1	- AT SB ISSUE, 13/02/2024, THE ENGINE HAS MORE THAN 50 FLIGHT HOURS TOTAL TIME SINCE NEW OR TOTAL TIME SINCE SHOP VISIT OR TOTAL TIME SINCE SECOND-STAGE POWER TURBINE (PT2) REPAIR. ENGINE IS NOT IMPACTED ENGINE TOTAL TIME SINCE NEW: 6127.58 FH TIME SINCE OVERHAUL: 2244 FH PT2 TIME SINCE REPAIR: 0 HRS
		MOS		(EFF)			
13-FEB-2024		HRS/MSC BF/F					
		ENC					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASB PT6A-72-A14574 R01	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF SECOND-STAGE POWER-TURBINE BLADES, ALERT SERVICE BULLETIN					CATEGORY 1	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: THIS REVISION IS ISSUED TO: CORRECT A TYPO FOR THE BLADE SERIAL NUMBER RANGE, SHOULD READ TH45F128 TO TH45F704 IN LIEU OF TH45F128 TO THF45F704. NO EFFET TO COMPLIANCE OFF PREVIOUS REVISION
20-FEB-2024		MOS HRS/MSC - ENC		23-FEB-2024			
ASB PT6A-72-A14575	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF SINGLE-ENGINE APPLICATION FIRST-STAGE PT BLADES, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY: CURRENTLY INSTALLED PT1 TURBINE BLADES IDENTIFIED WITH THE FOLLOWING P/N: 3118911-01, THIS SB IS APPLICABLE TO THE PT6A-67B/P, BUT NOT APPLICABLE TO THE JFA PT6-67B/P FLEET.
13-JUN-2024		MOS HRS/MSC - ENC		19-JUN-2024			
ASB PT6A-72-A14575 R01	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF SINGLE-ENGINE APPLICATION FIRST-STAGE PT BLADES, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY: CURRENTLY INSTALLED PT1 TURBINE BLADES IDENTIFIED WITH THE FOLLOWING P/N: 3118911-01, THIS SB IS APPLICABLE TO THE PT6A-67B/P, BUT NOT APPLICABLE TO THE JFA PT6-67B/P FLEET.
17-JUL-2024		MOS HRS/MSC - ENC		19-JUN-2024			
SB PT6A-72-14000 R07	NO. 1 ENGINE - OMNIBUS SERVICE BULLETIN, SERVICE BULLETIN					CATEGORY 11	COMPLIED WITH - AT MANUFACTURE
25-JAN-2008		MOS HRS/MSC - ENC		28-SEP-2015 1819.92 1496			
SB PT6A-72-14001 R19	NO. 1 ENGINE - TURBOPROP ENGINE APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH - CONSUMABLE USE BY JETFLY BP TURBO OIL 2380
11-MAY-2016		MOS HRS/MSC - ENC		12-MAY-2016			
SB PT6A-72-14001 R20	NO. 1 ENGINE - TURBOPROP ENGINE APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - CONSUMABLE USE BY JETFLY BP TURBO OIL 2380
05-MAY-2020		MOS HRS/MSC - ENC AFL					
SB PT6A-72-14002	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
27-MAR-1987		MOS HRS/MSC - ENC		31-JAN-2012 5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14002 R01	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
19-JAN-1988		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R02	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
13-JUN-1988		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R03	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
01-JUN-1989		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R04	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
04-JUN-1990		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R05	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
08-MAR-1991		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R06	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R07	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
22-SEP-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R08	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
20-SEP-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R09	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
03-OCT-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R10	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
07-NOV-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14002 R11	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN						COMPLIED WITH - TAKE IN ACCOUNT IN AMP
17-FEB-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	PT6A-72-14002 R12	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN					COMPLIED WITH - TAKE IN ACCOUNT IN AMP
	25-OCT-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB	PT6A-72-14002 R13	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN					COMPLIED WITH - TAKE IN ACCOUNT IN AMP
	28-MAY-2004	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB	PT6A-72-14002 R14	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN					COMPLIED WITH - TAKE IN ACCOUNT IN AMP
	07-DEC-2004	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB	PT6A-72-14002 R15	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN					COMPLIED WITH - TAKE IN ACCOUNT IN AMP
	29-SEP-2005	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB	PT6A-72-14002 R16	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS, SERVICE BULLETIN					COMPLIED WITH - TAKE IN ACCOUNT IN AMP
	01-DEC-2005	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB	PT6A-72-14002 R18	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS , SERVICE BULLETIN					COMPLIED WITH - TAKE IN ACCOUNT IN AMP
	18-OCT-2007	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB	PT6A-72-14002 R20	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS , SERVICE BULLETIN					COMPLIED WITH - TAKE IN ACCOUNT IN AMP
	21-APR-2010	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB	PT6A-72-14002 R23	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS , SERVICE BULLETIN					COMPLIED WITH - SB IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
	20-AUG-2015	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB	PT6A-72-14002 R24	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS , SERVICE BULLETIN					COMPLIED WITH - SB IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
	22-FEB-2017	MOS		27-FEB-2017			
		HRS/MSC -					
		ENC					
SB	PT6A-72-14002 R25	NO. 1 ENGINE - SERVICE LIFE - ROTOR COMPONENTS , SERVICE BULLETIN					COMPLIED WITH - SB IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
	21-JUN-2017	MOS					
		HRS/MSC -					
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14002 R26	NO. 1 ENGINE - ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH - INFORMATIONAL ONLY: SB IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
		MOS			04-DEC-2020		
	02-DEC-2020	HRS/MSC -					
		ENC					
SB PT6A-72-14002 R27	NO. 1 ENGINE - SERVICE LIFE ROTOR COMPONENTS, SERVICE BULLETIN						- TAKE IN ACCOUNT IN JETFLY AMP
		MOS		(EFF)			
	06-AUG-2021	HRS/MSC -					
		ENC					
SB PT6A-72-14004	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
		MOS			31-JAN-2012		
	15-DEC-1986	HRS/MSC -			5		
		ENC			5		
SB PT6A-72-14004 R01	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
		MOS			31-JAN-2012		
	24-AUG-1987	HRS/MSC -			5		
		ENC			5		
SB PT6A-72-14004 R02	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
		MOS			31-JAN-2012		
	18-NOV-1988	HRS/MSC -			5		
		ENC			5		
SB PT6A-72-14004 R03	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
		MOS			31-JAN-2012		
	20-SEP-1989	HRS/MSC -			5		
		ENC			5		
SB PT6A-72-14004 R04	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
		MOS			31-JAN-2012		
	20-JAN-1990	HRS/MSC -			5		
		ENC			5		
SB PT6A-72-14004 R05	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
		MOS			31-JAN-2012		
	29-OCT-1990	HRS/MSC -			5		
		ENC			5		
SB PT6A-72-14004 R06	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
		MOS			31-JAN-2012		
	22-SEP-1993	HRS/MSC -			5		
		ENC			5		
SB PT6A-72-14004 R07	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
		MOS			31-JAN-2012		
	15-SEP-1994	HRS/MSC -			5		
		ENC			5		
SB PT6A-72-14004 R08	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
		MOS			31-JAN-2012		
	01-SEP-1995	HRS/MSC -			5		
		ENC			5		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14004 R09	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
19-JUN-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14004 R10	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
06-DEC-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14004 R11	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
13-JAN-2004		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14004 R12	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
16-MAR-2005		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14004 R13	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
29-SEP-2005		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14004 R14	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
03-OCT-2006		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14004 R16	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						NOT APPLICABLE
14-SEP-2009		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14004 R18	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING, SERVICE BULLETIN						COMPLIED WITH - CONSUMABLE USE BY JETFLY JET A1 + ADDITIF MIL-DTL-85470B
13-MAY-2014		MOS		28-SEP-2015			
		HRS/MSC - (s)		1819.92			
		ENC		1496			
SB PT6A-72-14004 R19	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES, SERVICE BULLETIN						COMPLIED WITH - CONSUMABLE USE BY JETFLY JET A1 + ADDITIF MIL-DTL-85470B
14-JUL-2016		MOS		17-AUG-2016			
		HRS/MSC -					
		ENC					
SB PT6A-72-14004 R21	NO. 1 ENGINE - ENGINE FUELS AND ADDITIVES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - INFORMATIONAL ONLY: CONSUMABLE USE BY JETFLY JET A1 + ADDITIF MIL-DTL-85470B
12-JAN-2021		MOS		14-JAN-2021			
		HRS/MSC -					
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14028 R01	NO. 1 ENGINE - TACHOMETER DRIVE BEVEL GEARSHAFT ASSEMBLY - REPAIR / MODIFICATION OF, SERVICE BULLETIN						DEFERRED - SEE FORM 19 - SB 14028 REV 1
13-MAY-2014		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14028 R02	NO. 1 ENGINE - TACHOMETER DRIVE BEVEL GEARSHAFT ASSEMBLY - REPAIR / MODIFICATION OF, SERVICE BULLETIN						DEFERRED - SEE FORM 19 - SB 14028 REV 2
14-MAR-2016		MOS		18-MAR-2016			
		HRS/MSC - (s)					
		ENC					
SB PT6A-72-14028 R03	NO. 1 ENGINE - TACHOMETER DRIVE BEVEL GEARSHAFT ASSEMBLY - REPAIR / MODIFICATION OF, SERVICE BULLETIN						DEFERRED - SEE FORM 19 - SB 14028 REV 3
23-MAR-2016		MOS		25-MAR-2016			
		HRS/MSC - (s)					
		ENC					
SB PT6A-72-14028 R04	NO. 1 ENGINE - TACHOMETER DRIVE BEVEL GEARSHAFT ASSEMBLY - REPAIR / MODIFICATION OF, SERVICE BULLETIN						DEFERRED - SEE FORM 19 - SB 14028 REV 4
27-MAY-2016		MOS		31-MAY-2016			
		HRS/MSC -					
		ENC					
SB PT6A-72-14028 R05	NO. 1 ENGINE - TACHOMETER DRIVE BEVEL GEARSHAFT ASSEMBLY - REPAIR / MODIFICATION OF, SERVICE BULLETIN						DEFERRED - SEE FORM 19 SB 14028 R5
23-MAR-2017		MOS		10-MAY-2017			
		HRS/MSC -					
		ENC					
SB PT6A-72-14030	NO. 1 ENGINE - FLANGED OIL FILLER TUBE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
15-DEC-1989		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14030 R01	NO. 1 ENGINE - FLANGED OIL FILLER TUBE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
04-SEP-1990		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14030 R02	NO. 1 ENGINE - FLANGED OIL FILLER TUBE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
24-JAN-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14030 R03	NO. 1 ENGINE - FLANGED OIL FILLER TUBE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
19-JUL-2011		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14034	NO. 1 ENGINE - POWER-TURBINE SHAFT COUPLING - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
27-NOV-1990		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14034 R01	NO. 1 ENGINE - POWER-TURBINE SHAFT COUPLING - REPLACEMENT OF, SERVICE BULLETIN					CODE 6	NOT APPLICABLE
	23-JUN-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14044	NO. 1 ENGINE - PROPELLER REVERSING LEVER - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	12-DEC-1990	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14044 R01	NO. 1 ENGINE - PROPELLER REVERSING LEVER - MODIFICATION OF, SERVICE BULLETIN					CODE 5	NOT APPLICABLE
	24-APR-1991	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14052	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PRESSURE OIL TUBE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE
	06-MAR-1991	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14052 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PRESSURE OIL TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
	28-MAR-2000	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14054	NO. 1 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN						NOT APPLICABLE
	18-OCT-1991	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14054 R01	NO. 1 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN						NOT APPLICABLE
	14-FEB-1994	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14054 R02	NO. 1 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN						NOT APPLICABLE
	04-FEB-1998	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14054 R03	NO. 1 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN						NOT APPLICABLE
	12-JUL-1999	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14054 R04	NO. 1 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	06-OCT-2011	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14055	NO. 1 ENGINE - OUTER COMBUSTION - CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	11-APR-1991	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14055 R01	NO. 1 ENGINE - OUTER COMBUSTION - CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	07-JUN-1991	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14055 R02	NO. 1 ENGINE - OUTER COMBUSTION - CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	11-JAN-1993	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14055 R03	NO. 1 ENGINE - OUTER COMBUSTION - CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	05-JUL-1993	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14055 R04	NO. 1 ENGINE - OUTER COMBUSTION - CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	13-JAN-1997	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14055 R05	NO. 1 ENGINE - OUTER COMBUSTION - CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	28-SEP-1998	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14055 R06	NO. 1 ENGINE - OUTER COMBUSTION - CHAMBER LINER ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
		MOS		31-JAN-2012			
	22-JAN-1999	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14070	NO. 1 ENGINE - REPLACEMENT OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	22-MAR-1993	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14071	NO. 1 ENGINE - REPLACEMENT OF T5 IMMERSION THERMOCOUPLE, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	10-JAN-1992	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14071 R01	NO. 1 ENGINE - REPLACEMENT OF T5 IMMERSION THERMOCOUPLE, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	25-SEP-1998	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14071 R02	NO. 1 ENGINE - REPLACEMENT OF T5 IMMERSION THERMOCOUPLE, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	22-JAN-2008	HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14071 R03	NO. 1 ENGINE - REPLACEMENT OF T5 IMMERSION THERMOCOUPLE, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
25-JAN-2008		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14075	NO. 1 ENGINE - OIL-TO-FUEL HEATER - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
11-FEB-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14075 R01	NO. 1 ENGINE - OIL-TO-FUEL HEATER - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
12-MAY-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14075 R02	NO. 1 ENGINE - OIL-TO-FUEL HEATER - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
13-JUL-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14075 R03	NO. 1 ENGINE - OIL-TO-FUEL HEATER - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
17-MAR-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14076	NO. 1 ENGINE - PROPELLER GEARBOX FRONT ACCESSORY DRIVE BEVEL GEAR AND ADJUSTING SPACER WITH REDEFINED TOLERANCES - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
23-MAR-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14076 R01	NO. 1 ENGINE - PROPELLER GEARBOX FRONT ACCESSORY DRIVE BEVEL GEAR AND ADJUSTING SPACER WITH REDEFINED TOLERANCES - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
02-DEC-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14076 R02	NO. 1 ENGINE - PROPELLER GEARBOX FRONT ACCESSORY DRIVE BEVEL GEAR AND ADJUSTING SPACER WITH REDEFINED TOLERANCES - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14077	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING AND BEARING SUPPORT SLEEVE - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
13-DEC-1991		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14077 R01	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING AND BEARING SUPPORT SLEEVE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
05-JUL-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14078	NO. 1 ENGINE - T5 IMMERSION THERMOCOUPLES - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
10-JAN-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14078 R01	NO. 1 ENGINE - T5 IMMERSION THERMOCOUPLES - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
01-APR-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14079	NO. 1 ENGINE - COMPRESSOR TURBINE STATOR ASSEMBLY SHROUD HOUSING AND STATOR AIR SEAL - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
24-MAR-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14080	NO. 1 ENGINE - COMPRESSOR ROTOR TIE ROD SELF-LOCKING NUT - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
09-MAR-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14080 R01	NO. 1 ENGINE - COMPRESSOR ROTOR TIE ROD SELF-LOCKING NUT - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
30-JUN-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14082	NO. 1 ENGINE - IGNITER PORT PLUG - INTRODUCTION OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
02-JUL-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14087	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING AND DIAPHRAGM ASSEMBLIES KEYWASHERS AND CENTER BEARING RETAINING BOLTS - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
21-APR-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14087 R01	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING AND DIAPHRAGM ASSEMBLIES KEYWASHERS AND CENTER BEARING RETAINING BOLTS - REPLACEMENT OF, SERVICE BULLETIN					CODE 5	NOT APPLICABLE
06-JUL-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14091	NO. 1 ENGINE - PROPELLER REDUCTION GEARBOX PLANET GEAR SLEEVE BEARING KIT - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
28-JUL-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14091 R01	NO. 1 ENGINE - PROPELLER REDUCTION GEARBOX PLANET GEAR SLEEVE BEARING KIT - INTRODUCTION OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
13-OCT-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14093	NO. 1 ENGINE - POWER TURBINE STATOR AIR SEAL - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	26-MAY-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14093 R01	NO. 1 ENGINE - POWER TURBINE STATOR AIR SEAL - REPLACEMENT OF, SERVICE BULLETIN					CODE 6	NOT APPLICABLE
	28-OCT-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14093 R01 PART A	NO. 1 ENGINE - ACCOMPLISH POWER TURBINE STATOR AIR SEAL - REPLACEMENT OF, SERVICE BULLETIN TO IMPROVE CLEARANCE WITH THE POWER TURBINE ROTOR AIR SEAL.					CODE 6	NOT APPLICABLE
	28-OCT-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14093 R01 PART B	NO. 1 ENGINE - ACCOMPLISH POWER TURBINE STATOR AIR SEAL - REPLACEMENT OF, SERVICE BULLETIN TO IMPROVE SEALING CAPACITY AT HIGH ALTITUDE.					CODE 6	NOT APPLICABLE
	28-OCT-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14094	NO. 1 ENGINE - FUEL PUMP DRIVE PLAIN SEAL AND SEAL CARRIER - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	12-AUG-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14094 R01	NO. 1 ENGINE - FUEL PUMP DRIVE PLAIN SEAL AND SEAL CARRIER - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
	28-OCT-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14097	NO. 1 ENGINE - FUEL MANIFOLD ADAPTER ASSEMBLIES AND FUEL INLET MANIFOLD ADAPTER ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
	08-NOV-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14099	NO. 1 ENGINE - REDUCTION GEARBOX REAR HOUSING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
	22-JUL-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14104	NO. 1 ENGINE - ASBESTOS FIBER GASKETS - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	07-DEC-1995	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14104 R01	NO. 1 ENGINE - ASBESTOS FIBER GASKETS - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	08-FEB-1994	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14104 R02	NO. 1 ENGINE - ASBESTOS FIBER GASKETS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
	07-DEC-1995	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14106	NO. 1 ENGINE - NO. 2 BEARING HOUSING COVER FLANGE - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	06-OCT-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14106 R01	NO. 1 ENGINE - NO. 2 BEARING HOUSING COVER FLANGE - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
	06-OCT-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14107	NO. 1 ENGINE - COMPRESSOR TURBINE STATOR AIR SEAL AND GASKET - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	05-JUN-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14107 R01	NO. 1 ENGINE - COMPRESSOR TURBINE STATOR AIR SEAL AND GASKET - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
	06-OCT-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14110	NO. 1 ENGINE - COMPONENT - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	12-AUG-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14110 R01	NO. 1 ENGINE - COMPONENT - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	06-OCT-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14110 R02	NO. 1 ENGINE - COMPONENT - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
	02-MAY-2005	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14112	NO. 1 ENGINE - ACCESSORY GEARBOX ASSEMBLY WITH SEPARATE COUPLING SHAFT AND DRIVE GEARSHAFT - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
	12-APR-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14112 R01	NO. 1 ENGINE - ACCESSORY GEARBOX ASSEMBLY WITH SEPARATE COUPLING SHAFT AND DRIVE GEARSHAFT - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
	04-JUL-1994	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14112 R02	NO. 1 ENGINE - ACCESSORY GEARBOX ASSEMBLY WITH SEPARATE COUPLING SHAFT AND DRIVE GEARSHAFT - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
29-SEP-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14112 R03	NO. 1 ENGINE - ACCESSORY GEARBOX ASSEMBLY WITH SEPARATE COUPLING SHAFT AND DRIVE GEARSHAFT - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
02-MAY-2005		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14115	NO. 1 ENGINE - OIL TO COOLER TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
07-OCT-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14117	NO. 1 ENGINE - COMPRESSOR TURBINE STATOR AIR SEAL - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
13-JAN-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14119	NO. 1 ENGINE - POWER TURBINE STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
24-AUG-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14119 R01	NO. 1 ENGINE - POWER TURBINE STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CODE 4	NOT APPLICABLE - BY EFFECTIVITY
05-OCT-1992		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14120	NO. 1 ENGINE - REVERSING LEVER GUIDE PIN BRACKET ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 2	NOT APPLICABLE - BY EFFECTIVITY
07-OCT-1992		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14121	NO. 1 ENGINE - COMPRESSOR TURBINE DISK BALANCING ASSEMBLY - INSPECTION/MODIFICATION OF, SERVICE BULLETIN					CODE 6	NOT APPLICABLE
21-OCT-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14122	NO. 1 ENGINE - FIRST-STAGE COMPRESSOR STATOR ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
16-DEC-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14123	NO. 1 ENGINE - FUEL CONTROL DRIVE GEARSHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
02-OCT-1992		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14123 R01	NO. 1 ENGINE - FUEL CONTROL DRIVE GEARSHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
	30-NOV-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14124	NO. 1 ENGINE - COMPRESSOR TURBINE BLADE - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	13-NOV-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14124 R01	NO. 1 ENGINE - COMPRESSOR TURBINE BLADE - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
	22-MAR-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14125	NO. 1 ENGINE - GASKETS CONTAINING ASBESTOS FIBERS - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
	17-DEC-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14127	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY SPACER RING HALF - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
	25-FEB-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14132	NO. 1 ENGINE - COMPRESSOR TURBINE (C.T.) STATOR ASSEMBLY C.T. SHROUD HOUSING SMALL EXIT DUCT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	24-MAR-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14132 R01	NO. 1 ENGINE - COMPRESSOR TURBINE (C.T.) STATOR ASSEMBLY C.T. SHROUD HOUSING SMALL EXIT DUCT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 4	NOT APPLICABLE - BY EFFECTIVITY
	12-MAY-1993	MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14134	NO. 1 ENGINE - REPLACEMENT OF POWER-TURBINE ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE
	23-DEC-1992	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14134 R01	NO. 1 ENGINE - REPLACEMENT OF POWER-TURBINE ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE
	15-SEP-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14134 R02	NO. 1 ENGINE - REPLACEMENT OF POWER-TURBINE ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN					CODE 5	NOT APPLICABLE
	04-JUL-1994	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14137	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY AND NO. 2 BEARING HOUSING - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	22-MAR-1993	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14139	NO. 1 ENGINE - COMBUSTION-CHAMBER INNER-LINER ASSEMBLY AND SMALL EXIT-DUCT ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	07-JUN-1993	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14139 R01	NO. 1 ENGINE - COMBUSTION-CHAMBER INNER-LINER ASSEMBLY AND SMALL EXIT-DUCT ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	15-JUN-1995	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14139 R02	NO. 1 ENGINE - COMBUSTION-CHAMBER INNER-LINER ASSEMBLY AND SMALL EXIT-DUCT ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	16-JAN-1997	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14140	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	12-JUL-1993	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14142	NO. 1 ENGINE - COMPRESSOR TURBINE BLADE WITH FEATHER SEALS - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	24-MAR-1993	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14142 R01	NO. 1 ENGINE - COMPRESSOR TURBINE BLADE WITH FEATHER SEALS - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	12-MAY-1993	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14142 R02	NO. 1 ENGINE - COMPRESSOR TURBINE BLADE WITH FEATHER SEALS - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	17-MAY-2004	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14142 R03	NO. 1 ENGINE - COMPRESSOR TURBINE BLADE WITH FEATHER SEALS - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - BY EFFECTIVITY
		MOS		01-MAR-2015			
	17-SEP-2008	HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14143	NO. 1 ENGINE - POWER TURBINE ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	15-MAR-1993	HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14143 R01	NO. 1 ENGINE - POWER TURBINE ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
15-SEP-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14143 R02	NO. 1 ENGINE - POWER TURBINE ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
07-MAR-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14143 R03	NO. 1 ENGINE - POWER TURBINE ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
12-JUL-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14146	NO. 1 ENGINE - FUEL PUMP AND (DRY SPLINE) FUEL CONTROL DRIVE GEARSHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
06-DEC-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14146 R01	NO. 1 ENGINE - FUEL PUMP AND (DRY SPLINE) FUEL CONTROL DRIVE GEARSHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
13-SEP-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14146 R02	NO. 1 ENGINE - FUEL PUMP AND (DRY SPLINE) FUEL CONTROL DRIVE GEARSHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
26-JUL-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14146 R03	NO. 1 ENGINE - FUEL PUMP AND (DRY SPLINE) FUEL CONTROL DRIVE GEARSHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
06-JUN-2006		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14147	NO. 1 ENGINE - NO. 1 BEARING HOUSING AND COMPRESSOR STATOR AIR-SEAL ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
06-JAN-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14147 R01	NO. 1 ENGINE - NO. 1 BEARING HOUSING AND COMPRESSOR STATOR AIR-SEAL ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
09-JAN-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14150	NO. 1 ENGINE - THIRD-STAGE POWER-TURBINE VANE RING - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
18-OCT-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14150 R01	NO. 1 ENGINE - THIRD-STAGE POWER-TURBINE VANE RING - MODIFICATION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
19-OCT-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14151	NO. 1 ENGINE - FIRESEAL MOUNTING RINGS - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
11-MAY-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14153	NO. 1 ENGINE - OIL TEMPERATURE BULB AND PRESSURE SENSOR TEE - REPLACEMENT OF, SERVICE BULLETIN					CODE 5	NOT APPLICABLE
03-MAY-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14154	NO. 1 ENGINE - OVERTORQUE LIMITER - INTRODUCTION OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
15-NOV-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14155	NO. 1 ENGINE - POWER-TURBINE ROTOR BALANCING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
18-OCT-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14156	NO. 1 ENGINE - NO. 2 BEARING HOUSING-COVER FLANGE RETAINING-BOLTS - REPLACEMENT OF, SERVICE BULLETIN					CODE 6	NOT APPLICABLE
28-JUN-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14159	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
13-SEP-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14160	NO. 1 ENGINE - COMPRESSOR TURBINE VANE SEALING RING - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
19-JUL-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14160 R01	NO. 1 ENGINE - COMPRESSOR TURBINE VANE SEALING RING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
16-JUL-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14161	NO. 1 ENGINE - AIR BLEED ADAPTER - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
25-OCT-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14163	NO. 1 ENGINE - COMPRESSOR STATOR ASSEMBLIES ROTORS AND SHAFT ASSEMBLY - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
22-JUN-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14163 R01	NO. 1 ENGINE - COMPRESSOR STATOR ASSEMBLIES ROTORS AND SHAFT ASSEMBLY - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	04-DEC-1996	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14163 R02	NO. 1 ENGINE - COMPRESSOR STATOR ASSEMBLIES ROTORS AND SHAFT ASSEMBLY - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
	11-JUL-2003	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14165	NO. 1 ENGINE - INTERSTAGE VANE RING RETAINING RING - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
	08-NOV-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14166	NO. 1 ENGINE - FUEL MANIFOLD ADAPTER RETAINING NUTS - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
	08-NOV-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14167	NO. 1 ENGINE - ASBESTOS FIBER GASKETS - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
	19-OCT-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14168	NO. 1 ENGINE - ASBESTOS FIBER GASKETS - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	18-OCT-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14168 R01	NO. 1 ENGINE - ASBESTOS FIBER GASKETS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
	05-JUN-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14169	NO. 1 ENGINE - ASBESTOS FIBER INSULATION AND SHIELDS - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	04-NOV-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14169 R01	NO. 1 ENGINE - ASBESTOS FIBER INSULATION AND SHIELDS - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
	05-MAY-1994	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14170	NO. 1 ENGINE - PRIMARY FUEL-PRESSURE-TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 6	NOT APPLICABLE
	15-SEP-1993	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14172	NO. 1 ENGINE - POWER-TURBINE ROTOR BALANCING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14172 R01	NO. 1 ENGINE - POWER-TURBINE ROTOR BALANCING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
12-APR-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14174	NO. 1 ENGINE - COMPRESSOR TURBINE DISK BALANCING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
01-SEP-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14174 R01	NO. 1 ENGINE - COMPRESSOR TURBINE DISK BALANCING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
18-MAR-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14175	NO. 1 ENGINE - IGNITION CABLE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 7	NOT APPLICABLE
23-NOV-1993		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14179	NO. 1 ENGINE - OIL TEMPERATURE BULB ADAPTER - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
03-JAN-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14181	NO. 1 ENGINE - POWER-TURBINE STATOR-HOUSING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
03-JAN-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14181 R01	NO. 1 ENGINE - POWER-TURBINE STATOR-HOUSING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
08-FEB-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14181 R02	NO. 1 ENGINE - POWER-TURBINE STATOR-HOUSING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
21-NOV-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14182	NO. 1 ENGINE - SCAVENGE PUMP HOUSING - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
04-APR-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14183	NO. 1 ENGINE - PROPELLER DE-ICING HARDWARE MOUNTING BRACKET - INTRODUCTION OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
02-MAR-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14185	NO. 1 ENGINE - OVERTORQUE-LIMITER SOLENOID VALVE - DELETION OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
02-MAR-1994		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14186	NO. 1 ENGINE - OIL-TO-FUEL-HEATER THERMAL-ELEMENT RETAINING-CAP - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
27-JUL-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14186 R01	NO. 1 ENGINE - OIL-TO-FUEL-HEATER THERMAL-ELEMENT RETAINING-CAP - MODIFICATION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
		MOS		31-JAN-2012			
20-SEP-2000		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14188	NO. 1 ENGINE - THIRD-STAGE POWER-TURBINE VANE RING - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
19-OCT-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14188 R01	NO. 1 ENGINE - THIRD-STAGE POWER-TURBINE VANE RING - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
26-AUG-2004		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14189	NO. 1 ENGINE - DUAL-ORIFICE FUEL-MANIFOLD INLET AND FUEL-MANIFOLD ADAPTER ASSEMBLIES - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
15-APR-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14191	NO. 1 ENGINE - PROPELLER CONTROL CAM - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
		MOS		31-JAN-2012			
19-APR-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14193	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
		MOS		31-JAN-2012			
02-JUN-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14194	NO. 1 ENGINE - WIRING-HARNESS RETAINING PLATE - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
14-SEP-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14196	NO. 1 ENGINE - REVERSING-LEVER GUIDE-PIN BRACKET ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CODE 8	NOT APPLICABLE
		MOS		31-JAN-2012			
10-JUN-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14198	NO. 1 ENGINE - POWER-TURBINE HOUSING SEALING RING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
		MOS		31-JAN-2012			
14-MAR-1995		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14200	NO. 1 ENGINE - CABIN BLEED-AIR TRANSFER-TUBE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
08-FEB-1995		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14201	NO. 1 ENGINE - POWER TURBINE BLADES - MDOFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
05-MAY-1995		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14201 R01	NO. 1 ENGINE - POWER TURBINE BLADES - MDOFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
27-JAN-1997		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14202	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY - INSPECTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14202 R01	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY - INSPECTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14202 R02	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY - INSPECTION OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
		MOS		31-JAN-2012			
24-AUG-1995		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14202 R03	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY - INSPECTION OF, SERVICE BULLETIN					CATEGORY 10	NOT APPLICABLE
		MOS		31-JAN-2012			
10-MAY-2007		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14204	NO. 1 ENGINE - COMBUSTION-CHAMBER SMALL-EXIT DUCT ASSEMBLY OF - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
25-NOV-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14204 R01	NO. 1 ENGINE - COMBUSTION-CHAMBER SMALL-EXIT DUCT ASSEMBLY OF - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
22-DEC-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14206	NO. 1 ENGINE - POWER-TURBINE STATOR HOUSING ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
05-DEC-1994		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14206 R01	NO. 1 ENGINE - POWER-TURBINE STATOR HOUSING ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
17-JAN-1995		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14206 R02	NO. 1 ENGINE - POWER-TURBINE STATOR HOUSING ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
19-JUN-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14206 R03	NO. 1 ENGINE - POWER-TURBINE STATOR HOUSING ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
25-JUN-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14206 R04	NO. 1 ENGINE - POWER-TURBINE STATOR HOUSING ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
15-OCT-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14206 R05	NO. 1 ENGINE - POWER-TURBINE STATOR HOUSING ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
01-JUN-2004		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14207	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
29-SEP-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14207 R01	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
08-DEC-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14207 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY: BY ENGINE MODEL
30-SEP-2021		MOS		04-OCT-2021			
		HRS/MSC -					
		ENC					
SB PT6A-72-14210	NO. 1 ENGINE - POWER-TURBINE SHAFT COUPLING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
09-MAR-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14213	NO. 1 ENGINE - MAIN SCAVENGE-PUMP SCREEN ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
01-MAR-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14214	NO. 1 ENGINE - FUEL NOZZLE SHEATH - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
01-MAR-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14215	NO. 1 ENGINE - ACCESSORY-GEARBOX ASSEMBLY SEAL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	14-MAR-1995	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14217	NO. 1 ENGINE - FIRST-STAGE REDUCTION PLANET GEARS - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	07-JUN-1995	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14217 R01	NO. 1 ENGINE - FIRST-STAGE REDUCTION PLANET GEARS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14218	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	13-FEB-1995	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14219	NO. 1 ENGINE - NON-METALLIC SEAL RING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	01-MAR-1995	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14222	NO. 1 ENGINE - IDENTIFICATION SUPPORT PLATE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	20-MAY-1997	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14223	NO. 1 ENGINE - BLADE PLATFORM SEAL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
	05-FEB-1997	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14224	NO. 1 ENGINE - FIRESEAL SEAL PLATES SEALS AND INSULATION - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	07-JAN-1997	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14225	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	14-MAR-1997	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14225 R01	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	08-MAY-1998	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14230	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	15-AUG-1995	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14230 R01	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) - MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
18-DEC-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14231	NO. 1 ENGINE - COMPRESSOR TURBINE BLADE - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
31-AUG-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14231 R01	NO. 1 ENGINE - COMPRESSOR TURBINE BLADE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
22-JAN-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14233	NO. 1 ENGINE - SEALING PLATES AND SPACER - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
06-NOV-1995		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14233 R01	NO. 1 ENGINE - SEALING PLATES AND SPACER - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
18-MAR-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14234	NO. 1 ENGINE - NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
16-JUL-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14234 R01	NO. 1 ENGINE - NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
24-JAN-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14234 R02	NO. 1 ENGINE - NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
23-MAY-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14239	NO. 1 ENGINE - ACCESSORY DRIVE PLAIN COVER - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
03-JUN-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14242	NO. 1 ENGINE - TURBOPROP FUEL CONTROL UNIT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
31-MAY-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14242 R01	NO. 1 ENGINE - TURBOPROP FUEL CONTROL UNIT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
06-MAR-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14243	NO. 1 ENGINE - POWER TURBINE STATOR HOUSING - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
13-FEB-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14243 R01	NO. 1 ENGINE - POWER TURBINE STATOR HOUSING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
25-JUN-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14246	NO. 1 ENGINE - ELECTRICAL OIL LEVEL INDICATOR AND OIL LEVEL SIGHT GAGE, SERVICE BULLETIN						NOT APPLICABLE
21-OCT-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14246 R01	NO. 1 ENGINE - ELECTRICAL OIL LEVEL INDICATOR AND OIL LEVEL SIGHT GAGE, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
07-FEB-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14248	NO. 1 ENGINE - TURBOPROP FUEL CONTROL UNIT - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
05-NOV-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14248 R01	NO. 1 ENGINE - TURBOPROP FUEL CONTROL UNIT - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
21-MAY-1997		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14248 R02	NO. 1 ENGINE - TURBOPROP FUEL CONTROL UNIT - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
28-SEP-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14249	NO. 1 ENGINE - TURBINE EXHAUST DUCT ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
18-OCT-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14250	NO. 1 ENGINE - FUEL CONTROL UNIT - INSPECTION OF, SERVICE BULLETIN						NOT APPLICABLE
02-DEC-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14250 R01	NO. 1 ENGINE - FUEL CONTROL UNIT - INSPECTION OF, SERVICE BULLETIN						NOT APPLICABLE
06-DEC-1996		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14250 R02	NO. 1 ENGINE - FUEL CONTROL UNIT - INSPECTION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
07-APR-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14251	NO. 1 ENGINE - BLEED OFF VALVE (BOV) COVER - INSPECTION / REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	28-NOV-1996	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14251 R01	NO. 1 ENGINE - BLEED OFF VALVE (BOV) COVER - INSPECTION / REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	02-DEC-1996	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14251 R02	NO. 1 ENGINE - BLEED OFF VALVE (BOV) COVER - INSPECTION / REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14252	NO. 1 ENGINE - COMPRESSOR SEALING RING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
		MOS		31-JAN-2012			
	11-AUG-1998	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14253	NO. 1 ENGINE - NO. 4 BEARING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	12-FEB-1997	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14253 R01	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - BY EFFECTIVITY: BY ENGINE MODEL
		MOS		11-AUG-2021			
	10-AUG-2021	HRS/MSC -					
		ENC					
SB PT6A-72-14254	NO. 1 ENGINE - FUEL CONTROL UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	07-MAR-1997	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14254 R01	NO. 1 ENGINE - FUEL CONTROL UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
		MOS		31-JAN-2012			
	21-JAN-1998	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14255	NO. 1 ENGINE - IGNITION CABLES - NEW ROUTING - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - BY ENGINE SERIAL NUMBER
		MOS		31-JAN-2012			
	26-SEP-1997	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14256	NO. 1 ENGINE - FUEL NOZZLE ``U" SEALS - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	05-SEP-1997	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14256 R01	NO. 1 ENGINE - FUEL NOZZLE ``U" SEALS - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	22-AUG-2002	HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14258	NO. 1 ENGINE - WIRING HARNESS THERMOCOUPLE POWER TURBINE STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	08-APR-1998	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14258 R01	NO. 1 ENGINE - WIRING HARNESS THERMOCOUPLE POWER TURBINE STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	26-MAR-2003	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14258 R02	NO. 1 ENGINE - WIRING HARNESS THERMOCOUPLE POWER TURBINE STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	16-AUG-2004	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14259	NO. 1 ENGINE - POWER TURBINE DISK ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	04-NOV-1997	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14259 R01	NO. 1 ENGINE - POWER TURBINE DISK ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
	17-NOV-1999	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14262	NO. 1 ENGINE - OIL FILLER TUBE - FLANGE - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	06-OCT-2000	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14266	NO. 1 ENGINE - COMBUSTION CHAMBER SMALL-EXIT DUCT ASSEMBLY OF - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	21-JAN-1998	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14266 R01	NO. 1 ENGINE - COMBUSTION CHAMBER SMALL-EXIT DUCT ASSEMBLY OF - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	05-NOV-1998	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14266 R02	NO. 1 ENGINE - COMBUSTION CHAMBER SMALL-EXIT DUCT ASSEMBLY OF - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	28-JUN-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14266 R03	NO. 1 ENGINE - COMBUSTION CHAMBER SMALL-EXIT DUCT ASSEMBLY OF - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	02-MAY-2005	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14267	NO. 1 ENGINE - REDUCTION GEARBOX SECOND STAGE RING GEAR AND PROPELLER REDUCTION GEARBOX FRONT HOUSING - REPLACEMENT OF , SERVICE BULLETIN						NOT APPLICABLE
20-FEB-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14267 R01	NO. 1 ENGINE - REDUCTION GEARBOX SECOND STAGE RING GEAR AND PROPELLER REDUCTION GEARBOX FRONT HOUSING - REPLACEMENT OF , SERVICE BULLETIN						NOT APPLICABLE
10-MAY-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14267 R02	NO. 1 ENGINE - REDUCTION GEARBOX SECOND STAGE RING GEAR AND PROPELLER REDUCTION GEARBOX FRONT HOUSING - REPLACEMENT OF , SERVICE BULLETIN						NOT APPLICABLE
05-NOV-2001		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14267 R03	NO. 1 ENGINE - REDUCTION GEARBOX SECOND STAGE RING GEAR AND PROPELLER REDUCTION GEARBOX FRONT HOUSING - REPLACEMENT OF , SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
15-SEP-2010		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14269	NO. 1 ENGINE - P3 AIR PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
21-AUG-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14269 R01	NO. 1 ENGINE - P3 AIR PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
22-JAN-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14269 R02	NO. 1 ENGINE - P3 AIR PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
23-NOV-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14269 R05	NO. 1 ENGINE - P3 AIR PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
01-MAR-2015		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14271	NO. 1 ENGINE - PROPELLER GOVERNOR - TEST/INSPECTION OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
28-APR-1998		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14272	NO. 1 ENGINE - ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
27-OCT-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14272 R01	NO. 1 ENGINE - ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
01-FEB-2002		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14272 R02	NO. 1 ENGINE - ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
13-DEC-2005		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14273	NO. 1 ENGINE - POWER TURBINE DISK ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
12-AUG-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14275	NO. 1 ENGINE - OIL FILLER CAP AND LEVEL INDICATOR - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
13-MAY-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14275 R01	NO. 1 ENGINE - OIL FILLER CAP AND LEVEL INDICATOR - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
27-MAY-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14275 R02	NO. 1 ENGINE - OIL FILLER CAP AND LEVEL INDICATOR - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
13-JUN-2011		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14278	NO. 1 ENGINE - PROPELLER SHAFT - ON WING REPAIR OF, SERVICE BULLETIN						NOT APPLICABLE
28-SEP-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14278 R01	NO. 1 ENGINE - PROPELLER SHAFT - ON WING REPAIR OF, SERVICE BULLETIN						NOT APPLICABLE
27-JAN-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14278 R02	NO. 1 ENGINE - PROPELLER SHAFT - ON WING REPAIR OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
09-NOV-2006		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14280	NO. 1 ENGINE - SCAVENGE PUMP HOUSING ASSEMBLY - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
15-SEP-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14280 R01	NO. 1 ENGINE - SCAVENGE PUMP HOUSING ASSEMBLY - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
28-JUN-2001		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14280 R02	NO. 1 ENGINE - SCAVENGE PUMP HOUSING ASSEMBLY - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
01-NOV-2002		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14280 R03	NO. 1 ENGINE - SCAVENGE PUMP HOUSING ASSEMBLY - MODIFICATION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
13-NOV-2003		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14281	NO. 1 ENGINE - NEW INSULATION SEAL RETAINING PLATE, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
22-JAN-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14283	NO. 1 ENGINE - NO.2 BEARING SCAVENGE-TUBE SEAL-RETAINING-PLATE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
20-AUG-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14285	NO. 1 ENGINE - TURBOPROP PROPELLER GOVERNOR - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
13-OCT-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14286	NO. 1 ENGINE - PROPELLER SHAFT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
28-SEP-1998		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14286 R01	NO. 1 ENGINE - PROPELLER SHAFT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
27-JAN-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14286 R02	NO. 1 ENGINE - PROPELLER SHAFT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
27-JUN-2001		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14290	NO. 1 ENGINE - GAS GENERATOR OIL-SCAVENGE-TUBE - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
30-MAR-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14290 R01	NO. 1 ENGINE - GAS GENERATOR OIL-SCAVENGE-TUBE - MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
02-JUN-2004		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14293	NO. 1 ENGINE - EXHAUST DUCT DRAIN TUBE NIPPLE AND CAP ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
23-JUN-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14293 R01	NO. 1 ENGINE - EXHAUST DUCT DRAIN TUBE NIPPLE AND CAP ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
25-JAN-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14297	NO. 1 ENGINE - COMPRESSOR TURBINE DISK - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
17-DEC-1999		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14297 R01	NO. 1 ENGINE - COMPRESSOR TURBINE DISK - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
25-AUG-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14298	NO. 1 ENGINE - PROPELLER THRUST COVER ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
08-FEB-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14298 R01	NO. 1 ENGINE - PROPELLER THRUST COVER ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
24-MAR-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14298 R02	NO. 1 ENGINE - PROPELLER THRUST COVER ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
27-SEP-2001		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14299	NO. 1 ENGINE - T-5 TRIM THERMOCOUPLE - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
11-FEB-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14299 R01	NO. 1 ENGINE - T-5 TRIM THERMOCOUPLE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
10-JUL-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14306	NO. 1 ENGINE - COMPRESSOR INLET CASE AND FOURTH STAGE COMPRESSOR STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
18-MAY-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14306 R01	NO. 1 ENGINE - COMPRESSOR INLET CASE AND FOURTH STAGE COMPRESSOR STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
26-MAY-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14306 R02	NO. 1 ENGINE - COMPRESSOR INLET CASE AND FOURTH STAGE COMPRESSOR STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14306 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR INLET CASE AND FOURTH STAGE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - By Effectivity: BY ENGINE MODEL
06-FEB-2020		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14306 R04	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR INLET CASE AND FOURTH STAGE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - By Effectivity: BY ENGINE MODEL
08-FEB-2020		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14307	NO. 1 ENGINE - COMPRESSOR ROTOR - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
18-MAY-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14309	NO. 1 ENGINE - COMPRESSOR ROTOR - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
18-MAY-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14310	NO. 1 ENGINE - COMPRESSOR ROTOR - REVERT BACK TO PRIOR CONFIGURATON, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
18-MAY-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14313 R01	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE MODEL
26-MAR-2014		MOS		02-JUN-2014			
		HRS/MSC -		1056.33			
		ENC		863			
SB PT6A-72-14313 R02	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE MODEL
23-FEB-2017		MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-14314	NO. 1 ENGINE - NEW CLAMPING ARRANGEMENT REAR AIR TUBE - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
27-DEC-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14315	NO. 1 ENGINE - FUEL CONTROL UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
12-DEC-2000		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14315 R01	NO. 1 ENGINE - FUEL CONTROL UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	13-DEC-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14315 R02	NO. 1 ENGINE - FUEL CONTROL UNIT - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	04-MAR-2004	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14317	NO. 1 ENGINE - OUTER LINER - REPLACEMENT OF AND INER LINER - INSPECTION OF, SERVICE BULLETIN						NOT APPLICABLE
	11-SEP-2000	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14317 R01	NO. 1 ENGINE - OUTER LINER - REPLACEMENT OF AND INER LINER - INSPECTION OF, SERVICE BULLETIN						NOT APPLICABLE
	01-NOV-2000	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14317 R02	NO. 1 ENGINE - OUTER LINER - REPLACEMENT OF AND INER LINER - INSPECTION OF, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE
	18-DEC-2006	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14317 R03	NO. 1 ENGINE - OUTER LINER - REPLACEMENT OF AND INNER LINER - INSPECTION OF, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE
	14-DEC-2010	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14317 R05	NO. 1 ENGINE - OUTER LINER - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14317 R06	NO. 1 ENGINE - OUTER LINER - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
	06-JAN-2017	MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-14320	NO. 1 ENGINE - COMPRESSOR TURBINE AIR SEAL AND NO. 2 BEARING OIL NOZZLE AND HOUSING COVER AND FLANGE - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	27-MAR-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14320 R01	NO. 1 ENGINE - COMPRESSOR TURBINE AIR SEAL AND NO. 2 BEARING OIL NOZZLE AND HOUSING COVER AND FLANGE - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	11-APR-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14320 R02	NO. 1 ENGINE - COMPRESSOR TURBINE AIR SEAL AND NO. 2 BEARING OIL NOZZLE AND HOUSING COVER AND FLANGE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE
		MOS		31-JAN-2012			
24-AUG-2001		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14321	NO. 1 ENGINE - PROPELLER SHAFT SET - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
16-FEB-2001		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14326	NO. 1 ENGINE - NEW OVERTORQUE LIMITER - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
23-AUG-2001		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14327	NO. 1 ENGINE - POWER-SECTION IDENTIFICATION PLATE - REWORK OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
26-APR-2001		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14328	NO. 1 ENGINE - ACCESSORY GEARBOX MAGNETIC CHIP DETECTOR - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
17-AUG-2001		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14328 R01	NO. 1 ENGINE - ACCESSORY GEARBOX MAGNETIC CHIP DETECTOR - INTRODUCTION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
30-MAY-2005		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14328 R02	NO. 1 ENGINE - ACCESSORY GEARBOX MAGNETIC CHIP DETECTOR - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
16-MAY-2007		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14329	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER - REPLACEMENT / MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
11-JUN-2001		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14329 R01	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER - REPLACEMENT / MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
30-OCT-2001		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14329 R02	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER - REPLACEMENT / MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
14-JAN-2002		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14329 R03	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER - REPLACEMENT / MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
31-OCT-2002		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14329 R04	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER - REPLACEMENT / MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
	30-APR-2010	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14329 R05	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER - REPLACEMENT / MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - N/A ENGINE MODEL
	21-APR-2017	MOS		18-MAY-2017			
		HRS/MSC -					
		ENC					
SB PT6A-72-14329 R06	NO. 1 ENGINE - COMBUSTION CHAMBER OUTER LINER - REPLACEMENT / MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - By Effectivity: n/a by engine model
	23-MAR-2019	MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-14330	NO. 1 ENGINE - FUEL PRESSURE TUBE SPACER - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	31-OCT-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14332	NO. 1 ENGINE - OIL TO FUEL HEATER - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	01-OCT-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14333	NO. 1 ENGINE - PROTECTIVE CAPS AND PLUGS - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	16-NOV-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14333 R01	NO. 1 ENGINE - PROTECTIVE CAPS AND PLUGS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	19-FEB-2004	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14335	NO. 1 ENGINE - FUEL CONTROL UNIT - INSPECTION OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
	22-FEB-2010	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14335 R01	NO. 1 ENGINE - FUEL CONTROL UNIT - INSPECTION OF, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
	22-FEB-2010	DAYS		01-MAR-2015			
		HRS/MSC N/A		1440.83			
		ENC		1182			
SB PT6A-72-14336	NO. 1 ENGINE - IGNITOR PORT PLUG - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	16-NOV-2001	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14337	NO. 1 ENGINE - SHIPPING CONTAINER SKID BASE - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 9	NOT APPLICABLE
	22-AUG-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14338	NO. 1 ENGINE - REAR FIRESEAL MOUNTING RING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	02-APR-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14339	NO. 1 ENGINE - INTERMEDIATE FIRESEAL MOUNTING RING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	02-APR-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14340	NO. 1 ENGINE - CENTER FIRESEAL MOUNTING RING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	02-APR-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14341	NO. 1 ENGINE - NEW OIL-LEVEL SIGHT GAGE - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	21-JAN-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14342	NO. 1 ENGINE - NEW OIL-TO-FUEL HEATER TRANSFER TUBE - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	01-FEB-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14344	NO. 1 ENGINE - NEW THERMOSTATIC-BYPASS-VALVE TRANSFER TUBE - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14345	NO. 1 ENGINE - BRUSH-BLOCK MOUNTING BRACKET - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	21-OCT-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14347	NO. 1 ENGINE - POWER-TURBINE-STATOR HOUSING ASSEMBLY - MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
	20-AUG-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14347 R01	NO. 1 ENGINE - POWER-TURBINE-STATOR HOUSING ASSEMBLY - MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
	24-SEP-2002	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14351	NO. 1 ENGINE - PROPELLER SHAFT SEAL - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	08-SEP-2005	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14351 R01	NO. 1 ENGINE - PROPELLER SHAFT SEAL - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
	08-DEC-2005	MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14351 R02	NO. 1 ENGINE - PROPELLER SHAFT SEAL - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
27-FEB-2006		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14351 R03	NO. 1 ENGINE - PROPELLER SHAFT SEAL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14352	NO. 1 ENGINE - PROPELLER SHAFT & SLEEVE SET - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
17-JAN-2003		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14353	NO. 1 ENGINE - AIR INLET SCREEN WASHERS - REMOVAL OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
15-MAY-2003		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14355	NO. 1 ENGINE - PROPELLER GOVERNOR FLIGHT CLOSURE - INTRODUCTION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
05-MAY-2003		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14357 R02	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY - INSPECTION OF, SERVICE BULLETIN					CATEGORY 3	- NOT CONCERNED BY PREFIX (FUEL NOZZLE TIPS IDENTIFIED WITH THE PREFIX 2BRH OR 2BRK.)
		MOS		26-OCT-2013			
		HRS/MSC -		713.83			
		ENC		573			
SB PT6A-72-14357 R05	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY - INSPECTION OF (SUPERSEDED BY P&WC S.B. NO. PT6A-72-14495), SERVICE BULLETIN					CATEGORY 10	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: NO EFFECT OF REVISION ON PRIOR ACCOMPLISHMENT REV 2
19-JUN-2018		MOS		26-JUN-2018			
		HRS/MSC -					
		ENC					
SB PT6A-72-14359	NO. 1 ENGINE - PROPELLER SHAFT OIL SEAL RETAINING RINGS - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
18-MAY-2004		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14359 R01	NO. 1 ENGINE - PROPELLER SHAFT OIL SEAL RETAINING RINGS - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
03-DEC-2004		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14360	NO. 1 ENGINE - INTERCONNECT ROD - INSPECTION OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
02-AUG-2004		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14361	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY (BOV) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	04-AUG-2004	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14363	NO. 1 ENGINE - SAFETY WIRE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - BY EFFECTIVITY
		MOS		28-SEP-2015			
	12-JUL-2013	HRS/MSC - (s)		1819.92			
		ENC		1496			
SB PT6A-72-14363 R01	NO. 1 ENGINE - SAFETY WIRE - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - BY EFFECTIVITY
		MOS					
	21-MAR-2017	HRS/MSC -					
		ENC					
SB PT6A-72-14364	NO. 1 ENGINE - FUEL CONTROL UNIT - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	23-DEC-2004	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14364 R01	NO. 1 ENGINE - FUEL CONTROL UNIT - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	22-AUG-2005	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14364 R02	NO. 1 ENGINE - FUEL CONTROL UNIT - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
		MOS		31-JAN-2012			
	23-JAN-2006	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14366	NO. 1 ENGINE - COMPRESSOR TURBINE AIR SEAL ASSY OF - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	21-FEB-2005	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14366 R01	NO. 1 ENGINE - COMPRESSOR TURBINE AIR SEAL ASSY OF - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	01-MAR-2005	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14368	NO. 1 ENGINE - POWER TURBINE SEALING RING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	21-MAR-2005	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14369	NO. 1 ENGINE - POWER TURBINE BLADES - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
		MOS		31-JAN-2012			
	22-MAR-2005	HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14369 R01	NO. 1 ENGINE - POWER TURBINE BLADES - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
		MOS		31-JAN-2012			
	06-JUN-2006	HRS/MSC -		5			
		ENC		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14369 R02	NO. 1 ENGINE - POWER TURBINE BLADES - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE - BY ENGINE MODEL
16-MAY-2014		MOS		19-JUN-2014			
		HRS/MSC -		1105.17			
		ENC		898			
SB PT6A-72-14371	NO. 1 ENGINE - REPLACEMENT OF TURBOPROP ENGINE FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
15-APR-2005		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14374	NO. 1 ENGINE - SEAL PLAIN - REPLACEMENT OF, SERVICE BULLETIN						NOT APPLICABLE
28-JUN-2005		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14374 R01	NO. 1 ENGINE - SEAL PLAIN - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE
		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14377	NO. 1 ENGINE - POWER TURBINE SHAFT HOUSING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
09-NOV-2005		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14377 R02	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY EFFECTIVITY: BY ENGINE MODEL
30-AUG-2021		MOS		04-OCT-2021			
		HRS/MSC -					
		ENC					
SB PT6A-72-14379	NO. 1 ENGINE - AIR PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
23-SEP-2005		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14381 R03	NO. 1 ENGINE - STARTER GENERATOR DRIVE GEARSHAFT - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - By Part: N/A BY ENGINE MODEL
05-SEP-2017		MOS					
		HRS/MSC -					
		ENC					
		ACH					
		FLTS					
SB PT6A-72-14384	NO. 1 ENGINE - FUEL PUMP COUPLING SHAFT SPLINE - INSPECTION OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14386 R03	NO. 1 ENGINE - POWER TURBINE BLADES - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY ENGINE MODEL
14-MAR-2016		MOS					
		HRS/MSC -					
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14387	NO. 1 ENGINE - BRUSH-BLOCK MOUNTING BRACKET - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - BY ENGINE MODEL
16-JUN-2006		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14388	NO. 1 ENGINE - COMPONENT - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE
11-JUN-2006		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14391 R01	NO. 1 ENGINE - OIL FILTER ELEMENT - REPLACEMENT OF (SUPERSEDED BY SPARE PARTS BULLETIN SPB 149), SERVICE BULLETIN					CANCELLED	NOT APPLICABLE
15-JUN-2009		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14392 R01	NO. 1 ENGINE - OIL FILTER ELEMENT - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	DECLINED - BY EXECUTIVE MANAGER DECISION
11-JUN-2009		MOS		04-SEP-2018			
		HRS/MSC -					
		ENC					
SB PT6A-72-14393	NO. 1 ENGINE - P3-AIR-PRESSURE TUBE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE
14-NOV-2006		MOS		31-JAN-2012			
		HRS/MSC -		5			
		ENC		5			
SB PT6A-72-14395 R03	NO. 1 ENGINE - BOLTS AND NUTS OF THE FCU CONNECTOR ROD - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY EFFECTIVITY
21-AUG-2008		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14399 R02	NO. 1 ENGINE - AIR SEAL OF THE COMPRESSOR TURBINE STATOR - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	COMPLIED WITH - AT MANUFACTURE
28-NOV-2007		MOS		29-NOV-2011			
		HRS/MSC -		0			
		ENC		0			
SB PT6A-72-14399 R03	NO. 1 ENGINE - REPLACEMENT OF AIR SEAL OF THE COMPRESSOR TURBINE STATOR, SERVICE BULLETIN					CATEGORY 6	DECLINED - BY EXECUTIVE MANAGER DECISION
18-NOV-2021		MOS		(EFF)			
		HRS/MSC -					
		ENC					
SB PT6A-72-14400 R01	NO. 1 ENGINE - PROPELLER-SHAFT OIL SEAL RUNNER - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
07-MAY-2014		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14405 R02	NO. 1 ENGINE - AIR INLET SCREEN - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
09-JUL-2008		MOS		28-SEP-2015			
		HRS/MSC -					
		ENC					
SB PT6A-72-14407	NO. 1 ENGINE - THE OIL PRESSURE TUBE OF THE NO. 3 & 4 BEARING - REPLACEMENT OF, SERVICE BULLETIN						COMPLIED WITH
22-AUG-2007		MOS		09-JUL-2011			
		HRS/MSC -					
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14407 R03	NO. 1 ENGINE - THE OIL PRESSURE TUBE OF THE NO. 3 & 4 BEARING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
30-OCT-2009		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14408 R02	NO. 1 ENGINE - REPLACEMENT OF CT ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
14-MAY-2008		MOS		29-NOV-2011			
		HRS/MSC -		0			
		ENC		0			
SB PT6A-72-14411	NO. 1 ENGINE - REPLACEMENT OF BOLTS AND NUTS OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
27-SEP-2007		MOS		09-JUL-2011			
		HRS/MSC -					
		ENC					
SB PT6A-72-14411 R02	NO. 1 ENGINE - REPLACEMENT OF BOLTS AND NUTS OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - BY EFFECTIVITY
21-AUG-2008		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14415 R01	NO. 1 ENGINE - STARTER-GENERATOR GEARSHAFT - REPLACEMENT / MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
21-AUG-2008		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14417	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY EFFECTIVITY
22-APR-2008		MOS		28-SEP-2015			
		HRS/MSC - (s)		1819.92			
		ENC		1496			
SB PT6A-72-14417 R01	NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN						NOT APPLICABLE - BY EFFECTIVITY
12-DEC-2016		MOS		15-DEC-2016			
		HRS/MSC -					
		ENC					
SB PT6A-72-14419	NO. 1 ENGINE - INTRODUCTION OF PREFORMED PACKINGS BETWEEN THE AGB AND THE SCAVENGE PUMP HOUSING , SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY EFFECTIVITY
26-JUN-2008		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14421 R02	NO. 1 ENGINE - REPLACEMENT OF PROPELLER SHAFT PLAIN SEAL, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
05-JUN-2009		MOS		28-SEP-2015			
		HRS/MSC -					
		ENC					
SB PT6A-72-14425	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF EXTERNAL OIL SCAVENGE TUBE, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
15-JAN-2009		MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14427	NO. 1 ENGINE - REPLACEMENT OF PROPELLER SHAFT PLAIN SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
23-JAN-2009		MOS		09-JUL-2011			
		HRS/MSC -					
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14427 R01	NO. 1 ENGINE - REPLACEMENT OF PROPELLER SHAFT PLAIN SEAL, SERVICE BULLETIN						COMPLIED WITH
	28-JAN-2009	MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-14427 R02	NO. 1 ENGINE - REPLACEMENT OF PROPELLER SHAFT PLAIN SEAL, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY EFFECTIVITY
	28-JAN-2009	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14428 R02	NO. 1 ENGINE - PROPELLER-SHAFT OIL SEAL RETAINING-RING-HALVES - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
	31-MAR-2017	MOS		04-SEP-2018			
		HRS/MSC -					
		ENC					
SB PT6A-72-14429 R01	NO. 1 ENGINE - PROPELLER SHAFT SEAL RUNNER - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
	05-JUN-2009	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14430	NO. 1 ENGINE - REPLACEMENT OF REAR FIRESEAL MOUNTING RINGS, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
	09-JUN-2009	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14431 R01	NO. 1 ENGINE - FUEL CONTROL UNIT - INSPECTION, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
	06-JUL-2009	MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14441 R02	NO. 1 ENGINE - PY AND P3 INSULATED AIR PRESSURE TUBES - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	DEFERRED - WILL BE PERFORMED AT THE NEXT OVERHAUL ( CAT 5 ) COVER BY ESP GOLD CONTRACT
	07-JAN-2013	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14442	NO. 1 ENGINE - INSPECTION OF PROPELLER SHAFT SEAL, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - BY EFFECTIVITY
	01-JUN-2010	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14443 R02	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR INLET CASE, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - DURING ENG OH. SEE WO JFS-007-19 R02
	22-AUG-2013	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14444	NO. 1 ENGINE - INSTALLATION OF FIRST STAGE CARRIER BOLTS , SERVICE BULLETIN					CATEGORY 3	- SUPERSEDED BY SB PT6A-72-14456 R01
		MOS					
		HRS/MSC -					
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14444 R01	NO. 1 ENGINE - INSTALLATION OF FIRST STAGE CARRIER BOLTS, SERVICE BULLETIN					CATEGORY 3	- SUPERSEDED BY SB PT6A-72-14456 R01
	11-NOV-2010	MOS					
		HRS/MSC -					
		ENC					
SB PT6A-72-14444 R02	NO. 1 ENGINE - INSTALLATION OF FIRST STAGE CARRIER BOLTS (SUPERSEDED BY SB PT6A-72-14456 R02), SERVICE BULLETIN					SUPERSEDED	- SUPERSEDED BY P&WC S.B. NO. 14456.
	06-NOV-2019	MOS		07-NOV-2019			
		HRS/MSC -		4176.75			
		ENC		3488			
SB PT6A-72-14445	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - IAW SB 14603 LAST REVISION
	20-DEC-2010	MOS		28-NOV-2013			
		HRS/MSC -		777.92			
		ENC		623			
SB PT6A-72-14445 R01	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - IAW SB 14603 LAST REVISION
	20-DEC-2010	MOS		28-NOV-2013			
		HRS/MSC -		777.92			
		ENC		623			
SB PT6A-72-14445 R02	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - IAW SB 14603 LAST REVISION
		MOS		28-NOV-2013			
		HRS/MSC -		777.92			
		ENC		623			
SB PT6A-72-14445 R03	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - IAW SB 14603 LAST REVISION
		MOS		28-NOV-2013			
		HRS/MSC -		777.92			
		ENC		623			
SB PT6A-72-14445 R04	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 10	COMPLIED WITH - IAW SB 14603 LAST REVISION
	29-AUG-2013	MOS		28-NOV-2013			
		HRS/MSC -		777.92			
		ENC		623			
SB PT6A-72-14447	NO. 1 ENGINE - INSPECTION OF GAS GENERATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY ENGINE S/N
	26-NOV-2010	MOS		24-JUL-2014			
		HRS/MSC -		1166.42			
		ENC		951			
SB PT6A-72-14447 R01	NO. 1 ENGINE - INSPECTION OF GAS GENERATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
	23-APR-2013	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14449	NO. 1 ENGINE - REPLACEMENT OF 4TH STAGE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
	14-FEB-2012	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14450	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY
	08-JUL-2011	MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14451	NO. 1 ENGINE - REPLACEMENT OF NO.2 BEARING OIL PACKING, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
01-JUN-2011		MOS HRS/MSC - ENC		09-JUL-2011			
SB PT6A-72-14451 R01	NO. 1 ENGINE - REPLACEMENT OF NO.2 BEARING OIL PACKING, SERVICE BULLETIN					CATEGORY 6	- PREVIOUSLY C/W R0 (AT MANUFACTURE)
09-MAR-2015		MOS HRS/MSC - ENC		28-SEP-2015 1819.92 1496			
SB PT6A-72-14452 R01	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL OIL LEVEL FILLER CAP AND INDICATOR, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
02-AUG-2011		MOS HRS/MSC - ENC		04-SEP-2018			
SB PT6A-72-14453	NO. 1 ENGINE - REPLACEMENT OF PROPELLER GEARBOX ASSEMBLY KEY WASHERS AND 1ST STAGE CARRIER BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
12-JUL-2011		MOS HRS/MSC - ENC		04-SEP-2018			
SB PT6A-72-14456	NO. 1 ENGINE - FIRST STAGE REDUCTION CARRIER BOLTS - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 5	DEFERRED - WILL BE PERFORMED AT THE NEXT OVERHAUL ( CAT 5 ) COVER BY ESP GOLD CONTRACT
03-FEB-2012		MOS HRS/MSC - ENC		28-SEP-2015 1819.92 1496			
SB PT6A-72-14456 R01	NO. 1 ENGINE - FIRST STAGE REDUCTION CARRIER BOLTS - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 5	DEFERRED - WILL BE PERFORMED AT THE NEXT OVERHAUL ( CAT 5 ) COVER BY ESP GOLD CONTRACT
11-NOV-2015		MOS HRS/MSC - ENC		11-NOV-2015			
SB PT6A-72-14456 R02	NO. 1 ENGINE - FIRST STAGE REDUCTION CARRIER BOLTS - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 5	- TO BE PERFORM AT NEXT OVERHAUL
06-NOV-2019		MOS HRS/MSC - ENC AFL		(EFF)			
SB PT6A-72-14457	NO. 1 ENGINE - TURBOPROP ENGINE X-RAY INSPECTION OF THE NO. 2 BEARING OIL-PRESSURE-TUBE BOSS OF THE GAS GENERATOR CASE, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY EFFECTIVITY
20-JAN-2012		MOS HRS/MSC - ENC		28-SEP-2015 1819.92 1496			
SB PT6A-72-14469	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR INLET CASE ASSEMBLY, SERVICE BULLETIN						DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS HRS/MSC - ENC					
SB PT6A-72-14469 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR INLET CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
16-MAY-2014		MOS HRS/MSC - ENC		04-SEP-2018			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14470 R06	NO. 1 ENGINE - SHAFT AND SLEEVE SET PROPELLER - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	- Informational Only: WILL BE EMBODIED AT NEXT OVERHAUL (ESP)
20-JAN-2018		MOS HRS/MSC - ENC AFL		04-SEP-2018			
SB PT6A-72-14470 R07	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF SHAFT AND SLEEVE SET PROPELLER, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DECLINED BY EXECUTIVE MANAGER DECISION
19-DEC-2019		MOS HRS/MSC - ENC AFL					
SB PT6A-72-14470 R08	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF SHAFT AND SLEEVE SET PROPELLER, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
26-FEB-2021		MOS HRS/MSC - ENC		(EFF)			
SB PT6A-72-14470 R09	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF SHAFT AND SLEEVE SET PROPELLER, SERVICE BULLETIN					CATEGORY 7	- WILL BE PERFORM AT NEXT OVERHAUL
11-MAY-2021		MOS HRS/MSC - ENC		(EFF)			
SB PT6A-72-14473	NO. 1 ENGINE - INSPECTION OF TORQUE LIMITER, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
25-OCT-2013		MOS HRS/MSC - ENC		19-FEB-2014 868.67 703			
SB PT6A-72-14473 R01	NO. 1 ENGINE - INSPECTION OF TORQUE LIMITER, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
10-DEC-2013		MOS HRS/MSC - ENC		19-FEB-2014 868.67 706			
SB PT6A-72-14473 R02	NO. 1 ENGINE - INSPECTION OF TORQUE LIMITER, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
24-APR-2014		MOS HRS/MSC - ENC		28-APR-2014 1005.67 820			
SB PT6A-72-14473 R03	NO. 1 ENGINE - INSPECTION OF TORQUE LIMITER, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - P C/W REV 2
26-FEB-2015		MOS HRS/MSC - ENC		01-MAR-2015 1440.83 1182			
SB PT6A-72-14479	NO. 1 ENGINE - REPLACEMENT OF ROTOR COMPRESSOR TIE RODS, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
19-MAR-2014		MOS HRS/MSC - ENC		28-SEP-2015 1819.92 1496			
SB PT6A-72-14481 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT , SERVICE BULLETIN					CATEGORY 6	DEFERRED - WILL BE PERFORMED AT THE NEXT OVERHAUL ( CAT 6 ) COVER BY ESP GOLD CONTRACT
08-JUL-2014		MOS HRS/MSC - ENC		28-SEP-2015 1819.92 1496			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14484	NO. 1 ENGINE - REPLACEMENT OF PROPELLER OVERSPEED GOVERNOR, SERVICE BULLETIN					CATEGORY 7	DECLINED - SEE SB 14484 REV 1
	20-AUG-2014	MOS		28-SEP-2015			
		HRS/MSC - (s)		1819.92			
		ENC		1496			
SB PT6A-72-14484 R01	NO. 1 ENGINE - REPLACEMENT OF PROPELLER OVERSPEED GOVERNOR, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
	20-JUN-2016	MOS		20-OCT-2016			
		HRS/MSC -					
		ENC					
SB PT6A-72-14484 R02	NO. 1 ENGINE - REPLACEMENT OF PROPELLER OVERSPEED GOVERNOR, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - declined by executive manager decision
	19-JUN-2018	MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14485	NO. 1 ENGINE - REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY
	07-MAY-2014	MOS		01-MAR-2015			
		HRS/MSC -		1440.83			
		ENC		1182			
SB PT6A-72-14492 R06	NO. 1 ENGINE - INTRODUCTION OF AERO SHELL TURBO OIL 560 (ASTO 560) OIL, SERVICE BULLETIN					CANCELLED	DECLINED - BY EXECUTIVE MANAGER DECISION
	09-MAY-2016	MOS		12-MAY-2016			
		HRS/MSC -					
		ENC					
SB PT6A-72-14495 R01	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - NEW SET NOZZLE INCORPORATED WITH SB INCLUDED
		MOS		11-JUN-2015			
		HRS/MSC -		1588.17			
		ENC		1305			
SB PT6A-72-14495 R02	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - NEW SET NOZZLE INCORPORATED WITH SB INCLUDED REVISION 1 COMPLIED IAW SB PT6A-72-14495 REV 1 & R2 NO EVOLUTION WITH R1
		MOS		04-NOV-2015			
		HRS/MSC -					
		ENC					
SB PT6A-72-14495 R03	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - NO EFFECT OF REVISION ON PRIOR ACCOMPLISHMENT REVISION 2
		MOS		11-DEC-2015			
		HRS/MSC -					
		ENC					
SB PT6A-72-14495 R04	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - NO EFFECT OF REVISION ON PRIOR ACCMPLISHMENT REVISION 2
	28-OCT-2016	MOS		08-NOV-2016			
		HRS/MSC -					
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14495 R05	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - PREVIOUSLY COMPLIED WITH: INSPECTION OF FUEL NOZZLE TIPS - FOUND N/A BY S/N FITTED - NO FURTHER ACTION REQUIRED NEW SET NOZZLE INCORPORATED WITH SB INCLUDED SEE WORK REPORT PILATUS UK N° J0084 AND WORK ORDER JETFLY AVIATION PC12-130-15
04-FEB-2019		MOS HRS/MSC - ENC		11-JUN-2015 1588.17 1305			
SB PT6A-72-14495 R06	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - By Effectivity- N/A BY ENGINE TYPE EFFECTIVITY. REVISION 6 DOES NOT SUPPRESS REVISION 5
14-MAR-2022		MOS HRS/MSC - ENC AFL					
SB PT6A-72-14496 R02	NO. 1 ENGINE - FUEL PUMP - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - BY ENGINE TYPE (ENGINE PT6A-67P INSTALLED)
		MOS HRS/MSC - ENC		13-MAY-2015			
SB PT6A-72-14497 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
27-MAY-2015		MOS HRS/MSC - ENC		16-APR-2017 1819.92 2683			
SB PT6A-72-14497 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - declined by executive manager decision
19-JUN-2018		MOS HRS/MSC - ENC AFL					
SB PT6A-72-14498	NO. 1 ENGINE - INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY PART NUMBER OF POWER TURBINE STATOR HOUSINGS (P/N:3043705-1 INSTALLED)
20-MAR-2015		MOS HRS/MSC - ENC		25-MAR-2015			
SB A PT6A-72-14498 PART	NO. 1 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIR (PER OHM IN A P&WC SERVICE CENTER OR P&WC DOF)					CATEGORY 3	NOT APPLICABLE - BY PART NUMBER OF POWER TURBINE STATOR HOUSINGS (P/N:3043705-1 INSTALLED)
20-MAR-2015		MOS HRS/MSC - ENC		25-MAR-2015			
SB B PT6A-72-14498 PART	NO. 1 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIRED (PER OHM DATED MAR 24/2014 IN ANOTHER FACILITY (NOT P&WC SERVICE CENTERS OR P&WC DOFS))					CATEGORY 3	NOT APPLICABLE - BY PART NUMBER OF POWER TURBINE STATOR HOUSINGS (P/N:3043705-1 INSTALLED)
20-MAR-2015		MOS HRS/MSC - ENC		25-MAR-2015			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14499	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - POST SB PT6A-72-14452 REV 1 (P/N:3045457-01 INSTALLED)
		MOS		18-MAY-2015			
		HRS/MSC -					
		ENC					
SB PT6A-72-14499 PART A	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT					CATEGORY 3	NOT APPLICABLE - POST SB PT6A-72-14452 REV 1 (P/N:3045457-01 INSTALLED)
		MOS		18-MAY-2015			
		HRS/MSC -					
		ENC					
SB PT6A-72-14499 PART B	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED					CATEGORY 3	NOT APPLICABLE - POST SB PT6A-72-14452 REV 1 (P/N:3045457-01 INSTALLED)
		MOS		18-MAY-2015			
		HRS/MSC -					
		ENC					
SB PT6A-72-14499 R01	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR (THIS SERVICE BULLETIN REMOVES THIS MODEL FROM APPLICABILITY), SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - POST SB PT6A-72-14452 REV 1 (P/N:3045457-01 INSTALLED)
		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14499 R01 PART A	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR (THIS SERVICE BULLETIN REMOVES THIS MODEL FROM APPLICABILITY), SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT					CATEGORY 3	NOT APPLICABLE - POST SB PT6A-72-14452 REV 1 (P/N:3045457-01 INSTALLED)
		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14499 R01 PART B	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR (THIS SERVICE BULLETIN REMOVES THIS MODEL FROM APPLICABILITY), SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED					CATEGORY 3	NOT APPLICABLE - POST SB PT6A-72-14452 REV 1 (P/N:3045457-01 INSTALLED)
		MOS		28-SEP-2015			
		HRS/MSC -		1819.92			
		ENC		1496			
SB PT6A-72-14506 R01	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		11-DEC-2017			
		HRS/MSC -					
		ENC					
SB PT6A-72-14506 R02	NO. 1 ENGINE - REPLACEMENT OF TURBOPROP ENGINE COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
		MOS		(EFF)			
		HRS/MSC -					
		ENC					
SB PT6A-72-14507	NO. 1 ENGINE - INSPECTION OF INTERCONNECT ROD, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS		14-AUG-2015			
		HRS/MSC -		1734.75			
		ENC		1429			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14507 R01	NO. 1 ENGINE - INSPECTION OF INTERCONNECT ROD, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - SB 14507 R0 PERFORMED
06-JUL-2016		MOS HRS/MSC - ENC		17-AUG-2016			
SB PT6A-72-14507 R02	NO. 1 ENGINE - INSPECTION OF INTERCONNECT ROD, SERVICE BULLETIN						COMPLIED WITH - PREVIOUSLY COMPLIED WITH: ALREADY COMPLIED WITH
15-JAN-2019		MOS HRS/MSC - ENC		01-FEB-2020 4314.67 3610			
SB PT6A-72-14511	NO. 1 ENGINE - SECOND STAGE POWER TURBINE - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY ( ENGINE SERIAL NUMBER )
		MOS HRS/MSC - (s) ENC		04-DEC-2015			
SB PT6A-72-14511 R01	NO. 1 ENGINE - SECOND STAGE POWER TURBINE - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY (ENGINE SERIAL NUMBER)
21-JAN-2016		MOS HRS/MSC - (s) ENC		25-JAN-2016			
SB PT6A-72-14511 R02	NO. 1 ENGINE - SECOND STAGE POWER TURBINE - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY EFFECTIVITY (ENGINE SERIAL NUMBER)
08-MAR-2016		MOS HRS/MSC - (s) ENC		10-MAR-2016			
SB PT6A-72-14511 R03	NO. 1 ENGINE - SECOND STAGE POWER TURBINE - INSPECTION/REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY SERIAL NUMBER ENGINE
17-AUG-2016		MOS HRS/MSC - ENC		19-AUG-2016			
SB PT6A-72-14511 R04	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF POWER TURBINE - SECOND STAGE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - BY SERIAL: ENGINE POWER SECTION SERIAL NUMBER
19-OCT-2022		MOS HRS/MSC - ENC		31-OCT-2022			
SB PT6A-72-14512 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION. SB WILL BE EMBODIED WHEN FCU EXCHANGE BY PWC
15-DEC-2016		MOS HRS/MSC - ENC		19-JAN-2017			
SB PT6A-72-14512 R05	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - PERFORMED DURING ENGINE OVERHAUL
24-OCT-2017		MOS HRS/MSC - ENC		04-JUL-2019 3894.5 3208			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14512 R06	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY: THIS SERVICE BULLETIN IS REVISED TO MODIFY THE PT6A-66B EFFECTIVITY.
28-APR-2023		MOS HRS/MSC - ENC		02-MAY-2023			
SB PT6A-72-14513 R01	NO. 1 ENGINE - REPLACEMENT OF NO. 3 BEARING SCAVENGE TUBE RETAINING PLATE, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
19-OCT-2016		MOS HRS/MSC - ENC					
SB PT6A-72-14514 R01	NO. 1 ENGINE - CONVERSION OF PT6A-67P ENGINE (BS1226) TO PT6A-67P ENGINE (BS1361), SERVICE BULLETIN					CATEGORY 8	DECLINED - BY EXECUTIVE MANAGER DECISION
23-JUN-2016		MOS HRS/MSC - ENC		20-OCT-2016			
SB PT6A-72-14516	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE VANE RING, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
18-DEC-2015		MOS HRS/MSC - ENC		09-MAR-2016			
SB PT6A-72-14516 R01	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE VANE RING, SERVICE BULLETIN					CATEGORY 7	DECLINED - BY EXECUTIVE MANAGER DECISION
08-DEC-2017		MOS HRS/MSC - ENC AFL					
SB PT6A-72-14520	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR INLET CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY (ENGINE'S MODEL NOT CONCERNED)
28-APR-2016		MOS HRS/MSC - ENC		04-MAY-2016			
SB PT6A-72-14520 R01	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR INLET CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - By Effectivity: BY ENGINE MODEL
08-NOV-2019		MOS HRS/MSC - ENC AFL					
SB PT6A-72-14531	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 6	DEFERRED - WILL BE EMBODIED AT NEXT OVERHAUL
09-JAN-2018		MOS HRS/MSC - ENC AFL		04-SEP-2018			
SB PT6A-72-14532	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	- SUPERSEDED BY LATEST REVISION
17-NOV-2017		MOS HRS/MSC - ENC		(EFF)			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14532 R01	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - Superseded: by SB 72-14532 Rev.2
23-APR-2017		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14532 R02	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	- SUPERSEDED BY LATEST VERSION
25-APR-2018		MOS		(EFF)			
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14532 R03	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - Superseded: by new revision R04
09-MAY-2018		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14532 R04	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - declined by executive manager decision
27-JUL-2018		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14533 R02	NO. 1 ENGINE - OIL FILTER AND P3 AIR FILTER INSPECTION INTERVAL - EVALUATION OF, SERVICE BULLETIN						NOT APPLICABLE - By Effectivity: engine s/n
18-JUL-2018		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14533 R03	NO. 1 ENGINE - OIL FILTER INSPECTION INTERVAL - EVALUATION OF, SERVICE BULLETIN						NOT APPLICABLE - By Effectivity: BY ENGINE MSN
18-OCT-2018		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14533 R04	NO. 1 ENGINE - OIL FILTER INSPECTION INTERVAL - EVALUATION OF, SERVICE BULLETIN						NOT APPLICABLE - By Effectivity: see SB TABLE 1, Engine Serial Number listed
18-OCT-2019		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14533 R05	NO. 1 ENGINE - OIL FILTER INSPECTION INTERVAL - EVALUATION OF, SERVICE BULLETIN						NOT APPLICABLE - By Serial: by Eng. SN (TABLE 1, Engine Serial Number)
27-APR-2020		MOS					
		HRS/MSC -					
		ENC					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14534	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - INFORMATIONAL ONLY: SUPERSEDED BY LATEST REVISION
		MOS		25-MAY-2018			
		09-MAR-2018	HRS/MSC -	3469.25			
			ENC	2852			
SB PT6A-72-14534 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - INFORMATIONAL ONLY: SUPERSEDED BY LATEST REVISION
		MOS		25-MAY-2018			
		27-MAR-2018	HRS/MSC -	3469.25			
			ENC	2852			
SB PT6A-72-14534 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - Superseded: by new revision R03
		MOS					
		09-MAY-2018	HRS/MSC -				
			ENC				
			AFL				
SB PT6A-72-14534 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
		MOS		04-NOV-2021			
		18-SEP-2018	HRS/MSC -	4881			
			ENC	4090			
SB PT6A-72-14535	NO. 1 ENGINE - REPLACEMENT OF FIRST-STAGE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - declined by executive manager decision
		MOS					
		01-JUN-2018	HRS/MSC -				
			ENC				
			AFL				
SB PT6A-72-14535 R01	NO. 1 ENGINE - REPLACEMENT OF FIRST-STAGE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - declined by executive manager decision
		MOS					
		25-JAN-2019	HRS/MSC -				
			ENC				
SB PT6A-72-14535 R02	NO. 1 ENGINE - REPLACEMENT OF FIRST-STAGE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 5	- TO BE PERFORMED AT NEXT OVERHAUL
		MOS		(EFF)			
		24-JUL-2019	HRS/MSC -				
			ENC				
			AFL				
SB PT6A-72-14535 R03	NO. 1 ENGINE - REPLACEMENT OF FIRST-STAGE COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- AT NEXT OVERHAUL
		MOS		(EFF)			
		11-DEC-2020	HRS/MSC -				
			ENC				
			AFL				
SB PT6A-72-14536	NO. 1 ENGINE - INSPECTION OF SECOND-STAGE POWER TURBINE BLADE LIFE LIMIT, SERVICE BULLETIN						NOT APPLICABLE - By Effectivity: BY ENGINE S/N
		MOS					
		12-JUN-2018	HRS/MSC -				
			ENC				
			AFL				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14537	NO. 1 ENGINE - FUEL NOZZLE EVALUATION, SERVICE BULLETIN						NOT APPLICABLE - By Effectivity: engine s/n
18-JUL-2018		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14537 R01	NO. 1 ENGINE - FUEL NOZZLE EVALUATION, SERVICE BULLETIN						NOT APPLICABLE - By Effectivity: BY ENGINE MSN
18-OCT-2018		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14537 R02	NO. 1 ENGINE - FUEL NOZZLE EVALUATION, SERVICE BULLETIN						NOT APPLICABLE - By Effectivity: BY ACFT MSN
03-APR-2019		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14546	NO. 1 ENGINE - REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- SUPERSEDED BY R1
07-FEB-2020		MOS		(EFF)			
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14546 R01	NO. 1 ENGINE - REPLACEMENT OF NO. 3 AND 4 BEARING OIL-PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	- SB WILL BE DONE AT NEXT OVERHAUL
03-MAR-2020		MOS		(EFF)			
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14549	NO. 1 ENGINE - INSPECTION OF SMALL EXIT DUCT, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - BY ESN
16-JUL-2020		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-72-14553	NO. 1 ENGINE - REPLACEMENT OF OIL TEMPERATURE BULB BOLTS, SERVICE BULLETIN					CATEGORY 8	- AT NEXT OVERHAUL
01-FEB-2021		MOS		(EFF)			
		HRS/MSC -					
		ENC					
SB PT6A-72-14560	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX GEARSHAFT DRIVE, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY: BY ENGINE MODEL (PT6A-67B)
24-NOV-2021		MOS			25-NOV-2021		
		HRS/MSC -					
		ENC					
SB PT6A-72-14560 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX GEARSHAFT DRIVE, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - By Effectivity- BY ENGINE MODEL
05-JAN-2022		MOS					
		HRS/MSC -					
		ENC					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14562	NO. 1 ENGINE - MODIFICATION OF SHIPPING CONTAINER, SERVICE BULLETIN						NOT APPLICABLE - BY PART: ENGINE
19-OCT-2022		MOS HRS/MSC - ENC		21-OCT-2022			
SB PT6A-72-14565	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY SERIAL: ESN
19-JAN-2023		MOS HRS/MSC - ENC		23-JAN-2023			
SB PT6A-72-14565 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - BY EFFECTIVITY: BY ENGINE MODEL
03-FEB-2023		MOS HRS/MSC - ENC		08-FEB-2023			
SB PT6A-72-14573	NO. 1 ENGINE - MODIFICATION OF COMBUSTION-CHAMBER OUTER-LINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	- PLANNED AT NEXT ENGINE OH
26-JAN-2024		MOS HRS/MSC - ENC AFL			<b>8394.5 M</b>		
SB PT6A-72-14603	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
13-JUL-1990		MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R01	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
19-FEB-1991		MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R02	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
27-SEP-1993		MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R03	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
19-JUN-1995		MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R04	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
14-SEP-2000		MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R05	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
08-NOV-2000		MOS HRS/MSC - ENC		31-JAN-2012 5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14603 R06	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	07-MAY-2002	MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R07	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	04-JUN-2003	MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R08	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	18-DEC-2003	MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R09	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	19-FEB-2004	MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R10	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	29-SEP-2005	MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R11	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	04-JAN-2006	MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R12	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	29-MAR-2007	MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R13	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	01-APR-2008	MOS HRS/MSC - ENC		31-JAN-2012 5 5			
SB PT6A-72-14603 R14	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
	01-AUG-2008	MOS HRS/MSC - ENC		31-JAN-2012 5 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14603 R15	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						NOT APPLICABLE - SUPERSEDED
08-APR-2010		MOS		31-JAN-2012			
		HRS/MSC	-	5			
		ENC		5			
SB PT6A-72-14603 R22	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH - ACTION PROCESS
12-DEC-2013		MOS		28-SEP-2015			
		HRS/MSC	-	1819.92			
		ENC		1496			
SB PT6A-72-14603 R23	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH - SB IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
19-OCT-2015		MOS		04-NOV-2015			
		HRS/MSC	-(s)				
		ENC					
SB PT6A-72-14603 R24	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH - SB IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
05-JAN-2016		MOS		07-JAN-2016			
		HRS/MSC	-(s)				
		ENC					
SB PT6A-72-14603 R25	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH - SB IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
17-MAR-2016		MOS		25-MAR-2016			
		HRS/MSC	-(s)				
		ENC					
SB PT6A-72-14603 R26	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN						COMPLIED WITH - SB IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
19-SEP-2016		MOS		21-SEP-2016			
		HRS/MSC	-				
		ENC					
SB PT6A-72-14603 R27	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - TAKE IN ACCOUNT IN JETFLY AMP
07-JUL-2017		MOS					
		HRS/MSC	-				
		ENC					
SB PT6A-72-14603 R28	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - TAKE IN ACCOUNT JETFLY AMP
02-AUG-2019		MOS					
		HRS/MSC	-				
		ENC					
		AFL					
SB PT6A-72-14603 R29	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - TAKE IN ACCOUNT IN JETFLY AMP
21-MAY-2020		MOS					
		HRS/MSC	-				
		ENC					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14603 R30	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
13-SEP-2021		MOS		04-NOV-2021			
		HRS/MSC -		4881			
		ENC		4090			
SB PT6A-72-14603 R31	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY , SERVICE BULLETIN						- Informational Only - TIME LIMITS / AMP. TBO AND HIS FREQUENCY
26-APR-2024		MOS		(EFF)			
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-73-14545	NO. 1 ENGINE - REPLACEMENT OF TORQUE LIMITER ATTACHMENT BOLTS, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - By Effectivity: BY ENGINE MSN
25-JAN-2020		MOS					
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-73-14545 R01	NO. 1 ENGINE - REPLACEMENT OF TORQUE LIMITER ATTACHMENT BOLTS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
26-MAR-2020		MOS		06-APR-2023			
		HRS/MSC -		5729.5			
		ENC		4902			
SB PT6A-73-14547	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF OIL TO FUEL HEATER, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - INFORMATIONAL ONLY: COVER BY ESP GOLD AT NEXT ENGINE OVERHAUL.
11-MAR-2020		MOS		12-MAR-2020			
		HRS/MSC -					
		ENC					
SB PT6A-73-14547 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF OIL TO FUEL HEATER, SERVICE BULLETIN					CATEGORY 6	- INCLUDE THIS SERVICE BULLETIN AT OVERHAUL.
06-APR-2020		MOS		(EFF)			
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-73-14548	NO. 1 ENGINE - INTRODUCTION OF PARTS KIT, SERVICE BULLETIN					CATEGORY 9	COMPLIED WITH - INFORMATIONAL ONLY: SPARE PARTS INFORMATION ONLY.
20-APR-2020		MOS		27-APR-2020			
		HRS/MSC -					
		ENC					
SB PT6A-74-14564	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF IGNITION CABLE ASSEMBLY, SERVICE BULLETIN					CATEGORY 5	- SUPERSEDED BY R01
09-DEC-2022		MOS		(EFF)			
		HRS/MSC -					
		ENC					
		AFL					
SB PT6A-74-14564 R01	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF IGNITION CABLE ASSEMBLY, SERVICE BULLETIN					CATEGORY 5	- AT NEXT ENG OH
27-DEC-2022		MOS		(EFF)	19-JUN-2031 M		
		HRS/MSC -			9155.58 M		
		ENC					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SIL GEN-055 R08	NO. 1 ENGINE - GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES, SERVICE INFORMATION LETTER					RECOMMENDED	COMPLIED WITH - INFORMATIONAL ONLY: JETFLY USING EHM CAMP
06-NOV-2018		MOS		13-NOV-2018			
		HRS/MSC -		3836.25			
		ENC		3148			
SIL GEN-055 R09	NO. 1 ENGINE - GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES, SERVICE INFORMATION LETTER					RECOMMENDED	COMPLIED WITH - INFORMATIONAL ONLY: JETFLY USING EHM CAMP
08-NOV-2018		MOS		13-NOV-2018			
		HRS/MSC -		3835.33			
		ENC		3147			
SIL GEN-055 R10	NO. 1 ENGINE - GUIDELINES AND STANDARDS FOR SUBSCRIBING AND UTILIZING THE INTERNET-BASED ENGINE CONDITION TREND MONITORING EHM SERVICES, SERVICE INFORMATION LETTER					RECOMMENDED	COMPLIED WITH - INFORMATIONAL ONLY: JETFLY USING EHM CAMP
13-NOV-2018		MOS		16-NOV-2018			
		HRS/MSC -		3840.42			
		ENC		3157			
SIL GEN-153 R04	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R05), SERVICE INFORMATION LETTER					INFORMATIONAL	COMPLIED WITH - INFORMATIONAL ONLY: P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION
05-MAY-2020		MOS		24-MAY-2020			
		HRS/MSC -					
		ENC					
SIL GEN-153 R05	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06), SERVICE INFORMATION LETTER					INFORMATIONAL	- R05 APPLY ONLT FOR PT6T-3/3B/3BE/3BF/3BG, PT6T-3D/3DE/3DF, PT6T-6/6B, PT6T-9,PW206A/B/B2/B3/C/E, PW207C/D/D1/D2/E/K
28-SEP-2020		MOS		(EFF)			
		HRS/MSC -					
		ENC					
		AFL					
SIL GEN-153 R06	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	COMPLIED WITH - INFORMATIONAL ONLY: P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION
30-OCT-2020		MOS		06-NOV-2020			
		HRS/MSC -					
		ENC					
SIL GEN-153 R07	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER						COMPLIED WITH - INFORMATIONAL ONLY: FOR INFORMATION ONLY
05-JAN-2021		MOS		12-JAN-2021			
		HRS/MSC -					
		ENC					
SIL GEN-153 R08	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER						COMPLIED WITH - INFORMATIONAL ONLY:
15-SEP-2021		MOS		21-SEP-2021			
		HRS/MSC -					
		ENC					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SIL GEN-153 R09	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	- FOR INFORMATION ONLY
18-JAN-2022		MOS HRS/MSC ENC AFL	A/R	(EFF)			
SIL GEN-153 R10	NO. 1 ENGINE - P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION, SERVICE INFORMATION LETTER					INFORMATIONAL	- FOR INFORMATION ONLY. THE NEW REVISION ADDS THE FOLLOWING ENGINE P/NS: PT6A-34/42, PT6E-66XT, AND PW118/118A/118B/119A/120/120A/121/121A/123/12 3A/123AF/123B/123C/123D/123E/124B/125B/126/12 6A/127/127B/127C/127D/127E/127F/127G/127H/127 J/127M/127N/150A
31-OCT-2022		MOS HRS/MSC ENC AFL	A/R	(EFF)			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>PROPELLER NO. 1 - AD - KX1388/HC-E4A-3D</b>							
FAA 1994-10-01	NO. 1 PROPELLER - PROPELLERS - HARTZELL PROPELLER INC. MODEL HC-E4A-3A/E10950() PROPELLERS - MODIFICATION					MANDATORY	NOT APPLICABLE - BY PART NUMBER PROPELLER ( HC-EA4-3D )
39-8908 22-JUN-1994		MOS HRS/MSC - (s) ENC		20-SEP-2016 320.42			
FAA 1996-15-04	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. MODELS HC-B3TN, HC-B5MP, HC-E4A, AND HC-D4N SERIES PROPELLERS - INSPECTION					MANDATORY	NOT APPLICABLE - BY EFFECTIVITY MANUFACTURING PROPELLER ( NO MFG BETWEEN 1992 AND 1996 )
39-9697 29-JUL-1996		MOS HRS/MSC - (s)		19-SEP-2016 191.33			
FAA 1998-02-07	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. MODEL HC-E4A-3(A,I) PROPELLERS - MODIFICATION					MANDATORY	NOT APPLICABLE - BY PART NUMBER PROPELLER ( HC-EA4-3D )
39-10289 12-FEB-1998		MOS HRS/MSC - (s)		19-SEP-2016 191.33			
FAA 1998-17-04	NO. 1 PROPELLER - PROPELLER - ONE TIME INSPECTION OF THE PROPELLER BLADE COUNTERWEIGHT CLAMPS FOR THREAD DAMAGE IN THE BOLT HOLES AND, IF NECESSARY, REPLACEMENT WITH SERVICEABLE PARTS					MANDATORY	NOT APPLICABLE - BY PART NUMBER PROPELLER ( HC-EA4-3D )
39-10706		MOS HRS/MSC - (s)		19-SEP-2016 191.33			
FAA 2005-14-11	NO. 1 PROPELLER - PROPELLER - HARTZELL, MCCAULEY AND SENSENICH PROPELLERS RETURNED TO SERVICE BY SOUTHERN CALIFORNIA PROPELLER SERVICE OF INGLEWOOD, CA - MAINTENANCE ACTIONS AMOUNTING TO AN OVERHAUL					MANDATORY	NOT APPLICABLE - BY SUPPLIER
39-14188		MOS HRS/MSC - (s)					
FAA 2006-24-07	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. HC, BHC, AND PHC SERIES PROPELLERS AND MCCAULEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS					MANDATORY	NOT APPLICABLE
39-14836 03-JAN-2007		MOS HRS/MSC - (s)					
FAA 2006-24-07 PARA (H)	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. HC, BHC, AND PHC SERIES PROPELLERS AND MCCAULEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS PERFORM THE REQUIREMENTS SPECIFIED IN PARAGRAPH (J) OR PARAGRAPH (K) OF THIS AD (IF PROPELLER WAS INVOLVED IN A GROUND STRIKE)					MANDATORY	NOT APPLICABLE
39-14836 03-JAN-2007		MOS HRS/MSC - (s)					
FAA 2006-24-07 PARA (I)(1)	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. HC, BHC, AND PHC SERIES PROPELLERS AND MCCAULEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS PERFORM THE REQUIREMENTS SPECIFIED IN PARAGRAPH (J) OR PARAGRAPH (K) OF THIS AD AS APPLICABLE (NOT INVOLVED IN GROUND STRIKE / TSO 1500 FH OR MORE)					MANDATORY	NOT APPLICABLE
39-14836 03-JAN-2007		MOS HRS/MSC - (s)					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2006-24-07 PARA (I)(2)	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. HC, BHC, AND PHC SERIES PROPELLERS AND MCCAULEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS PERFORM THE REQUIREMENTS SPECIFIED IN PARAGRAPH (J) OR PARAGRAPH (K) OF THIS AD AS APPLICABLE (NOT INVOLVED IN GROUND STRIKE / TSO MORE THAN 1000 FH BUT LESS THAN 1500 FH)					MANDATORY	NOT APPLICABLE
39-14836 03-JAN-2007		MOS HRS/MSC	- (s)				
FAA 2006-24-07 PARA (I)(3)	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. HC, BHC, AND PHC SERIES PROPELLERS AND MCCAULEY PROPELLER SYSTEMS CONTROLLABLE PROPELLERS PERFORM THE REQUIREMENTS SPECIFIED IN PARAGRAPH (J) OR PARAGRAPH (K) OF THIS AD AS APPLICABLE (NOT INVOLVED IN GROUND STRIKE / TSO LESS THAN 1000 FH)					MANDATORY	NOT APPLICABLE
39-14836 03-JAN-2007		MOS HRS/MSC	- (s)				
FAA 2007-08-02	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. MODEL HC-E4A-3( ) / E10950( ) PROPELLERS - INSPECT / REPLACE					MANDATORY	NOT APPLICABLE - BY PART NUMBER PROPELLER ( HC-EA4-3D )
39-15019 27-APR-2007		MOS HRS/MSC	- (s)	19-SEP-2016 191.33			
FOCA HB-2005-372	NO. 1 PROPELLER - PROPELLER INSPECTION						NOT APPLICABLE - BY SUPPLIER
		MOS HRS/MSC	A/R (s)				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC	
<b>PROPELLER NO. 1 - SB - KX1388/HC-E4A-3D</b>								
ASB	HC-ASB-61-219 R01	NO. 1 PROPELLER - PROPELLER - COUNTERWEIGHT INSPECTION, ALERT SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY PROPELLER TYPE (HC.E4A.3D INSTALLED)
	02-JUL-1996	MOS HRS/MSC -		22-SEP-2016				
ASB	HC-ASB-61-220	NO. 1 PROPELLER - PROPELLER - BLADE INSPECTION, ALERT SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY PROPELLER SERIAL NUMBER
	08-JUL-1996	MOS HRS/MSC -		22-SEP-2016				
ASB	HC-ASB-61-237	NO. 1 PROPELLER - COUNTERWEIGHT INSPECTION, ALERT SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - BY PROPELLER TYPE (HC-E4A-3D INSTALLED)
		MOS HRS/MSC -		22-SEP-2016				
ASB	HC-ASB-61-386	NO. 1 PROPELLER - BLADES - SHOT PEENING (SHENYANG AVIAS), ALERT SERVICE BULLETIN						NOT APPLICABLE - By Effectivity: BY PROPELLER SN
		MOS HRS/MSC  AFL						
ASB	HC-ASB-61-399	NO. 1 PROPELLER - PROPELLERS OVERHAULED BY CHINA FLYING DRAGON GENERAL AVIATION, ALERT SERVICE BULLETIN						NOT APPLICABLE - NOT APPLICABLE. PARTS NOT OVHL BY CHINA FLYING DRAGON GENERAL AVIATION
	03-AUG-2022	MOS HRS/MSC -		08-AUG-2022				
ASB	HC-ASB-61-399 R01	NO. 1 PROPELLER - PROPELLERS OVERHAULED BY CHINA FLYING DRAGON GENERAL AVIATION, ALERT SERVICE BULLETIN						NOT APPLICABLE - NOT APPLICABLE. PARTS NOT OVHL BY CHINA FLYING DRAGON GENERAL AVIATION
	05-OCT-2022	MOS HRS/MSC -		10-OCT-2022				
ASB	HC-ASB-61-402	NO. 1 PROPELLER - TRINITY SPECIALIZED SERVICES/MID AMERICA PROPELLER, ALERT SERVICE BULLETIN						NOT APPLICABLE - ASB NOT APPLICABLE TO THE FLEET AS JETFLY FLEET PROPELLER ARE OH IN EUROPE ONLY.
	08-MAR-2023	MOS HRS/MSC -		20-MAR-2023				
SB	HC-SB-61-136 REV I	NO. 1 PROPELLER - BLADES-ADDITIONAL OVERHAUL AND INSPECTION PROCEDURES FOR SINGLE-AND DOUBLE SHOULDER BLADE BORES, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PERFORMED DURING OVH SEE JFS-014-21
	25-APR-2003	MOS HRS/MSC -		22-DEC-2021 3302.92				

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB HC-SB-61-291 R03	NO. 1 PROPELLER - PITCH CHANGE KNOB BRACKET REPLACEMENT, SERVICE BULLETIN						DEFERRED - TO BE PERFORMED AT NEXT PROPELLER OVH
27-OCT-2014		MOS HRS/MSC	-				
SB HC-SB-61-346 R02	NO. 1 PROPELLER - PROPELLER - PITCH CHANGE KNOB INSPECTION, REWORK, AND INTRODUCTION OF AN IMPROVED PITCH CHANGE KNOB BRACKET, SERVICE BULLETIN						- TO BE PERFORMED AT THE NEXT OVERHAULL
21-OCT-2016		MOS HRS/MSC	DUE		<b>27-DEC-2027 M</b> <b>9653 M</b>		
SB HC-SB-61-346 R03	NO. 1 PROPELLER - PROPELLER - PITCH CHANGE KNOB INSPECTION, REWORK, AND INTRODUCTION OF AN IMPROVED PITCH CHANGE KNOB BRACKET, SERVICE BULLETIN						- TO BE PERFORMED AT NEXT OH INPUT
05-JAN-2023		MOS HRS/MSC	DUE	18-JAN-2023			
		AFL					
SB HC-SB-61-356 R02	NO. 1 PROPELLER - BLADE - SECONDARY WINDINGS ON ( )7690( ) AND ( )7890( ) COMPOSITE BLADES, SERVICE BULLETIN						NOT APPLICABLE - Not Equipped: NO COMPOSITE BLADE
02-OCT-2017		MOS HRS/MSC					
		AFL ACH					
SB HC-SB-61-374 R01	NO. 1 PROPELLER - BLADE BEARING RACE INSPECTION CRITERIA, SERVICE BULLETIN						COMPLIED WITH - PERFORMED DURING OVH SEE JFS-014-21
01-AUG-2017		MOS HRS/MSC	-	22-DEC-2021 3302.92			
SB HC-SB-61-385	NO. 1 PROPELLER - D-5117-1 COUNTERWEIGHT CLAMPS, SERVICE BULLETIN						NOT APPLICABLE - By Part: BY BLADE DESIGN PN
26-FEB-2019		DAYS HRS/MSC					
		AFL					
SB HC-SB-61-389	NO. 1 PROPELLER - PITCH CHANGE KNOB BRACKETS/MOUNTING HARDWARE, SERVICE BULLETIN						- SUPERSEDED BY R01
05-JAN-2023		MOS HRS/MSC	DUE				
		AFL					
SB HC-SB-61-389 R01	NO. 1 PROPELLER - PITCH CHANGE KNOB BRACKETS/MOUNTING HARDWARE, SERVICE BULLETIN						- AT NEXT PROPELLER OVERHAUL OR PITCH CHANGE KNOB BRACKET REMOVAL, WHICHEVER OCCURS FIRST
08-FEB-2023		MOS HRS/MSC	DUE	21-FEB-2023			
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB HC-SB-61-397	NO. 1 PROPELLER - EROSION SHIELD INSPECTION: E10950P( ) BLADES, SERVICE BULLETIN						NOT APPLICABLE - BY PART: HARTZELL PROPELLER INC. HC-E4A-3(A,I,J)/E10950( ) LIGHTWEIGHT TURBINE PROPELLERS INSTALLED ON BEECH 1900D AIRLINER AIRCRAFT ARE AFFECTED BY THIS SERVICE BULLETIN.
01-SEP-2022		MOS HRS/MSC -		15-SEP-2022			
SB HC-SB-61-397 PARA (E)(1)(A)	NO. 1 PROPELLER - ACCOMPLISH EROSION SHIELD INSPECTION: E10950P( ) BLADES, SERVICE BULLETIN COIN-TAP INSPECTION OF THE EXPOSED SECTION OF THE BLADE						NOT APPLICABLE - BY PART: HARTZELL PROPELLER INC. HC-E4A-3(A,I,J)/E10950( ) LIGHTWEIGHT TURBINE PROPELLERS INSTALLED ON BEECH 1900D AIRLINER AIRCRAFT ARE AFFECTED BY THIS SERVICE BULLETIN.
01-SEP-2022		MOS HRS/MSC -		15-SEP-2022			
SB HC-SB-61-397 PARA (E)(1)(B)	NO. 1 PROPELLER - ACCOMPLISH EROSION SHIELD INSPECTION: E10950P( ) BLADES, SERVICE BULLETIN COIN-TAP INSPECTION OF THE EROSION SHIELD SURFACE						NOT APPLICABLE - BY PART: HARTZELL PROPELLER INC. HC-E4A-3(A,I,J)/E10950( ) LIGHTWEIGHT TURBINE PROPELLERS INSTALLED ON BEECH 1900D AIRLINER AIRCRAFT ARE AFFECTED BY THIS SERVICE BULLETIN.
01-SEP-2022		MOS HRS/MSC -		15-SEP-2022			
SB HC-SL-61-277 R04	NO. 1 PROPELLER - GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS (SUPERSEDED BY SB HC-SL-61-277 R05) , SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - BY PROPELLER GOVERNOR
03-OCT-2016		MOS HRS/MSC -					
SL HC-SL-30-259 R14	NO. 1 PROPELLER - PROPELLER - HARTZELL PROPELLER INC. MOUNTED ICE PROTECTION COMPONENTS, SERVICE LETTER						COMPLIED WITH
15-MAR-2016		MOS HRS/MSC -		22-DEC-2021 3302.33			
SL HC-SL-30-259 R15	NO. 1 PROPELLER - HARTZELL PROPELLER INC. MOUNTED ICE PROTECTION COMPONENTS, SERVICE LETTER						NOT APPLICABLE - NOT EQUIPPED: NOT APPLICABLE BY PART ADDED TO THE REVISION. REVISION 5 DOES NOT SUPERSEDE REVISION 4 FOR JETFLY FLEET
09-MAR-2022		MOS HRS/MSC -		14-APR-2022			
SL HC-SL-30-260 R22	NO. 1 PROPELLER - DE-ICE BOOTS, ANTI-ICING BOOTS, AND AIRFRAME MOUNTED ICE PROTECTION SYSTEM COMPONENTS, SERVICE LETTER						COMPLIED WITH
27-OCT-2014		MOS HRS/MSC -		22-DEC-2021 3302.33			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL HC-SL-30-260 R23	NO. 1 PROPELLER - DE-ICE BOOTS, ANTI-ICING BOOTS, AND AIRFRAME MOUNTED ICE PROTECTION SYSTEM COMPONENTS, SERVICE LETTER						- WAITING MANAGEMENT DECISION
01-SEP-2022		MOS HRS/MSC -		(EFF)			
		AFL					
SL HC-SL-30-295 R03	NO. 1 PROPELLER - DE-ICE: HARTZELL DE-ICE WIRE HARNESS AND DE-ICE BOOT FOR PILATUS PC-12, SERVICE LETTER						COMPLIED WITH
		MOS HRS/MSC 4000	72	22-DEC-2021 3302.33	<b>22-DEC-2027</b> <b>7302.33</b>	RECURRING	
SL HC-SL-30-369	NO. 1 PROPELLER - EROSION TAPE INSTALLATION ON BLADES WITH DE-ICE BOOTS, SERVICE LETTER					OPTIONAL	NOT APPLICABLE - BY PROPELLER PN
03-NOV-2021		MOS HRS/MSC -		08-NOV-2021			
SL HC-SL-61-185 R02	NO. 1 PROPELLER - TACHOMETERS (SUPERSEDED BY SB HC-SL-61-185 R03) , SERVICE LETTER					RECOMMENDED	- SUPERSEDED BY R03
08-JAN-2016		MOS HRS/MSC -					
SL HC-SL-61-185 R03	NO. 1 PROPELLER - TACHOMETERS, SERVICE LETTER					RECOMMENDED	NOT APPLICABLE - NOT EQUIPPED
21-OCT-2016		MOS HRS/MSC -					
SL HC-SL-61-187 R04	NO. 1 PROPELLER - PROPELLER - ALTERNATE LUBRICATION FITTINGS, SERVICE LETTER						COMPLIED WITH - P C/W DURING PROPELLER OH. SEE WR BRINLEY - PROPELLER P59440
18-NOV-2021		MOS HRS/MSC -		16-JUL-2019			
SL HC-SL-61-187 R05	NO. 1 PROPELLER - PROPELLER - ALTERNATE LUBRICATION FITTINGS, SERVICE LETTER						- P C/W DURING PROPELLER OH. SEE WR BRINLEY - PROPELLER P59440 2019-07-16
09-MAR-2022		MOS HRS/MSC DUE					
		AFL					
SL HC-SL-61-217	NO. 1 PROPELLER - PROPELLER - REPLACEMENT OF HARDWARE AT PROPELLER OVERHAUL, SERVICE LETTER						COMPLIED WITH
21-MAR-2003		MOS HRS/MSC -		22-DEC-2021 3302.33			
SL HC-SL-61-231	NO. 1 PROPELLER - PROPELLERS - USE OF PROPELLER JACK, SERVICE LETTER						COMPLIED WITH - INFORMATIONAL ONLY:
		MOS HRS/MSC -		13-AUG-2018 1470.08			
SL HC-SL-61-241 R03	NO. 1 PROPELLER - NEW BLADE SEAL, SERVICE LETTER						COMPLIED WITH - PREVIOUSLY
02-FEB-2015		MOS HRS/MSC -		22-DEC-2021			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL	HC-SL-61-277 R05	NO. 1 PROPELLER - GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS, SERVICE LETTER				OPTIONAL	NOT APPLICABLE - BY PROPELLER GOVERNOR MODEL
	01-FEB-2017	MOS	HRS/MSC -				
SL	HC-SL-61-277 R06	NO. 1 PROPELLER - GOVERNOR - INSTALLATION OF HARTZELL PROPELLER INC. GOVERNORS, SERVICE LETTER				OPTIONAL	NOT APPLICABLE - NOT EQUIPPED: BY PROPELLER GOVERNOR
	16-SEP-2020	MOS	HRS/MSC -		20-OCT-2020		
SL	HC-SL-61-282 R01	NO. 1 PROPELLER - PROPELLER - PRELOAD PLATE WEAR LIMITS, SERVICE LETTER					COMPLIED WITH
		MOS	HRS/MSC DUE		22-DEC-2021 3302.33		
SL	HC-SL-61-303	NO. 1 PROPELLER - PROPELLER - NEW C-3317-340-8 BLADE O-RING FOR HC-E4A-3(A,I,J) PROPELLERS CURRENTLY USING THE C-6337-1 BLADE SEAL , SERVICE LETTER					NOT APPLICABLE - By Effectivity: by aircraft model
	09-APR-2010	MOS	HRS/MSC -				
		AFL					
SL	HC-SL-61-329	NO. 1 PROPELLER - PROPELLER BLADES - BLADE PAINT, SERVICE LETTER					COMPLIED WITH
	27-AUG-2012	MOS	HRS/MSC -		22-DEC-2021 3302.33		
SL	HC-SL-61-348	NO. 1 PROPELLER - PROPELLER - HUB CLAMPING BOLT INSPECTION, SERVICE LETTER					COMPLIED WITH
	01-JUL-2015	MOS	HRS/MSC DUE		22-DEC-2021 3302.33		
SL	HC-SL-61-354	NO. 1 PROPELLER - PROPELLER - LUBRICATION FITTINGS, SERVICE LETTER					COMPLIED WITH
	01-AUG-2016	MOS	HRS/MSC -		22-DEC-2021 3302.33		
SL	HC-SL-61-355	NO. 1 PROPELLER - BLADE - COMPOSITE BLADE MINOR REPAIR KITS, SERVICE LETTER					NOT APPLICABLE - NOT EQUIPPED
	01-AUG-2016	MOS	HRS/MSC -				
SL	HC-SL-61-356	NO. 1 PROPELLER - PRIMER SEALER COLOR CHANGE, SERVICE LETTER					COMPLIED WITH - FOR INFORMATION ONLY
	13-JUL-2016	MOS	HRS/MSC -				
SL	HC-SL-61-364	NO. 1 PROPELLER - PROPELLER - CORROSION INHIBITOR ON COUNTERWEIGHTS, SERVICE LETTER					COMPLIED WITH - DURING PROPELLER OH. SE TECHNIC AVIATION WR: TA61621
	03-APR-2020	MOS	HRS/MSC -		22-DEC-2021 3302.33		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL HC-SL-61-366	NO. 1 PROPELLER - PROPELLER - NYCO GN3058 GREASE, SERVICE LETTER						COMPLIED WITH
06-JAN-2020		MOS HRS/MSC -		22-DEC-2021 3302.33			
SL HC-SL-61-367 R01	NO. 1 PROPELLER - 107995-( ) COUNTERWEIGHT MOUNTING BOLTS, SERVICE LETTER						NOT APPLICABLE - BY PROPELLER P/N
17-DEC-2020		MOS HRS/MSC -		04-JAN-2021			
SL HC-SL-61-372	NO. 1 PROPELLER - HARTZELL PROPELLER INC. BLADE DECALS, SERVICE LETTER						- INFORMATION ONLY. HARTZELL PROPELLER INC. HAS REVISED THE COMPANY LOGO ON THE DECAL APPLIED TO ALL HARTZELL ALUMINUM/COMPOSITE PROPELLER BLADES.
07-DEC-2022		MOS HRS/MSC -		(EFF)			
		AFL					
SL HC-SL-61-373	NO. 1 PROPELLER - SPLIT BEARING RACE ADHESIVE, SERVICE LETTER						- INFORMATION ONLY. NEW ADHESIVE TYPE AVAILABLE: CM94 ADHESIVE AS AN ALTERNATE FOR THE CM16
07-DEC-2022		MOS HRS/MSC -		(EFF)			
		AFL					
SL HC-SL-61-374	NO. 1 PROPELLER - ONLINE PRODUCT REGISTRATION, SERVICE LETTER						- ONLINE PRODUCT REGISTER. INFORMATION ONLY.
08-MAR-2023		MOS HRS/MSC DUE		(EFF)			
		AFL					
SL HC-SL-61-375	NO. 1 PROPELLER - TANIS AIRCRAFT PRODUCTS/HARTZELL PROPELLER INC. PART NUMBER CROSS-REFERENCE, SERVICE LETTER						- Informational Only -
02-JUN-2023		MOS HRS/MSC -		(EFF)			
		AFL					
SL HC-SL-61-375 R01	NO. 1 PROPELLER - TANIS AIRCRAFT PRODUCTS/HARTZELL PROPELLER INC. PART NUMBER CROSS-REFERENCE, SERVICE LETTER						- Informational Only -
25-AUG-2023		MOS HRS/MSC -		(EFF)			
		AFL					
SL HC-SL-61-61Y R10	NO. 1 PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS FOR HARTZELL PROPELLER INC. AVIATION COMPONENTS - PROPELLERS, GOVERNORS, ACCUMULATORS, AND PROPELLER DAMPER ASSEMBLIES (SUPERSEDED BY SL HC-SL-61-61Y R11) , SERVICE LETTER					RECOMMENDED	COMPLIED WITH - SL IS TAKEN INTO ACCOUNT ON MAINTENANCE PROGRAM
01-AUG-2016		MOS HRS/MSC -		09-NOV-2016			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SL HC-SL-61-61Y R11	NO. 1 PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS FOR HARTZELL PROPELLER INC. AVIATION COMPONENTS - PROPELLERS, GOVERNORS, ACCUMULATORS, AND PROPELLER DAMPER ASSEMBLIES, SERVICE LETTER	MOS					COMPLIED WITH - TAKED IN ACCOUNT IN THE CURRENT AIRCRAFT MAINTENANCE PROGRAM
02-OCT-2017		HRS/MSC	-				
SL HC-SL-61-61Y R12	NO. 1 PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS FOR HARTZELL PROPELLER INC. AVIATION COMPONENTS - PROPELLERS, GOVERNORS, ACCUMULATORS, AND PROPELLER DAMPER ASSEMBLIES, SERVICE LETTER	MOS		20-AUG-2018			COMPLIED WITH - INFORMATIONAL ONLY: TAKE IN ACCOUNT IN JETFLY AIRCRAFT MAINTENANCE PROGRAM
16-AUG-2018		HRS/MSC	-	1479.42			
SL HC-SL-61-61Y R13	NO. 1 PROPELLER - PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS FOR HARTZELL PROPELLER INC. AVIATION COMPONENTS - PROPELLERS, GOVERNORS, ACCUMULATORS, AND PROPELLER DAMPER ASSEMBLIES, SERVICE LETTER	MOS		10-MAR-2021			COMPLIED WITH - INFORMATIONAL ONLY: AT NEXT OVERHAUL
04-MAR-2021		HRS/MSC	-				
SL HC-SL-61-61Y R14	NO. 1 PROPELLER - PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS FOR HARTZELL PROPELLER INC. AVIATION COMPONENTS - PROPELLERS, GOVERNORS, ACCUMULATORS, AND PROPELLER DAMPER ASSEMBLIES, SERVICE LETTER	MOS		22-DEC-2021			COMPLIED WITH
07-JUL-2021		HRS/MSC	-	3302.33			
SL HC-SL-61-61Y R15	NO. 1 PROPELLER - PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS FOR HARTZELL PROPELLER INC. AVIATION COMPONENTS - PROPELLERS, GOVERNORS, ACCUMULATORS, AND PROPELLER DAMPER ASSEMBLIES, SERVICE LETTER	MOS		(EFF)			- Informational Only - AMP TBO INTERVAL IS SET TO 4000 FH / 72 MOS
13-DEC-2023		HRS/MSC	-				
		AFL					