



OWNER: AVESCO PTY. LTD.
ADDRESS: P.O. BOX 36
SPRINGSURE QLD 4722
OFFICE: 61-418-184131
FAX: 61-749-591667

OPERATOR: AVESCO PTY. LTD.
ADDRESS: P.O. BOX 36
SPRINGSURE QLD 4722
OFFICE: 61-418-184131
FAX: 61-749-591667

ANALYST: GOWTHAM THAMMISETTY -- (DIRECT)
EMAIL: GOWTHAM.THAMMISETTY@CAMPSYSTEMS.COM +1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Mode:WITH COMPLIANCE OR NEXT DUE; Group by Profile or Bulletin:PROFILE TYPE;

AIRCRAFT	SERIAL/REGNO: 55000008/N142GZ	MODEL: LEGACY 500	MANUFACTURER: EMBRAER
	CERTIFICATION DATE: 27-JAN-2015	LAST ACTUALS: 994.6 A/C HRS as of 15-DEC-2025 759 AFL as of 15-DEC-2025 976.5 APH as of 29-NOV-2025	
APU	SERIAL/PART: P-110/70720189-1	MODEL: GTCP36-150(EMB)	MANUFACTURER: HONEYWELL
	INSTALLED ON: 21-AUG-2014 0 APU HRS 0 A/C HRS 0 APUS	LAST ACTUALS: 976.5 APU HRS as of 29-NOV-2025 1709 APUS as of 29-NOV-2025	
ENGINE NO. 1	SERIAL/PART: P131119/70040119-1	MODEL: AS907-3-1E-A2	MANUFACTURER: HONEYWELL
	INSTALLED ON: 10-SEP-2014 136.1 ENG. HRS 0 A/C HRS 105 ENC	LAST ACTUALS: 994.6 ENG. HRS as of 15-DEC-2025 764 ENC as of 15-DEC-2025	
ENGINE NO. 2	SERIAL/PART: P131118/70040119-1	MODEL: AS907-3-1E-A2	MANUFACTURER: HONEYWELL
	INSTALLED ON: 10-SEP-2014 136.1 ENG. HRS 0 A/C HRS 105 ENC	LAST ACTUALS: 994.6 ENG. HRS as of 15-DEC-2025 764 ENC as of 15-DEC-2025	



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
AIRCRAFT - AD - LEGACY 500 55000008/N142GZ							
FAA 2020-25-07	WINDOWS - LH AND RH COCKPIT SIDE WINDOW - INSPECTION / REPLACEMENT					MANDATORY	Complied With
	MOS HRS AFL MSC		-	15-APR-2025 954.4 727			
	Eff. Date: 17-APR-2020						
FAA 2020-25-07 PARA (G)(1) (LH	CARRY OUT A DETAILED INSPECTION (DET) FOR CRACKS, DELAMINATION OR ANY OTHER DAMAGE ACCORDING TO THE TASK 56-12-00-200-801-A DETAILED INSPECTION OF COCKPIT SIDE WINDOW, REVISION 36 DATED MAY 15, 2020					MANDATORY	Complied With
	MOS HRS AFL MSC		-	15-APR-2025 954.4 727			
	Eff. Date: 21-JAN-2021						
FAA 2020-25-07 PARA (G)(1) (RH	CARRY OUT A DETAILED INSPECTION (DET) FOR CRACKS, D DELAMINATION OR ANY OTHER DAMAGE ACCORDING TO THE TASK 56-12-00-200-801-A DETAILED INSPECTION OF COCKPIT SIDE WINDOW, REVISION 36 DATED MAY 15, 2020					MANDATORY	Complied With
	MOS HRS AFL MSC		-	15-APR-2025 954.4 727			
	Eff. Date: 21-JAN-2021						
FAA 2020-25-07 PARA (G)(2) (LH	REPLACE THE COCKPIT LH SIDE WINDOW BY A MODIFIED WINDOW					MANDATORY	Not Applicable - REPLACEMENT OF SIDE WINDOW NOT REQUIRED, WINDOW FOUND IN ACCEPTABLE CONDITION.
	MOS HRS AFL MSC		-	04-FEB-2021 684.43 522			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
	FAA 2020-25-07 PARA (G)(2) (RH REPLACE THE COCKPIT RH SIDE WINDOW BY A MODIFIED WINDOW					MANDATORY	Not Applicable - REPLACEMENT OF SIDE WINDOW NOT REQUIRED, WINDOW FOUND IN ACCEPTABLE CONDITION.
		MOS		04-FEB-2021			
		HRS		684.43			
		AFL		522			
		MSC	-				
	FAA 2021-08-07 PARA (G)(1) REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100					MANDATORY	Not Applicable
		MOS		07-FEB-2023			
		HRS		790.57			
		AFL		605			
		MSC	-				
	Eff. Date: 12-MAY-2021						
	FAA 2022-19-14 EQUIPMENT/FURNISHINGS - DIVAN-SEAT ADDITIONAL-PROTECTION FAIRING - INSTALLATION					MANDATORY	
		MOS	48		14-APR-2027		
	Eff. Date: 14-APR-2023						
	FAA 2022-21-08 INTEGRATED MODULAR AVIONICS - AVIONICS EICAS - INSTALLATION					MANDATORY	Not Applicable
		MOS		05-SEP-2023			
		HRS		807.5			
		AFL		619			
		MSC	-				
	Eff. Date: 22-DEC-2022						
	FAA 2024-05-13 AIRPLANE FLIGHT MANUAL REVISION					MANDATORY	Complied With
		MOS		09-NOV-2024			
		HRS		931.5			
		AFL		712			
		MSC	-				
	Eff. Date: 10-APR-2024						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2024-05-13 PARA (G) ANAC (AIRPLANE FLIGHT MANUAL REVISION					MANDATORY	Complied With
<p>MOS DAYS HRS AFL MSC</p> <p>-</p>							
<p>09-NOV-2024 931.5 712</p>							
<p>Eff. Date: 10-APR-2024</p>							
FAA 2024-05-13 PARA (I)(1)	INSPECT ALL AIRCRAFT RECORDS FOR INSTANCES OF AOA LIMITER ENGAGEMENT THAT OCCUR AFTER PASSING THE FINAL APPROACH FIX INBOUND					MANDATORY	Complied With
<p>MOS DAYS HRS AFL MSC</p> <p>-</p>							
<p>17-APR-2025 954.4 727</p>							
<p>Eff. Date: 10-APR-2024</p>							
FAA 2024-05-13 PARA (I)(2)	REPORT THE RESULTS OF THE INSPECTION, REGARDLESS OF WHETHER THE INSPECTION FOUND ANY ENTRIES					MANDATORY	Complied With
<p>MOS DAYS HRS AFL MSC</p> <p>-</p>							
<p>09-NOV-2024 931.5 712</p>							
<p>Eff. Date: 10-APR-2024</p>							
FAA 2024-15-13 PARA (G) ANAC (PERFORM A GENERAL VISUAL INSPECTION (GVI) AT THE COCKPIT SIDE WINDOW TO DETECT CRACKS, DELAMINATION OR ANY OTHER DAMAGE AND REPLACE THE DAMAGED WINDOW WITH A MODIFIED ONE WITH A NEW P/N NP-200402-9 OR P/N NP-200402-10, AS APPLICABLE (IN CASE OF ANY CRACK IN THE OUTER LAYER IS DETECTED)					MANDATORY	
<p>MOS AFL</p> <p>1200</p>							
<p>1946</p>							
<p>RECURRING</p>							
<p>Eff. Date: 23-OCT-2024</p>							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
	FAA 2024-15-13 PARA (G) ANAC (PERFORM A GENERAL VISUAL INSPECTION (GVI) AT THE COCKPIT SIDE WINDOW TO DETECT CRACKS, DELAMINATION OR ANY OTHER DAMAGE AND REPLACE THE DAMAGED WINDOW WITH A MODIFIED ONE WITH A NEW P/N NP-200402-9 OR P/N NP-200402-10 (IN CASE OF ANY CRACK IN THE OUTER LAYER IS DETECTED)					MANDATORY	
		MOS AFL	1200		1946	RECURRING	
	Eff. Date: 23-OCT-2024						
	FAA 2024-16-16 PARA (G) ANAC (INITIAL AND REPETITIVE INSPECTION OF THE COCKPIT LH SIDE WINDOW					MANDATORY	Complied With
		MOS HRS AFL	750	15-APR-2025 954.4 727	1704.4	RECURRING	
	Eff. Date: 21-JAN-2021						
	FAA 2024-16-16 PARA (G) ANAC (INITIAL AND REPETITIVE INSPECTION OF THE COCKPIT RH SIDE WINDOW					MANDATORY	Complied With
		MOS HRS AFL	750	15-APR-2025 954.4 727	1704.4	RECURRING	
	Eff. Date: 21-JAN-2021						
	FAA 2024-16-16 PARA (G) ANAC (REPLACE THE COCKPIT LH SIDE WINDOW BY A MODIFIED WINDOW					MANDATORY	
		MOS AFL	50		804		
	Eff. Date: 30-OCT-2024						
	FAA 2024-16-16 PARA (G) ANAC (REPLACE THE COCKPIT RH SIDE WINDOW BY A MODIFIED WINDOW					MANDATORY	
		MOS AFL	50		804		
	Eff. Date: 30-OCT-2024						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
	FAA 2024-23-07 ANAC PARA (B)(1) INSPECTION OF THE NLG DOWN LOCK SPRING ASSEMBLIES					MANDATORY	
		MOS					
		DAYS					
		AFL					
		MSC	-				
	Eff. Date: 20-NOV-2024						
	FAA 2024-23-07 ANAC PARA (C)(1) INSPECTION OF THE LH AND RH MLG DOWN LOCK SPRING ASSEMBLIES					MANDATORY	
		MOS					
		DAYS					
		AFL					
		MSC	-				
	Eff. Date: 20-NOV-2024						
	FAA 2025-13-02 PARA (G) ANAC (MAIN DOOR SENSOR OPERATIONAL TEST					MANDATORY	Complied With - CARRIED OUT OPS CHECK OF MAIN DOOR SENSORS IAW EMBRAER LEGACY 500 AMM 52-71-20-710-801-AOREV 61 & COMPLIED WITH
		MOS	12	18-AUG-2025	18-AUG-2026	RECURRING	
		HRS		969.1			
		AFL		739			
	Eff. Date: 05-AUG-2025						
	FAA 2025-13-02 PARA (G) ANAC (MAIN DOOR SENSOR MECHANISM LUBRICATION					MANDATORY	Complied With
		MOS	24	18-AUG-2025	18-AUG-2027	RECURRING	
		HRS		969.1			
		AFL		739			
	Eff. Date: 05-AUG-2025						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
APPLIANCE - LEGACY 500 55000008/N142GZ							
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION					MANDATORY	Not Applicable - TO P/N 622-9210-411 INSTALLED
	MOS HRS AFL MSC			27-JAN-2015			
Eff. Date: 14-OCT-2014							
EASA 2010-0003 R02 PARA (1)	APPLIANCE ADP - VERIFY AIRCRAFT TYPE MODE STRAPPING CODE S SET TO '0' (ZERO) OR '1', AS DEFINED IN ROCKWELL-COLLINS SERVICE LETTER TDR-94() SIL 07-2.					MANDATORY	Not Applicable - TO P/N 622-9210-411 INSTALLED
	MOS HRS AFL MSC			27-JAN-2015			
Eff. Date: 14-OCT-2014							
EASA 2010-0003 R02 PARA (2)	APPLIANCE ADP - EXEMPTIONS: DASSAULT AEROPLANES					MANDATORY	Not Applicable - TO P/N 622-9210-411 INSTALLED
	MOS HRS AFL MSC			27-JAN-2015			
Eff. Date: 14-OCT-2014							
EASA 2010-0003 R02 PARA (3)	APPLIANCE ADP - EXEMPTIONS: ATR 42 AND ATR 72 AEROPLANES					MANDATORY	Not Applicable - TO P/N 622-9210-411 INSTALLED
	MOS HRS AFL MSC			27-JAN-2015			
Eff. Date: 14-OCT-2014							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
EASA 2010-0003 R02 PARA (4)	APPLIANCE ADP - EXEMPTIONS: SAAB 2000 AEROPLANES					MANDATORY	Not Applicable - TO P/N 622-9210-411 INSTALLED
	MOS HRS AFL MSC			27-JAN-2015			
Eff. Date: 14-OCT-2014							
EASA 2010-0003 R02 PARA (5)	APPLIANCE ADP - EXEMPTIONS: BOMBARDIER AEROSPACE (CANADAIR) AEROPLANES: CL-600-2B16 (604 VARIANT) AND CL-600-2B19 (RJ100 AND RJ200)					MANDATORY	Not Applicable - TO P/N 622-9210-411 INSTALLED
	MOS HRS AFL MSC			27-JAN-2015			
Eff. Date: 14-OCT-2014							
EASA 2010-0003 R02 PARA (6)	APPLIANCE ADP - EXEMPTIONS: CESSNA AIRCRAFT COMPANY AEROPLANES: CESSNA MODEL 525, 525A, 525B; AND CESSNA MODEL 525, 525A, 525B, 560; 560XL					MANDATORY	Not Applicable - TO P/N 622-9210-411 INSTALLED
	MOS HRS AFL MSC			27-JAN-2015			
Eff. Date: 14-OCT-2014							
EASA 2010-0003 R02 PARA (7)	APPLIANCE ADP - EXEMPTIONS: PIAGGIO AERO INDUSTRIES AEROPLANES: P.180 (AVANTI) AND P.180 (AVANTI II)					MANDATORY	Not Applicable - TO P/N 622-9210-411 INSTALLED
	MOS HRS AFL MSC			27-JAN-2015			
Eff. Date: 14-OCT-2014							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2022

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

-2-Insufficient Information, +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement), (FFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT					MANDATORY	
MOS MSC							
Eff. Date: 12-JUN-2015							
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	Not Applicable - FAA 2015-08-07 FOUND NOT APPLICABLE. P/N & S/N INSTALLED ARE AS FOLLOWS. COPILOT: P/N: MR-1002NEMB, S/N: E1400363 OBSERVER: P/N: MR-1002NEMB, S/N: E1400392
MOS HRS AFL MSC							
09-FEB-2017 410.2 308							
Eff. Date: 15-JUL-2016							
FAA 2016-11-20 PARA (G)	APPLIANCE ADP - PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	Not Applicable
MOS HRS AFL MSC							
09-FEB-2017 410.2 308							
Eff. Date: 15-JUL-2016							
FAA 2016-11-20 PARA (H.1)	APPLIANCE ADP - REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	Not Applicable
MOS HRS AFL MSC							
09-FEB-2017 410.2 308							
Eff. Date: 15-JUL-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2016-11-20 PARA (H.2)	APPLIANCE ADP - REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	Not Applicable
		MOS		09-FEB-2017			
		HRS		410.2			
		AFL		308			
		MSC	-				
Eff. Date: 15-JUL-2016							
FAA 2017-16-01 PARA (G)	APPLIANCE ADP - PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						Not Applicable - AD NOT APPLICABLE - EQUIPMENT NOT INSTALLED A/C IS FILLED WITH ESSEX PBE'S PN: S1821502, SN: LX1100112710.
		MOS		06-OCT-2017			
		HRS		469.5			
		AFL		358			
		MSC	-				
Eff. Date: 15-JUL-2016							
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	Not Applicable - EQUIPMENT NOT INSTALLED A/C IS FILLED WITH ESSEX PBE'S. PN: MR-10022NEMB PN: 10051N
		MOS		06-OCT-2017			
		HRS		469.5			
		AFL		358			
		MSC	-				
Eff. Date: 16-OCT-2017							
FAA 2017-18-12 PARA (G)	APPLIANCE ADP - INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	Not Applicable - EQUIPMENT NOT INSTALLED A/C IS FILLED WITH ESSEX PBE'S. PN: MR-10022NEMB PN: 10051N
		MOS		06-OCT-2017			
		HRS		469.5			
		AFL		358			
		MSC	-				
Eff. Date: 15-JUL-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2017-18-12 PARA (H)	APPLIANCE ADP - REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	Not Applicable - EQUIPMENT NOT INSTALLED A/C IS EQUIPPED WITH ESSEX PBE'S. PN: MR-10022NEMB PN: 10051N
		MOS		06-OCT-2017			
		HRS		469.5			
		AFL		358			
		MSC	-				
Eff. Date: 15-JUL-2016							
FAA 2017-18-12 PARA (I) & (J)	APPLIANCE ADP - INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	Not Applicable - EQUIPMENT NOT INSTALLED A/C IS FILLED WITH ESSEX PBE'S. PN: MR-10022NEMB PN: 10051N
		MOS		06-OCT-2017			
		HRS		469.5			
		AFL		358			
		MSC	-				
Eff. Date: 16-OCT-2017							
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS					MANDATORY	Complied With - COMPLIED WITH IAW SB 550-42-0008 REV 03.
		MOS		06-MAR-2018			
		HRS		500.7			
		AFL		379			
		MSC	-				
Eff. Date: 20-DEC-2017							
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR					MANDATORY	Not Applicable - PN/SN NOT INSTALLED. ALL FITTED WITH PN: 66601-505 & RSS-301 LIFE VESTS. NO FURTHER ACTION REQUIRED.
		MOS		01-MAY-2020			
		HRS		654.7			
		AFL		502			
		MSC	-				
Eff. Date: 19-SEP-2019							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2019-15-10 PARA (G)	APPLIANCE ADP - REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION					MANDATORY	Not Applicable - PN/SN NOT INSTALLED. ALL FITTED WITH PN: 66601-505 & RSS-301 LIFE VESTS. NO FURTHER ACTION REQUIRED.
		MOS		01-MAY-2020			
		HRS		654.7			
		AFL		502			
		MSC	-				
Eff. Date: 19-SEP-2019							
FAA 2019-15-10 PARA (H)	APPLIANCE ADP - DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA					MANDATORY	Not Applicable - PN/SN NOT INSTALLED. ALL FITTED WITH PN: 66601-505 & RSS-301 LIFE VESTS. NO FURTHER ACTION REQUIRED.
		MOS		01-MAY-2020			
		HRS		654.7			
		AFL		502			
		MSC	-				
Eff. Date: 19-SEP-2019							
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE					MANDATORY	Complied With - INSERTED AND NO ACTION REQUIRED IAW FAA AD 2021-08-07 PARA (G) (1) GPS UNIT 1 P/N 822-2189-010 SN 4JF7N; GPS UNIT 2 P/N 822-2189-010 SN 4JF7P.
		MOS		07-FEB-2023			
		HRS		790.57			
		AFL		605			
		MSC	-				
Eff. Date: 12-MAY-2021							
FAA 2021-08-07 PARA (G)(2)	APPLIANCE ADP - DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE					MANDATORY	Complied With - GPS UNIT 1 AND GPS UNIT 2 INSPECTED AND FOUND NOT TO BE P/N 822-2189-100 IN EITHER CASE. NO ACTION REQUIRED.
		MOS		07-FEB-2023			
		HRS		790.57			
		AFL		605			
		MSC	-				
Eff. Date: 12-MAY-2021							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	Not Applicable - BY P/N OF RAD ALT FITTED TO L500 REFER TO FOL 500-00-001/22
		MOS		15-FEB-2022			
		HRS		737.3			
		AFL		562			
		MSC	-				
Eff. Date: 09-DEC-2021							
FAA 2023-10-02 PARA (I)	APPLIANCE ADP - REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)					MANDATORY	Complied With
		MOS		09-MAR-2024			
		HRS		851.38			
		AFL		648			
		MSC	-				
Eff. Date: 26-MAY-2023							
FAA 2025-25-02	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS					MANDATORY	
		MOS					
		DAY	30				
Eff. Date: 24-DEC-2025							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
AIRCRAFT - SB - LEGACY 500 55000008/N142GZ							
SB 550-21-0003	AIR CONDITIONING - CONDITIONED AIR DUCTS REPLACEMENT (SUPERSEDED BY 550-21-0003 REV 01), SERVICE BULLETIN					RECOMMENDED	Complied With
	MOS			20-FEB-2017			
	HRS			410.2			
	AFL			308			
	MSC		-				
Eff. Date: 05-OCT-2016							
SB 550-21-0003 REV 01	AIR CONDITIONING - CONDITIONED AIR DUCTS REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Complied With - 20-FEB-2017
	MOS			02-MAR-2020			
	HRS			648.5			
	AFL			499			
	MSC		-				
Eff. Date: 27-APR-2017							
SB 550-21-0003 REV 01 PART I	ACCOMPLISH AIR CONDITIONING - CONDITIONED AIR DUCTS REPLACEMENT, SERVICE BULLETIN CONDITIONED AIR DUCTS REPLACEMENT					RECOMMENDED	Complied With - 20-FEB-2017
	MOS			02-MAR-2020			
	HRS			648.5			
	AFL			499			
	MSC		-				
Eff. Date: 27-APR-2017							
SB 550-21-0003 REV 01 PART II	ACCOMPLISH AIR CONDITIONING - CONDITIONED AIR DUCTS REPLACEMENT, SERVICE BULLETIN ADDITIONAL ACTION -CABIN LEAKAGE FUNCTIONAL TEST					RECOMMENDED	Complied With - CARRIED OUT IAW SB 550-21-0003 REV 01 PART II
	MOS			02-MAR-2020			
	HRS			648.5			
	AFL			499			
	MSC		-				
Eff. Date: 27-APR-2017							
SB 550-22-0001	AUTO FLIGHT - CAT II CONFIGURATION (SUPERSEDED BY SB 550-22-0001 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
	MOS						
	MSC		-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 14-DEC-2015							
SB 550-22-0001 REV 01	AUTO FLIGHT - CAT II CONFIGURATION (SUPERSEDED BY SB 550-22-0001 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 22-JAN-2016							
SB 550-23-0001	COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT (SUPERSEDED BY SB 550-23-0001 REV 01), SERVICE BULLETIN					OPTIONAL	Not Applicable
MOS MSC							
Eff. Date: 01-FEB-2016							
SB 550-23-0001 REV 01	COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT (SUPERSEDED BY SB 550-23-0001 REV 02), SERVICE BULLETIN					OPTIONAL	Not Applicable
MOS MSC							
Eff. Date: 09-MAR-2016							
SB 550-23-0001 REV 03	COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	Complied With
MOS HRS AFL MSC							
19-JUL-2017 459.1 350							
Eff. Date: 12-APR-2017							
SB 550-23-0001 REV 03 PART I	ACCOMPLISH COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT, SERVICE BULLETIN ACCOMPLISH ELECTRICAL POWER DISTRIBUTION MODIFICATION					OPTIONAL	Complied With
MOS HRS AFL MSC							
19-JUL-2017 459.1 350							
Eff. Date: 12-APR-2017							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-23-0001 REV 03 PART II	ACCOMPLISH COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT, SERVICE BULLETIN ACCOMPLISH IRIDIUM PLATE ELECTRICAL BONDING					OPTIONAL	Complied With
	MOS			19-JUL-2017			
	HRS			459.1			
	AFL			350			
	MSC		-				
Eff. Date: 12-APR-2017							
SB 550-23-0003	COMMUNICATIONS - HEADSET INSTALLATION AT THE CABINET OBSERVER SEAT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
	MOS						
	MSC		-				
Eff. Date: 16-MAR-2016							
SB 550-24-0001	ELECTRICAL POWER - RESISTORS INSTALLATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
	MOS						
	MSC		-				
Eff. Date: 18-MAR-2015							
SB 550-24-0002	ELECTRICAL POWER - RESISTORS INSTALLATION, SERVICE BULLETIN					RECOMMENDED	Complied With
	MOS			25-SEP-2015			
	HRS			269.58			
	AFL			194			
	MSC		-				
Eff. Date: 27-APR-2015							
SB 550-24-0003	ELECTRICAL POWER - LPDC AND RPDC TERMINALS PROTECTION, SERVICE BULLETIN					RECOMMENDED	Not Applicable - -EQUIVALENT MODIFICATION FACTORY INCORPORATED
	MOS						
	MSC		-				
Eff. Date: 28-JUN-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-24-0004	ELECTRICAL POWER - HIGH POWER OUTLETS INSTALLATION (SUPERSEDED BY SB 550-24-0004 REV 01), SERVICE BULLETIN					OPTIONAL	Not Applicable
<p>MOS MSC</p> <p>-</p>							
<p>Eff. Date: 06-MAY-2016</p>							
SB 550-24-0004 REV 01	ELECTRICAL POWER - HIGH POWER OUTLETS INSTALLATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
<p>MOS MSC</p> <p>-</p>							
<p>Eff. Date: 03-JUN-2016</p>							
SB 550-24-0008	ELECTRICAL POWER - BATTERIES AND RESISTORS INSTALLATION, SERVICE BULLETIN					CATEGORY 04 - OPTIONAL	Complied With
<p>MOS HRS AFL MSC</p> <p>-</p>							
<p>17-MAR-2023 790.57 605</p>							
<p>Eff. Date: 03-FEB-2022</p>							
SB 550-24-0011	ELECTRICAL POWER - MAIN DC ELECTRIC GENERATOR V-BAND CLAMP - TORQUE APPLICATION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
<p>MOS</p> <p>12</p> <p>17-FEB-2026</p>							
SB 550-25-0002	EQUIPMENT/FURNISHINGS - DOOR GUIDE INSTALLATION, SERVICE BULLETIN					RECOMMENDED	Not Applicable - -EQUIVALENT MODIFICATION FACTORY INCORPORATED
<p>MOS MSC</p> <p>-</p>							
<p>Eff. Date: 11-FEB-2015</p>							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-25-0003	EQUIPMENT/FURNISHINGS - STONE FLOOR PANELS REPLACEMENT, SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
	MOS MSC	-					
Eff. Date: 06-MAY-2016							
SB 550-25-0004	EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION (SUPERSEDED BY SB 550-25-0004 REV 01), SERVICE BULLETIN					RECOMMENDED	
	MOS MSC	-					
Eff. Date: 04-SEP-2015							
SB 550-25-0004 REV 01	EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION (SUPERSEDED BY SB 550-25-0004 REV 02), SERVICE BULLETIN					RECOMMENDED	Complied With - C/O IAW SB 550-25-0004 R1
	MOS HRS AFL MSC	-		21-JAN-2016 297.12 215			
Eff. Date: 22-DEC-2015							
SB 550-25-0004 REV 02	EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION FOR AIRCRAFT SN 55000008, SERVICE BULLETIN					RECOMMENDED	Complied With
	MOS HRS AFL MSC	-		20-FEB-2017 410.2 308			
Eff. Date: 17-JAN-2017							
SB 550-25-0004 REV 02 PART I	ACCOMPLISH EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION FOR AIRCRAFT SN 55000008, SERVICE BULLETIN OBSERVER SEAT INSTALLATION					RECOMMENDED	Complied With - PREVIOUSLY COMPLIED WITH
	MOS HRS AFL MSC	-		20-FEB-2017 410.2 308			
Eff. Date: 17-JAN-2017							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-25-0004 REV 02 PART II	ACCOMPLISH EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION FOR AIRCRAFT SN 55000008, SERVICE BULLETIN ADDITIONAL ACTION					RECOMMENDED	Complied With - CARRIED OUT IAW SB INSTRUCTIONS
	MOS			20-FEB-2017			
	HRS			410.2			
	AFL			308			
	MSC		-				
Eff. Date: 17-JAN-2017							
SB 550-25-0006	EQUIPMENT/FURNISHINGS - REFRIGERATOR INSTALLATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
	MOS						
	MSC		-				
Eff. Date: 26-JUN-2015							
SB 550-25-0007	EQUIPMENT/FURNISHINGS - DIVAN BERTHING FUNCTIONALITY - ACTIVATION, SERVICE BULLETIN					OPERATORS DISCRETION	Complied With - SB 550-25-0007 COMPLIED WITH.
	MOS			25-SEP-2015			
	HRS			269.58			
	AFL			194			
	MSC		-				
Eff. Date: 30-JUL-2015							
SB 550-25-0008	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE FAUCETS FROM THE GALLEY AND LAVATORY AND REPLACEMENT OF THE GASPERS, READING LIGHTS, AND PLACARDS OF THE CABIN PASSENGERS, SERVICE BULLETIN					OPTIONAL	Not Applicable
	MOS						
	MSC		-				
Eff. Date: 29-SEP-2015							
SB 550-25-0010	EQUIPMENT/FURNISHINGS - CONVECTION OVEN INSTALLATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
	MOS						
	MSC		-				
Eff. Date: 09-MAR-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-25-0012	EQUIPMENT/FURNISHINGS - INTERNAL STOWAGE DOOR LATCH - REPLACEMENT OF CATCH, SERVICE BULLETIN				RECOMMENDED		Complied With - CARRIED OUT IAW SB INSTRUCTIONS
	MOS			08-FEB-2017			
	HRS			410.2			
	AFL			308			
	MSC	-					
Eff. Date: 27-SEP-2016							
SB 550-25-0013 REV 07	EQUIPMENT/FURNISHINGS - BELTED TOILET ASSEMBLY - MODIFICATIONS (SUPERSEDED BY 550-25-0013 REV 08), SERVICE BULLETIN				OPTIONAL		Complied With - SB 550-25-0013 REV 07 COMPLETED
	MOS			02-MAR-2018			
	HRS			500.7			
	AFL			379			
	MSC	-					
Eff. Date: 21-DEC-2017							
SB 550-25-0014	EQUIPMENT/FURNISHINGS - REMOVAL OF OCCUPANCY LIMITATION OF THE AFT- FACING SEAT DURINGTTL (TAKE-OFF, TAXI AND LANDING) (SUPERSEDED BY SB 550-25-0014 REV 01), SERVICE BULLETIN				OPERATORS DISCRETION		Not Applicable
	MOS						
	MSC	-					
Eff. Date: 24-JUN-2016							
SB 550-25-0014 REV 01	EQUIPMENT/FURNISHINGS - REMOVAL OF OCCUPANCY LIMITATION OF THE AFT- FACING SEAT DURINGTTL (TAKE-OFF, TAXI AND LANDING), SERVICE BULLETIN				OPERATORS DISCRETION		Not Applicable
	MOS						
	MSC	-					
Eff. Date: 28-JUN-2016							
SB 550-25-0016	EQUIPMENT/FURNISHINGS - PAX OXYGEN BOX COVER LANYARD - INSPECTION / MODIFICATION, SERVICE BULLETIN				RECOMMENDED		Complied With
	MOS			07-SEP-2016			
	HRS			347.1			
	AFL			258			
	MSC	-					
Eff. Date: 02-SEP-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-25-0016 PART I	ACCOMPLISH EQUIPMENT/FURNISHINGS - PAX OXYGEN BOX COVER LANYARD - INSPECTION / MODIFICATION, SERVICE BULLETIN INSPECTION OF PAX OXYGEN BOX COVER LANYARD					RECOMMENDED	Complied With
	MOS			07-SEP-2016			
	HRS			347.1			
	AFL			258			
	MSC		-				
Eff. Date: 02-SEP-2016							
SB 550-25-0016 PART II	ACCOMPLISH EQUIPMENT/FURNISHINGS - PAX OXYGEN BOX COVER LANYARD - INSPECTION / MODIFICATION, SERVICE BULLETIN MODIFICATION OF PAX OXYGEN BOX COVER LANYARD					RECOMMENDED	Complied With
	MOS			07-SEP-2016			
	HRS			347.1			
	AFL			258			
	MSC		-				
Eff. Date: 02-SEP-2016							
SB 550-25-0019	EQUIPMENT/FURNISHINGS - BELTED TOILET FUNCTIONALITY DE-ACTIVATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
	MOS						
	MSC		-				
Eff. Date: 27-SEP-2016							
SB 550-25-0034	EQUIPMENT/FURNISHINGS - VANITY AND SIDELEDGE - THERAPEUTIC OXYGEN PLACARDS INSTALLATION, SERVICE BULLETIN					OPTIONAL	Complied With - SB 550-25-0034 COMPLETED
	MOS			14-FEB-2018			
	HRS			500.7			
	AFL			379			
	MSC		-				
Eff. Date: 03-AUG-2017							
SB 550-25-0067 REV 02	EQUIPMENT/FURNISHINGS - DIVAN-SEAT ADDITIONAL-PROTECTION FAIRING - INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
	MOS						
	MSC		-				
Eff. Date: 02-AUG-2021							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-25-0067 REV 03	EQUIPMENT/FURNISHINGS - DIVAN-SEAT ADDITIONAL-PROTECTION FAIRING - INSTALLATION, SERVICE BULLETIN					MANDATORY	Complied With
		MOS		16-FEB-2022			
		HRS		737.3			
		AFL		562			
		MSC	-				
Eff. Date: 30-DEC-2021							
SB 550-25-0074	EQUIPMENT/FURNISHINGS - OBSERVER SEAT PLACARD - INSTALLATION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Complied With
		MOS		07-FEB-2023			
		HRS		790.57			
		AFL		605			
		MSC	-				
Eff. Date: 07-DEC-2022							
SB 550-26-0001	FIRE PROTECTION - LAVATORY SMOKE DETECTOR INSTALLATION (SUPERSEDED BY SB 550-26-0001 REV 01), SERVICE BULLETIN					RECOMMENDED	Complied With
		MOS		14-JAN-2016			
		HRS		297.12			
		AFL		215			
		MSC	-				
Eff. Date: 19-DEC-2015							
SB 550-26-0002	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
		MOS					
		MSC	-				
Eff. Date: 10-MAY-2016							
SB 550-27-0001 REV 02	FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE, SERVICE BULLETIN					RECOMMENDED	Complied With - NEW P/N:494910-1007
		MOS		25-SEP-2015			
		HRS		269.58			
		AFL		194			
		MSC	-				
Eff. Date: 23-JUL-2015							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-27-0002	FLIGHT CONTROLS - HIGH-ALTITUDE LANDING AND TAKE-OFF OPERATION PLACARD INSTALLATION (SUPERSEDED BY SB 550-27-0002 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 15-DEC-2015							
SB 550-27-0002 REV 01	FLIGHT CONTROLS - HIGH-ALTITUDE LANDING AND TAKE-OFF OPERATION PLACARD INSTALLATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
MOS MSC							
Eff. Date: 02-JUN-2016							
SB 550-27-0003	FLIGHT CONTROLS - CORRECTION OF THE IDENTIFICATION PLACARDS POSITION (REU 7 /REU 8) (SUPERSEDED BY 550-27-0003 REV 01), SERVICE BULLETIN					RECOMMENDED	Complied With
MOS HRS AFL MSC							
17-FEB-2017 410.2 308							
Eff. Date: 02-JUN-2016							
SB 550-27-0004	FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 15-DEC-2015							
SB 550-27-0004 REV 01	FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 03-MAY-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-27-0004 REV 01 PART I	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 02), SERVICE BULLETIN STEEP APPROACH INSTALLATION					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 03-MAY-2016							
SB 550-27-0004 REV 01 PART II	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 02), SERVICE BULLETIN ADDITIONAL ACTION					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 03-MAY-2016							
SB 550-27-0004 REV 02	FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 03), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 29-JUL-2016							
SB 550-27-0004 REV 02 PART I	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 03), SERVICE BULLETIN STEEP APPROACH INSTALLATION					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 29-JUL-2016							
SB 550-27-0004 REV 02 PART II	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 03), SERVICE BULLETIN ADDITIONAL ACTION					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 29-JUL-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-27-0004 REV 03	FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 04), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 03-AUG-2016							
SB 550-27-0004 REV 03 PART I	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 04), SERVICE BULLETIN STEEP APPROACH INSTALLATION					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 03-AUG-2016							
SB 550-27-0004 REV 03 PART II	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 04), SERVICE BULLETIN ADDITIONAL ACTION					OPERATORS DISCRETION	Not Applicable
MOS MSC							
Eff. Date: 03-AUG-2016							
SB 550-27-0005	FLIGHT CONTROLS - REPLACEMENT OF THE REMOTE ELECTRONIC UNITS (REU'S), SERVICE BULLETIN					RECOMMENDED	Complied With
MOS HRS AFL MSC							
23-FEB-2019 573.43 436							
Eff. Date: 22-JUN-2016							
SB 550-27-0006	FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE TO 494910-1009, SERVICE BULLETIN					RECOMMENDED	Complied With
MOS HRS AFL MSC							
02-MAR-2020 648.5 499							
Eff. Date: 20-DEC-2019							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2022

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-27-0007	FLIGHT CONTROLS - FLAP POWER DRIVE UNIT REPLACEMENT, SERVICE BULLETIN					CATEGORY 04 - OPTIONAL	Complied With
	MOS HRS AFL MSC		-	16-MAR-2023 790.57 605			
Eff. Date: 24-JAN-2023							
SB 550-27-0008	FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER CONNECTOR O-RING INSPECTION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Complied With
	MOS HRS AFL MSC		-	12-MAR-2025 954.4 727			
Eff. Date: 10-OCT-2024							
SB 550-27-0008 PART I	ACCOMPLISH FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER CONNECTOR O-RING INSPECTION, SERVICE BULLETIN INSPECTION OF THE RUBBER BLUE O-RINGS CONNECTOR					CATEGORY 02 - RECOMMENDED	Complied With
	MOS HRS AFL MSC		-	12-MAR-2025 954.4 727			
Eff. Date: 10-OCT-2024							
SB 550-27-0008 PART II	ACCOMPLISH FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER CONNECTOR O-RING INSPECTION, SERVICE BULLETIN REMOVE OF THE RUBBER BLUE O-RINGS CONNECTOR					CATEGORY 02 - RECOMMENDED	Complied With
	MOS HRS AFL MSC		-	12-MAR-2025 954.4 727			
Eff. Date: 10-OCT-2024							
SB 550-27-0009	FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE TO PN 494910-1011, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
	MOS HRS	48 2400		07-APR-2029 3467.82			

Eff. Date: 07-APR-2025

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-28-0002	FUEL - FUEL QUANTITY INCREASE (SUPERSEDED BY SB 550-28-0002 REV 01), SERVICE BULLETIN					RECOMMENDED	Not Applicable
	MOS MSC		-				
	Eff. Date: 29-JUL-2016						
SB 550-28-0002 REV 01	FUEL - FUEL QUANTITY INCREASE, SERVICE BULLETIN					RECOMMENDED	Not Applicable
	MOS MSC		-				
	Eff. Date: 16-SEP-2016						
SB 550-29-0002	HYDRAULIC POWER - HYDRAULIC SYSTEM 1 DCMP (DIRECT CURRENT MOTOR PUMP) - REPLACEMENT (SUPERSEDED BY 550-29-0002 REV 01), SERVICE BULLETIN					RECOMMENDED	Not Applicable - SUPERSEDED BY SB 550-29-0002 REV 01.
	MOS HRS AFL MSC		-	11-FEB-2020 648.5 499			
	Eff. Date: 09-OCT-2018						
SB 550-29-0002 REV 01	HYDRAULIC POWER - HYDRAULIC SYSTEM 1 DCMP (DIRECT CURRENT MOTOR PUMP) - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Not Applicable - SUPERSEDED BY SB 550-29-0002 REV 02.
	MOS HRS AFL MSC		-	11-FEB-2020 648.5 499			
	Eff. Date: 29-OCT-2018						
SB 550-29-0002 REV 02	HYDRAULIC POWER - HYDRAULIC SYSTEM 1 DCMP (DIRECT CURRENT MOTOR PUMP) - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Complied With - ALL WORK CARRIED OUT IAW LEG 500 AMM 29-11-02-000-801-A-400-801-A, REV 34. CALIBRATING TOOLING: EJCE0251-\$ EXP: 24-OCT-20.
	MOS HRS AFL MSC		-	14-FEB-2020 648.5 499			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 29-MAR-2019							
SB 550-31-0001	INDICATING/RECORDING SYSTEMS - INDICATING AND RECORDING SYSTEMS - QAR - QUICK ACCESS RECORDER INSTALLATION (SUPERSEDED BY 550-31-0001 REV 01), SERVICE BULLETIN					OPTIONAL	Not Applicable
MOS MSC							
Eff. Date: 28-JUN-2016							
SB 550-31-0002	INDICATING/RECORDING SYSTEMS - VOLUME ADJUSTMENT OF THE AURAL WARNING, SERVICE BULLETIN					OPERATORS DISCRETION	Complied With
MOS HRS AFL MSC							
06-MAR-2018 500.7 379							
Eff. Date: 01-SEP-2016							
SB 550-31-0003	INDICATING/RECORDING SYSTEMS - HEAD-UP DISPLAY INSTALLATION (SUPERSEDED BY 550-31-0003 REV 01), SERVICE BULLETIN					OPTIONAL	Not Applicable
MOS MSC							
Eff. Date: 31-OCT-2016							
SB 550-31-0004	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ENHANCED FLIGHT VISION SYSTEM (EFVS) (SUPERSEDED BY 550-31-0004 REV 01), SERVICE BULLETIN					OPTIONAL	Not Applicable
MOS MSC							
Eff. Date: 31-OCT-2016							
SB 550-32-0001	LANDING GEAR - REWORK OF MLG AND NLG ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	Not Applicable - -EQUIVALENT MODIFICATION FACTORY INCORPORATED
MOS MSC							
Eff. Date: 16-MAR-2015							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-32-0002	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0002 REV 01), SERVICE BULLETIN					RECOMMENDED	Not Applicable
	MOS MSC		-				
	Eff. Date: 16-MAR-2015						
SB 550-32-0002 REV 01	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0008), SERVICE BULLETIN					RECOMMENDED	Not Applicable
	MOS MSC		-				
	Eff. Date: 10-AUG-2016						
SB 550-32-0003 REV 01	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0003 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	Complied With - NEW P/N: 80-230021-02
	MOS HRS AFL MSC		-	25-SEP-2015 269.58 194			
	Eff. Date: 06-JUL-2015						
SB 550-32-0003 REV 02	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0008), SERVICE BULLETIN					RECOMMENDED	Not Applicable - COMPLIED WITH AT REV 01, NO FURTHER ACTION REQUIRED 25SEP15, 269:58/194
	MOS HRS AFL MSC		-	14-FEB-2020 648.5 499			
	Eff. Date: 10-AUG-2016						
SB 550-32-0004 REV 01	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	Complied With
	MOS HRS AFL MSC		-	14-JAN-2016 297.12 215			
	Eff. Date: 30-NOV-2015						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-32-0004 REV 02	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 03), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable - SUPERSEDED BY SB 550-32-0004 REV 03.
		MOS		02-MAR-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
	Eff. Date: 26-JAN-2016						
SB 550-32-0004 REV 03	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 04), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable - SUPERSEDED BY SB 550-32-0004 REV 04.
		MOS		02-MAR-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
	Eff. Date: 05-SEP-2016						
SB 550-32-0004 REV 04	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 05), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable - SUPERSEDED BY SB 550-32-0004 REV 05.
		MOS		02-MAR-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
	Eff. Date: 23-FEB-2017						
SB 550-32-0004 REV 05	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 06), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable - SUPERSEDED BY SB 550-32-0004 REV 06.
		MOS		02-MAR-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
	Eff. Date: 27-MAR-2017						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-32-0004 REV 06	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 07), SERVICE BULLETIN					OPERATORS DISCRETION	Complied With - PART I COMPLIED WITH SB 550-32-0004 REV 1 15-JAN-2016.
		MOS		02-MAR-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
Eff. Date: 17-OCT-2019							
SB 550-32-0004 REV 06 PART I	ACCOMPLISH LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 07), SERVICE BULLETIN AUTOBRAKE CONFIGURATION					OPERATORS DISCRETION	Complied With - PART I COMPLIED WITH SB 550-32-0004 REV 1 15-JAN-2016.
		MOS		02-MAR-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
Eff. Date: 17-OCT-2019							
SB 550-32-0004 REV 06 PART II	ACCOMPLISH LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 07), SERVICE BULLETIN ADDITIONAL ACTION - UPDATE THE WEIGHT AND BALANCE DATA					OPERATORS DISCRETION	Complied With - CARRIED OUT IAW SB 550-32-0004 REV 06
		MOS		02-MAR-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
Eff. Date: 17-OCT-2019							
SB 550-32-0006	LANDING GEAR - UPLock BOX - REPLACEMENT (SUPERSEDED BY SB 550-32-0006 REV 01), SERVICE BULLETIN					RECOMMENDED	Complied With - SB 550-32-0006 COMPLIED WITH
		MOS		25-SEP-2015			
		HRS		269.58			
		AFL		194			
		MSC	-				
Eff. Date: 21-AUG-2015							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-32-0008	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0010 REV 01), SERVICE BULLETIN					RECOMMENDED	Complied With - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT CARRIED OUT IN FULL IAW SB 550-32-0008
		MOS		14-FEB-2017			
		HRS		410.2			
		AFL		308			
		MSC	-				
Eff. Date: 10-AUG-2016							
SB 550-32-0009	LANDING GEAR - REWORK OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT AND SHOCK ABSORBER (SUPERSEDED BY 550-32-0009 REV 01), SERVICE BULLETIN					RECOMMENDED	Complied With
		MOS		03-MAR-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
SB 550-32-0009 REV 01	LANDING GEAR - REWORK OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT AND SHOCK ABSORBER, SERVICE BULLETIN					RECOMMENDED	Complied With - PREVIOUS REVISION ON 03-MAR-2020.
		MOS		27-JAN-2015			
		AFL					
		MSC	-				
SB 550-32-0010	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU), SERVICE BULLETIN					RECOMMENDED	Complied With
		MOS		17-FEB-2021			
		HRS		684.43			
		AFL		522			
		MSC	-				
Eff. Date: 09-JUN-2020							
SB 550-32-0011	LANDING GEAR - BRAKE ASSEMBLY - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Complied With
		MOS		21-JUL-2020			
		HRS		659.3			
		AFL		505			
		MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 03-APR-2020							
SB 550-32-0011 PART I	ACCOMPLISH LANDING GEAR - BRAKE ASSEMBLY - REPLACEMENT, SERVICE BULLETIN INSPECT THE BRAKE ASSEMBLY FOR THE PART NUMBER INSTALLED (IF ONE OR MORE BRAKE ASSEMBLY INSTALLED IS THE PART NUMBER PN 90006967-3PR, KEEP IT (OR THEM)INSTALLED) AND REPLACE THE OTHERS FOUNDWITH DIFFERENT PN WITH NEW ONES ACCORDING TO PART II					RECOMMENDED	Complied With
MOS 21-JUL-2020 HRS 659.3 AFL 505 MSC -							
Eff. Date: 03-APR-2020							
SB 550-32-0011 PART II	ACCOMPLISH LANDING GEAR - BRAKE ASSEMBLY - REPLACEMENT, SERVICE BULLETIN REPLACE THE BRAKE ASSEMBLY WITH NEW ONES BEARING PN 90006967-3PR					RECOMMENDED	Complied With
MOS 21-JUL-2020 HRS 659.3 AFL 505 MSC -							
Eff. Date: 03-APR-2020							
SB 550-32-0012	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT OR UPDATE, SERVICE BULLETIN					RECOMMENDED	Complied With
MOS 22-FEB-2021 HRS 684.43 AFL 522 MSC -							
Eff. Date: 29-JAN-2021							
SB 550-32-0013	LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Not Applicable - BY PART NUMBER
MOS 22-MAY-2025 HRS 962.45 AFL 733 MSC -							
Eff. Date: 05-AUG-2022							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-32-0013 PART I	ACCOMPLISH LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT, SERVICE BULLETIN LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT (PRE-MOD SB550-32-0009)					CATEGORY 02 - RECOMMENDED	Not Applicable - BY PART NUMBER
	MOS			22-MAY-2025			
	HRS			962.45			
	AFL			733			
	MSC		-				
Eff. Date: 05-AUG-2022							
SB 550-32-0013 PART II	ACCOMPLISH LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT, SERVICE BULLETIN LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT (POST-MOD SB550-32-0009)					CATEGORY 02 - RECOMMENDED	Not Applicable - BY PART NUMBER
	MOS			22-MAY-2025			
	HRS			962.45			
	AFL			733			
	MSC		-				
Eff. Date: 05-AUG-2022							
SB 550-32-0014 REV 05	LANDING GEAR - RE-ROUTING OF THE NLG HARNESSSES OF THE NLG DRESSED SHOCK STRUT ASSEMBLY, SERVICE BULLETIN					CATEGORY 03 - DESIRABLE	Complied With
	MOS			08-FEB-2023			
	HRS			790.57			
	AFL			605			
	MSC		-				
Eff. Date: 01-JUL-2022							
SB 550-32-0014 REV 05 PART I	ACCOMPLISH LANDING GEAR - RE-ROUTING OF THE NLG HARNESSSES OF THE NLG DRESSED SHOCK STRUT ASSEMBLY, SERVICE BULLETIN INSPECT THE NLG HARNESS					CATEGORY 03 - DESIRABLE	Complied With
	MOS			08-FEB-2023			
	HRS			790.57			
	AFL			605			
	MSC		-				
Eff. Date: 01-JUL-2022							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-32-0014 REV 05 PART II	ACCOMPLISH LANDING GEAR - RE-ROUTING OF THE NLG HARNESSSES OF THE NLG DRESSED SHOCK STRUT ASSEMBLY, SERVICE BULLETIN RE-ROUTING OF THE NLG HARNESSSES					CATEGORY 03 - DESIRABLE	Complied With
	MOS			08-FEB-2023			
	HRS			790.57			
	AFL			605			
	MSC		-				
Eff. Date: 01-JUL-2022							
SB 550-32-0016 PART I	ACCOMPLISH LANDING GEAR - NOSE LANDING GEAR T-SEAL SCAPE INSPECTION, SERVICE BULLETIN INSPECTION OF THE LANDING GEAR SERIAL NUMBER					CATEGORY 02 - RECOMMENDED	
	MOS			27-JAN-2015			
	HRS						
	MSC		-				
Eff. Date: 05-SEP-2022							
SB 550-32-0016 PART II	ACCOMPLISH LANDING GEAR - NOSE LANDING GEAR T-SEAL SCAPE INSPECTION, SERVICE BULLETIN REPLACEMENT OF THE T-SEAL LANDING GEAR					CATEGORY 02 - RECOMMENDED	
	MOS			27-JAN-2015			
	HRS						
	MSC		-				
Eff. Date: 05-SEP-2022							
SB 550-32-0019 PART I	ACCOMPLISH LANDING GEAR - MLG AND NLG DOWN LOCK SPRING ASSEMBLIES REPLACEMENT, SERVICE BULLETIN REPLACEMENT OF THE NLG DOWN LOCK SPRING ASSEMBLIES					RECOMMENDED	
	MOS						
	DAYS						
	AFL						
	MSC		-				
Eff. Date: 09-OCT-2024							
SB 550-32-0019 PART II	ACCOMPLISH LANDING GEAR - MLG AND NLG DOWN LOCK SPRING ASSEMBLIES REPLACEMENT, SERVICE BULLETIN REPLACEMENT OF THE MLG DOWN LOCK SPRING ASSEMBLIES					RECOMMENDED	
	MOS						
	DAYS						
	AFL						
	MSC		-				
Eff. Date: 09-OCT-2024							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-32-0019 REV 02	LANDING GEAR - MLG AND NLG DOWN LOCK SPRING ASSEMBLIES REPLACEMENT, SERVICE BULLETIN					CATEGORY 01 - MANDATORY	Not Applicable
	MOS HRS AFL MSC			09-NOV-2024 931.5 712			
	Eff. Date: 24-OCT-2024						
SB 550-32-0019 REV 02 PART I	ACCOMPLISH LANDING GEAR - MLG AND NLG DOWN LOCK SPRING ASSEMBLIES REPLACEMENT, SERVICE BULLETIN REPLACEMENT OF THE NLG DOWN LOCK SPRING ASSEMBLIES					CATEGORY 01 - MANDATORY	Not Applicable
	MOS DAYS HRS AFL MSC			09-NOV-2024 931.5 712			
	Eff. Date: 09-OCT-2024						
SB 550-32-0019 REV 02 PART II	ACCOMPLISH LANDING GEAR - MLG AND NLG DOWN LOCK SPRING ASSEMBLIES REPLACEMENT, SERVICE BULLETIN REPLACEMENT OF THE MLG DOWN LOCK SPRING ASSEMBLIES					CATEGORY 01 - MANDATORY	Not Applicable
	MOS DAYS HRS AFL MSC			09-NOV-2024 931.5 712			
	Eff. Date: 09-OCT-2024						
SB 550-32-0020 PART I	ACCOMPLISH LANDING GEAR - NLG LOWER DRAG BRACE - PARTS INSPECTION AND REPLACEMENT, SERVICE BULLETIN VISUAL INSPECTION - COTTER PIN OF THE SELF-LOCKING NUT AND LOWER DRAG BRACE PIN					CATEGORY 02 - RECOMMENDED	
	MOS MSC						
	Eff. Date: 10-MAR-2025						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-32-0020 PART II	ACCOMPLISH LANDING GEAR - NLG LOWER DRAG BRACE - PARTS INSPECTION AND REPLACEMENT, SERVICE BULLETIN REPLACEMENT - SELF-LOCKING NUT AND LOWER DRAG BRACE PIN					CATEGORY 02 - RECOMMENDED	
		MOS		27-JAN-2015			
		MSC	-				
SB 550-33-0001	LIGHTS - INTERFERENCE IN THE REFUELING/DEFUELING CONTROL PANEL DISPLAY, SERVICE BULLETIN					OPTIONAL	Not Applicable - -EQUIVALENT MODIFICATION FACTORY INCORPORATED
		MOS					
		MSC	-				
Eff. Date: 20-FEB-2015							
SB 550-33-0007	LIGHTS - EMERGENCY LIGHTS HARNESS REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Deferred - OPTIONAL, SB DEFERRED.
		MOS		17-APR-2025			
		HRS		954.4			
		AFL		727			
		MSC	-				
SB 550-34-0001	NAVIGATION - INSTALLATION OF THE PROVISIONAL HARNESS IN THE SYSTEMS LINE OF THE HUD (HEAD-UP DISPLAY) AND EVS (ENHANCED VISION SYSTEM), SERVICE BULLETIN					OPTIONAL	Not Applicable
		MOS					
		MSC	-				
Eff. Date: 28-SEP-2015							
SB 550-34-0002	NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY SB 550-34-0002 REV 01), SERVICE BULLETIN					OPTIONAL	Not Applicable
		MOS					
		MSC	-				
Eff. Date: 25-MAY-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-34-0002 REV 01	NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY SB 550-34-0002 REV 02), SERVICE BULLETIN					OPTIONAL	Not Applicable
MOS MSC							
Eff. Date: 19-SEP-2016							
SB 550-34-0002 REV 08	NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION, SERVICE BULLETIN					OPTIONAL	Complied With
MOS HRS AFL MSC							
23-FEB-2019 573.43 436							
Eff. Date: 08-AUG-2018							
SB 550-34-0002 REV 08 PART I	ACCOMPLISH NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION, SERVICE BULLETIN ADS-B OUT SYSTEM INSTALLATION					OPTIONAL	Complied With
MOS HRS AFL MSC							
23-FEB-2019 573.43 436							
Eff. Date: 08-AUG-2018							
SB 550-34-0002 REV 08 PART II	ACCOMPLISH NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION, SERVICE BULLETIN ADDITIONAL ACTION - REPLACEMENT OF TCAS/TRANSPONDER FILES					OPTIONAL	Not Applicable - PER EFFECTIVITY
MOS HRS AFL MSC							
23-FEB-2019 573.43 436							
Eff. Date: 08-AUG-2018							
SB 550-34-0004	NAVIGATION - INSTALLATION OF THE EVS (ENHANCED VISION SYSTEM) (SUPERSEDED BY 550-34-0004 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable
MOS MSC							
-							
Eff. Date: 31-OCT-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-34-0009 REV 02	NAVIGATION - SURFACE MANAGEMENT SYSTEM (SMS) INHIB PANEL INSTALLATION (SUPERSEDED BY 550 -34-0009 REV 03), SERVICE BULLETIN					OPTIONAL	Complied With - PREVIOUSLY COMPLIED WITH AT PRODUCTION.
	MOS			20-FEB-2019			
	HRS			573.5			
	AFL			436			
	MSC		-				
Eff. Date: 12-SEP-2018							
SB 550-34-0013	NAVIGATION - INTEGRATED PITOT/STATIC/AOA/ADC SENSOR NEW PART NUMBER REPLACEMENT, SERVICE BULLETIN					OPERATORS DISCRETION	Complied With
	MOS			19-FEB-2019			
	HRS			573.43			
	AFL			436			
	MSC		-				
Eff. Date: 21-SEP-2018							
SB 550-34-0019	NAVIGATION - WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Complied With
	MOS			07-FEB-2022			
	HRS			737.3			
	AFL			562			
	MSC		-				
Eff. Date: 08-JUL-2020							
SB 550-34-0019 PART I	ACCOMPLISH NAVIGATION - WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) INSPECTION AND REPLACEMENT, SERVICE BULLETIN WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) INSPECTION					RECOMMENDED	Complied With
	MOS			07-FEB-2022			
	HRS			737.3			
	AFL			562			
	MSC		-				
Eff. Date: 08-JUL-2020							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-34-0019 PART II	ACCOMPLISH NAVIGATION - WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) INSPECTION AND REPLACEMENT, SERVICE BULLETIN WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) REPLACEMENT					RECOMMENDED	Complied With
		MOS		07-FEB-2022			
		HRS		737.3			
		AFL		562			
		MSC	-				
Eff. Date: 08-JUL-2020							
SB 550-34-0024 REV 01	NAVIGATION - AHRS - ATTITUDE AND HEADING REFERENCE SYSTEM COMPUTER FLIGHT CONTROLS - LOCATION REPOSITIONING, SERVICE BULLETIN					RECOMMENDED	
		MOS					
		HRS					
		MSC	-				
Eff. Date: 30-NOV-2021							
SB 550-34-0024 REV 02	NAVIGATION - AHRS - ATTITUDE AND HEADING REFERENCE SYSTEM COMPUTER FLIGHT CONTROLS - LOCATION REPOSITIONING, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Deferred - DEFERRED UNTIL 180 MOS INSPECTION JAN 2030
		MOS		17-APR-2025			
		HRS		954.4			
		AFL		727			
		MSC	-				
Eff. Date: 22-JAN-2021							
SB 550-36-0001	PNEUMATIC - PNEUMATIC SYSTEM CONTROLLER SOFTWARE UPDATE (SUPERSEDED BY SB 550-36-0001 REV 01), SERVICE BULLETIN					RECOMMENDED	Complied With - P/N UPGRADE TO P/N:MM-00150-12-39
		MOS		25-SEP-2015			
		HRS		269.58			
		AFL		194			
		MSC	-				
Eff. Date: 29-JUL-2015							
SB 550-36-0002	PNEUMATIC - NEW SOFTWARE PN MM-00150-12-40 FOR PNEUMATIC SYSTEM CONTROLLER (PSC), SERVICE BULLETIN					RECOMMENDED	Complied With
		MOS		03-APR-2025			
		HRS		954.4			
		AFL		727			
		MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
Eff. Date: 27-OCT-2016							
SB 550-36-0005 REV 01	PNEUMATIC - UPSTREAM PRE-COOLER BLEED 1/2 - RESISTORS INSTALLATION, SERVICE BULLETIN					RECOMMENDED	Complied With
MOS 17-MAR-2023 HRS 790.57 AFL 605 MSC -							
Eff. Date: 17-SEP-2021							
SB 550-36-0006	PNEUMATIC - PRSOV - PRESSURE REGULATING AND SHUT-OFF VALVE REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
MOS MSC -							
Eff. Date: 19-JUL-2023							
SB 550-36-0007	PNEUMATIC - NEW SOFTWARE PN MM-00150-12-41 OR PN MM-00150-14-41 FOR PNEUMATIC SYSTEM CONTROLLER (PSC), SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
MOS HRS MSC -							
Eff. Date: 28-FEB-2024							
SB 550-36-0007 REV 02	PNEUMATIC - NEW SOFTWARE PN MM-00150-12-41 OR PN MM-00150-14-41 FOR PNEUMATIC SYSTEM CONTROLLER (PSC), SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Complied With - SB COMPLIED WITH AS PEA EM8550 SB 550-SS-0007 REV 2PNEUMATIC SYSTEM CONTROLLER ASSEMBLYUPGRADED FROM:PN: MM-001 S0-12-39 S/N: 00076UPGRADED TO:PN: MM-00150-12-41 S/N:00076
MOS 15-APR-2025 HRS 954.4 AFL 727 MSC -							
Eff. Date: 28-FEB-2024							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-36-0009 PART I	ACCOMPLISH PNEUMATIC - ENGINE LOW PRESSURE BLEED CHECK-VALVE (LPBCV) - INSPECTION AND REPLACEMENT, SERVICE BULLETIN INSPECTION FOR AFFECTED SERIAL NUMBER					CATEGORY 02 - RECOMMENDED	
	MOS HRS MSC	-					
	Eff. Date: 27-NOV-2024						
SB 550-36-0009 PART II	ACCOMPLISH PNEUMATIC - ENGINE LOW PRESSURE BLEED CHECK-VALVE (LPBCV) - INSPECTION AND REPLACEMENT, SERVICE BULLETIN COMPLY WITH HONEYWELL SB 36-11-006					CATEGORY 02 - RECOMMENDED	
	MOS HRS MSC	-					
	Eff. Date: 27-NOV-2024						
SB 550-36-0011	PNEUMATIC - HIGH PRESSURE BLEED DUCT ELBOW - INSPECTION AND REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
	MOS HRS	750			1704.4		
	Eff. Date: 13-NOV-2025						
SB 550-42-0001 REV 01	INTEGRATED MODULAR AVIONICS - LOAD 3.2.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM, SERVICE BULLETIN					OPTIONAL	Complied With
	MOS HRS AFL MSC	-		25-SEP-2015 269.58 194			
	Eff. Date: 23-SEP-2015						
SB 550-42-0001 REV 01 PART I	INTEGRATED MODULAR AVIONICS - LOAD 3.2.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM, SERVICE BULLETIN INSTALLING LOAD 3.2.1					OPTIONAL	Complied With
	MOS HRS AFL MSC	-		25-SEP-2015 269.58 194			
	Eff. Date: 23-SEP-2015						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-42-0001 REV 01 PART II	INTEGRATED MODULAR AVIONICS - LOAD 3.2.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM, SERVICE BULLETIN ADDITIONAL ACTION					OPTIONAL	Complied With
		MOS		25-SEP-2015			
		HRS		269.58			
		AFL		194			
		MSC	-				
Eff. Date: 23-SEP-2015							
SB 550-42-0002	INTEGRATED MODULAR AVIONICS - APM CONFIGURATION FILES UPDATED (SUPERSEDED BY SB 550-42-0002 REV 01), SERVICE BULLETIN					OPTIONAL	Complied With
		MOS		25-SEP-2015			
		HRS		269.58			
		AFL		194			
		MSC	-				
Eff. Date: 02-JUL-2015							
SB 550-42-0004 REV 01	INTEGRATED MODULAR AVIONICS - LOAD 4.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY SB 550-42-0004 REV 02), SERVICE BULLETIN					OPTIONAL	Complied With
		MOS		14-JAN-2016			
		HRS		297.12			
		AFL		215			
		MSC	-				
Eff. Date: 21-DEC-2015							
SB 550-42-0006	INTEGRATED MODULAR AVIONICS - LOAD 4.1.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE - SOFTWARE SYSTEM (SUPERSEDED BY SB 550-42-0006 REV 01), SERVICE BULLETIN					OPTIONAL	Complied With - INTEGRATED MODULAR AVIONICS - LOAD 4.1.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM CARRIED OUT IN FULL IAW SB 550-42-0006
		MOS		14-FEB-2017			
		HRS		410.2			
		AFL		308			
		MSC	-				
Eff. Date: 23-SEP-2016							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-42-0007	INTEGRATED MODULAR AVIONICS - LOAD 4.2 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0007 REV 01), SERVICE BULLETIN					OPTIONAL	Not Applicable
MOS MSC							
Eff. Date: 31-OCT-2016							
SB 550-42-0008 REV 03	INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN					RECOMMENDED	Complied With
MOS HRS AFL MSC							
Eff. Date: 08-DEC-2017							
SB 550-42-0008 REV 03 PART I	ACCOMPLISH INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM INSTALLATION					RECOMMENDED	Complied With
MOS HRS AFL MSC							
Eff. Date: 30-JUN-2017							
SB 550-42-0008 REV 03 PART II	ACCOMPLISH INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN ADDITIONAL ACTION - APPLICABLE TO REVISION 01 OF THIS SERVICE BULLETIN					RECOMMENDED	Not Applicable - AIRCRAFT NOT PREVIOUSLY MODIFIED
MOS HRS AFL MSC							
Eff. Date: 30-JUN-2017							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-42-0008 REV 03 PART III	ACCOMPLISH INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD -LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN ADDITIONAL ACTION - APPLICABLE TO REVISION 02 OF THIS SERVICE BULLETIN					RECOMMENDED	Not Applicable - AIRCRAFT NOT PREVIOUSLY MODIFIED

MOS 06-MAR-2018
HRS 500.7
AFL 379
MSC -

Eff. Date: 30-JUN-2017

SB 550-42-0008 REV 03 PART IV	ACCOMPLISH INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD- LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN ADDITIONAL ACTION - APPLICABLE TO REVISION 03 OF THIS SERVICE BULLETIN				RECOMMENDED	Not Applicable - AIRCRAFT NOT PREVIOUSLY MODIFIED

MOS 06-MAR-2018
HRS 500.7
AFL 379
MSC -

Eff. Date: 30-JUN-2017

SB 550-42-0009	INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN				OPTIONAL	Complied With

MOS 16-FEB-2018
HRS 500.7
AFL 379
MSC -

Eff. Date: 13-JUL-2017

SB 550-42-0009 PART I	ACCOMPLISH INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN IMS PN INSPECTION				OPTIONAL	Complied With

MOS 16-FEB-2018
HRS 500.7
AFL 379
MSC -

Eff. Date: 13-JUL-2017

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-42-0009 PART II	ACCOMPLISH INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN IMS REPLACEMENT					OPTIONAL	Complied With
	MOS			16-FEB-2018			
	HRS			500.7			
	AFL			379			
	MSC	-					
Eff. Date: 13-JUL-2017							
SB 550-42-0009 REV 01	INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	Not Applicable - COMPLIED WITH AT THE ORIGINAL ISSUE OF THE SB. NO FURTHER ACTION REQUIRED. 16-FEB-18. 500.7 HRS/379 LDGS.
	MOS			14-FEB-2020			
	HRS			648.5			
	AFL			499			
	MSC	-					
Eff. Date: 24-JUL-2018							
SB 550-42-0009 REV 01 PART I	ACCOMPLISH INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN IMS PN INSPECTION					OPTIONAL	Not Applicable - PCW
	MOS			14-FEB-2020			
	HRS			648.5			
	AFL			499			
	MSC	-					
Eff. Date: 24-JUL-2018							
SB 550-42-0009 REV 01 PART II	ACCOMPLISH INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN IMS REPLACEMENT					OPTIONAL	Not Applicable - PCW
	MOS			14-FEB-2020			
	HRS			648.5			
	AFL			499			
	MSC	-					
Eff. Date: 24-JUL-2018							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-42-0010	INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM APPLICATION SOFTWARE (IMSA-008) UPDATING, SERVICE BULLETIN					OPTIONAL	Complied With - PREVIOUSLY COMPLIED WITH AT INSTLLATION OF SB 550-42-0008 REVISION 3 "LOAD 5.4", PART I
		MOS		29-JAN-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
Eff. Date: 15-MAR-2019							
SB 550-42-0011	INTEGRATED MODULAR AVIONICS - LOAD 6.3.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0011 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable - SUPERSEDED BY SB 550-42-0011 REV 01
		MOS		20-FEB-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
Eff. Date: 08-JUL-2019							
SB 550-42-0011 REV 01	INTEGRATED MODULAR AVIONICS - LOAD 6.3.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0011 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	Complied With
		MOS		06-SEP-2019			
		HRS		606.5			
		AFL		469			
		MSC	-				
Eff. Date: 29-AUG-2019							
SB 550-42-0011 REV 02	INTEGRATED MODULAR AVIONICS - LOAD 6.3.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0011 REV 03), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable - COMPLIED WITH AT REV 01. NO FURTHER ACTION REQUIRED 06-SEP-19, 606.5, 469
		MOS		14-FEB-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
Eff. Date: 29-OCT-2019							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-42-0011 REV 03	INTEGRATED MODULAR AVIONICS - LOAD 6.3.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0011 REV 04), SERVICE BULLETIN					OPERATORS DISCRETION	Not Applicable - COMPLIED WITH AT REV 01. NO FURTHER ACTION REQUIRED 06-SEP-19, 606.5, 469
		MOS		14-FEB-2020			
		HRS		648.5			
		AFL		499			
		MSC	-				
Eff. Date: 27-NOV-2019							
SB 550-42-0014	INTEGRATED MODULAR AVIONICS - AVIONICS EICAS FLEX 3.3, OMS FLEX 5.5, AND IFIS DOCS FILES, SERVICE BULLETIN						
FAA 2022-21-08		MOS					
		HRS					
		MSC	-				
Eff. Date: 26-FEB-2021							
SB 550-42-0014 REV 01	INTEGRATED MODULAR AVIONICS - AVIONICS EICAS FLEX 3.3, OMS FLEX 5.5, AND IFIS DOCS FILES, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Complied With
		MOS		15-FEB-2022			
		HRS		737.3			
		AFL		562			
		MSC	-				
Eff. Date: 14-DEC-2023							
SB 550-42-0017	INTEGRATED MODULAR AVIONICS - INTEGRATED MODULAR AVIONICS - AVIONICS OMS FLEX 5.6 UPDATE, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Complied With
		MOS		09-FEB-2024			
		HRS		846.6			
		AFL		645			
		MSC	-				
Eff. Date: 10-DEC-2015							
SB 550-44-0001	CABIN SYSTEMS - PILOT ANNOUNCEMENT IN THE CABIN AUDIO SYSTEM - ENABLE, SERVICE BULLETIN					RECOMMENDED	Not Applicable
		MOS					
		MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-44-0002	CABIN SYSTEMS - INSTALLATION OF THE AIRCELL HIGH SPEED INTERNET SYSTEM (AHSI) (SUPERSEDED BY SB 550-44-0002 REV 01), SERVICE BULLETIN					OPTIONAL	Not Applicable
	MOS MSC		-				
	Eff. Date: 06-JUN-2016						
SB 550-44-0002 REV 01	CABIN SYSTEMS - INSTALLATION OF THE AIRCELL HIGH SPEED INTERNET SYSTEM (AHSI) (SUPERSEDED BY SB 550-44-0002 REV 02), SERVICE BULLETIN					OPTIONAL	Not Applicable
	MOS MSC		-				
	Eff. Date: 28-SEP-2016						
SB 550-44-0002 REV 02	CABIN SYSTEMS - INSTALLATION OF THE AIRCELL HIGH SPEED INTERNET SYSTEM (AHSI) (SUPERSEDED BY 550-44-0002 REV 03), SERVICE BULLETIN					OPTIONAL	Not Applicable
	MOS MSC		-				
	Eff. Date: 28-OCT-2016						
SB 550-44-0011 REV 03	CABIN SYSTEMS - MEDIA INTERFACE UNIT (MIU) - INSTALLATION, SERVICE BULLETIN					CATEGORY 04 - OPTIONAL	
	MOS MSC		-				
	Eff. Date: 28-MAY-2024						
SB 550-52-0003	DOORS - MAIN DOOR AIRSTAIRS REWORK, SERVICE BULLETIN					RECOMMENDED	Not Applicable
	MOS MSC		-				
	Eff. Date: 30-JUN-2016						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-52-0005	DOORS - RAT COMPARTMENT DOOR SEAL - INSTALLATION IMPROVEMENT (SUPERSEDED BY 550-52-0005 REV 01), SERVICE BULLETIN					RECOMMENDED	
MOS HRS MSC -							
Eff. Date: 27-APR-2018							
SB 550-52-0005 REV 01	DOORS - RAT COMPARTMENT DOOR SEAL - INSTALLATION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	Complied With
MOS HRS AFL MSC -							
19-FEB-2019 573.43 436							
Eff. Date: 22-MAY-2018							
SB 550-52-0008 REV 01	DOORS - MAIN-DOOR LOCK SENSOR MECHANISM - CHECK AND REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Complied With
MOS HRS AFL MSC -							
05-SEP-2023 807.5 619							
Eff. Date: 20-JAN-2023							
SB 550-52-0008 REV 01 PART I	ACCOMPLISH DOORS - MAIN-DOOR LOCK SENSOR MECHANISM - CHECK AND REPLACEMENT, SERVICE BULLETIN MAIN-DOOR LOCK SENSOR MECHANISM - CHECK					CATEGORY 02 - RECOMMENDED	Complied With
MOS HRS AFL MSC -							
05-SEP-2023 807.5 619							
Eff. Date: 21-DEC-2022							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2022

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-52-0008 REV 01 PART II	ACCOMPLISH DOORS - MAIN-DOOR LOCK SENSOR MECHANISM - CHECK AND REPLACEMENT, SERVICE BULLETIN MAIN-DOOR LOCK SENSOR MECHANISM - REPLACEMENT					CATEGORY 02 - RECOMMENDED	Not Applicable - MAIN DOOR SENSORS OPERATIONAL PERFORMED NO FAILURE EVIDENT SYSTEM OPERATION SATISFACTORY.
		MOS		05-SEP-2023			
		HRS		807.5			
		AFL		619			
		MCC					

Eff. Date: 21-DEC-2022

SB 550-53-0001 FUSELAGE - REPLACEMENT OF INTERCOSTAL ON STRINGERS 5L/5R BETWEEN FRAME 44 AND 46 (SUPERSEDED BY 550-53-0001 REV 01), SERVICE BULLETIN
MOS 27-JAN-2015
AFL
MSC -

Eff. Date: 20-MAR-2017

SB 550-53-0001 REV 01 FUSELAGE - REPLACEMENT OF INTERCOSTAL ON STRINGERS 5L/5R BETWEEN FRAME 44 AND 46, RECOMMENDED Complied With
SERVICE BULLETIN
MOS 21-FEB-2018
HRS 500.7
AFL 379
MSC -

Eff. Date: 18-APR-2017

SB 550-53-0004 FUSELAGE - HUD&EVS STRUCTURAL PROVISION INSTALLATION (SUPERSEDED BY SB 550-53-0004 REV 04), OPTIONAL Not Applicable
SERVICE BULLETIN
MOS
MSC -

Eff. Date: 31-OCT-2016



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-56-0001	WINDOWS - COCKPIT SIDE WINDOWS - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Not Applicable - REPLACEMENT NOT REQUIRED, SIDE WINDOWS FOUND IN ACCEPTABLE CONDITION.
FAA 2020-25-07		MOS HRS AFL MSC	-	04-FEB-2021 684.43 522			
SB 550-57-0001	WINGS - LH AND RH WINGS SPAR II - STEEL DOUBLER INSTALLATION, SERVICE BULLETIN	MOS AFL MSC	-	27-JAN-2015			
SB 550-57-0001 REV 01	WINGS - LH AND RH WINGS SPAR II - STEEL DOUBLER INSTALLATION, SERVICE BULLETIN	MOS AFL	3750		3750	RECOMMENDED	
SB 550-57-0002	WINGS - WING LOWER SKIN ATTACHMENT TO LONGITUDINAL STRIP - RIVET REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC	-	07-MAR-2018 500.7 379		RECOMMENDED	Complied With
SB 550-57-0002 REV 01	WINGS - WING LOWER SKIN ATTACHMENT TO LONGITUDINAL STRIP - RIVET REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC	-	03-APR-2025 954.4 727		RECOMMENDED	Complied With

Eff. Date: 19-OCT-2017

SB 550-57-0002 REV 01

WINGS - WING LOWER SKIN ATTACHMENT TO LONGITUDINAL STRIP - RIVET REPLACEMENT, SERVICE BULLETIN

RECOMMENDED

Complied With

Eff. Date: 12-JAN-2018

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-57-0004 PART I	ACCOMPLISH WINGS - LH AND RH WINGS - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION (SUPERSEDED BY 550-57-0004 REV 01), SERVICE BULLETIN LH WING - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION					Deferred - THIS SB WAS DEFERRED DUE TO PARTS AVAILABILITY AT EMBRAER. THE SB IS NOT OVERDUE AND WILL BE COMPLIED WITH AT A TIME CONVENIENT TO US AS THE OPERATOR AND WHEN PARTS BECOME AVAILABLE.	
		MOS		27-JAN-2015			
		AFL					
		MSC	-				
SB 550-57-0004 PART II	ACCOMPLISH WINGS - LH AND RH WINGS - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION (SUPERSEDED BY 550-57-0004 REV 01), SERVICE BULLETIN RH WING - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION					Deferred - THIS SB WAS DEFERRED DUE TO PARTS AVAILABILITY AT EMBRAER. THE SB IS NOT OVERDUE AND WILL BE COMPLIED WITH AT A TIME CONVENIENT TO US AS THE OPERATOR AND WHEN PARTS BECOME AVAILABLE.	
		MOS		27-JAN-2015			
		AFL					
		MSC	-				
SB 550-57-0004 REV 02 PART I	ACCOMPLISH WINGS - LH AND RH WINGS - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION, SERVICE BULLETIN LH WING - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION					RECOMMENDED	
		MOS		27-JAN-2015			
		HRS					
		AFL	3750		3750		
SB 550-57-0004 REV 02 PART II	ACCOMPLISH WINGS - LH AND RH WINGS - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION, SERVICE BULLETIN RH WING - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION					RECOMMENDED	
		MOS		27-JAN-2015			
		HRS					
		AFL	3750		3750		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-57-0005	WINGS - STRUCTURAL REPAIR ALLOWABLE DAMAGE INSPECTION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Complied With
		MOS		15-MAR-2023			
		HRS		790.57			
		AFL		605			
		MSC	-				
Eff. Date: 22-MAR-2022							
SB 550-57-0007 PART I	ACCOMPLISH WINGS - HORIZONTAL STABILIZER AND WING HINGE BEARINGS - REPLACEMENT, SERVICE BULLETIN HORIZONTAL STABILIZER HINGE BEARINGS - REPLACEMENT					CATEGORY 02 - RECOMMENDED	
		MOS		27-JAN-2015			
		HRS					
		MSC	-				
Eff. Date: 27-MAY-2025							
SB 550-57-0007 PART II	ACCOMPLISH WINGS - HORIZONTAL STABILIZER AND WING HINGE BEARINGS - REPLACEMENT, SERVICE BULLETIN WING HINGE BEARINGS - REPLACEMENT					CATEGORY 02 - RECOMMENDED	
		MOS		27-JAN-2015			
		HRS					
		MSC	-				
Eff. Date: 27-MAY-2025							
SB 550-57-0007 REV 02 PART I	ACCOMPLISH WINGS - HORIZONTAL STABILIZER AND WING HINGE BEARINGS - REPLACEMENT, SERVICE BULLETIN HORIZONTAL STABILIZER HINGE BEARINGS - REPLACEMENT					CATEGORY 02 - RECOMMENDED	
		MOS					
		HRS	7500		7500		
		MSC	-				
SB 550-57-0007 REV 02 PART II	ACCOMPLISH WINGS - HORIZONTAL STABILIZER AND WING HINGE BEARINGS - REPLACEMENT, SERVICE BULLETIN WING HINGE BEARINGS - REPLACEMENT					CATEGORY 02 - RECOMMENDED	
		MOS					
		HRS	7500		7500		
		MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-73-0001	ENGINE FUEL AND CONTROL - ENGINE ECU SOFTWARE UPGRADE VERSION 4.0, SERVICE BULLETIN					RECOMMENDED	Complied With
<p>MOS 07-APR-2017 HRS 423.6 AFL 319 MSC -</p>							
Eff. Date: 05-MAY-2016							
SB 550-73-0002 REV 04	ENGINE FUEL AND CONTROL - ENGINE ECU SOFTWARE UPGRADE VERSION 5.0, SERVICE BULLETIN					RECOMMENDED	
<p>MOS MSC -</p>							
Eff. Date: 22-JUL-2020							
SB 550-73-0002 REV 06	ENGINE FUEL AND CONTROL - ENGINE ECU SOFTWARE UPGRADE VERSION 5.0, SERVICE BULLETIN					RECOMMENDED	Complied With
<p>MOS 18-FEB-2021 HRS 684.43 AFL 522 MSC -</p>							
Eff. Date: 06-NOV-2020							
SB 550-78-0001	EXHAUST - THRUST REVERSER HEAT SHIELD INSTALLATION (SUPERSEDED BY SB 550-78-0001 REV 01), SERVICE BULLETIN					RECOMMENDED	Complied With - SB 550-78-0001 COMPLIED WITH
<p>MOS 24-SEP-2015 HRS 269.58 AFL 194 MSC -</p>							
Eff. Date: 22-JUL-2015							
SB 550-78-0001 REV 01	EXHAUST - THRUST REVERSER HEAT SHIELD INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
<p>MOS MSC -</p>							
Eff. Date: 30-SEP-2015							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 550-78-0002	EXHAUST - THRUST REVERSER UNIT (TRU) - DOOR AND BEAM ASSEMBLY - IMPROVED CORROSION PROTECTION, SERVICE BULLETIN						
	MOS MSC		-				
SB 550-78-0002 R01	EXHAUST - THRUST REVERSER UNIT (TRU) - DOOR AND BEAM ASSEMBLY - IMPROVED CORROSION PROTECTION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Complied With
	MOS HRS AFL MSC		-	15-APR-2025 954.4 727			
Eff. Date: 17-DEC-2021							
SB 550-78-0003	EXHAUST - THRUST REVERSER ISOLATION CONTROL UNIT (ICU) - REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	Not Applicable - AS PER INSTALLED ICU SERIAL NUMBERS
	MOS HRS AFL MSC		-	11-FEB-2025 954.4 727			
Eff. Date: 17-MAY-2024							
SB 550-78-0003 PART I	ACCOMPLISH EXHAUST - THRUST REVERSER ISOLATION CONTROL UNIT (ICU) - REPLACEMENT, SERVICE BULLETIN LH AND RH ISOLATION CONTROL UNIT (ICU) SERIAL NUMBER - INSPECTION					CATEGORY 02 - RECOMMENDED	Not Applicable - AS PER INSTALLED ICU SERIAL NUMBERS
	MOS HRS AFL MSC		-	11-FEB-2025 954.4 727			
SB 550-78-0003 PART II	ACCOMPLISH EXHAUST - THRUST REVERSER ISOLATION CONTROL UNIT (ICU) - REPLACEMENT, SERVICE BULLETIN LH AND/OR RH ISOLATION CONTROL UNIT (ICU) - REPLACEMENT					CATEGORY 02 - RECOMMENDED	Not Applicable - AS PER INSTALLED ICU SERIAL NUMBERS
	MOS HRS AFL MSC		-	11-FEB-2025 954.4 727			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex) -Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
APU - SB - GTCP36-150(EMB) P-110/70720189-1							
SB 3615880-49-8149 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
	MOS						
	MSC						
Eff. Date: 20-OCT-2015							
SB 36-49-8116 R03	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE STARTER MOTOR, PN 2704458-1 WITH PN 2704458-2, SERVICE BULLETIN					RECOMMENDED	Complied With
	MOS			18-AUG-2025			
	HRS			954.5			
	APUS			1667			
	MSC			-			
Eff. Date: 18-DEC-2023							
SB 36-49-8210	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECT AND REPLACE FUEL SHUTOFF VALVE (FSOV), PN 692545-18, ON 36-150 APUS (EXPORT CONTROLLED), SERVICE BULLETIN					RECOMMENDED	Not Applicable - S/N 6176 NOT APPLICABLE, REPLACEMENT OF FSOV NOT REQUIRED
	MOS			02-AUG-2016			
	MSC			-			
Eff. Date: 04-APR-2016							
SB 36-49-8255	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REMOVE/REPLACE IGNITION EXCITER, PN 3876280-4 ON ENGINE MODEL NUMBER 36-150F2M AND 36-150EMB SPECIFIED UNITS, SERVICE BULLETIN					RECOMMENDED	
	MOS						
	MSC		ESV				
Eff. Date: 30-MAR-2021							
SB 3822101-49-8148 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
	MOS						
	MSC			-			
Eff. Date: 20-OCT-2015							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 70721598-49-8168 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
	MOS						
	MSC		-				
Eff. Date: 20-OCT-2015							
SB 70721725-49-8152 R01	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS, SERVICE BULLETIN					RECOMMENDED	
	MOS						
	MSC		-				
Eff. Date: 24-AUG-2015							
SIL APU-49 R13	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER					RECOMMENDED	Complied With
	MOS			11-APR-2025			
	HRS			940			
	APUS			1633			
	MSC		-				
Eff. Date: 23-NOV-2023							
SIL APU-49 R14	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER					RECOMMENDED	
	MOS					RECURRING	
	HRS	500			1352.5		
	MSC		-				
Eff. Date: 12-FEB-2025							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 1 - AD - AS907-3-1E-A2 P131119/70040119-1							
FAA 2018-04-13	NO. 1 ENGINE - ENGINE CONTROLS SECTION - APPLYING SEALANT TO IDENTIFIED AREAS OF THE ECU AND REQUIRES INSERTING A COPY OF CERTAIN AIRPLANE OPERATING PROCEDURES INTO THE APPLICABLE FLIGHT MANUALS					MANDATORY	Complied With - AD COMPLIED WITH IAW HONEYWELL SB AS907-76-9021, ORIGINAL ISSUE.
	MOS HRS ENC MSC			23-MAY-2018 526.8 393			
Eff. Date: 12-APR-2018							
FAA 2018-04-13 PARA (G)(1)	NO. 1 ENGINE - APPLY SEALANT TO THE ECU (IF NO SEALANT HAS BEEN APPLIED TO THE ECU IN THE AREAS IDENTIFIED IN FIGURES 1 TO 13 OF SB AS907-76-9021 R01) (FOR APPLICABLE ENGINES AND ECUS)					MANDATORY	Complied With - AD COMPLIED WITH IAW SB AS907-76-9021, ORIGINAL ISSUE.
	MOS HRS ENC MSC			23-MAY-2018 526.8 393			
Eff. Date: 12-APR-2018							
FAA 2018-04-13 PARA (G)(2)	NO. 1 ENGINE - INSERT A COPY OF FIGURE 1, 2, OR 3 TO PARA (G) (FOR ALL AIRPLANES THAT HAVE AN AFFECTED ENGINE INSTALLED WITH AN Affected ECU), CHECK THE CURRENT FAULT MESSAGES IN THE MDC/ OMS FOR (G)(2)(I)(A) TO (G)(2)(I)(F) ((IF A CYAN WARNING IS ANNOUNCED) AND REPLACE THE ECU (IF ANY OF THE FAULT MESSAGES LISTED IN MDC/OMS)					MANDATORY	Not Applicable
	MOS DAYS HRS ENC MSC			23-MAY-2018 526.8 393			
Eff. Date: 12-APR-2018							
FAA 2018-04-13 PARA (G)(2)(I)(NO. 1 ENGINE - CHECK THE CURRENT FAULT MESSAGES IN THE MDC/ OMS FOR (G)(2)(I)(A) TO (G)(2) (I)(F) ((IF A CYAN WARNING IS ANNOUNCED) AND REPLACE THE ECU (IF ANY OF THE FAULT MESSAGES LISTED IN MDC/OMS)					MANDATORY	Not Applicable
	MOS HRS ENC MSC			23-MAY-2018 526.8 393			
Eff. Date: 12-APR-2018							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2018-04-13 PARA (I)	NO. 1 ENGINE - TERMINATING ACTION: REMOVE FROM THE AFM, FIGURE 1, 2, OR 3 TO PARA (G), AFTER PARA (G)(1)(I) IS ACCOMPLISHED				23-MAY-2018	MANDATORY	Not Applicable

MOS
HRS
ENC
MSC

Eff. Date: 12-APR-2018

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 2 - AD - AS907-3-1E-A2 P131118/70040119-1							
FAA 2018-04-13	NO. 2 ENGINE - ENGINE CONTROLS SECTION - APPLYING SEALANT TO IDENTIFIED AREAS OF THE ECU AND REQUIRES INSERTING A COPY OF CERTAIN AIRPLANE OPERATING PROCEDURES INTO THE APPLICABLE FLIGHT MANUALS					MANDATORY	Complied With - AD COMPLIED WITH IAW HONEYWELL SB AS907-76-9021, ORIGINAL ISSUE.
	MOS HRS ENC MSC			23-MAY-2018 526.8 393			
Eff. Date: 12-APR-2018							
FAA 2018-04-13 PARA (G)(1)	NO. 2 ENGINE - APPLY SEALANT TO THE ECU (IF NO SEALANT HAS BEEN APPLIED TO THE ECU IN THE AREAS IDENTIFIED IN FIGURES 1 TO 13 OF SB AS907-76-9021 R01) (FOR APPLICABLE ENGINES AND ECUS)					MANDATORY	Complied With - COMPLIED WITH IAW SB AS907-76-9021, ORIGINAL ISSUE.
	MOS HRS ENC MSC			23-MAY-2018 526.8 393			
Eff. Date: 12-APR-2018							
FAA 2018-04-13 PARA (G)(2)	NO. 2 ENGINE - INSERT A COPY OF FIGURE 1, 2, OR 3 TO PARA (G) (FOR ALL AIRPLANES THAT HAVE AN AFFECTED ENGINE INSTALLED WITH AN Affected ECU), CHECK THE CURRENT FAULT MESSAGES IN THE MDC/ OMS FOR (G)(2)(I)(A) TO (G)(2)(I)(F) ((IF A CYAN WARNING IS ANNOUNCED) AND REPLACE THE ECU (IF ANY OF THE FAULT MESSAGES LISTED IN MDC/OMS)					MANDATORY	Not Applicable
	MOS DAYS HRS ENC MSC			23-MAY-2018 526.8 393			
Eff. Date: 12-APR-2018							
FAA 2018-04-13 PARA (G)(2)(I)(NO. 2 ENGINE - CHECK THE CURRENT FAULT MESSAGES IN THE MDC/ OMS FOR (G)(2)(I)(A) TO (G)(2) (I)(F) ((IF A CYAN WARNING IS ANNOUNCED) AND REPLACE THE ECU (IF ANY OF THE FAULT MESSAGES LISTED IN MDC/OMS)					MANDATORY	Not Applicable
	MOS HRS ENC MSC			23-MAY-2018 526.8 393			
Eff. Date: 12-APR-2018							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2018-04-13 PARA (I)	NO. 2 ENGINE - TERMINATING ACTION: REMOVE FROM THE AFM, FIGURE 1, 2, OR 3 TO PARA (G), AFTER PARA (G)(1)(I) IS ACCOMPLISHED				23-MAY-2018	MANDATORY	Not Applicable

MOS
HRS
ENC
MSC

Eff. Date: 12-APR-2018



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 1 - SB - AS907-3-1E-A2 P131119/70040119-1							
SB 78-30-001 R0	NO. 1 ENGINE - ADDITION OF HEAT SHIELD TO REDUCE THE TEMPERATURE SEEN BY HE INNER DUCT, SERVICE BULLETIN					Complied With	
	MOS MSC		-	24-SEP-2015			
SB AS907-72-9005 R05	NO. 1 ENGINE - GENERAL - INSTALLATION OF ENGINE WATER WASH SYSTEM, ON AS907 ENGINES MODELS, SERVICE BULLETIN				CATEGORY 3	Complied With	
	MOS HRS ENC MSC		-	03-APR-2025 954.4 732			
Eff. Date: 23-JAN-2025							
SB AS907-72-9084	NO. 1 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN					Complied With	
	MOS HRS AFL MSC		-	04-SEP-2019 606.5 469			
SB AS907-72-9084 R01 PARA (E)(3)	NO. 1 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN DOWNLOAD ENGINE ECU						
	MOS DAYS MSC		-	26-MAR-2020			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB AS907-72-9084 R02	NO. 1 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN					CATEGORY 2	Complied With - SB CARRIED OUT.
	MOS			02-FEB-2021			
	HRS			684.43			
	ENC			522			
	MSC		-				
Eff. Date: 03-APR-2020							
SB AS907-72-9084 R02 PARA (E)(2)	NO. 1 ENGINE - ACCOMPLISH SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN OIL FILTER REPLACEMENT						Complied With - SB CARRIED OUT.
	MOS			02-FEB-2021			
	HRS			684.43			
	ENC			522			
	MSC		-				
SB AS907-72-9084 R02 PARA (E)(3)	NO. 1 ENGINE - ACCOMPLISH SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN DOWNLOAD ENGINE ECU						Complied With - SB CARRIED OUT.
	MOS			31-MAY-2021			
	DAYs						
	MSC		-				
SB AS907-72-9084 R03	NO. 1 ENGINE - SERVICING - REDUCE TIME INTERVAL FOR OIL FILTER REPLACEMENT OR ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN					CATEGORY 2	Complied With - C/W - DOWNLOAD UPLOADED TO CAMP
	MOS			30-MAY-2025			
	HRS			965.2			
	ENC			740			
	MSC		-				

Eff. Date: 26-JUN-2021

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB AS907-72-9084 R03 PARA (E)(2)(NO. 1 ENGINE - DOWNLOAD ECU PER PARA 3.B.(3)					CATEGORY 2	Complied With
MOS						RECURRING	
DAYS	30			29-NOV-2025			
HRS				990.7			
ENC				761			
SB AS907-72-9084 R03 PARA (E)(2)(NO. 1 ENGINE - PERFORM OIL FILTER ANALYSIS PER PARA 3.B.(2)					CATEGORY 2	Complied With
MOS				09-NOV-2024			
HRS				931.5			
ENC				712			
MSC	-						
Eff. Date: 26-JUN-2021							
SB AS907-72-9084 R03 PARA (E)(2)(NO. 1 ENGINE - TERMINATING ACTION: COMPLIANCE WITH SB AS907-72-9094 TERMINATES THE INSPECTIONS REQUIRED BY PARA (E)(2)(A) & (E)(2)(B)					CATEGORY 2	Complied With
MOS				09-NOV-2024			
HRS				931.5			
ENC				712			
MSC	-						
Eff. Date: 26-JUN-2021							
SB AS907-72-9093 R03	NO. 1 ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED STAGE 4 COMPRESSOR STATOR VANE, PN 70041641-1 OR PN 70041641-2, ON AS907-3-1E MODEL ENGINES, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
MOS							
HRS	4400			4400			
SB AS907-73-9007	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE NON-CONFORMING FUEL HOSE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN						
MOS							
HRS							
MSC	-						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB AS907-73-9007 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE NON-CONFORMING FUEL HOSE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	Complied With
		MOS		01-SEP-2022			
		HRS		761.57			
		ENC		584			
		MSC	-				
Eff. Date: 14-AUG-2018							
SB AS907-76-9021	NO. 1 ENGINE - ENGINE CONTROLS - POWER CONTROLS - APPLY SEALANT TO PREVENT WATER ENTRY INTO ELECTRONIC CONTROL UNIT (ECU) ON AS907 MODEL ENGINES (EXPORT CONTROLLED) (SUPERSEDED BY AS907-76-9021 R01), SERVICE BULLETIN					CATEGORY 1	Complied With
		MOS		10-FEB-2017			
		HRS		410.2			
		ENC		308			
		MSC	-				
Eff. Date: 13-MAY-2016							
SB AS907-76-9021 R01	NO. 1 ENGINE - ENGINE CONTROLS - POWER CONTROLS - APPLY SEALANT TO PREVENT WATER ENTRY INTO ELECTRONIC CONTROL UNIT (ECU) ON AS907 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 1	Not Applicable - SB PREVIOUSLY COMPLIED WITH AT ORIGINAL ISSUE.
FAA 2018-04-13 PARA (G)(1)		MOS		23-MAY-2018			
		HRS		526.8			
		ENC		393			
		MSC	-				
Eff. Date: 13-MAY-2016							
SB AS907-76-9029 R01	NO. 1 ENGINE - ENGINE CONTROLS - POWER CONTROLS - REWORK ELECTRONIC CONTROL UNITS 2119576-4103 TO 2119576-4104, 2119576-4203 TO 2119576-4204, OR INSTALL ELECTRONIC CONTROL UNITS 2119576-4104 OR 2119576-4204 ON AS907-3-1E ENGINE MODELS, SERVICE BULLETIN					CATEGORY 1	Complied With
		MOS		18-FEB-2021			
		HRS		684.43			
		ENC		522			
		MSC	-				
Eff. Date: 05-JUN-2020							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB AS907-79-9007 R02	NO. 1 ENGINE - OIL - STORAGE SECTION - REWORK OIL FILLER CAP ASSEMBLY, PN 3036061-3, TO PREVENT CHAIN INTERFERENCE DURING OIL SUPPLY SERVICING, FOR AS907 MODEL ENGINES (SUPERSEDED BY AS907-79-9007 R03), SERVICE BULLETIN					CATEGORY 2	Complied With
		MOS		10-FEB-2017			
		HRS		410.2			
		ENC		308			
		MSC	-				
Eff. Date: 09-MAR-2015							
SB AS907-79-9010	NO. 1 ENGINE - OIL - DISTRIBUTION - REPLACE NON-CONFORMING OIL HOSE AND TUBE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN						
		MOS					
		HRS					
		MSC	-				
SB AS907-79-9010 R01	NO. 1 ENGINE - OIL - DISTRIBUTION - REPLACE NON-CONFORMING OIL HOSE AND TUBE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	Complied With
		MOS		01-SEP-2022			
		HRS		761.57			
		ENC		584			
		MSC	-				

Eff. Date: 28-AUG-2018

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 2 - SB - AS907-3-1E-A2 P131118/70040119-1							
SB 78-30-001 R0	NO. 2 ENGINE - ADDITION OF HEAT SHIELD TO REDUCE THE TEMPERATURE SEEN BY HE INNER DUCT, SERVICE BULLETIN					Complied With	
	MOS			24-SEP-2015			
	MSC		-				
SB AS907-72-9005 R05	NO. 2 ENGINE - GENERAL - INSTALLATION OF ENGINE WATER WASH SYSTEM, ON AS907 ENGINES MODELS, SERVICE BULLETIN				CATEGORY 3	Complied With	
	MOS			03-APR-2025			
	HRS			954.4			
	ENC			732			
	MSC		-				
Eff. Date: 23-JAN-2025							
SB AS907-72-9084	NO. 2 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN					Complied With	
	MOS			04-SEP-2019			
	HRS			606.5			
	AFL			469			
	MSC		-				
SB AS907-72-9084 R01 PARA (E)(3)	NO. 2 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN DOWNLOAD ENGINE ECU						
	MOS						
	DAYS			26-MAR-2020			
	MSC		-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB AS907-72-9084 R02	NO. 2 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN					CATEGORY 2	Complied With - SB CARRIED OUT.
	MOS HRS ENC MSC		-	02-FEB-2021 684.43 522			
Eff. Date: 03-APR-2020							
SB AS907-72-9084 R02 PARA (E)(2)	NO. 2 ENGINE - ACCOMPLISH SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN OIL FILTER REPLACEMENT						Complied With - SB CARRIED OUT.
	MOS HRS ENC MSC		-	02-FEB-2021 684.43 522			
SB AS907-72-9084 R02 PARA (E)(3)	NO. 2 ENGINE - ACCOMPLISH SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN DOWNLOAD ENGINE ECU						Complied With - SB CARRIED OUT.
	MOS DAYS MSC		-	31-MAY-2021			
SB AS907-72-9084 R03	NO. 2 ENGINE - SERVICING - REDUCE TIME INTERVAL FOR OIL FILTER REPLACEMENT OR ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN					CATEGORY 2	Complied With
	MOS HRS ENC MSC		-	09-NOV-2024 931.5 712			

Eff. Date: 26-JUN-2021

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB AS907-72-9084 R03 PARA (E)(2)(NO. 2 ENGINE - DOWNLOAD ECU PER PARA 3.B.(3)					CATEGORY 2	Complied With
MOS						RECURRING	
DAYS	30			29-NOV-2025			
HRS				990.7			
ENC				761			
SB AS907-72-9084 R03 PARA (E)(2)(NO. 2 ENGINE - PERFORM OIL FILTER ANALYSIS PER PARA 3.B.(2)					CATEGORY 2	Complied With
MOS				09-NOV-2024			
HRS				931.5			
ENC				712			
MSC	-						
Eff. Date: 26-JUN-2021							
SB AS907-72-9084 R03 PARA (E)(2)(NO. 2 ENGINE - TERMINATING ACTION: COMPLIANCE WITH SB AS907-72-9094 TERMINATES THE INSPECTIONS REQUIRED BY PARA (E)(2)(A) & (E)(2)(B)					CATEGORY 2	Complied With
MOS				09-NOV-2024			
HRS				931.5			
ENC				712			
MSC	-						
Eff. Date: 26-JUN-2021							
SB AS907-72-9093 R03	NO. 2 ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED STAGE 4 COMPRESSOR STATOR VANE, PN 70041641-1 OR PN 70041641-2, ON AS907-3-1E MODEL ENGINES, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
MOS							
HRS	4400			4400			
SB AS907-73-9007	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE NON-CONFORMING FUEL HOSE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN						
MOS							
HRS							
MSC	-						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT
All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB AS907-73-9007 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE NON-CONFORMING FUEL HOSE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	Complied With
	MOS HRS ENC MSC			01-SEP-2022 761.57 584 -			
	Eff. Date: 14-AUG-2018						
SB AS907-76-9021	NO. 2 ENGINE - ENGINE CONTROLS - POWER CONTROLS - APPLY SEALANT TO PREVENT WATER ENTRY INTO ELECTRONIC CONTROL UNIT (ECU) ON AS907 MODEL ENGINES (EXPORT CONTROLLED) (SUPERSEDED BY AS907-76-9021 R01), SERVICE BULLETIN					CATEGORY 1	Complied With
	MOS HRS ENC MSC			10-FEB-2017 410.2 308 -			
	Eff. Date: 13-MAY-2016						
SB AS907-76-9021 R01	NO. 2 ENGINE - ENGINE CONTROLS - POWER CONTROLS - APPLY SEALANT TO PREVENT WATER ENTRY INTO ELECTRONIC CONTROL UNIT (ECU) ON AS907 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 1	Not Applicable - SB PREVIOUSLY COMPLIED WITH AT ORIGINAL ISSUE.
FAA 2018-04-13 PARA (G)(1)	MOS HRS ENC MSC			23-MAY-2018 526.8 393 -			
	Eff. Date: 13-MAY-2016						
SB AS907-76-9029 R01	NO. 2 ENGINE - ENGINE CONTROLS - POWER CONTROLS - REWORK ELECTRONIC CONTROL UNITS 2119576-4103 TO 2119576-4104, 2119576-4203 TO 2119576-4204, OR INSTALL ELECTRONIC CONTROL UNITS 2119576-4104 OR 2119576-4204 ON AS907-3-1E ENGINE MODELS, SERVICE BULLETIN					CATEGORY 1	Complied With
	MOS HRS ENC MSC			18-FEB-2021 684.43 522 -			
	Eff. Date: 05-JUN-2020						

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time



MASTER AD/SI REPORT

Model: LEGACY 500 Serial: 55000008 RegNo: N142GZ HRS: 994.6 AFL: 759 As Of: 15-Dec-2025

AIRCRAFT

All Bulletins With Compliance or Due

29-Dec-2025 06:54 PM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB AS907-79-9007 R02	NO. 2 ENGINE - OIL - STORAGE SECTION - REWORK OIL FILLER CAP ASSEMBLY, PN 3036061-3, TO PREVENT CHAIN INTERFERENCE DURING OIL SUPPLY SERVICING, FOR AS907 MODEL ENGINES (SUPERSEDED BY AS907-79-9007 R03), SERVICE BULLETIN					CATEGORY 2	Complied With
		MOS		10-FEB-2017			
		HRS		410.2			
		ENC		308			
		MSC	-				
Eff. Date: 09-MAR-2015							
SB AS907-79-9010	NO. 2 ENGINE - OIL - DISTRIBUTION - REPLACE NON-CONFORMING OIL HOSE AND TUBE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN						
		MOS					
		HRS					
		MSC	-				
SB AS907-79-9010 R01	NO. 2 ENGINE - OIL - DISTRIBUTION - REPLACE NON-CONFORMING OIL HOSE AND TUBE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	Complied With
		MOS		01-SEP-2022			
		HRS		761.57			
		ENC		584			
		MSC	-				

Eff. Date: 28-AUG-2018

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time