

**OWNER:** AVESCO PTY. LTD.  
**ADDRESS:** P.O. BOX 36  
SPRINGSURE QLD 4722  
**PHONE:** 61-418-184131  
**FAX:** 61-749-591667

**OPERATOR:** AVESCO PTY. LTD.  
**ADDRESS:** P.O. BOX 36  
SPRINGSURE QLD 4722  
**PHONE:** 61-418-184131  
**FAX:** 61-749-591667

**ANALYST:** GOWTHAM THAMMISETTY  
**EMAIL:** GOWTHAM.THAMMISETTY@CAMPSTE  
MS.COM

-- (DIRECT)  
+91-40-30275000 (OFFICE)  
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST  
ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO  
CAMP.

**Filter Criteria:** Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe, Engine, APU Etc;

**AIRCRAFT** **SERIAL/REGNO:** 55000008/N142GZ

**MODEL:** LEGACY 500

**MANUFACTURER:** EMBRAER

<b>DATES</b>		<b>LAST ACTUALS</b>		<b>CURRENT ACTUAL</b>	
CERTIFICATION DATE:	27-JAN-2015	994.6 A/C HRS	as of 15-DEC-2025	_____ A/C HRS	as of ____/____/____
INSERVICE DATE:	29-JAN-2015	759 AFL	as of 15-DEC-2025	_____ AFL	as of ____/____/____
		976.5 APH	as of 29-NOV-2025	_____ APH	as of ____/____/____

**APU**

**SERIAL/PART:** P-110/70720189-1

**MODEL:** GTCP36-150(EMB)

**MANUFACTURER:** HONEYWELL

<b>INSTALLED ON 21-AUG-2014</b>		<b>LAST ACTUALS</b>		<b>CURRENT ACTUAL</b>	
0 APU HRS		976.5 APU HRS	as of 29-NOV-2025	_____ APU HRS	as of ____/____/____
0 APUS		1709 APUS	as of 29-NOV-2025	_____ APUS	as of ____/____/____

**ENGINE NO. 1** **SERIAL/PART:** P131119/70040119-1

**MODEL:** AS907-3-1E-A2

**MANUFACTURER:** HONEYWELL

<b>INSTALLED ON 10-SEP-2014</b>		<b>LAST ACTUALS</b>		<b>CURRENT ACTUAL</b>	
136.1 ENG. HRS	0 A/C HRS	994.6 ENG. HRS	as of 15-DEC-2025	_____ ENG. HRS	as of ____/____/____
105 ENC		764 ENC	as of 15-DEC-2025	_____ ENC	as of ____/____/____

**ENGINE NO. 2** **SERIAL/PART:** P131118/70040119-1

**MODEL:** AS907-3-1E-A2

**MANUFACTURER:** HONEYWELL

<b>INSTALLED ON 10-SEP-2014</b>		<b>LAST ACTUALS</b>		<b>CURRENT ACTUAL</b>	
136.1 ENG. HRS	0 A/C HRS	994.6 ENG. HRS	as of 15-DEC-2025	_____ ENG. HRS	as of ____/____/____
105 ENC		764 ENC	as of 15-DEC-2025	_____ ENC	as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - AD - 55000008/N142GZ</b>							
FAA 2020-25-07	WINDOWS - LH AND RH COCKPIT SIDE WINDOW - INSPECTION / REPLACEMENT					MANDATORY	COMPLIED WITH
21-JAN-2021	MOS HRS/MSC - (s) AFL			15-APR-2025 954.4 727			
FAA 2020-25-07 PARA (G)(1) (LH)	CARRY OUT A DETAILED INSPECTION (DET) FOR CRACKS, DELAMINATION OR ANY OTHER DAMAGE ACCORDING TO THE TASK 56-12-00-200-801-A DETAILED INSPECTION OF COCKPIT SIDE WINDOW, REVISION 36 DATED MAY 15, 2020					MANDATORY	COMPLIED WITH
21-JAN-2021	MOS HRS/MSC - AFL			15-APR-2025 954.4 727			
FAA 2020-25-07 PARA (G)(1) (RH)	CARRY OUT A DETAILED INSPECTION (DET) FOR CRACKS, D DELAMINATION OR ANY OTHER DAMAGE ACCORDING TO THE TASK 56-12-00-200-801-A DETAILED INSPECTION OF COCKPIT SIDE WINDOW, REVISION 36 DATED MAY 15, 2020					MANDATORY	COMPLIED WITH
21-JAN-2021	MOS HRS/MSC - AFL			15-APR-2025 954.4 727			
FAA 2020-25-07 PARA (G)(2) (LH)	REPLACE THE COCKPIT LH SIDE WINDOW BY A MODIFIED WINDOW					MANDATORY	NOT APPLICABLE - REPLACEMENT OF SIDE WINDOW NOT REQUIRED, WINDOW FOUND IN ACCEPTABLE CONDITION.
21-JAN-2021	MOS HRS/MSC - AFL			04-FEB-2021 684.43 522			
FAA 2020-25-07 PARA (G)(2) (RH)	REPLACE THE COCKPIT RH SIDE WINDOW BY A MODIFIED WINDOW					MANDATORY	NOT APPLICABLE - REPLACEMENT OF SIDE WINDOW NOT REQUIRED, WINDOW FOUND IN ACCEPTABLE CONDITION.
21-JAN-2021	MOS HRS/MSC - AFL			04-FEB-2021 684.43 522			
FAA 2021-08-07 PARA (G)(1)	REPLACE EACH GPS-4000S GPS P/N 822-2189-100 WITH A GPS THAT DOES NOT HAVE P/N 822-2189-100					MANDATORY	NOT APPLICABLE
	MOS HRS/MSC - AFL			07-FEB-2023 790.57 605			
FAA 2022-19-14	EQUIPMENT/FURNISHINGS - DIVAN-SEAT ADDITIONAL-PROTECTION FAIRING - INSTALLATION					MANDATORY	
14-APR-2023	MOS 48 HRS/MSC AFL			(EFF)	14-APR-2027		
FAA 2022-21-08	INTEGRATED MODULAR AVIONICS - AVIONICS EICAS - INSTALLATION					MANDATORY	NOT APPLICABLE
22-DEC-2022	MOS HRS/MSC - AFL			05-SEP-2023 807.5 619			
FAA 2024-05-13	AIRPLANE FLIGHT MANUAL REVISION					MANDATORY	COMPLIED WITH
39-22705 10-APR-2024	MOS HRS/MSC - AFL			09-NOV-2024 931.5 712			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2024-05-13 PARA (G) ANAC (A)	AIRPLANE FLIGHT MANUAL REVISION					MANDATORY	COMPLIED WITH
10-APR-2024		DAYs		09-NOV-2024			
		HRS/MSC	-	931.5			
		AFL		712			
FAA 2024-05-13 PARA (I)(1)	INSPECT ALL AIRCRAFT RECORDS FOR INSTANCES OF AOA LIMITER ENGAGEMENT THAT OCCUR AFTER PASSING THE FINAL APPROACH FIX INBOUND					MANDATORY	COMPLIED WITH
10-APR-2024		DAYs		17-APR-2025			
		HRS/MSC	-	954.4			
		AFL		727			
FAA 2024-05-13 PARA (I)(2)	REPORT THE RESULTS OF THE INSPECTION, REGARDLESS OF WHETHER THE INSPECTION FOUND ANY ENTRIES					MANDATORY	COMPLIED WITH
10-APR-2024		DAYs		09-NOV-2024			
		HRS/MSC	-	931.5			
		AFL		712			
FAA 2024-15-13 PARA (G) ANAC (B) LH	PERFORM A GENERAL VISUAL INSPECTION (GVI) AT THE COCKPIT SIDE WINDOW TO DETECT CRACKS, DELAMINATION OR ANY OTHER DAMAGE AND REPLACE THE DAMAGED WINDOW WITH A MODIFIED ONE WITH A NEW P/N NP-200402-9 OR P/N NP-200402-10, AS APPLICABLE (IN CASE OF ANY CRACK IN THE OUTER LAYER IS DETECTED)					MANDATORY	
39-22805 23-OCT-2024		MOS		(EFF)			RECURRING
		HRS/MSC					
		AFL	1200		1946		
FAA 2024-15-13 PARA (G) ANAC (B) RH	PERFORM A GENERAL VISUAL INSPECTION (GVI) AT THE COCKPIT SIDE WINDOW TO DETECT CRACKS, DELAMINATION OR ANY OTHER DAMAGE AND REPLACE THE DAMAGED WINDOW WITH A MODIFIED ONE WITH A NEW P/N NP-200402-9 OR P/N NP-200402-10 (IN CASE OF ANY CRACK IN THE OUTER LAYER IS DETECTED)					MANDATORY	
39-22805 23-OCT-2024		MOS		(EFF)			RECURRING
		HRS/MSC					
		AFL	1200		1946		
FAA 2024-16-16 PARA (G) ANAC (B) (LH)	INITIAL AND REPETITIVE INSPECTION OF THE COCKPIT LH SIDE WINDOW					MANDATORY	COMPLIED WITH
39-21349 30-OCT-2024		MOS		15-APR-2025			RECURRING
		HRS/MSC	750	954.4	1704.4		
		AFL		727			
FAA 2024-16-16 PARA (G) ANAC (B) (RH)	INITIAL AND REPETITIVE INSPECTION OF THE COCKPIT RH SIDE WINDOW					MANDATORY	COMPLIED WITH
39-21349 30-OCT-2024		MOS		15-APR-2025			RECURRING
		HRS/MSC	750	954.4	1704.4		
		AFL		727			
FAA 2024-16-16 PARA (G) ANAC (C) (LH)	REPLACE THE COCKPIT LH SIDE WINDOW BY A MODIFIED WINDOW					MANDATORY	
39-21349 30-OCT-2024		MOS		(EFF)			
		HRS/MSC					
		AFL	50		804		
FAA 2024-16-16 PARA (G) ANAC (C) (RH)	REPLACE THE COCKPIT RH SIDE WINDOW BY A MODIFIED WINDOW					MANDATORY	
39-21349 30-OCT-2024		MOS		(EFF)			
		HRS/MSC					
		AFL	50		804		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2025-13-02 PARA (G) ANAC (B)	MAIN DOOR SENSOR OPERATIONAL TEST					MANDATORY	COMPLIED WITH - CARRIED OUT OPS CHECK OF MAIN DOOR SENSORS IAW EMBRAER LEGACY 500 AMM 52-71-20-710-801-A0REV 61 & COMPLIED WITH
05-AUG-2025		MOS HRS/MSC AFL	12	18-AUG-2025 969.1 739	18-AUG-2026	RECURRING	
FAA 2025-13-02 PARA (G) ANAC (D)	MAIN DOOR SENSOR MECHANISM LUBRICATION					MANDATORY	COMPLIED WITH
05-AUG-2025		MOS HRS/MSC AFL	24	18-AUG-2025 969.1 739	18-AUG-2027	RECURRING	

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>APPLIANCE - 55000008/N142GZ</b>							
EASA 2010-0003 R02	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			
EASA 2010-0003 R02 PARA (1)	VERIFY AIRCRAFT TYPE MODE STRAPPING CODE S SET TO '0' (ZERO) OR '1', AS DEFINED IN ROCKWELL-COLLINS SERVICE LETTER TDR-94( ) SIL 07-2.				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			
EASA 2010-0003 R02 PARA (2)	EXEMPTIONS: DASSAULT AEROPLANES				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			
EASA 2010-0003 R02 PARA (3)	EXEMPTIONS: ATR 42 AND ATR 72 AEROPLANES				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			
EASA 2010-0003 R02 PARA (4)	EXEMPTIONS: SAAB 2000 AEROPLANES				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			
EASA 2010-0003 R02 PARA (5)	EXEMPTIONS: BOMBARDIER AEROSPACE (CANADAIR) AEROPLANES: CL-600-2B16 (604 VARIANT) AND CL-600-2B19 (RJ100 AND RJ200)				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			
EASA 2010-0003 R02 PARA (6)	EXEMPTIONS: CESSNA AIRCRAFT COMPANY AEROPLANES: CESSNA MODEL 525, 525A, 525B; AND CESSNA MODEL 525, 525A, 525B, 560; 560XL				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			
EASA 2010-0003 R02 PARA (7)	EXEMPTIONS: PIAGGIO AERO INDUSTRIES AEROPLANES: P.180 (AVANTI) AND P.180 (AVANTI II)				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION				MANDATORY	NOT APPLICABLE - TO P/N 622-9210-411 INSTALLED	
14-OCT-2014		MOS		27-JAN-2015			
		HRS/MSC	-	0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES					MANDATORY	NOT APPLICABLE - FAA 2015-08-07 FOUND NOT APPLICABLE. P/N & S/N INSTALLED ARE AS FOLLOWS. PILOT: P/N: MC40-011, S/N: 249 COPILOT: P/N: MC40-011, S/N: 382 OBSERVER: P/N: MC40-011, S/N: 328
16-JUN-2015		MOS		09-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011					MANDATORY	NOT APPLICABLE
16-JUN-2015		MOS		09-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES					MANDATORY	NOT APPLICABLE
16-JUN-2015		MOS		09-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE - FAA 2015-08-07 FOUND NOT APPLICABLE. P/N & S/N INSTALLED ARE AS FOLLOWS. COPILOT: P/N: MR-10022NEMB, S/N: E1400363 OBSERVER: P/N: MR-10022NEMB, S/N: E1400392
15-JUL-2016		MOS		09-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE
15-JUL-2016		MOS		09-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE
15-JUL-2016		MOS		09-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	NOT APPLICABLE
15-JUL-2016		MOS		09-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						NOT APPLICABLE - AD NOT APPLICABLE -EQUIPMENT NOT INSTALLED A/C IS FILLED WITH ESSEX PBE'S PN: S1821502, SN: LX1100112710.
24-OCT-2017		MOS		06-OCT-2017			
		HRS/MSC	-	469.5			
		AFL		358			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED A/C IS FILLED WITH ESSEX PBE'S. PN: MR-10022NEMB PN: 10051N
16-OCT-2017	MOS HRS/MSC - AFL			06-OCT-2017 469.5 358			
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED A/C IS FILLED WITH ESSEX PBE'S. PN: MR-10022NEMB PN: 10051N
16-OCT-2017	MOS HRS/MSC - AFL			06-OCT-2017 469.5 358			
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED A/C IS EQUIPPED WITH ESSEX PBE'S. PN: MR-10022NEMB PN: 10051N
16-OCT-2017	MOS HRS/MSC - AFL			06-OCT-2017 469.5 358			
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	NOT APPLICABLE - EQUIPMENT NOT INSTALLED A/C IS FILLED WITH ESSEX PBE'S. PN: MR-10022NEMB PN: 10051N
16-OCT-2017	MOS HRS/MSC - AFL			06-OCT-2017 469.5 358			
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILLANCE SYSTEM PROCESSING UNITS					MANDATORY	COMPLIED WITH - COMPLIED WITH IAW SB 550-42-0008 REV 03.
20-DEC-2017	MOS HRS/MSC - AFL			06-MAR-2018 500.7 379			
FAA 2019-15-10	APPLIANCE AD - EQUIPMENT / FURNISHING - LIFE JACKET - REMOVAL / REPAIR					MANDATORY	NOT APPLICABLE - PN/SN NOT INSTALLED. ALL FITTED WITH PN: 66601-505 & RSS-301 LIFE VESTS. NO FURTHER ACTION REQUIRED.
19-SEP-2019	MOS HRS/MSC - (s) AFL			01-MAY-2020 654.7 502			
FAA 2019-15-10 PARA (G)	REMOVE EACH AFFECTED LIFE JACKET FROM THE AIRPLANE AND REPLACE THE LIFE JACKET WITH A LIFE JACKET ELIGIBLE FOR INSTALLATION					MANDATORY	NOT APPLICABLE - PN/SN NOT INSTALLED. ALL FITTED WITH PN: 66601-505 & RSS-301 LIFE VESTS. NO FURTHER ACTION REQUIRED.
19-SEP-2019	MOS HRS/MSC - AFL			01-MAY-2020 654.7 502			
FAA 2019-15-10 PARA (H)	DO NOT INSTALL ON ANY AIRPLANE AN AFFECTED LIFE JACKET UNLESS IT HAS BEEN REPAIRED AND MARKED TO INDICATE COMPLIANCE WITH SUCH REPAIR IN ACCORDANCE WITH ZODIAC AEROSPACE SERVICES SB 25-65-34, REVISION 01, DATED MARCH 15, 2019, OR ORIGINAL ISSUE, DATED JANUARY 8, 2019; OR A METHOD APPROVED BY THE FAA					MANDATORY	NOT APPLICABLE - PN/SN NOT INSTALLED. ALL FITTED WITH PN: 66601-505 & RSS-301 LIFE VESTS. NO FURTHER ACTION REQUIRED.
19-SEP-2019	MOS HRS/MSC - (s) AFL			01-MAY-2020 654.7 502			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2021-08-07	APPLIANCE AD - ROCKWELL COLLINS - GLOBAL POSITIONING SYSTEM GPS-4000S - UPGRADE					MANDATORY	COMPLIED WITH - INSERTED AND NO ACTION REQUIRED IAW FAA AD 2021-08-07 PARA (G)(1) GPS UNIT 1 P/N 822-2189-010 SN 4JF7N; GPS UNIT 2 P/N 822-2189-010 SN 4JF7P.
12-MAY-2021		MOS		07-FEB-2023			
		HRS/MSC	-	790.57			
		AFL		605			
FAA 2021-08-07 PARA (G)(2)	DO NOT INSTALL GPS-4000S GPS P/N 822-2189-100 ON ANY AIRPLANE					MANDATORY	COMPLIED WITH - GPS UNIT 1 AND GPS UNIT 2 INSPECTED AND FOUND NOT TO BE P/N 822-2189-100 IN EITHER CASE. NO ACTION REQUIRED.
12-MAY-2021		MOS		07-FEB-2023			
		HRS/MSC	- (s)	790.57			
		AFL		605			
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	NOT APPLICABLE - BY P/N OF RAD ALT FITTED TO L500 REFER TO FOL 500-00-001/22
09-DEC-2021		MOS		15-FEB-2022			
		HRS/MSC	-	737.3			
		AFL		562			
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)					MANDATORY	COMPLIED WITH
26-MAY-2023		MOS		09-MAR-2024			
		HRS/MSC	-	851.38			
		AFL		648			
FAA 2025-25-02	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS					MANDATORY	
39-23210		DAYs	30	(EBT)	23-JAN-2026		
24-DEC-2025		HRS/MSC					
		AFL					

NEW REQUIREMENT ADDED ON 10-DEC-2025 (EFFECTIVE: 24-DEC-2025). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - SB - 55000008/N142GZ</b>							
SB 550-21-0003	AIR CONDITIONING - CONDITIONED AIR DUCTS REPLACEMENT (SUPERSEDED BY 550-21-0003 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
05-OCT-2016		MOS		20-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
SB 550-21-0003 REV 01	AIR CONDITIONING - CONDITIONED AIR DUCTS REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - 20-FEB-2017
27-APR-2017		MOS		02-MAR-2020			
		HRS/MSC	-	648.5			
		AFL		499			
SB 550-21-0003 REV 01 PART I	ACCOMPLISH AIR CONDITIONING - CONDITIONED AIR DUCTS REPLACEMENT, SERVICE BULLETIN CONDITIONED AIR DUCTS REPLACEMENT					RECOMMENDED	COMPLIED WITH - 20-FEB-2017
27-APR-2017		MOS		02-MAR-2020			
		HRS/MSC	-	648.5			
		AFL		499			
SB 550-21-0003 REV 01 PART II	ACCOMPLISH AIR CONDITIONING - CONDITIONED AIR DUCTS REPLACEMENT, SERVICE BULLETIN ADDITIONAL ACTION - CABIN LEAKAGE FUNCTIONAL TEST					RECOMMENDED	COMPLIED WITH - CARRIED OUT IAW SB 550-21-0003 REV 01 PART II
27-APR-2017		MOS		02-MAR-2020			
		HRS/MSC	-	648.5			
		AFL		499			
SB 550-22-0001	AUTO FLIGHT - CAT II CONFIGURATION (SUPERSEDED BY SB 550-22-0001 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
14-DEC-2015		MOS					
		HRS/MSC	-				
		AFL					
SB 550-22-0001 REV 01	AUTO FLIGHT - CAT II CONFIGURATION (SUPERSEDED BY SB 550-22-0001 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
22-JAN-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 550-23-0001	COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT (SUPERSEDED BY SB 550-23-0001 OPTIONAL REV 01), SERVICE BULLETIN					NOT APPLICABLE	
01-FEB-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 550-23-0001 REV 01	COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT (SUPERSEDED BY SB 550-23-0001 OPTIONAL REV 02), SERVICE BULLETIN					NOT APPLICABLE	
09-MAR-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 550-23-0001 REV 03	COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
12-APR-2017		MOS		19-JUL-2017			
		HRS/MSC	-	459.1			
		AFL		350			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-23-0001 REV 03 PART I	ACCOMPLISH COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT, SERVICE BULLETIN ACCOMPLISH ELECTRICAL POWER DISTRIBUTION MODIFICATION					OPTIONAL	COMPLIED WITH
12-APR-2017		MOS HRS/MSC - AFL		19-JUL-2017 459.1 350			
SB 550-23-0001 REV 03 PART II	ACCOMPLISH COMMUNICATIONS - IRIDIUM SYSTEM ELECTRICAL POWER CIRCUIT IMPROVEMENT, SERVICE BULLETIN ACCOMPLISH IRIDIUM PLATE ELECTRICAL BONDING					OPTIONAL	COMPLIED WITH
12-APR-2017		MOS HRS/MSC - AFL		19-JUL-2017 459.1 350			
SB 550-23-0003	COMMUNICATIONS - HEADSET INSTALLATION AT THE CABINET OBSERVER SEAT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-MAR-2016		MOS HRS/MSC - AFL					
SB 550-24-0001	ELECTRICAL POWER - RESISTORS INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
18-MAR-2015		MOS HRS/MSC - AFL					
SB 550-24-0002	ELECTRICAL POWER - RESISTORS INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
27-APR-2015		MOS HRS/MSC - AFL		25-SEP-2015 269.58 194			
SB 550-24-0003	ELECTRICAL POWER - LPDC AND RPDC TERMINALS PROTECTION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - -EQUIVALENT MODIFICATION FACTORY INCORPORATED
28-JUN-2016		MOS HRS/MSC - AFL					
SB 550-24-0004	ELECTRICAL POWER - HIGH POWER OUTLETS INSTALLATION (SUPERSEDED BY SB 550-24-0004 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
06-MAY-2016		MOS HRS/MSC - AFL					
SB 550-24-0004 REV 01	ELECTRICAL POWER - HIGH POWER OUTLETS INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
03-JUN-2016		MOS HRS/MSC - AFL					
SB 550-24-0008	ELECTRICAL POWER - BATTERIES AND RESISTORS INSTALLATION, SERVICE BULLETIN					CATEGORY 04 - OPTIONAL	COMPLIED WITH
03-FEB-2022		MOS HRS/MSC - AFL		17-MAR-2023 790.57 605			
SB 550-24-0011	ELECTRICAL POWER - MAIN DC ELECTRIC GENERATOR V-BAND CLAMP - TORQUE APPLICATION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
19-SEP-2025		MOS HRS/MSC AFL	12		17-FEB-2026 M		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-25-0002	EQUIPMENT/FURNISHINGS - DOOR GUIDE INSTALLATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - -EQUIVALENT MODIFICATION FACTORY INCORPORATED
11-FEB-2015	MOS HRS/MSC - AFL						
SB 550-25-0003	EQUIPMENT/FURNISHINGS - STONE FLOOR PANELS REPLACEMENT, SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
06-MAY-2016	MOS HRS/MSC - AFL						
SB 550-25-0004 REV 01	EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION (SUPERSEDED BY SB 550-25-0004 REV 02), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - C/O IAW SB 550-25-0004 R1
22-DEC-2015	MOS HRS/MSC - AFL			21-JAN-2016 297.12 215			
SB 550-25-0004 REV 02	EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION FOR AIRCRAFT SN 55000008, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
17-JAN-2017	MOS HRS/MSC - AFL			20-FEB-2017 410.2 308			
SB 550-25-0004 REV 02 PART I	ACCOMPLISH EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION FOR AIRCRAFT SN 55000008, SERVICE BULLETIN OBSERVER SEAT INSTALLATION					RECOMMENDED	COMPLIED WITH - PREVIOUSLY COMPLIED WITH
17-JAN-2017	MOS HRS/MSC - AFL			20-FEB-2017 410.2 308			
SB 550-25-0004 REV 02 PART II	ACCOMPLISH EQUIPMENT/FURNISHINGS - OBSERVER SEAT INSTALLATION FOR AIRCRAFT SN 55000008, SERVICE BULLETIN ADDITIONAL ACTION					RECOMMENDED	COMPLIED WITH - CARRIED OUT IAW SB INSTRUCTIONS
17-JAN-2017	MOS HRS/MSC - AFL			20-FEB-2017 410.2 308			
SB 550-25-0006	EQUIPMENT/FURNISHINGS - REFRIGERATOR INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
26-JUN-2015	MOS HRS/MSC - AFL						
SB 550-25-0007	EQUIPMENT/FURNISHINGS - DIVAN BERTHING FUNCTIONALITY - ACTIVATION, SERVICE BULLETIN					OPERATORS DISCRETION	COMPLIED WITH - SB 550-25-0007 COMPLIED WITH.
30-JUL-2015	MOS HRS/MSC - AFL			25-SEP-2015 269.58 194			
SB 550-25-0008	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE FAUCETS FROM THE GALLEY AND LAVATORY AND REPLACEMENT OF THE GASPERS, READING LIGHTS, AND PLACARDS OF THE CABIN PASSENGERS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
29-SEP-2015	MOS HRS/MSC - AFL						
SB 550-25-0010	EQUIPMENT/FURNISHINGS - CONVECTION OVEN INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
09-MAR-2016	MOS HRS/MSC - AFL						

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-25-0012	EQUIPMENT/FURNISHINGS - INTERNAL STOWAGE DOOR LATCH - REPLACEMENT OF CATCH, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - CARRIED OUT IAW SB INSTRUCTIONS
27-SEP-2016		MOS HRS/MSC - AFL		08-FEB-2017 410.2 308			
SB 550-25-0013 REV 07	EQUIPMENT/FURNISHINGS - BELTED TOILET ASSEMBLY - MODIFICATIONS (SUPERSEDED BY 550-25-0013 REV 08), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SB 550-25-0013 REV 07 COMPLETED
21-DEC-2017		MOS HRS/MSC - AFL		02-MAR-2018 500.7 379			
SB 550-25-0014	EQUIPMENT/FURNISHINGS - REMOVAL OF OCCUPANCY LIMITATION OF THE AFT- FACING SEAT DURING TTL (TAKE-OFF, TAXI AND LANDING) (SUPERSEDED BY SB 550-25-0014 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
24-JUN-2016		MOS HRS/MSC - AFL					
SB 550-25-0014 REV 01	EQUIPMENT/FURNISHINGS - REMOVAL OF OCCUPANCY LIMITATION OF THE AFT- FACING SEAT DURING TTL (TAKE-OFF, TAXI AND LANDING), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
28-JUN-2016		MOS HRS/MSC - AFL					
SB 550-25-0016	EQUIPMENT/FURNISHINGS - PAX OXYGEN BOX COVER LANYARD - INSPECTION / MODIFICATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
02-SEP-2016		MOS HRS/MSC - AFL		07-SEP-2016 347.1 258			
SB 550-25-0016 PART I	ACCOMPLISH EQUIPMENT/FURNISHINGS - PAX OXYGEN BOX COVER LANYARD - INSPECTION / MODIFICATION, SERVICE BULLETIN INSPECTION OF PAX OXYGEN BOX COVER LANYARD					RECOMMENDED	COMPLIED WITH
02-SEP-2016		MOS HRS/MSC - AFL		07-SEP-2016 347.1 258			
SB 550-25-0016 PART II	ACCOMPLISH EQUIPMENT/FURNISHINGS - PAX OXYGEN BOX COVER LANYARD - INSPECTION / MODIFICATION, SERVICE BULLETIN MODIFICATION OF PAX OXYGEN BOX COVER LANYARD					RECOMMENDED	COMPLIED WITH
02-SEP-2016		MOS HRS/MSC - AFL		07-SEP-2016 347.1 258			
SB 550-25-0019	EQUIPMENT/FURNISHINGS - BELTED TOILET FUNCTIONALITY DE-ACTIVATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
27-SEP-2016		MOS HRS/MSC - AFL					
SB 550-25-0034	EQUIPMENT/FURNISHINGS - VANITY AND SIDELEDGE - THERAPEUTIC OXYGEN PLACARDS INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - SB 550-25-0034 COMPLETED
03-AUG-2017		MOS HRS/MSC - AFL		14-FEB-2018 500.7 379			
SB 550-25-0067 REV 03	EQUIPMENT/FURNISHINGS - DIVAN-SEAT ADDITIONAL-PROTECTION FAIRING - INSTALLATION, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
30-DEC-2021		MOS HRS/MSC - AFL		16-FEB-2022 737.3 562			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-25-0074	EQUIPMENT/FURNISHINGS - OBSERVER SEAT PLACARD - INSTALLATION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
07-DEC-2022	MOS HRS/MSC - AFL	07-FEB-2023 790.57 605					
SB 550-26-0001	FIRE PROTECTION - LAVATORY SMOKE DETECTOR INSTALLATION (SUPERSEDED BY SB 550-26-0001 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-DEC-2015	MOS HRS/MSC - AFL	14-JAN-2016 297.12 215					
SB 550-26-0002	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-MAY-2016	MOS HRS/MSC - AFL						
SB 550-27-0001 REV 02	FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - NEW P/N:494910-1007
23-JUL-2015	MOS HRS/MSC - AFL	25-SEP-2015 269.58 194					
SB 550-27-0002	FLIGHT CONTROLS - HIGH-ALTITUDE LANDING AND TAKE-OFF OPERATION PLACARD INSTALLATION (SUPERSEDED BY SB 550-27-0002 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
15-DEC-2015	MOS HRS/MSC - AFL						
SB 550-27-0002 REV 01	FLIGHT CONTROLS - HIGH-ALTITUDE LANDING AND TAKE-OFF OPERATION PLACARD INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
02-JUN-2016	MOS HRS/MSC - AFL						
SB 550-27-0003	FLIGHT CONTROLS - CORRECTION OF THE IDENTIFICATION PLACARDS POSITION (REU 7 /REU 8) (SUPERSEDED BY 550-27-0003 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
02-JUN-2016	MOS HRS/MSC - AFL	17-FEB-2017 410.2 308					
SB 550-27-0004	FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
15-DEC-2015	MOS HRS/MSC - AFL						
SB 550-27-0004 REV 01	FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
03-MAY-2016	MOS HRS/MSC - AFL						
SB 550-27-0004 REV 01 PART I	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 02), SERVICE BULLETIN STEEP APPROACH INSTALLATION					OPERATORS DISCRETION	NOT APPLICABLE
03-MAY-2016	MOS HRS/MSC - AFL						

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-27-0004 REV 01 PART II	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 02), SERVICE BULLETIN ADDITIONAL ACTION					OPERATORS DISCRETION	NOT APPLICABLE
03-MAY-2016		MOS HRS/MSC - AFL					
SB 550-27-0004 REV 02	FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 03), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
29-JUL-2016		MOS HRS/MSC - AFL					
SB 550-27-0004 REV 02 PART I	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 03), SERVICE BULLETIN STEEP APPROACH INSTALLATION					OPERATORS DISCRETION	NOT APPLICABLE
29-JUL-2016		MOS HRS/MSC - AFL					
SB 550-27-0004 REV 02 PART II	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 03), SERVICE BULLETIN ADDITIONAL ACTION					OPERATORS DISCRETION	NOT APPLICABLE
29-JUL-2016		MOS HRS/MSC - AFL					
SB 550-27-0004 REV 03	FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 04), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
03-AUG-2016		MOS HRS/MSC - AFL					
SB 550-27-0004 REV 03 PART I	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 04), SERVICE BULLETIN STEEP APPROACH INSTALLATION					OPERATORS DISCRETION	NOT APPLICABLE
03-AUG-2016		MOS HRS/MSC - AFL					
SB 550-27-0004 REV 03 PART II	ACCOMPLISH FLIGHT CONTROLS - STEEP APPROACH ACTIVATION (SUPERSEDED BY 550-27-0004 REV 04), SERVICE BULLETIN ADDITIONAL ACTION					OPERATORS DISCRETION	NOT APPLICABLE
03-AUG-2016		MOS HRS/MSC - AFL					
SB 550-27-0005	FLIGHT CONTROLS - REPLACEMENT OF THE REMOTE ELECTRONIC UNITS (REU'S), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
22-JUN-2016		MOS HRS/MSC - AFL		23-FEB-2019 573.43 436			
SB 550-27-0006	FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE TO 494910-1009, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
20-DEC-2019		MOS HRS/MSC - AFL		02-MAR-2020 648.5 499			
SB 550-27-0007	FLIGHT CONTROLS - FLAP POWER DRIVE UNIT REPLACEMENT, SERVICE BULLETIN					CATEGORY 04 - OPTIONAL	COMPLIED WITH
24-JAN-2023		MOS HRS/MSC - AFL		16-MAR-2023 790.57 605			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-27-0008	FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER CONNECTOR O-RING INSPECTION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
10-OCT-2024	MOS HRS/MSC - AFL			12-MAR-2025 954.4 727			
SB 550-27-0008 PART I	ACCOMPLISH FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER CONNECTOR O-RING INSPECTION, SERVICE BULLETIN INSPECTION OF THE RUBBER BLUE O-RINGS CONNECTOR					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
10-OCT-2024	MOS HRS/MSC - AFL			12-MAR-2025 954.4 727			
SB 550-27-0008 PART II	ACCOMPLISH FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER CONNECTOR O-RING INSPECTION, SERVICE BULLETIN REMOVE OF THE RUBBER BLUE O-RINGS CONNECTOR					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
10-OCT-2024	MOS HRS/MSC - AFL			12-MAR-2025 954.4 727			
SB 550-27-0009	FLIGHT CONTROLS - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPDATE TO PN 494910-1011, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
07-APR-2025	MOS 48 HRS/MSC 2400 AFL			(EFF)	07-APR-2029 3467.82		
SB 550-28-0002	FUEL - FUEL QUANTITY INCREASE (SUPERSEDED BY SB 550-28-0002 REV 01), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
29-JUL-2016	MOS HRS/MSC - AFL						
SB 550-28-0002 REV 01	FUEL - FUEL QUANTITY INCREASE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-SEP-2016	MOS HRS/MSC - AFL						
SB 550-29-0002	HYDRAULIC POWER - HYDRAULIC SYSTEM 1 DCMP (DIRECT CURRENT MOTOR PUMP) - REPLACEMENT (SUPERSEDED BY 550-29-0002 REV 01), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY SB 550-29-0002 REV 01.
09-OCT-2018	MOS HRS/MSC - AFL			11-FEB-2020 648.5 499			
SB 550-29-0002 REV 01	HYDRAULIC POWER - HYDRAULIC SYSTEM 1 DCMP (DIRECT CURRENT MOTOR PUMP) - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - SUPERSEDED BY SB 550-29-0002 REV 02.
29-OCT-2018	MOS HRS/MSC - AFL			11-FEB-2020 648.5 499			
SB 550-29-0002 REV 02	HYDRAULIC POWER - HYDRAULIC SYSTEM 1 DCMP (DIRECT CURRENT MOTOR PUMP) - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - ALL WORK CARRIED OUT IAW LEG 500 AMM 29-11-02-000-801-A-400-801-A, REV 34. CALIBRATING TOOLING: EJCE0251-\$ EXP: 24-OCT-20.
29-MAR-2019	MOS HRS/MSC - AFL			14-FEB-2020 648.5 499			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-31-0001	INDICATING/RECORDING SYSTEMS - INDICATING AND RECORDING SYSTEMS - QAR - QUICK ACCESS RECORDER INSTALLATION (SUPERSEDED BY 550-31-0001 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-JUN-2016		MOS HRS/MSC - AFL					
SB 550-31-0002	INDICATING/RECORDING SYSTEMS - VOLUME ADJUSTMENT OF THE AURAL WARNING, SERVICE BULLETIN					OPERATORS DISCRETION	COMPLIED WITH
01-SEP-2016		MOS HRS/MSC - AFL		06-MAR-2018 500.7 379			
SB 550-31-0003	INDICATING/RECORDING SYSTEMS - HEAD-UP DISPLAY INSTALLATION (SUPERSEDED BY 550-31-0003 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
31-OCT-2016		MOS HRS/MSC - AFL					
SB 550-31-0004	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ENHANCED FLIGHT VISION SYSTEM (EFVS) (SUPERSEDED BY 550-31-0004 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
31-OCT-2016		MOS HRS/MSC - AFL					
SB 550-32-0001	LANDING GEAR - REWORK OF MLG AND NLG ASSEMBLY, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - -EQUIVALENT MODIFICATION FACTORY INCORPORATED
16-MAR-2015		MOS HRS/MSC - AFL					
SB 550-32-0002	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0002 REV 01), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
16-MAR-2015		MOS HRS/MSC - AFL		(EFF)			
SB 550-32-0002 REV 01	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0008), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-AUG-2016		MOS HRS/MSC - AFL					
SB 550-32-0003 REV 01	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0003 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	COMPLIED WITH - NEW P/N: 80-230021-02
06-JUL-2015		MOS HRS/MSC - AFL		25-SEP-2015 269.58 194			
SB 550-32-0003 REV 02	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0008), SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - COMPLIED WITH AT REV 01, NO FURTHER ACTION REQUIRED 25SEP15, 269.58/194
10-AUG-2016		MOS HRS/MSC - AFL		14-FEB-2020 648.5 499			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-32-0004 REV 01	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 02), SERVICE BULLETIN					OPERATORS DISCRETION	COMPLIED WITH
30-NOV-2015	MOS HRS/MSC - AFL			14-JAN-2016 297.12 215			
SB 550-32-0004 REV 02	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 03), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE - SUPERSEDED BY SB 550-32-0004 REV 03.
26-JAN-2016	MOS HRS/MSC - AFL			02-MAR-2020 648.5 499			
SB 550-32-0004 REV 03	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 04), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE - SUPERSEDED BY SB 550-32-0004 REV 04.
05-SEP-2016	MOS HRS/MSC - AFL			02-MAR-2020 648.5 499			
SB 550-32-0004 REV 04	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 05), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE - SUPERSEDED BY SB 550-32-0004 REV 05.
23-FEB-2017	MOS HRS/MSC - AFL			02-MAR-2020 648.5 499			
SB 550-32-0004 REV 05	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 06), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE - SUPERSEDED BY SB 550-32-0004 REV 06.
27-MAR-2017	MOS HRS/MSC - AFL			02-MAR-2020 648.5 499			
SB 550-32-0004 REV 06	LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 07), SERVICE BULLETIN					OPERATORS DISCRETION	COMPLIED WITH - PART I COMPLIED WITH SB 550-32-0004 REV 1 15-JAN-2016.
17-OCT-2019	MOS HRS/MSC - AFL			02-MAR-2020 648.5 499			
SB 550-32-0004 REV 06 PART I	ACCOMPLISH LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 07), SERVICE BULLETIN AUTOBRAKE CONFIGURATION					OPERATORS DISCRETION	COMPLIED WITH - PART I COMPLIED WITH SB 550-32-0004 REV 1 15-JAN-2016.
17-OCT-2019	MOS HRS/MSC - AFL			02-MAR-2020 648.5 499			
SB 550-32-0004 REV 06 PART II	ACCOMPLISH LANDING GEAR - AUTOBRAKE CONFIGURATION (SUPERSEDED BY 550-32-0004 REV 07), SERVICE BULLETIN ADDITIONAL ACTION - UPDATE THE WEIGHT AND BALANCE DATA					OPERATORS DISCRETION	COMPLIED WITH - CARRIED OUT IAW SB 550-32-0004 REV 06
17-OCT-2019	MOS HRS/MSC - AFL			02-MAR-2020 648.5 499			
SB 550-32-0006	LANDING GEAR - UPLock BOX - REPLACEMENT (SUPERSEDED BY SB 550-32-0006 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB 550-32-0006 COMPLIED WITH
21-AUG-2015	MOS HRS/MSC - AFL			25-SEP-2015 269.58 194			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-32-0008	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) (SUPERSEDED BY SB 550-32-0010 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT CARRIED OUT IN FULL IAW SB 550-32-0008
10-AUG-2016		MOS HRS/MSC - AFL		14-FEB-2017 410.2 308			
SB 550-32-0009	LANDING GEAR - REWORK OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT AND SHOCK ABSORBER (SUPERSEDED BY 550-32-0009 REV 01), SERVICE BULLETIN				03-MAR-2020	RECOMMENDED	COMPLIED WITH
04-SEP-2019		MOS HRS/MSC - AFL		648.5 499			
SB 550-32-0009 REV 01	LANDING GEAR - REWORK OF THE MAIN LANDING GEAR (MLG) SHOCK STRUT AND SHOCK ABSORBER, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - PREVIOUS REVISION ON 03-MAR-2020.
25-MAR-2020		MOS HRS/MSC - AFL		(EFF)			
SB 550-32-0010	LANDING GEAR - UPDATE OF THE LANDING GEAR AND HYDRAULIC CONTROL UNIT (LGHCU) , SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
09-JUN-2020		MOS HRS/MSC - AFL		17-FEB-2021 684.43 522			
SB 550-32-0011	LANDING GEAR - BRAKE ASSEMBLY - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
03-APR-2020		MOS HRS/MSC - AFL		21-JUL-2020 659.3 505			
SB 550-32-0011 PART I	ACCOMPLISH LANDING GEAR - BRAKE ASSEMBLY - REPLACEMENT, SERVICE BULLETIN INSPECT THE BRAKE ASSEMBLY FOR THE PART NUMBER INSTALLED (IF ONE OR MORE BRAKE ASSEMBLY INSTALLED IS THE PART NUMBER PN 90006967-3PR, KEEP IT (OR THEM)INSTALLED) AND REPLACE THE OTHERS FOUND WITH DIFFERENT PN WITH NEW ONES ACCORDING TO PART II					RECOMMENDED	COMPLIED WITH
03-APR-2020		MOS HRS/MSC - AFL		21-JUL-2020 659.3 505			
SB 550-32-0011 PART II	ACCOMPLISH LANDING GEAR - BRAKE ASSEMBLY - REPLACEMENT, SERVICE BULLETIN REPLACE THE BRAKE ASSEMBLY WITH NEW ONES BEARING PN 90006967-3PR					RECOMMENDED	COMPLIED WITH
03-APR-2020		MOS HRS/MSC - AFL		21-JUL-2020 659.3 505			
SB 550-32-0012	LANDING GEAR - BRAKE CONTROL UNIT REPLACEMENT OR UPDATE, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
29-JAN-2021		MOS HRS/MSC - AFL		22-FEB-2021 684.43 522			
SB 550-32-0013	LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	NOT APPLICABLE - BY PART NUMBER
05-AUG-2022		MOS HRS/MSC - AFL		22-MAY-2025 962.45 733			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-32-0013 PART I	ACCOMPLISH LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT, SERVICE BULLETIN LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT (PRE-MOD SB550-32-0009)					CATEGORY 02 - RECOMMENDED	NOT APPLICABLE - BY PART NUMBER
05-AUG-2022		MOS		22-MAY-2025			
		HRS/MSC	-	962.45			
		AFL		733			
SB 550-32-0013 PART II	ACCOMPLISH LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT, SERVICE BULLETIN LANDING GEAR - MLG DRESSED SHOCK STRUT ASSEMBLY REPLACEMENT (POST-MOD SB550-32-0009)					CATEGORY 02 - RECOMMENDED	NOT APPLICABLE - BY PART NUMBER
05-AUG-2022		MOS		22-MAY-2025			
		HRS/MSC	-	962.45			
		AFL		733			
SB 550-32-0014 REV 05	LANDING GEAR - RE-ROUTING OF THE NLG HARNESSSES OF THE NLG DRESSED SHOCK STRUT ASSEMBLY, SERVICE BULLETIN					CATEGORY 03 - DESIRABLE	COMPLIED WITH
01-JUL-2022		MOS		08-FEB-2023			
		HRS/MSC	-	790.57			
		AFL		605			
SB 550-32-0014 REV 05 PART I	ACCOMPLISH LANDING GEAR - RE-ROUTING OF THE NLG HARNESSSES OF THE NLG DRESSED SHOCK STRUT ASSEMBLY, SERVICE BULLETIN INSPECT THE NLG HARNESS					CATEGORY 03 - DESIRABLE	COMPLIED WITH
01-JUL-2022		MOS		08-FEB-2023			
		HRS/MSC	-	790.57			
		AFL		605			
SB 550-32-0014 REV 05 PART II	ACCOMPLISH LANDING GEAR - RE-ROUTING OF THE NLG HARNESSSES OF THE NLG DRESSED SHOCK STRUT ASSEMBLY, SERVICE BULLETIN RE-ROUTING OF THE NLG HARNESSSES					CATEGORY 03 - DESIRABLE	COMPLIED WITH
01-JUL-2022		MOS		08-FEB-2023			
		HRS/MSC	-	790.57			
		AFL		605			
SB 550-32-0016 PART I	ACCOMPLISH LANDING GEAR - NOSE LANDING GEAR T-SEAL SCAPE INSPECTION, SERVICE BULLETIN INSPECTION OF THE LANDING GEAR SERIAL NUMBER					CATEGORY 02 - RECOMMENDED	
05-SEP-2022		MOS					
		HRS/MSC	-	(EFF)			
		AFL					
SB 550-32-0016 PART II	ACCOMPLISH LANDING GEAR - NOSE LANDING GEAR T-SEAL SCAPE INSPECTION, SERVICE BULLETIN REPLACEMENT OF THE T-SEAL LANDING GEAR					CATEGORY 02 - RECOMMENDED	
05-SEP-2022		MOS					
		HRS/MSC	-	(EFF)			
		AFL					
SB 550-32-0019 REV 02	LANDING GEAR - MLG AND NLG DOWN LOCK SPRING ASSEMBLIES REPLACEMENT, SERVICE BULLETIN					CATEGORY 01 - MANDATORY	NOT APPLICABLE
24-OCT-2024		MOS		09-NOV-2024			
		HRS/MSC	-	931.5			
		AFL		712			
SB 550-32-0019 REV 02 PART I	ACCOMPLISH LANDING GEAR - MLG AND NLG DOWN LOCK SPRING ASSEMBLIES REPLACEMENT, SERVICE BULLETIN REPLACEMENT OF THE NLG DOWN LOCK SPRING ASSEMBLIES					CATEGORY 01 - MANDATORY	NOT APPLICABLE
24-OCT-2024		DAYs		09-NOV-2024			
		HRS/MSC	-	931.5			
		AFL		712			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-32-0019 REV 02 PART II	ACCOMPLISH LANDING GEAR - MLG AND NLG DOWN LOCK SPRING ASSEMBLIES REPLACEMENT, SERVICE BULLETIN REPLACEMENT OF THE MLG DOWN LOCK SPRING ASSEMBLIES					CATEGORY 01 - MANDATORY	NOT APPLICABLE
24-OCT-2024		DAYS		09-NOV-2024			
		HRS/MSC	-	931.5			
		AFL		712			
SB 550-32-0020 PART II	ACCOMPLISH LANDING GEAR - NLG LOWER DRAG BRACE - PARTS INSPECTION AND REPLACEMENT, SERVICE BULLETIN REPLACEMENT - SELF-LOCKING NUT AND LOWER DRAG BRACE PIN					CATEGORY 02 - RECOMMENDED	
10-MAR-2025		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
SB 550-33-0001	LIGHTS - INTERFERENCE IN THE REFUELING/DEFUELING CONTROL PANEL DISPLAY, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE - -EQUIVALENT MODIFICATION FACTORY INCORPORATED
20-FEB-2015		MOS					
		HRS/MSC	-				
		AFL					
SB 550-33-0007	LIGHTS - EMERGENCY LIGHTS HARNESS REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	DEFERRED - OPTIONAL, SB DEFERRED.
26-JUL-2022		MOS		17-APR-2025			
		HRS/MSC	-	954.4			
		AFL		727			
SB 550-34-0001	NAVIGATION - INSTALLATION OF THE PROVISIONAL HARNESS IN THE SYSTEMS LINE OF THE HUD (HEAD-UP DISPLAY) AND EVS (ENHANCED VISION SYSTEM), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-SEP-2015		MOS					
		HRS/MSC	-				
		AFL					
SB 550-34-0002	NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY SB 550-34-0002 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
25-MAY-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 550-34-0002 REV 01	NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION (SUPERSEDED BY SB 550-34-0002 REV 02), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
19-SEP-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 550-34-0002 REV 08	NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
08-AUG-2018		MOS		23-FEB-2019			
		HRS/MSC	-	573.43			
		AFL		436			
SB 550-34-0002 REV 08 PART I	ACCOMPLISH NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION, SERVICE BULLETIN ADS-B OUT SYSTEM INSTALLATION					OPTIONAL	COMPLIED WITH
08-AUG-2018		MOS		23-FEB-2019			
		HRS/MSC	-	573.43			
		AFL		436			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-34-0002 REV 08 PART II	ACCOMPLISH NAVIGATION - ADS-B OUT (AUTOMATIC DEPENDENCE SURVEILLANCE - BROADCAST) INSTALLATION, SERVICE BULLETIN ADDITIONAL ACTION - REPLACEMENT OF TCAS/TRANSPONDER FILES					OPTIONAL	NOT APPLICABLE - PER EFFECTIVITY
08-AUG-2018		MOS HRS/MSC - AFL		23-FEB-2019 573.43 436			
SB 550-34-0004	NAVIGATION - INSTALLATION OF THE EVS (ENHANCED VISION SYSTEM) (SUPERSEDED BY 550-34-0004 REV 01), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE
31-OCT-2016		MOS HRS/MSC - AFL					
SB 550-34-0009 REV 02	NAVIGATION - SURFACE MANAGEMENT SYSTEM (SMS) INHIB PANEL INSTALLATION (SUPERSEDED BY 550-34-0009 REV 03), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - PREVIOUSLY COMPLIED WITH AT PRODUCTION.
12-SEP-2018		MOS HRS/MSC - AFL		20-FEB-2019 573.5 436			
SB 550-34-0013	NAVIGATION - INTEGRATED PITOT/STATIC/AOA/ADC SENSOR NEW PART NUMBER REPLACEMENT, SERVICE BULLETIN					OPERATORS DISCRETION	COMPLIED WITH
21-SEP-2018		MOS HRS/MSC - AFL		19-FEB-2019 573.43 436			
SB 550-34-0019	NAVIGATION - WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) INSPECTION AND REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
08-JUL-2020		MOS HRS/MSC - AFL		07-FEB-2022 737.3 562			
SB 550-34-0019 PART I	ACCOMPLISH NAVIGATION - WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) INSPECTION AND REPLACEMENT, SERVICE BULLETIN WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) INSPECTION					RECOMMENDED	COMPLIED WITH
08-JUL-2020		MOS HRS/MSC - AFL		07-FEB-2022 737.3 562			
SB 550-34-0019 PART II	ACCOMPLISH NAVIGATION - WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) INSPECTION AND REPLACEMENT, SERVICE BULLETIN WEATHER RECEIVER/TRANSMITTER ANTENNA (RTA) REPLACEMENT					RECOMMENDED	COMPLIED WITH
08-JUL-2020		MOS HRS/MSC - AFL		07-FEB-2022 737.3 562			
SB 550-34-0024 REV 02	NAVIGATION - AHRS - ATTITUDE AND HEADING REFERENCE SYSTEM COMPUTER FLIGHT CONTROLS - LOCATION REPOSITIONING, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	DEFERRED - DEFERRED UNTIL 180 MOS INSPECTION JAN 2030
25-OCT-2024		MOS HRS/MSC - AFL		17-APR-2025 954.4 727			
SB 550-36-0001	PNEUMATIC - PNEUMATIC SYSTEM CONTROLLER SOFTWARE UPDATE (SUPERSEDED BY SB 550-36-0001 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - P/N UPGRADE TO P/N:MM-00150-12-39
29-JUL-2015		MOS HRS/MSC - AFL		25-SEP-2015 269.58 194			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-36-0002	PNEUMATIC - NEW SOFTWARE PN MM-00150-12-40 FOR PNEUMATIC SYSTEM CONTROLLER (PSC), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
27-OCT-2016		MOS HRS/MSC - AFL		03-APR-2025 954.4 727			
SB 550-36-0005 REV 01	PNEUMATIC - UPSTREAM PRE-COOLER BLEED 1/2 - RESISTORS INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
17-SEP-2021		MOS HRS/MSC - AFL		17-MAR-2023 790.57 605			
SB 550-36-0007 REV 02	PNEUMATIC - NEW SOFTWARE PN MM-00150-12-41 OR PN MM-00150-14-41 FOR PNEUMATIC SYSTEM CONTROLLER (PSC), SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	COMPLIED WITH - SB COMPLIED WITH AS PEA EM8550 SB 550-SS-0007 REV 2 PNEUMATIC SYSTEM CONTROLLER ASSEMBLY UPGRADED FROM: PN: MM-001 S0-12-39 S/N: 00076 UPGRADED TO: PN: MM-00150-12-41 S/N:00076
28-JUN-2024		MOS HRS/MSC - AFL		15-APR-2025 954.4 727			
SB 550-36-0011	PNEUMATIC - HIGH PRESSURE BLEED DUCT ELBOW - INSPECTION AND REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
13-NOV-2025		MOS HRS/MSC - AFL		750	1704.4 M		
SB 550-42-0001 REV 01	INTEGRATED MODULAR AVIONICS - LOAD 3.2.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
23-SEP-2015		MOS HRS/MSC - AFL		25-SEP-2015 269.58 194			
SB 550-42-0001 REV 01 PART I	INTEGRATED MODULAR AVIONICS - LOAD 3.2.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM, SERVICE BULLETIN INSTALLING LOAD 3.2.1					OPTIONAL	COMPLIED WITH
23-SEP-2015		MOS HRS/MSC - AFL		25-SEP-2015 269.58 194			
SB 550-42-0001 REV 01 PART II	INTEGRATED MODULAR AVIONICS - LOAD 3.2.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM, SERVICE BULLETIN ADDITIONAL ACTION					OPTIONAL	COMPLIED WITH
23-SEP-2015		MOS HRS/MSC - AFL		25-SEP-2015 269.58 194			
SB 550-42-0002	INTEGRATED MODULAR AVIONICS - APM CONFIGURATION FILES UPDATED (SUPERSEDED BY SB 550-42-0002 REV 01), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
02-JUL-2015		MOS HRS/MSC - AFL		25-SEP-2015 269.58 194			
SB 550-42-0004 REV 01	INTEGRATED MODULAR AVIONICS - LOAD 4.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY SB 550-42-0004 REV 02), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
21-DEC-2015		MOS HRS/MSC - AFL		14-JAN-2016 297.12 215			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-42-0006	INTEGRATED MODULAR AVIONICS - LOAD 4.1.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE - SOFTWARE SYSTEM (SUPERSEDED BY SB 550-42-0006 REV 01), SERVICE BULLETIN					OPTIONAL	COMPLIED WITH - INTEGRATED MODULAR AVIONICS - LOAD 4.1.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM CARRIED OUT IN FULL IAW SB 550-42-0006
23-SEP-2016		MOS		14-FEB-2017			
		HRS/MSC	-	410.2			
		AFL		308			
SB 550-42-0007	INTEGRATED MODULAR AVIONICS - LOAD 4.2 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0007 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
31-OCT-2016		MOS					
		HRS/MSC	-				
		AFL					
SB 550-42-0008 REV 03	INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
08-DEC-2017		MOS		06-MAR-2018			
		HRS/MSC	-	500.7			
		AFL		379			
SB 550-42-0008 REV 03 PART I	ACCOMPLISH INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM INSTALLATION					RECOMMENDED	COMPLIED WITH
08-DEC-2017		MOS		06-MAR-2018			
		HRS/MSC	-	500.7			
		AFL		379			
SB 550-42-0008 REV 03 PART II	ACCOMPLISH INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN ADDITIONAL ACTION - APPLICABLE TO REVISION 01 OF THIS SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - AIRCRAFT NOT PREVIOUSLY MODIFIED
08-DEC-2017		MOS		06-MAR-2018			
		HRS/MSC	-	500.7			
		AFL		379			
SB 550-42-0008 REV 03 PART III	ACCOMPLISH INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN ADDITIONAL ACTION - APPLICABLE TO REVISION 02 OF THIS SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - AIRCRAFT NOT PREVIOUSLY MODIFIED
08-DEC-2017		MOS		06-MAR-2018			
		HRS/MSC	-	500.7			
		AFL		379			
SB 550-42-0008 REV 03 PART IV	ACCOMPLISH INTEGRATED MODULAR AVIONICS - LOAD 5.4 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0008 REV 04), SERVICE BULLETIN ADDITIONAL ACTION - APPLICABLE TO REVISION 03 OF THIS SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - AIRCRAFT NOT PREVIOUSLY MODIFIED
08-DEC-2017		MOS		06-MAR-2018			
		HRS/MSC	-	500.7			
		AFL		379			
SB 550-42-0009	INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
13-JUL-2017		MOS		16-FEB-2018			
		HRS/MSC	-	500.7			
		AFL		379			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-42-0009 PART I	ACCOMPLISH INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN IMS PN INSPECTION					OPTIONAL	COMPLIED WITH
13-JUL-2017		MOS HRS/MSC - AFL		16-FEB-2018 500.7 379			
SB 550-42-0009 PART II	ACCOMPLISH INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN IMS REPLACEMENT				OPTIONAL	COMPLIED WITH	
13-JUL-2017		MOS HRS/MSC - AFL		16-FEB-2018 500.7 379			
SB 550-42-0009 REV 01	INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN				OPTIONAL	NOT APPLICABLE - COMPLIED WITH AT THE ORIGINAL ISSUE OF THE SB. NO FURTHER ACTION REQUIRED. 16-FEB-18. 500.7 HRS/379 LDGS.	
24-JUL-2018		MOS HRS/MSC - AFL		14-FEB-2020 648.5 499			
SB 550-42-0009 REV 01 PART I	ACCOMPLISH INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN IMS PN INSPECTION				OPTIONAL	NOT APPLICABLE - PCW	
24-JUL-2018		MOS HRS/MSC - AFL		14-FEB-2020 648.5 499			
SB 550-42-0009 REV 01 PART II	ACCOMPLISH INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM (IMS) REPLACEMENT, SERVICE BULLETIN IMS REPLACEMENT				OPTIONAL	NOT APPLICABLE - PCW	
24-JUL-2018		MOS HRS/MSC - AFL		14-FEB-2020 648.5 499			
SB 550-42-0010	INTEGRATED MODULAR AVIONICS - INFORMATION MANAGEMENT SYSTEM APPLICATION SOFTWARE (IMSA-008) UPDATING, SERVICE BULLETIN				OPTIONAL	COMPLIED WITH - PREVIOUSLY COMPLIED WITH AT INSTLLATION OF SB 550-42-0008 REVISION 3 "LOAD 5.4", PART I	
15-MAR-2019		MOS HRS/MSC - AFL		29-JAN-2020 648.5 499			
SB 550-42-0011	INTEGRATED MODULAR AVIONICS - LOAD 6.3.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0011 REV 01), SERVICE BULLETIN				OPERATORS DISCRETION	NOT APPLICABLE - SUPERSEDED BY SB 550-42-0011 REV 01	
08-JUL-2019		MOS HRS/MSC - AFL		20-FEB-2020 648.5 499			
SB 550-42-0011 REV 01	INTEGRATED MODULAR AVIONICS - LOAD 6.3.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0011 REV 02), SERVICE BULLETIN				OPERATORS DISCRETION	COMPLIED WITH	
29-AUG-2019		MOS HRS/MSC - AFL		06-SEP-2019 606.5 469			
SB 550-42-0011 REV 02	INTEGRATED MODULAR AVIONICS - LOAD 6.3.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0011 REV 03), SERVICE BULLETIN				OPERATORS DISCRETION	NOT APPLICABLE - COMPLIED WITH AT REV 01. NO FURTHER ACTION REQUIRED 06-SEP-19, 606.5, 469	
29-OCT-2019		MOS HRS/MSC - AFL		14-FEB-2020 648.5 499			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-42-0011 REV 03	INTEGRATED MODULAR AVIONICS - LOAD 6.3.1 VERSION FOR PRO LINE FUSION FIELD-LOADABLE SOFTWARE SYSTEM (SUPERSEDED BY 550-42-0011 REV 04), SERVICE BULLETIN					OPERATORS DISCRETION	NOT APPLICABLE - COMPLIED WITH AT REV 01. NO FURTHER ACTION REQUIRED 06-SEP-19, 606.5, 469
27-NOV-2019		MOS HRS/MSC AFL		14-FEB-2020 648.5 499			
SB 550-42-0014 REV 01	INTEGRATED MODULAR AVIONICS - AVIONICS EICAS FLEX 3.3, OMS FLEX 5.5, AND IFIS DOCS FILES, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
22-DEC-2021		MOS HRS/MSC AFL		15-FEB-2022 737.3 562			
SB 550-42-0017	INTEGRATED MODULAR AVIONICS - INTEGRATED MODULAR AVIONICS - AVIONICS OMS FLEX 5.6 UPDATE, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
14-DEC-2023		MOS HRS/MSC AFL		09-FEB-2024 846.6 645			
SB 550-44-0001	CABIN SYSTEMS - PILOT ANNOUNCEMENT IN THE CABIN AUDIO SYSTEM - ENABLE, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
10-DEC-2015		MOS HRS/MSC AFL		(EFF)			
SB 550-44-0002	CABIN SYSTEMS - INSTALLATION OF THE AIRCELL HIGH SPEED INTERNET SYSTEM (AHSI) (SUPERSEDED BY SB 550-44-0002 REV 01), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
06-JUN-2016		MOS HRS/MSC AFL					
SB 550-44-0002 REV 01	CABIN SYSTEMS - INSTALLATION OF THE AIRCELL HIGH SPEED INTERNET SYSTEM (AHSI) (SUPERSEDED BY SB 550-44-0002 REV 02), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-SEP-2016		MOS HRS/MSC AFL					
SB 550-44-0002 REV 02	CABIN SYSTEMS - INSTALLATION OF THE AIRCELL HIGH SPEED INTERNET SYSTEM (AHSI) (SUPERSEDED BY 550-44-0002 REV 03), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
28-OCT-2016		MOS HRS/MSC AFL					
SB 550-52-0003	DOORS - MAIN DOOR AIRSTAIRS REWORK, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
30-JUN-2016		MOS HRS/MSC AFL					
SB 550-52-0005 REV 01	DOORS - RAT COMPARTMENT DOOR SEAL - INSTALLATION IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
22-MAY-2018		MOS HRS/MSC AFL		19-FEB-2019 573.43 436			
SB 550-52-0008 REV 01	DOORS - MAIN-DOOR LOCK SENSOR MECHANISM - CHECK AND REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
20-JAN-2023		MOS HRS/MSC AFL		05-SEP-2023 807.5 619			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-52-0008 REV 01 PART I	ACCOMPLISH DOORS - MAIN-DOOR LOCK SENSOR MECHANISM - CHECK AND REPLACEMENT, SERVICE BULLETIN MAIN-DOOR LOCK SENSOR MECHANISM - CHECK					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
20-JAN-2023		MOS HRS/MSC - AFL		05-SEP-2023 807.5 619			
SB 550-52-0008 REV 01 PART II	ACCOMPLISH DOORS - MAIN-DOOR LOCK SENSOR MECHANISM - CHECK AND REPLACEMENT, SERVICE BULLETIN MAIN-DOOR LOCK SENSOR MECHANISM - REPLACEMENT					CATEGORY 02 - RECOMMENDED	NOT APPLICABLE - MAIN DOOR SENSORS OPERATIONAL PERFORMED NO FAILURE EVIDENT SYSTEM OPERATION SATISFACTORY.
20-JAN-2023		MOS HRS/MSC - AFL		05-SEP-2023 807.5 619			
SB 550-53-0001	FUSELAGE - REPLACEMENT OF INTERCOSTAL ON STRINGERS 5L/5R BETWEEN FRAME 44 AND 46 (SUPERSEDED BY 550-53-0001 REV 01), SERVICE BULLETIN					RECOMMENDED	
20-MAR-2017		MOS HRS/MSC - AFL		(EFF)			
SB 550-53-0001 REV 01	FUSELAGE - REPLACEMENT OF INTERCOSTAL ON STRINGERS 5L/5R BETWEEN FRAME 44 AND 46, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
18-APR-2017		MOS HRS/MSC - AFL		21-FEB-2018 500.7 379			
SB 550-53-0004	FUSELAGE - HUD&EVS STRUCTURAL PROVISION INSTALLATION (SUPERSEDED BY SB 550-53-0004 REV 04), SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
31-OCT-2016		MOS HRS/MSC - AFL					
SB 550-56-0001	WINDOWS - COCKPIT SIDE WINDOWS - REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE - REPLACEMENT NOT REQUIRED, SIDE WINDOWS FOUND IN ACCEPTABLE CONDITION.
18-JUL-2019		MOS HRS/MSC - AFL		04-FEB-2021 684.43 522			
SB 550-57-0001	WINGS - LH AND RH WINGS SPAR II - STEEL DOUBLER INSTALLATION, SERVICE BULLETIN						
26-JUL-2019		MOS HRS/MSC - AFL		(EFF)			
SB 550-57-0001 REV 01	WINGS - LH AND RH WINGS SPAR II - STEEL DOUBLER INSTALLATION, SERVICE BULLETIN					RECOMMENDED	
09-MAR-2023		MOS HRS/MSC - AFL	3750		3750		
SB 550-57-0002	WINGS - WING LOWER SKIN ATTACHMENT TO LONGITUDINAL STRIP - RIVET REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
19-OCT-2017		MOS HRS/MSC - AFL		07-MAR-2018 500.7 379			
SB 550-57-0002 REV 01	WINGS - WING LOWER SKIN ATTACHMENT TO LONGITUDINAL STRIP - RIVET REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
12-JAN-2018		MOS HRS/MSC - AFL		03-APR-2025 954.4 727			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-57-0004 PART I	ACCOMPLISH WINGS - LH AND RH WINGS - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION (SUPERSEDED BY 550-57-0004 REV 01), SERVICE BULLETIN LH WING - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION					DEFERRED - THIS SB WAS DEFERRED DUE TO PARTS AVAILABILITY AT EMBRAER.	
20-DEC-2019		MOS				THE SB IS NOT OVERDUE AND WILL BE COMPLIED WITH AT A TIME CONVENIENT TO US AS THE OPERATOR AND WHEN PARTS BECOME AVAILABLE.	
		HRS/MSC	-				
		AFL		(EFF)			
SB 550-57-0004 PART II	ACCOMPLISH WINGS - LH AND RH WINGS - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION (SUPERSEDED BY 550-57-0004 REV 01), SERVICE BULLETIN RH WING - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION					DEFERRED - THIS SB WAS DEFERRED DUE TO PARTS AVAILABILITY AT EMBRAER.	
20-DEC-2019		MOS				THE SB IS NOT OVERDUE AND WILL BE COMPLIED WITH AT A TIME CONVENIENT TO US AS THE OPERATOR AND WHEN PARTS BECOME AVAILABLE.	
		HRS/MSC	-				
		AFL		(EFF)			
SB 550-57-0004 REV 02 PART I	ACCOMPLISH WINGS - LH AND RH WINGS - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION, SERVICE BULLETIN LH WING - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION					RECOMMENDED	
09-JUN-2020		MOS					
		HRS/MSC					
		AFL	3750	(EFF)	3750		
SB 550-57-0004 REV 02 PART II	ACCOMPLISH WINGS - LH AND RH WINGS - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION, SERVICE BULLETIN RH WING - STRUCTURAL REINFORCEMENT OF THE WING KINK REGION					RECOMMENDED	
09-JUN-2020		MOS					
		HRS/MSC					
		AFL	3750	(EFF)	3750		
SB 550-57-0005	WINGS - STRUCTURAL REPAIR ALLOWABLE DAMAGE INSPECTION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
22-MAR-2022		MOS		15-MAR-2023			
		HRS/MSC	-	790.57			
		AFL		605			
SB 550-57-0007 PART I	ACCOMPLISH WINGS - HORIZONTAL STABILIZER AND WING HINGE BEARINGS - REPLACEMENT, SERVICE BULLETIN HORIZONTAL STABILIZER HINGE BEARINGS - REPLACEMENT					CATEGORY 02 - RECOMMENDED	
27-MAY-2025		MOS		(EFF)			
		HRS/MSC	-				
		AFL					
SB 550-57-0007 PART II	ACCOMPLISH WINGS - HORIZONTAL STABILIZER AND WING HINGE BEARINGS - REPLACEMENT, SERVICE BULLETIN WING HINGE BEARINGS - REPLACEMENT					CATEGORY 02 - RECOMMENDED	
27-MAY-2025		MOS		(EFF)			
		HRS/MSC	-				
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 550-57-0007 REV 02 PART I	ACCOMPLISH WINGS - HORIZONTAL STABILIZER AND WING HINGE BEARINGS - REPLACEMENT, SERVICE BULLETIN HORIZONTAL STABILIZER HINGE BEARINGS - REPLACEMENT					CATEGORY 02 - RECOMMENDED	
14-OCT-2025	MOS HRS/MSC 7500 AFL				7500 M		
SB 550-57-0007 REV 02 PART II	ACCOMPLISH WINGS - HORIZONTAL STABILIZER AND WING HINGE BEARINGS - REPLACEMENT, SERVICE BULLETIN WING HINGE BEARINGS - REPLACEMENT					CATEGORY 02 - RECOMMENDED	
14-OCT-2025	MOS HRS/MSC 7500 AFL				7500 M		
SB 550-73-0001	ENGINE FUEL AND CONTROL - ENGINE ECU SOFTWARE UPGRADE VERSION 4.0, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
05-MAY-2016	MOS HRS/MSC - AFL			07-APR-2017 423.6 319			
SB 550-73-0002 REV 06	ENGINE FUEL AND CONTROL - ENGINE ECU SOFTWARE UPGRADE VERSION 5.0, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
06-NOV-2020	MOS HRS/MSC - AFL			18-FEB-2021 684.43 522			
SB 550-78-0001	EXHAUST - THRUST REVERSER HEAT SHIELD INSTALLATION (SUPERSEDED BY SB 550-78-0001 REV 01), SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - SB 550-78-0001 COMPLIED WITH
22-JUL-2015	MOS HRS/MSC - AFL			24-SEP-2015 269.58 194			
SB 550-78-0002 R01	EXHAUST - THRUST REVERSER UNIT (TRU) - DOOR AND BEAM ASSEMBLY - IMPROVED CORROSION PROTECTION, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	COMPLIED WITH
17-DEC-2021	MOS HRS/MSC - AFL			15-APR-2025 954.4 727			
SB 550-78-0003	EXHAUST - THRUST REVERSER ISOLATION CONTROL UNIT (ICU) - REPLACEMENT, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	NOT APPLICABLE - AS PER INSTALLED ICU SERIAL NUMBERS
17-MAY-2024	MOS HRS/MSC - AFL			11-FEB-2025 954.4 727			
SB 550-78-0003 PART I	ACCOMPLISH EXHAUST - THRUST REVERSER ISOLATION CONTROL UNIT (ICU) - REPLACEMENT, SERVICE BULLETIN LH AND RH ISOLATION CONTROL UNIT (ICU) SERIAL NUMBER - INSPECTION					CATEGORY 02 - RECOMMENDED	NOT APPLICABLE - AS PER INSTALLED ICU SERIAL NUMBERS
17-MAY-2024	MOS HRS/MSC - AFL			11-FEB-2025 954.4 727			
SB 550-78-0003 PART II	ACCOMPLISH EXHAUST - THRUST REVERSER ISOLATION CONTROL UNIT (ICU) - REPLACEMENT, SERVICE BULLETIN LH AND/OR RH ISOLATION CONTROL UNIT (ICU) - REPLACEMENT					CATEGORY 02 - RECOMMENDED	NOT APPLICABLE - AS PER INSTALLED ICU SERIAL NUMBERS
17-MAY-2024	MOS HRS/MSC - AFL			11-FEB-2025 954.4 727			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>APU - SB - P-110/70720189-1</b>							
SB	36-49-8116 R03	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE THE STARTER MOTOR, PN 2704458-1 WITH PN 2704458-2, SERVICE BULLETIN				RECOMMENDED	COMPLIED WITH
			18-DEC-2023	MOS HRS/MSC - AFL APUS	18-AUG-2025 954.5 1667		
SB	36-49-8210	APU - AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSPECT AND REPLACE FUEL SHUTOFF VALVE (FSOV), PN 692545-18, ON 36-150 APUS (EXPORT CONTROLLED), SERVICE BULLETIN				RECOMMENDED	NOT APPLICABLE - S/N 6176 NOT APPLICABLE, REPLACEMENT OF FSOV NOT REQUIRED
			04-APR-2016	MOS HRS/MSC - APUS	02-AUG-2016		
SIL	APU-49 R13	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER				RECOMMENDED	COMPLIED WITH
			23-NOV-2023	MOS HRS/MSC - APUS	11-APR-2025 940 1633		
SIL	APU-49 R14	APU - IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS), SERVICE INFORMATION LETTER				RECOMMENDED	
			12-FEB-2025	MOS HRS/MSC 500 APUS	1352.5 M	1452.5	RECURRING

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 1 - AD - P131119/70040119-1</b>							
FAA 2018-04-13	NO. 1 ENGINE - ENGINE CONTROLS SECTION - APPLYING SEALANT TO IDENTIFIED AREAS OF THE ECU AND REQUIRES INSERTING A COPY OF CERTAIN AIRPLANE OPERATING PROCEDURES INTO THE APPLICABLE FLIGHT MANUALS					MANDATORY	COMPLIED WITH - AD COMPLIED WITH IAW HONEYWELL SB AS907-76-9021, ORIGINAL ISSUE.
12-APR-2018		MOS HRS/MSC - (s) APUS ENC		23-MAY-2018 526.8 393			
FAA 2018-04-13 PARA (G)(1)	NO. 1 ENGINE - APPLY SEALANT TO THE ECU (IF NO SEALANT HAS BEEN APPLIED TO THE ECU IN THE AREAS IDENTIFIED IN FIGURES 1 TO 13 OF SB AS907-76-9021 R01) (FOR APPLICABLE ENGINES AND ECUS)					MANDATORY	COMPLIED WITH - AD COMPLIED WITH IAW SB AS907-76-9021, ORIGINAL ISSUE.
12-APR-2018		MOS HRS/MSC - ENC		23-MAY-2018 526.8 393			
FAA 2018-04-13 PARA (G)(2)	NO. 1 ENGINE - INSERT A COPY OF FIGURE 1, 2, OR 3 TO PARA (G) (FOR ALL AIRPLANES THAT HAVE AN Affected ENGINE INSTALLED WITH AN Affected ECU), CHECK THE CURRENT FAULT MESSAGES IN THE MDC/ OMS FOR (G)(2)(I)(A) TO (G)(2)(I)(F) ( (IF A CYAN WARNING IS ANNOUNCED) AND REPLACE THE ECU (IF ANY OF THE FAULT MESSAGES LISTED IN MDC/OMS)					MANDATORY	NOT APPLICABLE
12-APR-2018		DAYs HRS/MSC - ENC		23-MAY-2018 526.8 393			
FAA 2018-04-13 PARA (G)(2)(I)(II)	NO. 1 ENGINE - CHECK THE CURRENT FAULT MESSAGES IN THE MDC/ OMS FOR (G)(2)(I)(A) TO (G)(2)(I)(F) ( (IF A CYAN WARNING IS ANNOUNCED) AND REPLACE THE ECU (IF ANY OF THE FAULT MESSAGES LISTED IN MDC/OMS)					MANDATORY	NOT APPLICABLE
12-APR-2018		MOS HRS/MSC - (s) ENC		23-MAY-2018 526.8 393			
FAA 2018-04-13 PARA (I)	NO. 1 ENGINE - TERMINATING ACTION: REMOVE FROM THE AFM, FIGURE 1, 2, OR 3 TO PARA (G), AFTER PARA (G)(1)(I) IS ACCOMPLISHED					MANDATORY	NOT APPLICABLE
12-APR-2018		MOS HRS/MSC - ENC		23-MAY-2018 526.8 393			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 2 - AD - P131118/70040119-1</b>							
FAA 2018-04-13	NO. 2 ENGINE - ENGINE CONTROLS SECTION - APPLYING SEALANT TO IDENTIFIED AREAS OF THE ECU AND REQUIRES INSERTING A COPY OF CERTAIN AIRPLANE OPERATING PROCEDURES INTO THE APPLICABLE FLIGHT MANUALS					MANDATORY	COMPLIED WITH - AD COMPLIED WITH IAW HONEYWELL SB AS907-76-9021, ORIGINAL ISSUE.
12-APR-2018		MOS		23-MAY-2018			
		HRS/MSC	- (s)	526.8			
		ENC		393			
FAA 2018-04-13 PARA (G)(1)	NO. 2 ENGINE - APPLY SEALANT TO THE ECU (IF NO SEALANT HAS BEEN APPLIED TO THE ECU IN THE AREAS IDENTIFIED IN FIGURES 1 TO 13 OF SB AS907-76-9021 R01) (FOR APPLICABLE ENGINES AND ECUS)					MANDATORY	COMPLIED WITH - COMPLIED WITH IAW SB AS907-76-9021, ORIGINAL ISSUE.
12-APR-2018		MOS		23-MAY-2018			
		HRS/MSC	-	526.8			
		ENC		393			
FAA 2018-04-13 PARA (G)(2)	NO. 2 ENGINE - INSERT A COPY OF FIGURE 1, 2, OR 3 TO PARA (G) (FOR ALL AIRPLANES THAT HAVE AN Affected ENGINE INSTALLED WITH AN Affected ECU), CHECK THE CURRENT FAULT MESSAGES IN THE MDC/ OMS FOR (G)(2)(I)(A) TO (G)(2)(I)(F) ( (IF A CYAN WARNING IS ANNOUNCED) AND REPLACE THE ECU (IF ANY OF THE FAULT MESSAGES LISTED IN MDC/OMS)					MANDATORY	NOT APPLICABLE
12-APR-2018		DAYs		23-MAY-2018			
		HRS/MSC	-	526.8			
		ENC		393			
FAA 2018-04-13 PARA (G)(2)(I)(II)	NO. 2 ENGINE - CHECK THE CURRENT FAULT MESSAGES IN THE MDC/ OMS FOR (G)(2)(I)(A) TO (G)(2)(I)(F) ( (IF A CYAN WARNING IS ANNOUNCED) AND REPLACE THE ECU (IF ANY OF THE FAULT MESSAGES LISTED IN MDC/OMS)					MANDATORY	NOT APPLICABLE
12-APR-2018		MOS		23-MAY-2018			
		HRS/MSC	- (s)	526.8			
		ENC		393			
FAA 2018-04-13 PARA (I)	NO. 2 ENGINE - TERMINATING ACTION: REMOVE FROM THE AFM, FIGURE 1, 2, OR 3 TO PARA (G), AFTER PARA (G)(1)(I) IS ACCOMPLISHED					MANDATORY	NOT APPLICABLE
12-APR-2018		MOS		23-MAY-2018			
		HRS/MSC	-	526.8			
		ENC		393			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 1 - SB - P131119/70040119-1</b>							
SB 78-30-001 R0	NO. 1 ENGINE - ADDITION OF HEAT SHIELD TO REDUCE THE TEMPERATURE SEEN BY HE INNER DUCT, SERVICE BULLETIN						COMPLIED WITH
		MOS		24-SEP-2015			
		HRS/MSC	-				
		ENC					
SB AS907-72-9005 R05	NO. 1 ENGINE - GENERAL - INSTALLATION OF ENGINE WATER WASH SYSTEM, ON AS907 ENGINES MODELS, SERVICE BULLETIN			CATEGORY 3			COMPLIED WITH
		MOS		03-APR-2025			
23-JAN-2025		HRS/MSC	-	954.4			
		ENC		732			
SB AS907-72-9084	NO. 1 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN						COMPLIED WITH
		MOS		04-SEP-2019			
12-JUN-2019		HRS/MSC	-	606.5			
		ENC					
		AFL		469			
SB AS907-72-9084 R01 PARA (E)(3)	NO. 1 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN DOWNLOAD ENGINE ECU						
		DAY		26-MAR-2020			
21-FEB-2020		HRS/MSC	-				
		ENC					
SB AS907-72-9084 R02	NO. 1 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN			CATEGORY 2			COMPLIED WITH - SB CARRIED OUT.
		MOS		02-FEB-2021			
03-APR-2020		HRS/MSC	-	684.43			
		ENC		522			
SB AS907-72-9084 R02 PARA (E)(2)	NO. 1 ENGINE - ACCOMPLISH SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN OIL FILTER REPLACEMENT						COMPLIED WITH - SB CARRIED OUT.
		MOS		02-FEB-2021			
03-APR-2020		HRS/MSC	-	684.43			
		ENC		522			
SB AS907-72-9084 R02 PARA (E)(3)	NO. 1 ENGINE - ACCOMPLISH SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN DOWNLOAD ENGINE ECU						COMPLIED WITH - SB CARRIED OUT.
		DAY		31-MAY-2021			
03-APR-2020		HRS/MSC	-				
		ENC					
SB AS907-72-9084 R03	NO. 1 ENGINE - SERVICING - REDUCE TIME INTERVAL FOR OIL FILTER REPLACEMENT OR ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN			CATEGORY 2			COMPLIED WITH - C/W - DOWNLOAD uploaded TO CAMP
		MOS		30-MAY-2025			
26-JUN-2021		HRS/MSC	-	965.2			
		ENC		740			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB AS907-72-9084 R03 PARA (E)(2)(A)	NO. 1 ENGINE - DOWNLOAD ECU PER PARA 3.B.(3)					CATEGORY 2	COMPLIED WITH
		DAYs	30	+5	29-NOV-2025	29-DEC-2025	03-JAN-2026 RECURRING
		HRS/MSC			990.7		
		ENC			761		
SB AS907-72-9084 R03 PARA (E)(2)(B)	NO. 1 ENGINE - PERFORM OIL FILTER ANALYSIS PER PARA 3.B.(2)					CATEGORY 2	COMPLIED WITH
		MOS			09-NOV-2024		
		HRS/MSC	-		931.5		
		ENC			712		
SB AS907-72-9084 R03 PARA (E)(2)(C)	NO. 1 ENGINE - TERMINATING ACTION: COMPLIANCE WITH SB AS907-72-9094 TERMINATES THE INSPECTIONS REQUIRED BY PARA (E)(2)(A) & (E)(2)(B)					CATEGORY 2	COMPLIED WITH
		MOS			09-NOV-2024		
		HRS/MSC	-		931.5		
		ENC			712		
SB AS907-72-9093 R03	NO. 1 ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED STAGE 4 COMPRESSOR STATOR VANE, PN 70041641-1 OR PN 70041641-2, ON AS907-3-1E MODEL ENGINES, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
02-JUL-2022		MOS					
		HRS/MSC	4400		4400		
		ENC					
SB AS907-73-9007 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE NON-CONFORMING FUEL HOSE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	COMPLIED WITH
15-JUL-2022		MOS			01-SEP-2022		
		HRS/MSC	-		761.57		
		ENC			584		
SB AS907-76-9021	NO. 1 ENGINE - ENGINE CONTROLS - POWER CONTROLS - APPLY SEALANT TO PREVENT WATER ENTRY INTO ELECTRONIC CONTROL UNIT (ECU) ON AS907 MODEL ENGINES (EXPORT CONTROLLED) (SUPERSEDED BY AS907-76-9021 R01), SERVICE BULLETIN					CATEGORY 1	COMPLIED WITH
13-MAY-2016		MOS			10-FEB-2017		
		HRS/MSC	-		410.2		
		ENC			308		
SB AS907-76-9021 R01	NO. 1 ENGINE - ENGINE CONTROLS - POWER CONTROLS - APPLY SEALANT TO PREVENT WATER ENTRY INTO ELECTRONIC CONTROL UNIT (ECU) ON AS907 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 1	NOT APPLICABLE - SB PREVIOUSLY COMPLIED WITH AT ORIGINAL ISSUE.
20-APR-2017		MOS			23-MAY-2018		
		HRS/MSC	-		526.8		
		ENC			393		
SB AS907-76-9029 R01	NO. 1 ENGINE - ENGINE CONTROLS - POWER CONTROLS - REWORK ELECTRONIC CONTROL UNITS 2119576-4103 TO 2119576-4104, 2119576-4203 TO 2119576-4204, OR INSTALL ELECTRONIC CONTROL UNITS 2119576-4104 OR 2119576-4204 ON AS907-3-1E ENGINE MODELS, SERVICE BULLETIN					CATEGORY 1	COMPLIED WITH
29-JUN-2020		MOS			18-FEB-2021		
		HRS/MSC	-		684.43		
		ENC			522		
SB AS907-79-9007 R02	NO. 1 ENGINE - OIL - STORAGE SECTION - REWORK OIL FILLER CAP ASSEMBLY, PN 3036061-3, TO PREVENT CHAIN INTERFERENCE DURING OIL SUPPLY SERVICING, FOR AS907 MODEL ENGINES (SUPERSEDED BY AS907-79-9007 R03), SERVICE BULLETIN					CATEGORY 2	COMPLIED WITH
09-MAR-2015		MOS			10-FEB-2017		
		HRS/MSC	-		410.2		
		ENC			308		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB AS907-79-9010 R01	NO. 1 ENGINE - OIL - DISTRIBUTION - REPLACE NON-CONFORMING OIL HOSE AND TUBE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	COMPLIED WITH
15-JUL-2022		MOS HRS/MSC ENC		01-SEP-2022 761.57 584			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 2 - SB - P131118/70040119-1</b>							
SB 78-30-001 R0	NO. 2 ENGINE - ADDITION OF HEAT SHIELD TO REDUCE THE TEMPERATURE SEEN BY HE INNER DUCT, SERVICE BULLETIN						COMPLIED WITH
		MOS		24-SEP-2015			
		HRS/MSC	-				
		ENC					
SB AS907-72-9005 R05	NO. 2 ENGINE - GENERAL - INSTALLATION OF ENGINE WATER WASH SYSTEM, ON AS907 ENGINES MODELS, SERVICE BULLETIN			CATEGORY 3			COMPLIED WITH
23-JAN-2025		MOS		03-APR-2025			
		HRS/MSC	-	954.4			
		ENC		732			
SB AS907-72-9084	NO. 2 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN						COMPLIED WITH
12-JUN-2019		MOS		04-SEP-2019			
		HRS/MSC	-	606.5			
		ENC					
		AFL		469			
SB AS907-72-9084 R01 PARA (E)(3)	NO. 2 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN DOWNLOAD ENGINE ECU						
21-FEB-2020		DAYs		26-MAR-2020			
		HRS/MSC	-				
		ENC					
SB AS907-72-9084 R02	NO. 2 ENGINE - SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN			CATEGORY 2			COMPLIED WITH - SB CARRIED OUT.
03-APR-2020		MOS		02-FEB-2021			
		HRS/MSC	-	684.43			
		ENC		522			
SB AS907-72-9084 R02 PARA (E)(2)	NO. 2 ENGINE - ACCOMPLISH SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN OIL FILTER REPLACEMENT						COMPLIED WITH - SB CARRIED OUT.
03-APR-2020		MOS		02-FEB-2021			
		HRS/MSC	-	684.43			
		ENC		522			
SB AS907-72-9084 R02 PARA (E)(3)	NO. 2 ENGINE - ACCOMPLISH SERVICING - REDUCE TIME INTERVALS FOR OIL FILTER REPLACEMENT AND ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN DOWNLOAD ENGINE ECU						COMPLIED WITH - SB CARRIED OUT.
03-APR-2020		DAYs		31-MAY-2021			
		HRS/MSC	-				
		ENC					
SB AS907-72-9084 R03	NO. 2 ENGINE - SERVICING - REDUCE TIME INTERVAL FOR OIL FILTER REPLACEMENT OR ENGINE FAULT DIAGNOSTIC DATA (EEI) DOWNLOAD TO PROVIDE ENHANCED MONITORING OF AFT SUMP COMPONENTS, SERVICE BULLETIN			CATEGORY 2			COMPLIED WITH
26-JUN-2021		MOS		09-NOV-2024			
		HRS/MSC	-	931.5			
		ENC		712			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB AS907-72-9084 R03 PARA (E)(2)(A)	NO. 2 ENGINE - DOWNLOAD ECU PER PARA 3.B.(3)					CATEGORY 2	COMPLIED WITH
		DAYs	30	+5	29-NOV-2025	29-DEC-2025	03-JAN-2026 RECURRING
		HRS/MSC			990.7		
		ENC			761		
SB AS907-72-9084 R03 PARA (E)(2)(B)	NO. 2 ENGINE - PERFORM OIL FILTER ANALYSIS PER PARA 3.B.(2)					CATEGORY 2	COMPLIED WITH
		MOS			09-NOV-2024		
		HRS/MSC	-		931.5		
		ENC			712		
SB AS907-72-9084 R03 PARA (E)(2)(C)	NO. 2 ENGINE - TERMINATING ACTION: COMPLIANCE WITH SB AS907-72-9094 TERMINATES THE INSPECTIONS REQUIRED BY PARA (E)(2)(A) & (E)(2)(B)					CATEGORY 2	COMPLIED WITH
		MOS			09-NOV-2024		
		HRS/MSC	-		931.5		
		ENC			712		
SB AS907-72-9093 R03	NO. 2 ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED STAGE 4 COMPRESSOR STATOR VANE, PN 70041641-1 OR PN 70041641-2, ON AS907-3-1E MODEL ENGINES, SERVICE BULLETIN					CATEGORY 02 - RECOMMENDED	
02-JUL-2022		MOS					
		HRS/MSC	4400		4400		
		ENC					
SB AS907-73-9007 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE NON-CONFORMING FUEL HOSE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	COMPLIED WITH
15-JUL-2022		MOS			01-SEP-2022		
		HRS/MSC	-		761.57		
		ENC			584		
SB AS907-76-9021	NO. 2 ENGINE - ENGINE CONTROLS - POWER CONTROLS - APPLY SEALANT TO PREVENT WATER ENTRY INTO ELECTRONIC CONTROL UNIT (ECU) ON AS907 MODEL ENGINES (EXPORT CONTROLLED) (SUPERSEDED BY AS907-76-9021 R01), SERVICE BULLETIN					CATEGORY 1	COMPLIED WITH
13-MAY-2016		MOS			10-FEB-2017		
		HRS/MSC	-		410.2		
		ENC			308		
SB AS907-76-9021 R01	NO. 2 ENGINE - ENGINE CONTROLS - POWER CONTROLS - APPLY SEALANT TO PREVENT WATER ENTRY INTO ELECTRONIC CONTROL UNIT (ECU) ON AS907 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 1	NOT APPLICABLE - SB PREVIOUSLY COMPLIED WITH AT ORIGINAL ISSUE.
20-APR-2017		MOS			23-MAY-2018		
		HRS/MSC	-		526.8		
		ENC			393		
SB AS907-76-9029 R01	NO. 2 ENGINE - ENGINE CONTROLS - POWER CONTROLS - REWORK ELECTRONIC CONTROL UNITS 2119576-4103 TO 2119576-4104, 2119576-4203 TO 2119576-4204, OR INSTALL ELECTRONIC CONTROL UNITS 2119576-4104 OR 2119576-4204 ON AS907-3-1E ENGINE MODELS, SERVICE BULLETIN					CATEGORY 1	COMPLIED WITH
29-JUN-2020		MOS			18-FEB-2021		
		HRS/MSC	-		684.43		
		ENC			522		
SB AS907-79-9007 R02	NO. 2 ENGINE - OIL - STORAGE SECTION - REWORK OIL FILLER CAP ASSEMBLY, PN 3036061-3, TO PREVENT CHAIN INTERFERENCE DURING OIL SUPPLY SERVICING, FOR AS907 MODEL ENGINES (SUPERSEDED BY AS907-79-9007 R03), SERVICE BULLETIN					CATEGORY 2	COMPLIED WITH
09-MAR-2015		MOS			10-FEB-2017		
		HRS/MSC	-		410.2		
		ENC			308		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB AS907-79-9010 R01	NO. 2 ENGINE - OIL - DISTRIBUTION - REPLACE NON-CONFORMING OIL HOSE AND TUBE ASSEMBLIES ON AS907 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	COMPLIED WITH
15-JUL-2022		MOS HRS/MSC ENC		01-SEP-2022 761.57 584			