

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>															
<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
05	MM:	3034342	64 Manual Part No. 3034342, Issue No. 64.0, Dated Apr-07-2025	PCE-PK0278	L/H	18-Dec-23									As Req'd
05	MM:	3034342	64 Manual Part No. 3034342, Issue No. 64.0, Dated Apr-07-2025	PCE-PK0277	R/H	18-Dec-23									As Req'd
05	CAO:	CAAP 42B-1 APPENDIX F [Part: 200 Hours]	2.3 CASA Schedule 5 Radio inspection inc requirements of CAO 100.5 App1 Clause 18, 19, 20 & 21	FL-269		20-Oct-22	22-Oct-25 1 / 2.3	4915.70	5115.70	162.90	4946			22-Oct-26	Repeat
05	MM:	ML-B-300	20 ML-B-300-20 - King Air 300 Series	FL-269		01-May-00									As Req'd
24	SB:	SB 24-3363	IR Electrical - Installation of External Dc Power Switch Transient Suppression Kit	FL-269		01-Oct-00									Optional
26	AWB:	AWB 26-003 [Part: 6 Month]	Reweigh / Inspection Portable fire extinguishers	10717	Cockpit	30-Sep-25	6 /							30-Mar-26	Repeat
26	AWB:	AWB 26-003 [Part: 6 Month]	Reweigh / Inspection Portable fire extinguishers	10693	Cabin	30-Sep-25	6 /							30-Mar-26	Repeat
26	CAO:	CAO 100.5 Appendix 1 Clause 17	10 Fire protection in toilet areas	FL-269		20-Dec-99	24-Apr-23 2011 / 10	4437.00	5437.00	484.20	4523				Repeat
27	SB:	SB 27-3472	1 Flight Controls - Elevator Trim Tab Actuator Modification	FL-269		01-Mar-02									Optional
28	SB:	SB 28-3401	IR Fuel - Fuel Cell Cover And Gasket Installation	FL-269		01-Dec-01									Optional
30	SB:	SB 30-3471	IR Ice & Rain Protection - Cabin/cockpit Window Defrost System	FL-269		01-Oct-01									Optional
31	CAO:	CAO 100.5 Appendix 1 Clause 3	10 Test Pitot-static systems	FL-269		23-Oct-24	2011 / 10	4671.10			4753			31-Oct-26	Repeat
31	CAO:	CAO 100.5 Appendix 1 Clause 4	10 Testing pressure altimeters and air data computers	FL-269		23-Oct-24	2011 / 10	4671.10			4753			31-Oct-26	Repeat
31	CAO:	CAO 100.5 Appendix 1 Clause 5	10 Test Airspeed indicator	FL-269		20-Oct-22	2011 / 10	4394.40			4424			31-Oct-26	Repeat
31	CAO:	CAO 100.5 Appendix 1 Clause 9 [Part: Digital]	10 Cockpit voice recording systems	FL-269		23-Oct-24	2011 / 10	4671.10			4753			31-Oct-26	Repeat
31	SB:	MTB-31-03	1 Indicating/Recording Systems - Potentiometer Replacement	FL-269		08-Mar-23									Optional
31	SB:	MTB-31-04	IR Indicating/Recording Systems - Cockpit Overhead Dimming Potentiometer Replacement	FL-269		08-Mar-23									Optional

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>		<b>Eff</b>	<b>Last</b>	<b>Project/</b>	<b>Comp.</b>	<b>Due</b>	<b>Hrs.</b>	<b>Comp.</b>	<b>Ldg</b>	<b>Due</b>	<b>Due</b>			
<b>ATA/Ref No:</b>	<b>Rev: Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>From:</b>	<b>Comp'd:</b>	<b>Iss/Rev:</b>	<b>Hours:</b>	<b>Hours:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Date:</b>	<b>Status</b>
32	SB: SB 32-4010	IR Landing Gear - Introduction of Remote Control Circuit Breaker Kit (Kit 130-3100)	FL-269		01-May-12									Optional
33	SB: MTB-33-01	1 Lights - Replacement of Entry and Ice Light Sockets	FL-269		07-Oct-19									Optional
34	AWB: AWB 34-008	3 Calibration of compasses - Primary	FL-269		23-Oct-24	01 / 03	4671.10			4753			31-Oct-26	Repeat
34	AWB: AWB 34-008.	3 Calibration of compasses - Standby	FL-269		23-Oct-24	01 / 03	4671.10			4753			31-Oct-26	Repeat
34	CAO: CAO 100.5 Appendix 1 Clause 14	10 Periodic checking and testing of ATC transponders	FL-269		23-Oct-24	2011 / 10	4671.10			4753			31-Oct-26	Repeat
52	CAO: CAO 100.5 Appendix 1 Clause 10 [Part: Non Px Af]	10 Functional Check Emergency exits	FL-269											As Req'd
56	SB: MTB-56-01	IR Windows - Storm Weather Window Improvement	FL-269		04-Jun-25									Optional
57	AD: AD/BEECH 300/008 [Part: 1]	3 Wing Attach Fittings, Bolts and Nuts	FL-269		16-Aug-23	03-Nov-25	1 / 3	4915.70		4946			03-Nov-30	Repeat
61	SL: HC-SL-61-61Y [Part: 3000 / 60]	15 Propeller - Overhaul Periods and Service Life Limits for Hartzell Propeller Inc. Aviation Components - Propellers, Governors, Accumulators, and Propeller Damper Assemblies	FWA2937	L/H	24-Oct-25		5023.70	8023.70	2962.90				24-Oct-30	Repeat
61	SL: HC-SL-61-61Y [Part: 3000 / 60]	15 Propeller - Overhaul Periods and Service Life Limits for Hartzell Propeller Inc. Aviation Components - Propellers, Governors, Accumulators, and Propeller Damper Assemblies	FWA6264	R/H	30-Apr-22			3000.00	2384.60				30-Apr-27	Repeat
72	SB: 13002	20 Rotor Components - Service Life.	PCE-PK0277	R/H	27-Jul-23	1 / 19	4385.30			4413				As Req'd
72	SB: 13002	20 Rotor Components - Service Life.	PCE-PK0278	L/H										As Req'd
72	SB: 13077	1 Improved Second-Stage Reduction Planet Gear Sleeve Bearings (Premachined Bronze) - Introduction Of	PCE-PK0278	L/H										Optional
72	SB: 13077	1 Improved Second-Stage Reduction Planet Gear Sleeve Bearings (Premachined Bronze) - Introduction Of	PCE-PK0277	R/H										Optional
72	SB: 13097	1 Accessory Gearbox Housing Assembly - Modification Of	PCE-PK0277	R/H										Optional

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>		<i>Eff</i>	<i>Last</i>	<i>Project/</i>	<i>Comp.</i>	<i>Due</i>	<i>Hrs.</i>	<i>Comp.</i>	<i>Ldg</i>	<i>Due</i>	<i>Due</i>			
<b>ATA/Ref No:</b>	<b>Rev: Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>From:</b>	<b>Comp'd:</b>	<b>Iss/Rev:</b>	<b>Hours:</b>	<b>Hours:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Date:</b>	<b>Status</b>
72 SB: 13097	1 Accessory Gearbox Housing Assembly - Modification Of	PCE-PK0278	L/H											Optional
72 SB: 13110	1 Compressor Rotor - Introduction Of	PCE-PK0278	L/H											Optional
72 SB: 13110	1 Compressor Rotor - Introduction Of	PCE-PK0277	R/H											Optional
72 SB: 13303	20 Operating Time Between Overhauls and Hot Section Inspection Frequency	PCE-PK0278	L/H											As Req'd
72 SB: 13303	20 Operating Time Between Overhauls and Hot Section Inspection Frequency	PCE-PK0277	R/H											As Req'd
72 SB: 13327	2 Propeller Shaft Assembly - Modification Of	PCE-PK0278	L/H											Optional
72 SB: 13327	2 Propeller Shaft Assembly - Modification Of	PCE-PK0277	R/H											Optional
72 SB: 13329	1 Gearshaft Assembly - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13329	1 Gearshaft Assembly - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13337	IR Propeller Thrust Cover Assembly - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13337	IR Propeller Thrust Cover Assembly - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13340 [Part: 1.E]	4 Filler Cap and Oil Gage Assembly - Replacement Of	PCE-PK0278	L/H	17-Aug-23										Optional
72 SB: 13346	1 Outer Liner - Replacement Of And Inner Liner - Inspection Of	PCE-PK0278	L/H											Optional
72 SB: 13352	1 Combustion Chamber Outer Liner - Replacement / Modification Of	PCE-PK0277	R/H											Optional
72 SB: 13352	1 Combustion Chamber Outer Liner - Replacement / Modification Of	PCE-PK0278	L/H											Optional
72 SB: 13363	2 Aluminium Inlet Case Assembly - Introduction Of	PCE-PK0277	R/H											Optional
72 SB: 13363	2 Aluminium Inlet Case Assembly - Introduction Of	PCE-PK0278	L/H											Optional
72 SB: 13364	IR Power Turbine Shaft Coupling - Repair Of	PCE-PK0278	L/H											Optional
72 SB: 13364	IR Power Turbine Shaft Coupling - Repair Of	PCE-PK0277	R/H											Optional

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>		<i>Eff</i>	<i>Last</i>	<i>Project/</i>	<i>Comp.</i>	<i>Due</i>	<i>Hrs.</i>	<i>Comp.</i>	<i>Ldg</i>	<i>Due</i>	<i>Due</i>	
<b>ATA/Ref No:</b>	<b>Rev: Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>From: Comp'd:</b>	<b>Iss/Rev:</b>	<b>Hours:</b>	<b>Hours:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Date: Status</b>
72 SB: 13368	1 Power-Turbine-Stator Housing Assembly - Modification Of	PCE-PK0278	L/H									Optional
72 SB: 13368	1 Power-Turbine-Stator Housing Assembly - Modification Of	PCE-PK0277	R/H									Optional
72 SB: 13369	1 Compressor Inlet Case Drain Plug - Replacement Of	PCE-PK0278	L/H									Optional
72 SB: 13369	1 Compressor Inlet Case Drain Plug - Replacement Of	PCE-PK0277	R/H									Optional
72 SB: 13371	IR Air Inlet Screen Washers - Removal Of	PCE-PK0277	R/H									Optional
72 SB: 13371	IR Air Inlet Screen Washers - Removal Of	PCE-PK0278	L/H									Optional
72 SB: 13378	1 New Power Turbine Blades - Introduction Of	PCE-PK0278	L/H									Optional
72 SB: 13378	1 New Power Turbine Blades - Introduction Of	PCE-PK0277	R/H									Optional
72 SB: 13379	IR Combustion Chamber Outer Liner - Replacement Of	PCE-PK0278	L/H									Optional
72 SB: 13379	IR Combustion Chamber Outer Liner - Replacement Of	PCE-PK0277	R/H									Optional
72 SB: 13384	IR Center Fireseals And Rear Scavenge Oil Adapter - Replacement Of	PCE-PK0277	R/H									Optional
72 SB: 13384	IR Center Fireseals And Rear Scavenge Oil Adapter - Replacement Of	PCE-PK0278	L/H									Optional
72 SB: 13385	1 Propeller Shaft Oil Seal Retaining Rings - Replacement Of	PCE-PK0277	R/H									Optional
72 SB: 13385	1 Propeller Shaft Oil Seal Retaining Rings - Replacement Of	PCE-PK0278	L/H									Optional
72 SB: 13386	IR Compressor Inlet Case Assembly - Replacement Of	PCE-PK0277	R/H									Optional
72 SB: 13386	IR Compressor Inlet Case Assembly - Replacement Of	PCE-PK0278	L/H									Optional
72 SB: 13392	1 Combustion Chamber Outer Liner - Replacement Of	PCE-PK0277	R/H									Optional
72 SB: 13392	1 Combustion Chamber Outer Liner - Replacement Of	PCE-PK0278	L/H									Optional
72 SB: 13401	IR Power-Turbine Shaft Housing - Replacement Of	PCE-PK0278	L/H									Optional

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>				<i>Eff</i>	<i>Last</i>	<i>Project/</i>	<i>Comp.</i>	<i>Due</i>	<i>Hrs.</i>	<i>Comp.</i>	<i>Ldg</i>	<i>Due</i>	<i>Due</i>		
<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>From:</i>	<i>Comp'd:</i>	<i>Iss/Rev:</i>	<i>Hours:</i>	<i>Hours:</i>	<i>Rem.:</i>	<i>Ldgs:</i>	<i>Rem.:</i>	<i>Ldgs:</i>	<i>Date:</i>	<i>Status</i>
72 SB: 13401		IR Power-Turbine Shaft Housing - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13403		1 Accessory Gearbox Housing - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13403		1 Accessory Gearbox Housing - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13405		IR Starter Generator Drive Gearshaft - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13405		IR Starter Generator Drive Gearshaft - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13415 [Part: 1.E]		3 New Oil Tank Filler Cap and Gage Assembly - Replacement Of	PCE-PK0277	R/H	17-Aug-23										Optional
72 SB: 13422		1 Air Inlet Screen - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13425		2 CT Rotor Air-Seal - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13431		1 Accessory Gearbox Housing Assembly - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13431		1 Accessory Gearbox Housing Assembly - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13444		IR Compressor Inlet Case Assembly - Replacement / Modification Of	PCE-PK0278	L/H											Optional
72 SB: 13444		IR Compressor Inlet Case Assembly - Replacement / Modification Of	PCE-PK0277	R/H											Optional
72 SB: 13456		1 Compressor Rotor Air Seal - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13456		1 Compressor Rotor Air Seal - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13458		4 Propeller-Shaft Oil Seal Retaining-Ring-Halves - Replacement / Modification Of	PCE-PK0277	R/H											Optional
72 SB: 13458		4 Propeller-Shaft Oil Seal Retaining-Ring-Halves - Replacement / Modification Of	PCE-PK0278	L/H											Optional
72 SB: 13459		IR Lockwire - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13459		IR Lockwire - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13488		2 Classified Turbine Vane Ring - Introduction Of	PCE-PK0277	R/H											Optional
72 SB: 13488		2 Classified Turbine Vane Ring - Introduction Of	PCE-PK0278	L/H											Optional

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>				<i>Eff</i>	<i>Last</i>	<i>Project/</i>	<i>Comp.</i>	<i>Due</i>	<i>Hrs.</i>	<i>Comp.</i>	<i>Ldg</i>	<i>Due</i>	<i>Due</i>		
<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>From:</i>	<i>Comp'd:</i>	<i>Iss/Rev:</i>	<i>Hours:</i>	<i>Hours:</i>	<i>Rem.:</i>	<i>Ldgs:</i>	<i>Rem.:</i>	<i>Ldgs:</i>	<i>Date:</i>	<i>Status</i>
72 SB: 13491	5	Combustion Chamber Outer Liner Assembly - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13491	5	Combustion Chamber Outer Liner Assembly - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13493	IR	Overspeed Governor Washer - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13493	IR	Overspeed Governor Washer - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13496	IR	No. 3 Bearing Scavenge Tube Retaining Plate - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13496	IR	No. 3 Bearing Scavenge Tube Retaining Plate - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13500	2	Compressor Inlet Case Assembly - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13500	2	Compressor Inlet Case Assembly - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13503	1	Scavenge Pump Housing - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13503	1	Scavenge Pump Housing - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13507	1	Outer Combustion Chamber Liner - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13507	1	Outer Combustion Chamber Liner - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13508	IR	Compressor Disk Second and Third Stage - Modification / Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13508	IR	Compressor Disk Second and Third Stage - Modification / Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13514	IR	First-Stage Compressor Stator Assembly - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13514	IR	First-Stage Compressor Stator Assembly - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13516	IR	No. 3 and 4 Bearing Pressure Oil Tube Assembly - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13516	IR	No. 3 and 4 Bearing Pressure Oil Tube Assembly - Replacement Of	PCE-PK0278	L/H											Optional

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>		<i>Eff</i>	<i>Last</i>	<i>Project/</i>	<i>Comp.</i>	<i>Due</i>	<i>Hrs.</i>	<i>Comp.</i>	<i>Ldg</i>	<i>Due</i>	<i>Due</i>			
<b>ATA/Ref No:</b>	<b>Rev: Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>From:</b>	<b>Comp'd:</b>	<b>Iss/Rev:</b>	<b>Hours:</b>	<b>Hours:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Date:</b>	<b>Status</b>
72 SB: 13526	IR Accessory Gearbox Gearshaft Drive - Replacement / Modification Of	PCE-PK0277	R/H											Optional
72 SB: 13526	IR Accessory Gearbox Gearshaft Drive - Replacement / Modification Of	PCE-PK0278	L/H											Optional
72 SB: 13533	1 Accessory Gearbox Housing Assembly - Replacement Of	PCE-PK0277	R/H											Optional
72 SB: 13533	1 Accessory Gearbox Housing Assembly - Replacement Of	PCE-PK0278	L/H											Optional
72 SB: 13536	IR Combustion-Chamber Outer-Liner Assembly - Modification Of	PCE-PK0278	L/H											Optional
72 SB: 13536	IR Combustion-Chamber Outer-Liner Assembly - Modification Of	PCE-PK0277	R/H											Optional
72 SB: 13540	IR Reduction-Gearbox Propeller-Front-Housing Assembly - Replacement Of	PCE-PK0278	L/H	02-Feb-24										Optional
72 SB: 13540	IR Reduction-Gearbox Propeller-Front-Housing Assembly - Replacement Of	PCE-PK0277	R/H	02-Feb-24										Optional
73 SB: 13044	16 Engine Fuels and Additives	PCE-PK0278	L/H	17-Aug-23	1 / 16		4483.10			4537				As Req'd
73 SB: 13044	16 Engine Fuels and Additives	PCE-PK0277	R/H	17-Aug-23	1 / 16		4502.40			4547				As Req'd
73 SB: 13295	1 Fuel Nozzle "U" Seals - Introduction Of	PCE-PK0277	R/H											Optional
73 SB: 13295	1 Fuel Nozzle "U" Seals - Introduction Of	PCE-PK0278	L/H											Optional
73 SB: 13360	IR New Oil-To-Fuel Heater Transfer Tube - Introduction Of	PCE-PK0277	R/H											Optional
73 SB: 13360	IR New Oil-To-Fuel Heater Transfer Tube - Introduction Of	PCE-PK0278	L/H											Optional
73 SB: 13414 [Part: 1.E]	2 P3 Air-Pressure-Tube Assembly - Replacement	PCE-PK0277	R/H											Optional
73 SB: 13414 [Part: 1.E]	2 P3 Air-Pressure-Tube Assembly - Replacement	PCE-PK0278	L/H											Optional
73 SB: 13450	IR Py And P3 Insulated Air Pressure Tubes - Inspection / Replacement Of	PCE-PK0277	R/H											Optional
73 SB: 13517	2 Oil To Fuel Heater - Replacement / Modification Of	PCE-PK0277	R/H											Optional

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>		<i>Eff</i>	<i>Last</i>	<i>Project/</i>	<i>Comp.</i>	<i>Due</i>	<i>Hrs.</i>	<i>Comp.</i>	<i>Ldg</i>	<i>Due</i>	<i>Due</i>	
<b>ATA/Ref No:</b>	<b>Rev: Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>From: Comp'd:</b>	<b>Iss/Rev:</b>	<b>Hours:</b>	<b>Hours:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Date: Status</b>
73 SB: 13517	2 Oil To Fuel Heater - Replacement / Modification Of	PCE-PK0278	L/H									Optional
73 SB: 13544	IR Air-Pressure Tube Assembly and Front Governor Air-Pressure Tube Assembly - Inspection/Replacement of	PCE-PK0277	R/H									Optional
73 SB: 13544	IR Air-Pressure Tube Assembly and Front Governor Air-Pressure Tube Assembly - Inspection/Replacement of	PCE-PK0278	L/H									Optional
74 SB: 13355	1 Ignition Exciter - Replacement Of	PCE-PK0277	R/H									Optional
74 SB: 13355	1 Ignition Exciter - Replacement Of	PCE-PK0278	L/H									Optional
74 SB: 13440	1 Ignition Exciter - Replacement Of	PCE-PK0278	L/H									Optional
74 SB: 13440	1 Ignition Exciter - Replacement Of	PCE-PK0277	R/H									Optional
74 SB: 13481	IR Component - Replacement / Modification Of	PCE-PK0278	L/H									Optional
74 SB: 13481	IR Component - Replacement / Modification Of	PCE-PK0277	R/H									Optional
74 SB: 13510	1 Ignition Exciter - Replacement Of	PCE-PK0277	R/H									Optional
74 SB: 13510	1 Ignition Exciter - Replacement Of	PCE-PK0278	L/H									Optional
74 SB: 13523	3 Ignition Exciter - Replacement Of	PCE-PK0278	L/H									Optional
74 SB: 13523	3 Ignition Exciter - Replacement Of	PCE-PK0277	R/H									Optional
75 SB: 13063	IR New P3 Compressor Air Filter Cleanable Element - Introduction Of	PCE-PK0277	R/H									Optional
75 SB: 13063	IR New P3 Compressor Air Filter Cleanable Element - Introduction Of	PCE-PK0278	L/H									Optional
75 SB: 13511	IR Compressor Bleed Valve Assembly - Replacement / Modification Of	PCE-PK0277	R/H									Optional
75 SB: 13511	IR Compressor Bleed Valve Assembly - Replacement / Modification Of	PCE-PK0278	L/H									Optional
75 SB: 13519	1 Compressor Bleed Valve - Replacement Of	PCE-PK0278	L/H									Optional
75 SB: 13519	1 Compressor Bleed Valve - Replacement Of	PCE-PK0277	R/H									Optional

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

<b>Publication</b>		<b>Eff</b>	<b>Last</b>	<b>Project/</b>	<b>Comp.</b>	<b>Due</b>	<b>Hrs.</b>	<b>Comp.</b>	<b>Ldg</b>	<b>Due</b>	<b>Due</b>			
<b>ATA/Ref No:</b>	<b>Rev: Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>From:</b>	<b>Comp'd:</b>	<b>Iss/Rev:</b>	<b>Hours:</b>	<b>Hours:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Rem.:</b>	<b>Ldgs:</b>	<b>Date:</b>	<b>Status</b>
75 SB: 13521	IR Compressor Bleed Valve Assembly - Replacement / Modification Of	PCE-PK0277	R/H											Optional
75 SB: 13521	IR Compressor Bleed Valve Assembly - Replacement / Modification Of	PCE-PK0278	L/H											Optional
77 SB: 13132	1 Heat Shrinkable Tubing For Trim Thermocouple And T5 Wiring Harness Near The Terminal Lugs - Introduction Of	PCE-PK0278	L/H											Optional
77 SB: 13132	1 Heat Shrinkable Tubing For Trim Thermocouple And T5 Wiring Harness Near The Terminal Lugs - Introduction Of	PCE-PK0277	R/H											Optional
77 SB: 13338	1 T-5 Trim Thermocouple - Replacement Of	PCE-PK0277	R/H											Optional
77 SB: 13338	1 T-5 Trim Thermocouple - Replacement Of	PCE-PK0278	L/H											Optional
79 SB: 13001	22 Approved Listing Of (Synthetic) Lubricating Oils	PCE-PK0277	R/H	27-Jul-23	1 / 22		4385.30			4413				As Req'd
79 SB: 13001	22 Approved Listing Of (Synthetic) Lubricating Oils	PCE-PK0278	L/H											As Req'd
79 SB: 13365	1 New Thermostatic-Bypass-Valve Transfer Tube - Introduction Of	PCE-PK0277	R/H											Optional
79 SB: 13365	1 New Thermostatic-Bypass-Valve Transfer Tube - Introduction Of	PCE-PK0278	L/H											Optional
79 SB: 13455	IR External Coupling Scavenge Oil Transfer - Replacement Of	PCE-PK0277	R/H											Optional
79 SB: 13455	IR External Coupling Scavenge Oil Transfer - Replacement Of	PCE-PK0278	L/H											Optional
82 EO: ESE-Kingair-82-001	02 ESE-Kingair-82-001 - Installation of Compressor Drain Extension - Part 4 Continuing Airworthiness Drain Line Periodic Maintenance (Both Engines) 1. Prepare the aircraft for maintenance and remove the engine cowling per the AMM. 2. Remove the entire dra	PCE-PK0277	R/H	22-Oct-25	01 / 02		4906.60	5106.60	162.90	4891			22-Oct-26	Repeat

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
82	EO: ESE-Kingair-82-001	02 ESE-Kingair-82-001 - Installation of Compressor Drain Extension - Part 4 Continuing Airworthiness Drain Line Periodic Maintenance (Both Engines) 1. Prepare the aircraft for maintenance and remove the engine cowling per the AMM. 2. Remove the entire dra	PCE-PK0278	L/H	22-Oct-25	01 / 02		4887.30	5087.30	162.90	4881			22-Oct-26	Repeat

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
05	SB: SB 2213	3 Time Limits/Maintenance Checks - Inspection of Pilot and Copilot Seat Track Wear (RECURRING INSP)	FL-269		01-Apr-88										NFA
N/A - Due Model															
11	CASR: CASR 90.410	100 CASR 90.410 - Emergency Exits - Requirements	FL-269		08-Jul-21	20-Oct-22	1 / 97	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
11	SB: SB 2238	IR Placards and Markings - Installation of Landing Gear Servicing Information Placard	FL-269		01-Jul-88										NFA
N/A - Due Model															
21	AD: 2017-06-03	IR Meggitt Inc Combustion Heaters - Inspection / Disabling / Replacement	FL-269		05-May-17	20-Oct-22	1 / IR	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
21	AD: AD/AIRCON/012	5 Hartzell Engine Technologies, Kelly Aerospace Power Systems, and Janaero Devices - Cabin Combustion Heaters	FL-269		20-Dec-99	20-Oct-22	1 / 5	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
21	AD: AD/AIRCON/013	3 Kelly Aerospace Fuel Regulator Shutoff Valves & Cabin Heaters	FL-269		20-Dec-99	20-Oct-22	1 / 3	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
22	SB: SB 2283	2 Auto Flight - Installation of Autopilot Servo Covers	FL-269		01-May-89										NFA
N/A - Due Model															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
22	SB: SB 2388	IR Auto Flight - Autopilot Trim Fail Wiring Modification	FL-269		01-Jan-91										NFA
N/A - Due Model															
23	AD: 2017-16-01	IR Ameri-King Corporation Model AK-450-( ) and AK-451-( ) Series Emergency Locator Transmitters (ELTs)	FL-269		11-Jul-17	20-Oct-22	1 / IR	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
23	AD: 2019-0235 [Part: < 5 Y]	1 Equipment / Furnishings - Emergency Locator Transmitter - Inspection / Modification / Replacement (AD applies only if ELT fitted via the applicable EASA ETSOs)	FL-269			20-Oct-22	1 / 1	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
23	AD: AD/RAD/047	4 Periodic Testing of ATC Transponders	FL-269			20-Oct-22	1 / 4	4394.40			4424				NFA
N/A - Not A Part 42 Aircraft															
23	AD: AD/REC/001 [Part: Digital]	5 Maintenance of Cockpit Voice Recording Systems	FL-269			20-Oct-22									NFA
N/A - Not A Part 42 Aircraft															
24	AD: AD/ELECT/028	3 Prestolite Alternator SRE Bearing Inspection	FL-269			20-Oct-22	1 / 3	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
24	AD: AD/ELECT/054	IR Sealed Lead Acid Aircraft Batteries	FL-269		20-Dec-99	20-Oct-22	1 / IR	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
25	AD: 2016-0167	1 Equipment / Furnishings - Rear Cabin Attendant Seat - Inspection / Repair	FL-269			20-Oct-22	1 / 1	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
25	AD: 2017-0001	IR Equipment / Furnishings - Cabin Attendant Seat - Inspection	FL-269			20-Oct-22	1 / IR	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
25	AD: AD/EMY/002	7 Life Jackets and Inflatable Flotation Devices	FL-269			20-Oct-22	1 / 7	4394.40			4424				NFA
N/A - Not A Part 42 Aircraft															
25	AD: AD/EMY/010	IR Inflatable Escape Slide Regulators - Inspection	FL-269		01-Sep-73	20-Oct-22	1 / IR	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
25 AD: AD/EMY/016	2	Life Jackets (Beaufort) - Inspection	FL-269		31-Oct-84	20-Oct-22	1 / 2	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
25 AD: AD/RES/033 [Part: 1]	1	Anjou Aeronautique Restraint Systems	FL-269		11-Jan-03	20-Oct-22	1 / 1	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
25 AD: AD/SEATS/008	2	Sicma Seat - Aft Track Fittings	FL-269			20-Oct-22	1 / 2	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
25 AD: AD/SEATS/014	2	Avio Interiors - Series 312 Seats Centre Cross-member Cracking	FL-269		20-Dec-99	20-Oct-22	1 / 2	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
25 AD: AD/SEATS/016	1	Avio Interiors - Series 312 Seat Aisle Side Cross-member Cracking	FL-269		20-Dec-99	20-Oct-22	1 / 1	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
25 AD: AD/SEATS/018 [Part: 2]	1	Avio Interiors - Series 312 Box Mounted Seats Attachment	FL-269			20-Oct-22									NFA
N/A - Subject Equipment Not Fitted															
25 AD: AD/SEATS/020 [Part: 3]	IR	SICMA Passenger Seats (9g) - Backrest Link Inspection and Replacement	FL-269			20-Oct-22									NFA
N/A - Subject Equipment Not Fitted															
26 AD: 2021-0185	2	Fire Protection – Hand-operated Fire Extinguishers – Inspection / Replacement	FL-269		19-Aug-21	20-Oct-22	1 / 2	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
26 AD: 74-08-09 [Part: [i]]	3	Installation of No Smoking Placards and Ashtrays	FL-269			16-Aug-23									NFA
N/A - Due Aircraft Model & Serial Number															
27 AD: AD/GENERAL/087 [Part: B200]	1	Primary flight control cable terminals - Detailed visual inspection	FL-269		20-Dec-99	10-Jan-25	1 / 1	4740.80			4811				NFA
N/A - MTOW Above 5,700 kg															
27 SB: SB 2212	IR	Flight Controls - Inspection of Flight Control Cable Tensions	FL-269			01-Nov-87									NFA
N/A - Due Model															
27 SB: SB 27-3459	2	Flight Controls - Flight Control Gust Lock Inspection/Replacement (RECURRING INSP)	FL-269		01-Nov-01	17-Aug-23	1 / 2	4511.50			4602				NFA

Requirement Included in Phase 8 Task 27-70-01-2100

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
28	CAO: CAO 100.5 Appendix 1 Clause 6	10 Test Fuel quantity gauges	FL-269		20-Oct-22	2011 / 10	4394.40				4424				NFA
N/A - Capacitance System - Inspection Not Required															
31	AD: AD/INST/010 [Part: Dual]	2 Mechanical Fatigue Meters	FL-269		20-Oct-22										NFA
N/A - Subject Equipment Not Fitted															
32	AD: AD/BEECH 300/020	IR Nose Gear Lower Shock Absorber Assembly	FL-269		05-Jul-07	16-Aug-23	1 / IR	4511.50			4602				NFA
N/A - Due Aircraft Model & Serial Number															
32	AD: AD/ELECT/057	1 Landing Gear - Dunlop Fan and Transducer Installation	FL-269		20-Oct-22	1 / 1	4394.40				4424				NFA
N/A - Subject Equipment Not Fitted															
32	AD: AD/WHE/008	IR MLG Wheel Assembly Part Numbers C20500000 and C20452000	FL-269		20-Oct-22	1 / IR	4394.40				4424				NFA
N/A - Subject Equipment Not Fitted															
32	SB: SB 2046	IR Landing Gear - Modification of Power Time Delay Wiring	FL-269		01-Mar-85										NFA
N/A - Due Model															
32	SB: SB 2220 [Part: C/W]	IR Landing Gear - Inspection and/or Replacement of the Nose Landing Gear Steering Link	FL-269		01-Mar-90										NFA
N/A - Due Model															
32	SB: SB 2226 [Part: Part I]	2 Landing Gear - Part I, Replacement of the 250 Ampere Landing Gear Power Pack Motor Relay; Part II, Announcement of a New Replacement Landing Gear Power Pack Motor	FL-269		01-Apr-89										NFA
N/A - Due Model															
32	SB: SB 32-2102 [Part: Part I]	7 Landing Gear - Inspection/Replacement of Nose Gear Lower Shock Absorber Assembly (RECURRING INSP)	FL-269		01-Jul-86										NFA
N/A - Due Model															
34	AD: 2021-23-12	IR Radio Altimeter - 5G Interference - Aircraft Flight Manual Revision	FL-269		09-Dec-21										NFA
NFA: Publication Cancelled 31-May-2023 Superseded by 2023-10-02															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
34	SB: SB 2294	1 Navigation/Pitot Static - Modification To the Collins MCS-65 Compass System Wiring	FL-269		01-May-90										NFA
N/A - Due Model															
35	AD: AD/GAS/001 [Part: Fibre]	12 Inspection, Test and Retirement	FL-269		20-Oct-22										NFA
N/A - Not A Part 42 Aircraft															
51	AD: AD/GENERAL/029	IR Wooden Aircraft - Airframe Structural Inspection	FL-269		20-Oct-22	1 / IR		4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
52	AD: AD/GENERAL/037 [Part: Press]	10 Emergency Exits	FL-269		20-Oct-22	1 / 10		4394.40			4424				NFA
N/A - Not A Part 42 Aircraft															
53	SB: SB 2312	IR Fuselage - Inspection of Aft Fuselage Moisture Drainage System	FL-269		01-Dec-89										NFA
N/A - Due Model															
53	SB: SB 53-2472 [Part: Part I]	4 Fuselage - Inspection/Modification of Aft Fuselage Stringers (RECURRING INSP)	FL-269		01-Jun-93	23-Oct-23	1 / 4	4551.50			4651				NFA
N/A - Due Aircraft S/N															
55	SB: SB 2254	1 Stabilizers - Sealing of Horizontal Stabilizer and Dorsal Fin For Moisture Protection and Installation of Bonding Jumper	FL-269		01-Feb-89										NFA
N/A - Due Model															
55	SB: SB 2422	1 Stabilizers - Inspection/Modification of the Rudder Torque Shaft	FL-269		01-Sep-91										NFA
N/A - Due Model															
57	AD: AD/BEECH 300/002 [Part: (a) 300]	IR Wing Fatigue Life Limitation	FL-269		16-Aug-23										NFA
N/A - Due Aircraft Model & Serial Number															
57	SB: SB 2040	2 Wings - Inspection/Modification of Wing Skins (RECURRING INSP)	FL-269		01-Aug-84										NFA
N/A - Due Model															
57	SB: SB 2256	IR Wings - Removal Of Scotch Foam From Aileron Assemblies	FL-269		01-Nov-88										NFA
N/A - Due Model															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: 2009-22-03		IR Propeller Hub Cracks	FWA6264	R/H	25-Mar-22										NFA
N/A - Due Propeller Model															
61 AD: 2009-22-03		IR Propeller Hub Cracks	FWA2937	L/H	28-Feb-20										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/001		IR Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/001		IR Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/002		IR Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/002		IR Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/003		IR Blade Retaining Split Ring - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/003		IR Blade Retaining Split Ring - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/004		IR Blade Retaining Split Ring - Replacement and Life Limitation - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/004		IR Blade Retaining Split Ring - Replacement and Life Limitation - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/005		IR Piston Jack Assembly P/N B-804 - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/005		IR Piston Jack Assembly P/N B-804 - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/006		IR Link Screw P/N AN501-A10-6 Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/006		IR Link Screw P/N AN501-A10-6 Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/007		IR Guide Collar - Replacement and Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/007		IR Guide Collar - Replacement and Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/009		1 Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/009		1 Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/010		IR Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/010		IR Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/011		IR Propeller Mounting Bolt - Inspection and Modification - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/011		IR Propeller Mounting Bolt - Inspection and Modification - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/012		IR Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/012		IR Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/013		IR Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/013		IR Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/014		4 Blade and Hub - Shot Peening	FWA6264	R/H	20-Jun-95										NFA
N/A - Due Propeller Model															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/014	4	Blade and Hub - Shot Peening	FWA2937	L/H	20-Jun-95										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/015		IR Relief Valve Springs - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/015		IR Relief Valve Springs - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/016		IR Pitch Change Block - Inspection and Modification - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/016		IR Pitch Change Block - Inspection and Modification - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/017	1	Bearing Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/017	1	Bearing Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/018		IR Propeller Blade Clamp - Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/018		IR Propeller Blade Clamp - Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/019		IR Carbon Block Assembly - Modification - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/019		IR Carbon Block Assembly - Modification - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/020		IR Spinner Bulkhead - Modification - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/020		IR Spinner Bulkhead - Modification - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/021	1	Propeller Blade Shank - Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/021	1	Propeller Blade Shank - Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/022	2	Propeller Blade Bearing - Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/022	2	Propeller Blade Bearing - Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/023	5	Blade Shank - Inspection and Modification - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/023	5	Blade Shank - Inspection and Modification - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/024		IR Propeller Attachment - Modification and Inspection	FWA2937	L/H	15-Apr-69										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/024		IR Propeller Attachment - Modification and Inspection	FWA6264	R/H	15-Apr-69										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/025	2	Blade Shank - Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/025	2	Blade Shank - Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/026		IR Blade Shank - Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/026		IR Blade Shank - Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hrs:</i>	<i>Comp. Rem.:</i>	<i>Ldg Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/027		IR Propeller Blade - Inspection and Modification of Balance Cavity - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/027		IR Propeller Blade - Inspection and Modification of Balance Cavity - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/028	1	Propeller Blade - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/028	1	Propeller Blade - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/029	1	Propeller Blade - Inspection and Modification of Balance Cavity - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/029	1	Propeller Blade - Inspection and Modification of Balance Cavity - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/030		IR Pitch Change Knob Bushing - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/030		IR Pitch Change Knob Bushing - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/031	1	Propeller Blade - Inspection and Modification of Balance Cavity - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/031	1	Propeller Blade - Inspection and Modification of Balance Cavity - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/033		IR Pitch Change Forks - Shot Peening - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/033		IR Pitch Change Forks - Shot Peening - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/034		IR Blade and Hub - Shot Peening - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/034		IR Blade and Hub - Shot Peening - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/035		IR "Y" Shank Blade - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/035		IR "Y" Shank Blade - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/036		2 Propeller Blade - Inspection and Modification of Balance Cavity - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/036		2 Propeller Blade - Inspection and Modification of Balance Cavity - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/037		IR Hard Alloy Blades - Inspection	FWA6264	R/H	31-Jul-74										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/037		IR Hard Alloy Blades - Inspection	FWA2937	L/H	31-Jul-74										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/038		IR "Y" Shank Blade - Inspection and Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/038		IR "Y" Shank Blade - Inspection and Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/039		1 Propeller Damper - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
61 AD: AD/PHZL/039	1	Propeller Damper - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/040	IR	Propeller Blade - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/040	IR	Propeller Blade - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/041	IR	Propeller Blade Shank Bearing Radius - Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/041	IR	Propeller Blade Shank Bearing Radius - Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/042	5	Propeller Feather Assist Spring Kit - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/042	5	Propeller Feather Assist Spring Kit - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/043	10	Single Shoulder Aluminium Blades - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/043	10	Single Shoulder Aluminium Blades - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/044	9	Propeller Attachment Bolts	FWA6264	R/H	07-Jul-05										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/044	9	Propeller Attachment Bolts	FWA2937	L/H	07-Jul-05										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/045	IR	Propeller Hub Pilot Tubes - Replacement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/045	IR	Propeller Hub Pilot Tubes - Replacement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
61 AD: AD/PHZL/046	2	Propeller De-Icer System Slip Ring - Inspection	FWA6264	R/H	25-Mar-22										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/046	2	Propeller De-Icer System Slip Ring - Inspection	FWA2937	L/H	28-Feb-20										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/047	1	Propeller Blades TL10282 ( ) ( ) + 4 or LT10282 ( ) ( ) + 4 - Retirement - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/047	1	Propeller Blades TL10282 ( ) ( ) + 4 or LT10282 ( ) ( ) + 4 - Retirement - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/048	6	Propeller Blade Pilot Tube Bore - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/048	6	Propeller Blade Pilot Tube Bore - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/049	3	T10282 Blades (Hard Alloy) - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/049	3	T10282 Blades (Hard Alloy) - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/050	IR	A-4025 Spring Retainer - Inspection - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/050	IR	A-4025 Spring Retainer - Inspection - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/051	IR	Propeller Attach Bolts - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/051	IR	Propeller Attach Bolts - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/052		2 Propeller Blade Separation - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/052		2 Propeller Blade Separation - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/054		IR Hard Alloy Propeller Blades	FWA2937	L/H	30-Dec-86										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/054		IR Hard Alloy Propeller Blades	FWA6264	R/H	30-Dec-86										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/055		1 Pilot Tubes - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/055		1 Pilot Tubes - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/057		2 Blade Tip Stalling	FWA6264	R/H	25-Feb-88										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/057		2 Blade Tip Stalling	FWA2937	L/H	25-Feb-88										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/058		IR Piston Nut B474 - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/058		IR Piston Nut B474 - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/059		4 Two Blade "Y" Shank Aluminium Hub - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/059		4 Two Blade "Y" Shank Aluminium Hub - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/061		IR Mounting Studs - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/061		IR Mounting Studs - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/062		4 Propeller Blade Pilot Tube Bore - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/062	4	Propeller Blade Pilot Tube Bore - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/063	1	Propeller Blade Bore - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/063	1	Propeller Blade Bore - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61 AD: AD/PHZL/064	2	Hub Pilot Tube Bore	FWA2937	L/H	24-Feb-95										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/064	2	Hub Pilot Tube Bore	FWA6264	R/H	24-Feb-95										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/070	IR	Hard Alloy Blades - Removal	FWA2937	L/H	17-Apr-03										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/070	IR	Hard Alloy Blades - Removal	FWA6264	R/H	17-Apr-03										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/071	IR	Counterweight Clamp Bolts	FWA2937	L/H	23-Apr-98										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/071	IR	Counterweight Clamp Bolts	FWA6264	R/H	23-Apr-98										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/076	2	HC-C2YR-4CF Propeller Life Reduction	FWA6264	R/H	11-Mar-03										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/076	2	HC-C2YR-4CF Propeller Life Reduction	FWA2937	L/H	11-Mar-03										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/077	2	Australian Air Props - Cancelled	FWA6264	R/H											NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/077	2	Australian Air Props - Cancelled	FWA2937	L/H											NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/080	IR	Composite Blades Cracking	FWA6264	R/H	25-Mar-22										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/080	IR	Composite Blades Cracking	FWA2937	L/H	28-Feb-20										NFA
N/A - Due Propeller Model															
61 AD: AD/PHZL/086	1	Propeller Hub Cracks - Cancelled	FWA6264	R/H											NFA
N/A - Due Propeller Model															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
61	AD: AD/PHZL/086	1 Propeller Hub Cracks - Cancelled	FWA2937	L/H											NFA
N/A - Due Propeller Model															
61	AD: AD/PROP/003	1 Propeller Blade Bearings - Cancelled	FWA6264	R/H											NFA
N/A - The requirements of this AD has been cancelled															
61	AD: AD/PROP/003	1 Propeller Blade Bearings - Cancelled	FWA2937	L/H											NFA
N/A - The requirements of this AD has been cancelled															
61	SB: SB 2266	1 Propellers - Announcement of Hartzell Propeller Service Bulletin No. 159	FL-269		01-Jun-88										NFA
N/A - Due Model															
72	AD: AD/PT6A/016	IR Improved Strength P.T. Shaft Housing and Reduction Gearbox Condition Monitoring	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				NFA
N/A - Due Engine Model															
72	AD: AD/PT6A/016	IR Improved Strength P.T. Shaft Housing and Reduction Gearbox Condition Monitoring	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				NFA
N/A - Due Engine Model															
73	AD: AD/FSM/029	4 Precision Airmotive Corporation Carburetors	FL-269		20-Oct-22	1 / 4	4394.40				4424				NFA
N/A - Subject Equipment Not Fitted															
74	AD: AD/ELECT/038	IR Bendix Distributor Gear Electrode - Inspection/Replacement	FL-269		20-Oct-22	1 / IR	4394.40				4424				NFA
N/A - Subject Equipment Not Fitted															
74	AD: AD/ELECT/059	1 Ignition Switches	FL-269		20-Dec-99	20-Oct-22	1 / 1	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
74	AD: AD/ELECT/075	1 TCM Magneto Impulse Coupling	FL-269		20-Dec-99	20-Oct-22	1 / 1	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
75	AD: AD/AIRIND/001	IR Brackett Aircraft Specialities Air Inlet Filter Assembly Inspection	FL-269		20-Oct-22	1 / IR	4394.40				4424				NFA
N/A - Subject Equipment Not Fitted															
78	AD: AD/PT6A/032	IR Exhaust Duct Cracking	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				NFA
N/A - Due Engine Model															
78	AD: AD/PT6A/032	IR Exhaust Duct Cracking	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				NFA
N/A - Due Engine Model															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - No Further Action Required (NFA)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
79	AD: AD/LUB/002	2 Oil Filter Adapters	FL-269		20-Oct-22	1 / 2		4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
81	AD: 2023-09-09 I	IR Spot-Welded, Multi-segment Exhaust v-band Coupling (Applicable to Aircraft / Rotorcraft for which the FAA is the State of Design) - Annual Inspection	FL-269		17-Jul-23	31-May-24	1 / IR	4599.20			4689				NFA
N/A - Subject Equipment Not Fitted															
81	AD: 2024-0221	IR Exhaust - Engine / Turbocharger Exhaust System / Components - Inspection (Applicable to Aircraft / Rotorcraft for which EASA is the State of Design)	FL-269		06-Dec-24	24-Jan-25	1 / IR	4740.80			4811				NFA
N/A - Subject Equipment Not Fitted															
81	AD: AD/TURBO/001	1 Roto-Master (Rajay Industries, Inc.) Turbochargers - Inspection and Replacement	FL-269		20-Dec-99	20-Oct-22	1 / 1	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
95	AD: AD/SUPP/001 [Part: 2(a)]	3 Breeze Hoists	FL-269		20-Oct-22										NFA
N/A - Subject Equipment Not Fitted															
95	AD: AD/SUPP/003	2 Breeze Hoists	FL-269		20-Oct-22	1 / 2		4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
95	AD: AD/SUPP/008 [Part: 1]	1 Towing Release System	FL-269		20-Oct-22	1 / 1		4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
95	AD: AD/SUPP/011	IR Bronzavia-Air Equipment Rescue Hoist Attach Brackets	FL-269		20-Oct-22	1 / IR		4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															
95	AD: AD/SUPP/016	1 Electrical Hoist Assemblies - Earth Bonding Testing	FL-269		20-Dec-99	20-Oct-22	1 / 1	4394.40			4424				NFA
N/A - Subject Equipment Not Fitted															

## Publication - Not Applicable (N/A)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
24	MM: 5-0171 [Part: Turbo New]	Q RG Series Main Aircraft Battery Capacity Check - CMM 5-0171	41430844	R/H											N/A

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

**Publication - Not Applicable (N/A)**

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
25	CAO: CAO 100.5 Appendix 1 Clause 11	10 Life rafts, life jackets and inflatable flotation devices - Inspect to ensure equipment is in date	FL-269												N/A
N/A - Refer Components															
35	CAO: CAO 100.5 App1 Clause 15 - Retir [Part: 24 Years]	10 Retire Compress Gas cylinders	FL-269												N/A
N/A - Refer Components															
35	CAO: CAO 100.5 App1 Clause 15 -Test [Part: 3 YEAR]	10 Test Compress Gas cylinders	FL-269												N/A
N/A - Refer Components															
61	AD: 2013-15-04	IR Hydraulic Bladder Diaphragm - Replacement	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61	AD: 2013-15-04	IR Hydraulic Bladder Diaphragm - Replacement	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61	AD: AD/PHZL/008	IR Hub Spider - Replacement	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61	AD: AD/PHZL/008	IR Hub Spider - Replacement	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61	AD: AD/PHZL/032	IR Propeller Modification - Installation of Spring Back-up Kit	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61	AD: AD/PHZL/032	IR Propeller Modification - Installation of Spring Back-up Kit	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61	AD: AD/PHZL/053	2 Blade Clamps	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61	AD: AD/PHZL/053	2 Blade Clamps	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61	AD: AD/PHZL/056	IR Pitch Change Rod	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61	AD: AD/PHZL/056	IR Pitch Change Rod	FWA6264	R/H											N/A
N/A - Due Propeller Model															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

**Publication - Not Applicable (N/A)**

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/060		4 Three Bladed 'Y' Shank Aluminium Hubs	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/060		4 Three Bladed 'Y' Shank Aluminium Hubs	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/065		2 Hub Pilot Tube Bore Inspection	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/065		2 Hub Pilot Tube Bore Inspection	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/066		IR Blade Pitch Change Knob	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/066		IR Blade Pitch Change Knob	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/067		IR Propeller Blade Cracking	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/067		IR Propeller Blade Cracking	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/068		4 Turbine Engine; Steel Hub Propellers	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/068		4 Turbine Engine; Steel Hub Propellers	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/069		2 Hartzell X and V Shank Propellers	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/069		2 Hartzell X and V Shank Propellers	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/072		IR Counterweight Clamp Bolt Hole	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/072		IR Counterweight Clamp Bolt Hole	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/073		IR Discrepant "Y" Shank Propellers	FWA2937	L/H											N/A
N/A - Due Propeller Model															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Not Applicable (N/A)

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/073		IR Discrepant "Y" Shank Propellers	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/074		2 Two Blade "Y" Shank Aluminium Hub	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/074		2 Two Blade "Y" Shank Aluminium Hub	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/075		IR Propeller Hub Replacement	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/075		IR Propeller Hub Replacement	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/078		IR Anti-Ice Boots	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/078		IR Anti-Ice Boots	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/079		2 Propeller Vibration Placard	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/079		2 Propeller Vibration Placard	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/081		IR Propeller Attachment Bolts	FWA6264	R/H											N/A
FAA AD 2005-14-12 Complied With 25th March 2022															
61 AD: AD/PHZL/081		IR Propeller Attachment Bolts	FWA2937	L/H											N/A
FAA AD 2005-14-12 Complied With 2nd August 2005															
61 AD: AD/PHZL/082		1 Hub Certified Service Life	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/082		1 Hub Certified Service Life	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/083		IR Propeller Hub Cracks	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/083		IR Propeller Hub Cracks	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/084		IR Propeller Control Unit	FWA6264	R/H											N/A
N/A - Due Propeller Model															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

**Publication - Not Applicable (N/A)**

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
61 AD: AD/PHZL/084		IR Propeller Control Unit	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/085		IR Propeller Blade Thrust Bearing	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/085		IR Propeller Blade Thrust Bearing	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/087		2 Propeller Thrust Bearings	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/087		2 Propeller Thrust Bearings	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/088		IR CSE Aviation	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/088		IR CSE Aviation	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/089		IR Propeller Mounting Flanges	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/089		IR Propeller Mounting Flanges	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/090		IR Hub Mounting Bolt Holes	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/090		IR Hub Mounting Bolt Holes	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/091		IR Hub Blade Socket Lubrication Holes	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/091		IR Hub Blade Socket Lubrication Holes	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PHZL/092		IR Propeller Blade Counterweight Slug Attach Bolts	FWA2937	L/H											N/A
FAA AD 2009-10-14 Complied With 4th June 2009															
61 AD: AD/PHZL/092		IR Propeller Blade Counterweight Slug Attach Bolts	FWA6264	R/H											N/A
FAA AD 2009-10-14 Complied With 25th March 2022															

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Not Applicable (N/A)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
61 AD: AD/PROP/001 [Part: 200]	2	Propellers - Overhaul	FWA2937	L/H											N/A
N/A - Refer HC-SL-61-61Y															
61 AD: AD/PROP/001 [Part: 200]	2	Propellers - Overhaul	FWA6264	R/H											N/A
N/A - Refer HC-SL-61-61Y															
61 AD: AD/PROP/002	4	Feathering Propellers - Functional Check	FWA2937	L/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PROP/002	4	Feathering Propellers - Functional Check	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 AD: AD/PROP/004		IR Overhaul Affected Propellers	FWA2937	L/H											N/A
61 AD: AD/PROP/004		IR Overhaul Affected Propellers	FWA6264	R/H											N/A
61 AD: AD/PROP/005		IR Incomplete Maintenance	FWA2937	L/H											N/A
61 AD: AD/PROP/005		IR Incomplete Maintenance	FWA6264	R/H											N/A
61 AD: AD/PROP/006		IR "Fastprop" Propeller De-Icers	FWA6264	R/H											N/A
61 AD: AD/PROP/006		IR "Fastprop" Propeller De-Icers	FWA2937	L/H											N/A
61 CAO: CAO 100.5 Appendix 1 Clause 8	10	Functional check Feathering propellers	FWA6264	R/H											N/A
N/A - Due Propeller Model															
61 CAO: CAO 100.5 Appendix 1 Clause 8	10	Functional check Feathering propellers	FWA2937	L/H											N/A
N/A - Due Propeller Model															

## Task Card - Not Applicable (N/A)

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
05 5-21-36 B.		C4 Inspection Phase 36	FL-269												N/A
Applicable component(s) not fitted to A/C (Product Group: C2504)															

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
01 SB: SB 00-2001	6	General - Hawker Beechcraft Publications – What Is Available and How to Obtain It	FL-269		11-Apr-23	23-Oct-23	1 / 6	4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
01 SB: SB 00-3000	1	General - Publications - Information on the Introduction of a New Service Bulletin Format and Numbering System	FL-269		11-Apr-23	23-Oct-23	1 / 1	4551.50			4651				Complied
05 AD: AD/GENERAL/069	1	Additional Airworthiness Requirements for Extended Range Operation with Twin Engine Aeroplanes - Cancelled	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
05 AD: AD/GENERAL/086	IR	Darwin Inspection and Testing Service Ultrasonic Inspection	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
05 AD: AD/HOSE/001	1	Flexible Hose Assemblies - Inspection and Testing - Cancelled	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
05 AD: AD/HOSE/002	2	Airframe Flexible Hose Assemblies Inspection and Testing - Cancelled	FL-269			20-Oct-22	1 / 2	4394.40			4424				Complied
05 AD: AD/HOSE/003	6	Engine Compartment Flexible Hose Assemblies - Cancelled	FL-269			20-Oct-22	1 / 6	4394.40			4424				Complied
05 AD: AD/HOSE/004	2	Aeroquip 601 Hose - Cancelled	FL-269			20-Oct-22	1 / 2	4394.40			4424				Complied
05 AD: AD/HOSE/005	IR	Hose Recall - Buckeye Rubber Products	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
05 AD: AD/HOSE/006	IR	Hose Recall #2 - Buckeye Rubber Products	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
05 AD: AD/HOSE/007	IR	Titeflex Hose Assemblies - Inspection	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
05 AD: AD/HOSE/008	IR	Titeflex Hose	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
11 AD: AD/GENERAL/062	1	Turbo Insignia - Cancelled	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
11 CASR: CASR 90.130	100	CASR 90.130 - External Doors - Compliance with Civil Aviation Safety Regulations 1998 - Part 90 Additional Airworthiness Requirements - Subpart 90.B General Provisions - 90.130 External Doors Paragraphs (2), (3), (4), (5) and (6). Note: An external door m	FL-269		08-Jul-21	27-Mar-25	1 / 100	4777.20			4839				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
11	CASR: CASR 90.135	100 CASR 90.135 - Emergency Exits - Compliance with Civil Aviation Safety Regulations 1998 - Part 90 Additional Airworthiness Requirements - Subpart 90.B General Provisions - 90.135 Emergency Exits Paragraphs (2), (3), (4), (5) and (6).	FL-269		08-Jul-21	20-Oct-22	1 / 97	4394.40			4424				Complied
11	SB: SB 11-3211	IR Placards and Markings - Main and Auxiliary Fuel Tank Useable and Total Fuel Quantity Decal Installation	FL-269		01-Nov-98	23-Oct-23	1 / IR	4551.50			4651				Complied
11	SB: SB 2405	IR Placards and Markings - Inspection to Verify Installation and Addition of All Interior and Exterior Placards and Markings (Recurring Insp)	FL-269		01-Nov-92	03-Jun-25	1 / IR	4827.10			4877				Complied
21	AD: AD/AIRCON/001	IR Godfrey Cabin Supercharger Type 15 - Banjo Fitting - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
21	AD: AD/AIRCON/002	IR Godfrey Cabin Supercharger Type 15 - Modification	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
21	AD: AD/AIRCON/003	IR Godfrey Cabin Supercharger Type 15 - Rotor Balance - Inspection - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
21	AD: AD/AIRCON/004	IR Cabin Heater - Cessna Combustion Type - Inspection and Reconditioning - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
21	AD: AD/AIRCON/005	IR Cabin Heater - Stewart Warner (Southwind) - Combustion Type - Inspection and Reconditioning - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
21	AD: AD/AIRCON/006	IR Cabin Heater - Stewart Warner (Southwind) - Combustion Type - Inspection and Reconditioning - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
21	AD: AD/AIRCON/007	IR Cabin Heater - Stewart Warner (Southwind) - Combustion Type - Inspection and Reconditioning - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
21 AD: AD/AIRCON/008	2	Cabin Heater - Midland Ross Corp. (Janitrol) - Combustion Type - Inspection and Reconditioning - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
21 AD: AD/AIRCON/009	8	Combustion Type Cabin Heaters - Cancelled	FL-269		20-Oct-22	1 / 8		4394.40			4424				Complied
21 AD: AD/AIRCON/010	IR	Janitrol Cabin Heaters - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
21 AD: AD/AIRCON/011	IR	ABG Semca Cold Air Unit - Compressor Wheel and Scroll	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
21 AD: AD/AIRCON/014	4	Zonal Drying System Regeneration Air Duct Overheat	FL-269		20-Oct-22	1 / 4		4394.40			4424				Complied
21 AD: AD/BEECH 300/009	1	Outflow/Safety Valve	FL-269		26-Feb-98	16-Aug-23	1 / 1	4511.50			4602				Complied
21 AD: AD/BEECH 300/010	IR	Pressurisation Control System Pneumatic Tubing Inspection	FL-269		29-Jan-98	16-Aug-23	1 / IR	4511.50			4602				Complied
21 AD: AD/GENERAL/025	IR	Engine Exhaust Operated Cabin Heater - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
21 SL: MTL-21-01	IR	Air Conditioning - Inspection of The Cabin Altitude and Differential Pressure and the Cabin Rate of Climb Indicators for Installed Shipping Plugs	FL-269		10-Sep-19	23-Jan-25	1 / IR	4740.80			4811				Complied
21 SL: MTL-21-02	IR	Air Conditioning - Electric Heater Thermal Fuse Replacement	FL-269		10-Nov-21	23-Oct-23	1 / IR	4551.50			4651				Complied
21 SL: MTL-21-03	IR	Air Conditioning - Cockpit Foot Warmer Duct Inspection	FL-269		08-Aug-23	23-Oct-23	1 / IR	4551.50			4651				Complied
21 SL: MTL-21-04	IR	Air Conditioning - Lower Cabin Environmental Ducting Sleeve Replacement	FL-269		11-Feb-25	27-Mar-25	1 / IR	4777.20			4839				Complied
21 SB: SB 21-3303	1	Air Conditioning - Installation of New Compressor Drive Quill Shaft	FL-269		23-Oct-23	1 / 1		4551.50			4651				Complied
21 SB: SB 21-3838	IR	Environmental Systems - Introduction of Improved Environmental Controller	FL-269		01-May-08	23-Oct-23	1 / IR	4551.50			4651				Complied
21 SB: SB 21-3932	IR	Air Conditioning - Improved Air Conditioner Compressor Mounting Brackets (Kit 130-9702)	FL-269		01-Mar-09	23-Oct-23	1 / IR	4551.50			4651				Complied
21 SB: SB 21-4165	IR	Air Conditioning - Duct Plug Inspection	FL-269		09-Aug-16	23-Oct-23	1 / IR	4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
21 SB: SB 2166	IR	Environmental/Air Conditioning - Inspection of the Air Conditioning Receiver/Drier	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
21 SB: SB 2285	IR	Environmental/Air Conditioning - Installation of Overboard Pressurization Dump Kit	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
21 SB: SB 2484	1	Environmental/Air Conditioning - Outflow/Safety Valve Inspection/Replacement	FL-269		23-Oct-23	1 / 1		4551.50			4651				Complied
21 SB: SB 2676	IR	Environmental/Air Conditioning - Pressurization Control System Pneumatic Tubing Inspection/Repair	FL-269		01-Jan-97	23-Oct-23	1 / IR	4551.50			4651				Complied
22 AD: 2022-03-23	IR	Rudder Control System - GSA 9000 Yaw Servo Software Update	FL-269		28-Feb-22	16-Aug-23	1 / IR	4511.50			4602				Complied
22 AD: 2024-14-03	IR	Garmin GFC 500 Autopilot System installed per STC SA01866WI - Software Update	FL-269		20-Aug-24	24-Jan-25	1 / IR	4740.80			4811				Complied
22 AD: AD/GENERAL/018	1	Automatic Pilot Limitation Placard - Installation - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
22 AD: AD/GENERAL/044	IR	Autopilot Pitch Switch Placard - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/GENERAL/045	2	Mitchell Automatic Pilot Servo Bridle Cable Clamp - Replacement	FL-269		30-Sep-70	20-Oct-22	1 / 2	4394.40			4424				Complied
22 AD: AD/INST/007	IR	H14 Automatic Pilot Servo Housing - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/011	IR	Automatic Pilot Servo Actuators - Inspection	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/012	IR	SEP 6 Automatic Pilot Roll Computer Clutch Circuit - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/013	IR	Venting of SEP 2 Servomotor Clutches - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/014	IR	SEP 6 Automatic Pilot Pitch Computer Clutch Circuit - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/015	IR	AP106 Automatic Pilot Gain Programmer Type 161H-1 - Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
22 AD: AD/INST/019	IR	ARC PA 500A Actuators - Cessna Auto Pilot, AFCS & Yaw Damper - Inspection and Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/020	IR	Sep 2 Automatic Pilot Trim Servomotor Venting - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/021	IR	King KFC200 - IAFCS - Bridle Cable Clamps - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/026	IR	Navomatic 200A Automatic Pilot Computer - Amplifier Nav Input - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/028	IR	A.R.C. PA1050A Actuator and DA-1050A Decoupler Adapter - Cessna 1050A I.F.C.S. - Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/029	IR	Bendix M-4 (A,B,C,D) Automatic Flight Control System Servo - Inspection and Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/030	IR	King KAP 100/KAP 150/KFC 150 Flight Control System	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/033	1	King KAP/KFC 200 Autopilot - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
22 AD: AD/INST/034	IR	Honeywell SP-300 DFCS Mode Control Panel - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/035	IR	Collins APP-80/80A Autopilot Panel - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/036	IR	Collins ALI-80( ) Barometric Altimeter - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/037	IR	Altitude Preselector/Alerter - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/042	IR	KSA 470 Autopilot Servo Actuator	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/044	IR	KAP 140 and KFC 225 Autopilot Systems	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
22 AD: AD/INST/047	1	KC 225 AFCS	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
22 AD: G-2024-0002	IR	ATA 22 - Auto Flight / AFM - Category III Automatic Landing - Operational Limitation	FL-269		26-Jun-24	10-Jan-25	1 / IR	4740.80			4811				Complied
22 SB: MTB-22-01	IR	Auto Flight - Model B300/B300C Guard Mode Activation	FL-269		09-Jul-25	22-Oct-25	1 / IR	4915.70			4946				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
22 SL: MTL-22-02	IR	Auto Flight - Transmittal Of Innovative Solutions And Support INC Recall Notice RN2203	FL-269		02-Dec-22	23-Oct-23	1 / IR	4551.50			4651				Complied
22 SB: SB 22-3180	1	Auto Flight - Announcement of an Airworthiness Directive Against Allied Signal Aerospace Bendix/King Model KSA 470 Autopilot Servo Actuators	FL-269		01-Apr-98	23-Oct-23	1 / 1	4551.50			4651				Complied
22 SB: SB 22-3955	1	Autopilot - Reduction of Nuisance Pitch Trim Wheel Movement Per STC SA01502WI-D	FL-269			23-Oct-23	1 / 1	4551.50			4651				Complied
22 SB: SB 2423	IR	Auto Flight - Modification of Collins EFIS-85B (14) Electronic Flight Instrument System and APS-65H Autopilot Wiring	FL-269		01-Dec-91	23-Oct-23	1 / IR	4551.50			4651				Complied
23 AD: 2010-0003	2	Navigation - Mode S Transponder Aircraft Type Mode Strapping - Check / Modification	FL-269		14-Oct-14	20-Oct-22	1 / 2	4394.40			4424				Complied
23 AD: 2010-0186	IR	Communication - Very High Frequency (VHF/AM) Transceiver - Modification	FL-269		22-Sep-10	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2010-0204	1	Navigation Systems - Mode-S Transponder - Modification / Replacement	FL-269		20-Oct-10	20-Oct-22	1 / 1	4394.40			4424				Complied
23 AD: 2010-07-02	IR	Honeywell Primus II RNZ-850 or - 851 Integrated Navigation Units	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2011-0043	IR	Mode-S Transponder Control Panels - Modification	FL-269		30-Mar-11	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2011-0103	IR	Equipment / Furnishings - Emergency Locator Transmitter (ELT) Antenna - Modification / Replacement	FL-269		03-Jun-11	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2011-0239	IR	Navigation - Radio Altimeter Indicator- Modification	FL-269		29-Dec-11	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2012-02-08	IR	TCAS Software update for ACSS TCAS Equipment	FL-269		13-Mar-12	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2012-14-15	IR	Honeywell KGS200 WAAS GNSSU	FL-269		19-Jul-12	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2014-0088	IR	Communications - Cockpit Voice Recorder - Replacement	FL-269		15-Apr-14	20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
23 AD: 2014-0095	1	Equipment/Furnishings - Crash Position Indicator - Modification & Aircraft Flight Manual - Amendment	FL-269		12-May-14	20-Oct-22	1 / 1	4394.40			4424				Complied
23 AD: 2014-0125	IR	Equipment / Furnishings - Crash Position Indicator System - Replacement & Aircraft Flight Manual - Amendment	FL-269		22-May-14	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2014-05-27	IR	TPR-720 and TPR-900 Mode S Transponders Responding Intermittently to Mode S Interrogations	FL-269		02-May-14	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2014-18-01	IR	Rockwell Collins TDR-94 and TDR-94D Mode select (S) Transponders - Navigation	FL-269		14-Oct-14	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2015-0093	IR	Navigation - Attitude Heading Reference System - Modification / Replacement	FL-269		10-Jun-15	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2015-10-51	IR	Avidyne Integrated Flight Displays (IFDs) - Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2017-11-11	IR	NavWorx Automatic Dependent Surveillance Broadcast (ADS-B) Unit	FL-269		11-Jul-17	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2017-22-14	IR	Rockwell Collins TSS-4100 Traffic Surveillance System Processing Units - TSSA-4100 Field Loadable Software (FLS)	FL-269		20-Dec-17	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2018-0247	IR	Navigation - Trig Avionics, Avidyne Corporation, BendixKing / Honeywell Mode S Transponders - Inspection / Modification	FL-269		27-Nov-18	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: 2019-0004	1	Thales GPS/SBAS Receiver Topstar 200 LPV - Navigation - Global Navigation Satellite System - Operational Limitations	FL-269		25-Jan-19	20-Oct-22	1 / 1	4394.40			4424				Complied
23 AD: 2019-12-09	N/A	Rockwell Collins FDSA-6500 Flight Display System - AFM Revision / Placard Installation - TCAS Flight Operations TA/RA Mode Prohibition	FL-269		23-Jul-19	20-Oct-22	1 / N/A	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
23 AD: 2021-05-17		IR Rockwell Collins FDSA-6500 Flight Display System - AFM Revision / Placard Installation - TCAS Flight Operations TA/RA Mode Prohibition	FL-269		23-Jul-19	20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/GENERAL/005		IR Radio Installation - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/GENERAL/009		IR 3-LU. 88B Marker Receivers - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/GENERAL/042		IR Microphone/Compass Safe Distance - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/GENERAL/053		IR Flight Data Recorder Underwater Locating Device - Installation - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/GENERAL/058		IR Voice Recorders - Attachment of Reflective Strips - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/GENERAL/072		1 Mobile Cellular Telephone Installations - Cancelled	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
23 AD: AD/RAD/001		IR Bendix Transmitters, Type TA-2 Series - Modular Connecting Lead - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/002		IR Bendix Transmitters, Type TA-2 Series - Sub-Panel Cover Plate - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/003		IR Collins Transmitter, Type 18S-1, 2 and 3 - Replacement of Resistor R209 - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/004		IR Bendix D.F. Receiver Mechanical Filter Circuit - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/005		IR Collins Glide Slope Receivers, Flag Alarm and Deviation Circuits - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/006		IR Bendix VHF Nav. Receivers, Flag Alarm and Deviation Circuit Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/007		IR Marconi Automatic Loops - Capacitor Insulation - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/008		IR Channel Tuning Mechanism AWA VHF Nav/Com Receiver AD704 - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
23 AD: AD/RAD/009	1	Rexair Amspeaker - Fuse Installation - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23 AD: AD/RAD/010		IR VHF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/011	2	VHF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
23 AD: AD/RAD/012		IR HF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/013	1	VHF Transceiver Circuit Protection - Modification - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23 AD: AD/RAD/014		IR HF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/015		IR Localiser Flag Circuit - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/016		IR Localiser and Glide Slope Flag Circuit - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/017		IR AWA VC-10 VHF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/018		IR Aircom VHF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/019		IR "Aircom" VHF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/020		IR King VHF - KTR-900 Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/021		IR Instrument Landing Systems (ILS) Instrumentation - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/022		IR Press-to-Talk Assembly - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/023		IR Pantronics/Cessna HF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/024		IR Sunair HF Transceiver Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/025		IR Bayside VHF Transceiver Modification or Retirement - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/026	1	Leigh Emergency Locator Transmitter Systems - Modification - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
23	AD: AD/RAD/027	IR Chromalloy Rescue Locator Beacon - Withdrawal from Service - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/028	IR Garrett Rescue 88A Crash Locator Beacon - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/029	IR Sunair HF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/030	IR Sunair HF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/031	IR Sunair HF Transceiver - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/032	IR Garrett Emergency Locator Transmitter - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/033	IR Radio Magnetic Indicator - Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/034	IR Sunair HF Transceiver - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/035	1 Emergency Locator Transmitters and Crash Locator Beacons - Inspection - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23	AD: AD/RAD/036	1 Collins ADF Type ADF-650 - Operation From 27.5 Volt Supply - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23	AD: AD/RAD/037	IR Narco VHF NAV OBS Gear Assembly - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/038	IR Collins ATC Transponder TDR-950 - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/039	1 Lithium-Sulphur Dioxide Batteries - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23	AD: AD/RAD/040	IR Narco ADF-141 - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/041	IR Fairchild Cockpit Voice Recorder - Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/042	IR Sunstrand Cockpit Voice Recorders - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23	AD: AD/RAD/043	6 ATC Transponder Systems with Active Mode C - Cancelled	FL-269		20-Oct-22	1 / 6		4394.40			4424				Complied
23	AD: AD/RAD/044	IR Collins DME-42 Distance Measuring Equipment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
23 AD: AD/RAD/045		IR King KDM 7000B Distance Measuring Equipment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/046		IR Bendix/King VN 411B VHF Nav Receiver- Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/048		IR Collins TCAS II and TCAS 94 Systems	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/049		IR Collins TPR-720 ATC Radar Beacon System/Mode S Transponders	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/050		1 Periodic Maintenance of Emergency Locator Transmitters - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23 AD: AD/RAD/051		1 Rockwell International/Collins Aviation Division TDR-94D Transponder	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23 AD: AD/RAD/052		IR Rockwell International, Collins Air Transport Division DME-700	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/053		IR Australian Domestic Distance Measuring Equipment - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/054		IR Terra Transponders	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/055		IR Rockwell International, Collins Air Transport Division, TCAS II Processors - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/056		IR Honeywell, Commercial Flight Systems Group, TCAS II Processors - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/057		IR AlliedSignal, Air Transport Avionics TCAS II Processors - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/058		1 AlliedSignal CAS-81 TCAS II	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23 AD: AD/RAD/059		IR Centaurus Ground Proximity Warning System	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/060		1 GNS-XLS/GNS-XL Warning Placard	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23 AD: AD/RAD/061		IR GPS Installation for Non-Precision Approaches - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/062		IR KLN 89B RAIM Warning	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/063		IR KT 76A ATC Transponder	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
23 AD: AD/RAD/064		1 Skywatch SKY497	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
23 AD: AD/RAD/065		IR VN 411B VHF Navigation Receiver	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
23	AD: AD/RAD/066	IR Mode S Altitude - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/067	IR Skyforce Avionics Skymap and Tracker II Units	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/068	2 Mode C Transponder Altitude Checks - Cancelled	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
23	AD: AD/RAD/069	IR AlliedSignal RIA-32A ILS Receiver	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/070	IR Aerodata AeroNav II and III Display Units	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/071	IR Chelton VOR/LOC High Pass Filter Type 7-429/1	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/072	IR Apollo SL30 VHF NAVCOM	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/073	IR Rockwell Collins CTL-92 Transponder Control Panel	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/074	IR Garmin GNS 430	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/075	IR TDR-94/TDR-94D Transponders	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/076	1 Honeywell Primus II RNZ-850 or -851 Integrated Navigation Units - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
23	AD: AD/RAD/077	1 Goodrich Avionics Systems TAWS8000	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
23	AD: AD/RAD/078	IR Becker AR4201 VHF Transceiver	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/079	1 Thales Avionics TA/RA VSI-TCAS Indicator	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
23	AD: AD/RAD/080	IR AT150 Transponder	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/081	1 Garmin Mode S Transponders	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
23	AD: AD/RAD/082	IR Prevent GPS Navigation unit from Providing Erroneous Cross-Deviation	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/083	IR Honeywell MST 67A Transponder	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/084	IR Honeywell RCZ-83( ) and RCZ-85( ) Communications Units - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
23	AD: AD/RAD/085	1 Sandel ST3400 Terrain Awareness Warning System/Radio Magnetic Indicator	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
23	AD: AD/RAD/086	IR Caledonian Airborne Systems CPT-600/900 Emergency Locator Transmitters	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
23 AD: AD/RAD/087	1	Thales VHF Data Radios	FL-269		15-Feb-07	20-Oct-22	1 / 1	4394.40			4424				Complied
23 AD: AD/RAD/088	IR	Honeywell Communications and Mode S Transponder Units	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/089	IR	Funwerk Avionics GmbH TRT800A and TRT800H Transponders	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/090	IR	FreeFlight Systems 2101 I/O Approach Plus GPS Navigation System	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/RAD/091	1	Rockwell Collins TDR-94/94D Transponder - Air/Ground Discrete Inputs	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
23 AD: AD/RAD/092	2	Rockwell Collins TDR-94/94D Transponder/Honeywell AZ800/810 Air Data Computer Selected Altitude Data Inputs	FL-269			20-Oct-22	1 / 2	4394.40			4424				Complied
23 AD: AD/RAD/093	IR	Rockwell Collins TDR-94/94D Transponders - Aircraft Type Category - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: AD/REC/002	1	Fairchild Cockpit Voice Recorder - Inspection and Modification	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
23 AD: AD/REC/003	1	Sundstrand Cockpit Voice Recorders - Modification	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
23 AD: AD/REC/004	IR	Fairchild Model F800 Digital Flight Data Recorders Central Processor Unit - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: CF-2009-44	IR	Honeywell ASCa / Allied Sinal Aerospace Canada RESCU 406S Emergency Locator Transmitter	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
23 AD: CF-2013-25	IR	Emergency Locator Transmitter - Battery Wiring Installation Discrepancies (Replaces FAA AD 2013-18-09)	FL-269		26-Aug-13	20-Oct-22	1 / IR	4394.40			4424				Complied
23 SB: SB 23-3270	IR	Communications - International Civil Aviation Organization (ICAO) Requirement For 8.33 KHZ VHF Comm Spacing (Raytheon Aircraft Company STC ST00782WI-D)	FL-269		01-Jul-99	22-Dec-23	1 / IR	4555.70			4654				Complied
23 SB: SB 23-4175	1	Communications - Audio Storage and Playback Unit (ASPU) Configuration Change	FL-269		17-Jan-19	23-Oct-23	1 / 1	4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
23	SB: SB 2715	IR Communications - Replacement of the A017 Component Printed Circuit Board	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
24	AD: AD/ELECT/001	IR Relay - Leach - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/003	IR Circuit Breakers - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/011	1 Leach Relays - Control Terminal Insulation - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
24	AD: AD/ELECT/022	IR Wood Electric Corp. Circuit Breakers - Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/023	IR Nickel Cadmium Batteries with Polystyrene Cell Cases - Inspection and Replacement - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/024	1 Prestolite Alternator Fan - Replacement - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
24	AD: AD/ELECT/026	IR Nickel Cadmium Batteries - Double D Washers - Inspection and Removal - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/037	2 JET Electronics and Technology Inc. Standby Power Supply - Modification	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
24	AD: AD/ELECT/043	IR J.E.T. Emergency Power Supply - Inspection/Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/045	IR Aircraft Batteries - Exide Type 6AC9 and 6AC11 - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/048	3 Mechanical Products Inc - Circuit Breakers	FL-269		20-Oct-22	1 / 3		4394.40			4424				Complied
24	AD: AD/ELECT/050	IR Rebling Nickel Cadmium Battery Quick Disconnect Receptacles - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/051	1 SAFT 40AH Type 40976 Batteries	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
24	AD: AD/ELECT/052	IR Bruce Industries Fluorescent Lamp Ballast	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
24	AD: AD/ELECT/055	2 Texas Instruments Circuit Breakers	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
24	AD: AD/ELECT/056	1 Cabin Fluorescent Lighting System Components	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
24	AD: AD/ELECT/058	IR SAFT 1606-1 Batteries	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
24	AD: AD/ELECT/065	IR Marathon Power Technologies PC-250 Static Inverter - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
24	AD: AD/ELECT/071	IR SAFT America Inc. Nickel Cadmium Batteries	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
24	AD: AD/GENERAL/001	IR Electrical Switch - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
24	AD: AD/GENERAL/039	3 Generator System Warning Placard - Installation	FL-269			20-Oct-22	1 / 3	4394.40			4424				Complied
24	AD: AD/GENERAL/051	IR Electrical External Power Connection - Inspection - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
24	SB: MTB-24-01	IR Electrical Power - Enhanced Clearance for Pedestal Wire Harness	FL-269		06-Dec-18	22-Oct-25	1 / IR	4915.70			4946				Complied
24	SB: SB 24-3058	1 Electrical Power - Ground Interphone Amplifier	FL-269			23-Oct-23	1 / 1	4551.50			4651				Complied
24	SB: SB 24-3181	IR Electrical - Generator Control Unit Inspection/Replacement	FL-269		01-Jul-02	22-Oct-25	1 / IR	4915.70			4946				Complied
24	SB: SB 24-3245	IR Electrical Power - Relocation of the Landing Gear 60 AMP Circuit Breaker and Improvements to the Inboard Wing Leading Edge Inlet Duct	FL-269		01-Apr-99	23-Oct-23	1 / IR	4551.50			4651				Complied
24	SB: SB 24-3546	IR Electrical - Replacement of the "00" AWG Wire Harness Assembly	FL-269		01-Apr-03	23-Oct-23	1 / IR	4551.50			4651				Complied
24	SB: SB 24-3681	IR Electrical Power - Inspection of External Power Relay	FL-269		01-Oct-00	17-Aug-23	1 / IR	4511.50			4602				Complied
24	SB: SB 24-3937	IR Electrical Power - Discharge of Main Airplane Battery	FL-269		01-Jun-09	23-Oct-23	1 / IR	4551.50			4651				Complied
24	SB: SB 24-4017	IR Electrical Power - Inspection/Replacement of External Power Control Circuit Breaker	FL-269		01-Oct-00	17-Aug-23	1 / IR	4511.50			4602				Complied
24	SB: SB 2611	IR Electrical Power - Flight Control System (FCS) Circuit Breaker Replacement for Airplanes Equipped with a Collins APS-65 Autopilot System	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
25	AD: 2010-0009-E	IR Emergency Parachutes Thinback T104 and Slimpack T204	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25	AD: 2011-0094	IR Equipment and Furnishing – Life Jacket Vacuum Bag – Modification	FL-269		06-Jun-11	20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
25 AD: 2011-0098		IR Equipment & Furnishings - Passenger Seat - Replacement	FL-269		01-Aug-11	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2011-12-01		IR Equipment & Furnishings - Passenger Seat - Replacement	FL-269		01-Aug-11	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2011-25-01		IR Apical Industries Emergency Float Kits	FL-269		17-Jan-12	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2012-0038		IR Equipment & Furnishings - Passenger Seat Backrest Link - Inspection / Replacement	FL-269		26-Mar-12	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2012-06-25		IR Apical Industries Emergency Float Kits	FL-269		04-May-12	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2013-0020		4 Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement	FL-269		11-Jul-14	20-Oct-22	1 / 4	4394.40			4424				Complied
25 AD: 2013-005-E		IR Inspection of Ejection Seat Drogue Shackle Connection to Scissor Shackle	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2014-0187		IR Equipment & Furnishings - Safety Belt Attachment Bolts - Inspection / Replacement	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2014-0279		IR Equipment / Furnishing - Restraint System Rotary Buckle Sub-Assembly - Identification / Replacement	FL-269		02-Jan-15	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2016-0026		IR Equipment / Furnishings - Emergency Parachute Rubber Bands - Replacement	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2016-0062		IR Equipment / Furnishings - Emergency Parachute Harness - Modification	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2016-0163		IR Equipment / Furnishings - Cabin Attendant Seat - Modification / Replacement	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2016-0210		IR Equipment / Furnishings - Seat Energy Absorber Assembly - Replacement	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2017-0192		IR Equipment & Furnishing - Recaro Model 3510A and 3510D Passenger Seats - Modification	FL-269		12-Oct-17	20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
25 AD: 2017-0225		IR Equipment / Furnishings - Schroth Safety Products Seat Restraint Systems - AFM Amendment / Modification	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: 2017-09-09		IR Zodiac Seating Systems - Removal from Service	FL-269		28-Jun-17	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2018-0195		IR Equipment / Furnishings - Restraint Systems Rotary Buckle Sub Assembly - Removal from Service	FL-269		04-Sep-18	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2018-0223		IR Equipment / Furnishing - Seat Energy Absorber Assembly - Modification	FL-269		31-Oct-18	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2018-0262		N/A Equipment / Furnishings - Pilot and Co-pilot Seats - Modification / Inspection	FL-269		20-Dec-18	20-Oct-22	1 / N/A	4394.40			4424				Complied
25 AD: 2018-0264		1 AvioInteriors Centaurus Passenger Seats - Equipment / Furnishings - Life Vest Pouch - Inspection	FL-269		21-Dec-18	20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: 2018-23-12		IR Zodiac Aero Evacuation Systems - Fusible Plugs	FL-269		28-Dec-18	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2019-0010		IR Zodiac Aerosafety Systems (Aerazur) Life Jacket / Infant or Small Child Life Jacket - Removal / Repair	FL-269		23-Jan-19	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2020-0272		IR Schroth 4 Point Harness System P/N 18-()-() - Equipment / Furnishings - Buckle - Modification / Replacement	FL-269		09-Dec-20	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2021-0137		1 Safran 191 Series Seats - Equipment / Furnishings - Pilot and Co-pilot Seats / Longitudinal Locking System Pins - Measurement / Adjustment	FL-269		22-Jun-21	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2021-07-13 [Part: {e}1]		IR Pacific Scientific Rotary Buckle Assembly P/N 1111430 and 1111475	FL-269		11-May-21	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2021-09-09		IR Uninsured United Parachute Technologies Vector 3 SE Parachute Containers - Reserve Pin Covers	FL-269		16-Apr-21	20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
25 AD: 2022-0017-E		IR ATA 25 – Equipment / Furnishings – Emergency Parachutes – Removal from Service	FL-269		28-Jan-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2022-0018-E		IR ATA 25 – Equipment / Furnishings – Emergency Parachutes – Removal from Service	FL-269		31-Jan-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: 2022-0029-E		1 ATA 25 – Equipment / Furnishings – Emergency Parachutes – Removal from Service / Modification	FL-269		23-Feb-22	20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: 2024-01-11		IR All Helicopters - Pacific Scientific Rotary Buckle Assemblies (FAA Certified Helicopters Only)	FL-269		15-Feb-24	27-Mar-24	01 / IR	4565.90			4665				Complied
25 AD: 2024-20-04		IR Pacific Scientific Company Rotary Buckle Assembly P/N 1111475 or 1111548-01 - Inspection / Replacement	FL-269		12-Nov-24	10-Jan-25	1 / IR	4740.80			4811				Complied
25 AD: 2024-26-02 [Part: (g)1]		IR Pacific Scientific Rotary Buckle Assembly P/N 1111430 and 1111475	FL-269		07-Mar-25	27-Mar-25	1 / IR	4777.20			4839				Complied
25 AD: 2025-16-09 [Part: (g)]		IR Pacific Scientific Rotary Buckle Assembly P/N 1111475 or 1111548-01 - Screws - Inspection/Replacement	FL-269		22-Sep-25	22-Oct-25	1 / IR	4915.70			4946				Complied
25 AD: AD/BEECH 300/006		IR Cabin Seat Frame	FL-269		31-Mar-94	16-Aug-23	1 / IR	4511.50			4602				Complied
25 AD: AD/BEECH 300/019		IR Passenger Seat Modification	FL-269		23-Nov-06	16-Aug-23	1 / IR	4511.50			4602				Complied
25 AD: AD/ELECT/069		IR Steam Oven Motor Relay	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/EMY/001		IR Single Chamber Inflatable Life Jackets - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/EMY/003		1 Inflatable Escape Slides - Modification	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: AD/EMY/004		7 Life Rafts	FL-269			20-Oct-22	1 / 7	4394.40			4424				Complied
25 AD: AD/EMY/005		1 Life Jackets - Modification	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: AD/EMY/006		IR Inflatable Escape Slides - Modification	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/EMY/007		IR Life Jackets - Inspection	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/EMY/008		IR Life Jackets - Inspection and Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
25 AD: AD/EMY/009		IR Life Jackets - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/011		IR Patten/Pan Avion Inflatable Escape Slides - Modification	FL-269		31-Oct-75	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/EMY/012		IR Beaufort Operating Mechanism C.1855 (P/N ME 48) - Inspection and Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/013		IR Aircruisers Discharge Valves - Inspection	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/014		IR Aircruisers 6, 10, 25 & 35 Man Life Rafts - Inspection and Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/015		IR Life Jacket Inflation Mechanism P/Nos. WKA. 36044 and WKA. 35153 - Inspection	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/017		IR Life Jackets - Retirement - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/018		IR Life Jackets - Inspection	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/019		IR Life Jackets - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/020		IR Life Jackets - Pressure Test	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/021		IR Life Jackets (RFD) - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/022		IR Switlik Life Jackets and Flotation Devices - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/023		IR Aerazur Life Rafts	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/024		IR Aerazur Life Rafts	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/025		IR Emergency Evacuation Slide	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/026		IR Emergency Evacuation Slide	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/027		IR Aerazur Lifejackets	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/028		IR Aerazur Liferaft	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/029		IR RFD Liferaft	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/030		IR Dunlop-Beaufort Mk 28 Lifejacket	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/031		IR Aerazur Life Raft Type 606	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/032		IR This AD Not Issued	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/EMY/033		1 Emergency Evacuation Slide/Raft	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
25 AD: AD/EMY/034	1	Emergency Evacuation Slide/Raft - Pressure Relief Valves - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: AD/EMY/035		IR Life Vest Valise Zipper	FL-269		05-Jun-08	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/EMY/036		IR Evacuation Systems - Corroded Shear-Pin Restraints	FL-269		05-Jun-08	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/003	1	Flight Manual Stowage Requirements - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: AD/GENERAL/004	4	Aircraft Exits - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 4	4394.40			4424				Complied
25 AD: AD/GENERAL/008		IR GNM Agricultural Harness - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/010		IR Aviorex Harness - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/012		IR GNM Agricultural Harness - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/014		IR Aerolex (Harley) Safety Belt Attachment - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/015		IR Seat and Occupant Restraint Strength Standards - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/024		IR Stretcher Installation - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/028		IR Safety Belt and Harness Installations - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/030	1	Agricultural Aeroplanes - Safety Harness Installation - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: AD/GENERAL/034		IR Safety Harnesses - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/035	2	Restraint and Stowage of Cargo and Equipment - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 2	4394.40			4424				Complied
25 AD: AD/GENERAL/036		IR Seat Belts and Safety Harnesses - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/040		IR Teco Aircraft Seats - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/GENERAL/060	1	Flight Crew Compartment Seats - Safety Harness - Modification - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: AD/GENERAL/061	2	Cabin Attendant Seats - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 2	4394.40			4424				Complied
25 AD: AD/GENERAL/063	1	Flammability Requirements - Aircraft Seat Cushions - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 1	4394.40			4424				Complied
25 AD: AD/GENERAL/064	2	Side Facing (SF) Seats - Improved Occupant Restraint - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 2	4394.40			4424				Complied
25 AD: AD/GENERAL/066	1	Floor Proximity Escape Path Marking - Cancelled	FL-269		20-Oct-22	20-Oct-22	1 / 1	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
25 AD: AD/GENERAL/067	3	Passenger Safety Harnesses - Cancelled	FL-269		20-Oct-22	1 / 3	4394.40				4424				Complied
25 AD: AD/GENERAL/068	4	Cabin Interior Materials - Cancelled	FL-269		20-Oct-22	1 / 4	4394.40				4424				Complied
25 AD: AD/GENERAL/070	1	Cargo and Baggage Compartment Liner - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/GENERAL/071	1	Helicopter Occupant Harnesses - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/GENERAL/073	IR	Access to Type III Exits - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/GENERAL/074	1	Front Seat Occupant Restraint Installation - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/GENERAL/075	IR	AD/GENERAL/75 - This AD still to be issued	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/GENERAL/076	2	Class D Cargo Compartments Re-classification - Cancelled	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
25 AD: AD/GENERAL/084	2	Thermal/Acoustic Insulation Materials - Cancelled	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
25 AD: AD/GENERAL/085	IR	Improved Seats in Transport Category Aeroplanes - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/001	IR	GQ Security Aeroconical (SAC) Parachutes	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/002	IR	GQ Types 350, 850 and 4.8m SAC Parachutes	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/003	IR	PA Safety Systems Pigmee	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/004	IR	Rigging Innovations Skyhook Reserve Pilotchute	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/005	IR	Parachutes De France - Connector Links	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/006	IR	Vector Amp Fitting	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/007	2	MarS ATL-88 Parachutes	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
25 AD: AD/PARA/008	IR	STRATOS JU-40 Parachutes	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/009	IR	Emergency Parachute Opening Mechanism	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/010	1	PDF Techno 240 Emergency Parachute	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/PARA/011	IR	CAPEWELL Parachute Equipment	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/012	1	Parachutes de France - Emergency Parachutes	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
25 AD: AD/PARA/013	IR	MarS Emergency Parachute Ripcord Pin	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/014	1	OMEGA / QUICK Personal Parachute	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/PARA/015	1	VEGA 120 Type Reserve Canopy	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/PARA/016	2	Techno 240-B Reserve Parachute	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
25 AD: AD/PARA/017	1	Parachute Shop Parachutes	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/PARA/018	IR	VIGIL Parachute Automatic Activation Device - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/PARA/019	IR	Emergency Parachute	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/RES/001	IR	Safety Belt - Mills ME 2095 - Modification - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/RES/002	IR	Inertia Reels - AN-R-29 - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/RES/003	IR	Safety Belts - Davis FDC-2700 - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/RES/004	IR	Aerolex (Harley) Safety Belt Attachment - Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/RES/005	1	Inertia Reels - AN-R-29 - Replacement - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/RES/006	IR	Safety Belts - Mills ME 2402 and ME 2402T - Inspection and Rectification - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/RES/007	2	Safety Harness Buckles MS22013 and 44B26452 - Modification - Cancelled	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
25 AD: AD/RES/008	IR	Inertia Reels - Pacific Scientific Part No ASSY0107119 - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/RES/009	IR	Unapproved Safety Belts and Harnesses - Removal From Service - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
25 AD: AD/RES/010	4	Indiana Mills Safety Belts - Cancelled	FL-269		20-Oct-22	1 / 4	4394.40				4424				Complied
25 AD: AD/RES/011	1	Eon Corporation E8000 Buckle Assemblies - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
25 AD: AD/RES/012	1	Safety Harness Buckle - Pacific Scientific Rotary	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
25 AD: AD/RES/013	1	Teleflex Morse Inertia Reels - Modification	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/RES/014	IR	Integral Buckle Assembly, Pacific Scientific P/N 1107261-01, -05, -09 Replace Lower Cover P/N 1107270-01 with Cover Assembly P/N 1107525-01	FL-269		31-Aug-83	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/RES/015	IR	Pacific Scientific Dual Tension Reel Assembly P/Nos 0109101-01, -03, -05, -07 - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/016	IR	Safety Harness End Fittings - Davis Aircraft Products P/N FD 1497M - Removal From Service - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/017	1	American Safety Equipment Lap Belt/Shoulder Harness and/or Crotch Strap Buckle/Adaptor - Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/RES/018	IR	Securaiglon (Ex L'Aiglon) Safety Belts - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/019	IR	Am-Safe Harness Buckle Assemblies	FL-269		09-Apr-87	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/RES/020	1	Eon Corporation E6000 Buckle Assemblies	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/RES/021	IR	Pacific Scientific Lap Belt Assemblies	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/022	1	Pacific Scientific Buckle - Agricultural Aircraft - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/RES/023	1	Davis FDC-6400B Series Safety Belts	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/RES/024	IR	Aeronautique Seat Belts and Harnesses - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/025	IR	Seat Mounted Cargo Containers - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/026	IR	AMI Industries Pilot Lap Belt Attachment Link	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/027	2	HEMCO Seat Belts and Harnesses - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
25 AD: AD/RES/028		IR Pacific Scientific Lift Lever Buckle Assemblies	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/029		1 Seat Belts and Harnesses - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/RES/030		IR Aeronautique Equipment Seat Belts, Harnesses and Cargo Restraint Equipment - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/031		IR Sutton Harness Inspection and Life	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/032		IR Aircraft Belts Inc - Buckle Assemblies	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/034		IR Horizontal Net SRFW HN1	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/RES/035		IR Pacific Scientific Plastic Rotary Buckle - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/001		IR Pilots Seat - Reinforcement	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/002		IR Enviroform Fibreglass/Kevlar Reinforced Seats	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/003		IR Sicma Passenger Seats - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/004		IR Historical and Ex-Military Aircraft - Harness Attachment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/005		IR Ipeco Crew Seats	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/006		N/A Aviatech Flight Crew Seats	FL-269		20-Oct-22	1 / N/A		4394.40			4424				Complied
25 AD: AD/SEATS/007		1 Flight Equipment and Engineering Seats Model 121	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/SEATS/009		IR PTC Seating Products Division B/E Aerospace Model 950	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/010		IR Sicma Aero Seat Leg Collars	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/011		IR First Class Seats Motor System Cable	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/012 [Part: 1 & 3]		IR Aviointeriors/Alven Seats - Seat Belt Attachment Misalignment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/013		1 SICMA AERO SEAT and FARNER Cabin Attendant Seats	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/SEATS/015		IR Sicma Aero Seat Passenger Seats - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/017		2 SICMA Passenger Seats - Seat Belt Attachment	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
25 AD: AD/SEATS/019		IR SICMA Passenger Seats (16g) - Backrest Links Inspection and Replacement - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/021		IR B/E Aerospace Seat - Hydrolock Pin Orientation	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/022		IR Sicma Aero Seat Passenger Seats	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/023		IR SICMA Passenger Seat Central Spreaders	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/024		1 RECARO Passenger Seat Type 3410 - Seat Belt Attachment	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/SEATS/025		IR Sicma Aero Seats Reading Light Power Supplies	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: AD/SEATS/026		IR Aviointeriors Passenger Seat Rear Fitting Attachment - Replacement	FL-269		23-Nov-06	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/SEATS/027		IR Equipment - Passenger Seats - Inspection of Seatbelt Shackle	FL-269		23-Nov-06	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: AD/SEATS/028		1 Passenger Seat Backrest - Replacement	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
25 AD: AD/SEATS/029		N/A Sicma Passenger Seat Inspection	FL-269		20-Oct-22	1 / N/A		4394.40			4424				Complied
25 AD: F-2012-007		IR Production of Parts Without Approval	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
25 AD: G-2021-0003		IR Equipment / Furnishings - Life Jacket - Inspection	FL-269		16-Jun-21	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: G-2021-0004		IR Equipment / Furnishings - Life Raft - Inspection	FL-269		05-Jul-21	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: G-2022-0009		IR ATA 25 - Equipment / Furnishings - Lifejackets - Inspection	FL-269		21-Apr-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: G-2022-0011		IR ATA 25 - Equipment / Furnishings - Pilot & Co-Pilot Seats - Inspection / Modification	FL-269		23-Jun-22	20-Oct-22	1 / IR	4394.40			4424				Complied
25 AD: G-2025-0002		1 Equipment / Furnishings - Pilot & Co-Pilot Seats - Inspection / Modification	FL-269		25-Apr-25	03-Jun-25	1 / 1	4827.10			4877				Complied
25 AD: G-2025-0005 [Part: (1)]		IR Equipment / Furnishings - Acro Series 9 Passenger Seats - Passenger Seats - Modification	FL-269		12-Sep-25	22-Oct-25	1 / IR	4915.70			4946				Complied
25 SB: MTB-25-01		IR Equipment/Furnishings - B300 Manual Window Shade Installation To Replace Electronic Window Shade	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
25 SL: MTL-25-02		IR Equipment/Furnishings - Aft Curtain Placard Inspection	FL-269		10-Sep-19	22-Oct-25	1 / IR	4915.70			4946				Complied
25 SL: MTL-25-04		IR Equipment/furnishings - Transmittal of Ipeco Service Bulletin 480-25-02 Free Play Reduction Product Improvement for Passenger Seats	FL-269			10-Jan-25	1 / IR	4740.80			4811				Complied
25 SB: SB 2443		IR Equipment/Furnishings - Inspection/Modification of Cabin Seat Frames	FL-269		01-Jul-93	23-Oct-23	1 / IR	4551.50			4651				Complied
25 SB: SB 25-3418		IR Equipment/Furnishings - Emergency Locator Transmitter (Elt) Placard Removal	FL-269		01-Nov-02	17-Aug-23	1 / IR	4511.50			4602				Complied
25 SB: SB 25-3640		1 Equipment/Furnishings - Cabin Swiveling Chair Frame Modification	FL-269		01-May-05	17-Aug-23	1 / 1	4511.50			4602				Complied
25 SB: SB 25-3919		IR Equipment/Furnishings - Crew Seat Inertial Reel Web Stop Installation	FL-269		01-Jul-09	23-Jan-25	1 / IR	4740.80			4811				Complied
25 SB: SB 25-4020		IR Equipment/Furnishings - Inspection/Replacement of Crew Chair Frame	FL-269		01-Jun-10	23-Oct-23	1 / IR	4551.50			4651				Complied
25 SB: SB 25-4031		IR Equipment/Furnishings - Installation of Omitted Inserts and Washers in Aft Baggage Partition	FL-269		01-Dec-11	23-Oct-23	1 / IR	4551.50			4651				Complied
25 SB: SB 25-4055		IR Equipment/Furnishings - Inspection/Replacement of Cabin Seat Swivel Assemblies	FL-269		01-Jan-11	23-Oct-23	1 / IR	4551.50			4651				Complied
25 SB: SB 2598 [Part: C/W]	2	Equipment/Furnishings - Emergency Locator Transmitter Placard Installation	FL-269		01-Dec-94	23-Oct-23	1 / 2	4551.50			4651				Complied
25 AD: UF-2012-003		IR AERAZUR - Pickable Textile Reserve Handle	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
26 AD: 2009-0251-E		IR Fire Protection - Portable Fire Extinguishers - Identification / Replacement	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
26 AD: 2009-0262	1	Fire Protection - Portable Fire Extinguishers - Identification / Replacement	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
26 AD: 2009-0278		IR Fire Protection - Portable Fire Extinguishers - Identification / Replacement	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
26 AD: 2010-0062	1	Fire Protection – Portable Fire Extinguishers – Identification / Replacement	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
26 AD: 2012-0037	IR	Fire Protection – Hand Operated Fire Extinguisher – Modification	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: 2016-0024	IR	Fire Protection – Optical and Ambient Smoke Detectors – Identification / Replacement	FL-269		26-Jan-16	20-Oct-22	1 / IR	4394.40			4424				Complied
26 AD: 2016-0044	IR	Fire Protection – Engine and Auxiliary Power Unit Automatic Fire Extinguishers – Inspection/Overhaul	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: 2020-21-02	IR	Kidde Aerospace and Defense Cargo Fire Extinguisher Halon Bottles - Inspection / Replacement	FL-269		19-Nov-20	20-Oct-22	1 / IR	4394.40			4424				Complied
26 AD: AD/FPE/001	IR	Graviner Automatic Fire Extinguisher Cartridges Mk 2 - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/002	IR	Walter Kidde Fire Extinguisher Stop Valve - Modification - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/003	IR	Walter Kidde Fire Extinguisher - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/004	IR	Automatic Fire Extinguisher - Graviner - Inspection and Replacement - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/005	IR	Automatic Fire Extinguisher Container - Graviner - Inspection and Replacement - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/006	7	Fire Extinguishant Systems - Cancelled	FL-269		20-Oct-22	1 / 7	4394.40				4424				Complied
26 AD: AD/FPE/007	IR	Kidde Water Based Fire Extinguisher Cartridge Holder - Inspection	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/008	1	Fire Bottle Discharge Cartridges - Inspection	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
26 AD: AD/FPE/009	IR	Portable Extinguisher Discharge Head Trigger	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/010	IR	Portable Fire Extinguisher	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/011	IR	Engine and Auxiliary Power Unit Fire Extinguishers - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
26 AD: AD/FPE/012	IR	Fire Extinguisher Bottle Cartridges - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/013	IR	First Technology Fire and Safety Toilet Compartment Fire Extinguishers	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/014	IR	Model T1-FM 100 Fire Extinguisher	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/015	IR	Overland Aviation Services Fire Extinguisher Cartridges	FL-269		18-Apr-02	20-Oct-22	1 / IR	4394.40			4424				Complied
26 AD: AD/FPE/016	IR	Removal of Kidde Fire Extinguishers P/N 898052 from Service	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
26 AD: AD/FPE/017	IR	Meggitt Safety Systems Model 602 Smoke Detectors	FL-269		11-May-06	20-Oct-22	1 / IR	4394.40			4424				Complied
26 AD: AD/GENERAL/016	3	Hand Portable Fire Extinguishers - Installation - Cancelled	FL-269		20-Oct-22	1 / 3	4394.40				4424				Complied
26 AD: AD/GENERAL/038	1	Portable Fire Extinguishers - Removal of Methyl Bromide, Carbon Tetrachloride and Antifyre Pistole Types - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
26 AD: AD/GENERAL/048	3	Fire Protection In Toilet Areas - Cancelled	FL-269		20-Oct-22	1 / 3	4394.40				4424				Complied
26 AD: AD/GENERAL/065	5	Hand Held Portable Fire Extinguishers - Cancelled	FL-269		20-Oct-22	1 / 5	4394.40				4424				Complied
26 SB: MTB-26-01	1	Fire Protection - Replacement of The Halon Type 1211 Portable Fire Extinguishers	FL-269		23-Oct-23	1 / IR	4551.50				4651				Complied
26 SL: MTL-26-01	1	Fire Protection - Fuselage Only Bleed Air Ethylene Vinyl Acetate (EVA) Inspection	FL-269		30-Oct-24	16-Jan-25	1 / IR	4740.80			4811				Complied
26 SL: MTL-26-02	IR	Fire Protection - Center Wing & Nacelle Bleed Air Warning Line Inspection	FL-269		07-Oct-25	22-Oct-25	1 / IR	4915.70			4946				Complied
26 SL: MTL-26-03	IR	Fire Protection - Bleed Leak Sense Line Pro Seal Inspection	FL-269		03-Jul-25	22-Oct-25	1 / IR	4915.70			4946				Complied
27 AD: 2025-20-11 [Part: (g)(1)]	IR	Rudder Control Pushrod Failure	FL-269		17-Oct-25	04-Nov-25	1 / IR	4915.70			4946				Complied
27 AD: AD/BEECH 300/012	IR	Elevator Trim Tab System	FL-269		25-Mar-99	16-Aug-23	1 / IR	4511.50			4602				Complied
27 AD: AD/BEECH 300/013	IR	Inspection for Flight Control Interference with Wiring	FL-269		19-May-99	16-Aug-23	1 / IR	4511.50			4602				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
27	AD: AD/BEECH 300/016	IR Elevator Balance Weight Attachment	FL-269		20-Feb-03	16-Aug-23	1 / IR	4511.50			4602				Complied
27	AD: AD/BEECH 300/021	IR Flight Control System	FL-269		02-Aug-07	16-Aug-23	1 / IR	4511.50			4602				Complied
27	AD: AD/GENERAL/026	IR Duplicate Inspection of Flying Controls - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
27	AD: AD/GENERAL/056	3 Cable Operated Control Systems - Duplicate Inspection - Cancelled	FL-269			20-Oct-22	1 / 3	4394.40			4424				Complied
27	SB: MTB-27-02	IR Flight Controls - Installation of Power Lever Position And Elevator Control Position Potentiometer Brackets With FDR Installed	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
27	SB: MTB-27-03	IR Flight Controls - Rudder Pedal Force Transducer Interference Improvement	FL-269		02-May-23	23-Oct-23	1 / IR	4551.50			4651				Complied
27	SL: MTL-27-01	IR Flight Controls - Control Column Master Link Aileron Interconnect Chain Inspection	FL-269		04-Oct-17	23-Oct-23	1 / IR	4551.50			4651				Complied
27	SL: MTL-27-02	IR Flight Controls - Inspection Of The Elevator Trim Tab Servo Bracket Assembly	FL-269		29-Jan-20	23-Oct-23	1 / IR	4551.50			4651				Complied
27	SL: MTL-27-04	1 Flight Controls - Aileron Position Transducer Connector Bracket Relocation	FL-269		19-Apr-23	23-Oct-23	1 / 1	4551.50			4651				Complied
27	SL: MTL-27-06	IR Flight Controls - Rudder Pedal Pushrod Linkage Inspection	FL-269		06-Feb-25	27-Mar-25	1 / IR	4777.20			4839				Complied
27	SL: MTL-27-07	IR Flight Controls - Pilot and Copilot Rudder Pedal Pushrod Linkage Inspection	FL-269		25-Jul-25	22-Oct-25	1 / IR	4915.70			4946				Complied
27	SB: SB 2136	IR Flight Controls - Improvement of The Asymmetrical Flap Mechanism	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
27	SB: SB 2620 [Part: Part II]	IR Flight Controls - Elevator Trim Tab Actuator Modification	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
27	SB: SB 2629	IR Flight Controls - Flap Rib Replacement	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
27	SB: SB 27-3038	IR Stabilizers - Inspection of Rudder Torque Shaft Support Bearing Retention Nut For Thread Engagement	FL-269		01-Mar-00	23-Oct-23	1 / IR	4551.50			4651				Complied
27	SB: SB 27-3044	IR Flight Controls - Trim Tab Actuator Lubrication Placard	FL-269		01-Apr-00	23-Oct-23	1 / IR	4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
27 SB: SB 27-3095	IR	Flight Controls - Addition Of Jumper Wire To Stall Warning Lift Computer	FL-269		01-Nov-01	17-Aug-23	1 / IR	4511.50			4602				Complied
27 SB: SB 27-3187 [Part: Part I]	1	Flight Controls - Elevator Adjustment Weights Installation/Modification	FL-269		01-Apr-01	23-Oct-23	1 / 1	4551.50			4651				Complied
27 SB: SB 27-3232	IR	Flight Controls - Inspection For Control Column Interference With Wiring Behind The Instrument Panel	FL-269		01-Mar-99	23-Oct-23	1 / IR	4551.50			4651				Complied
27 SB: SB 27-3492	IR	Flight Controls - Control Column Inspection/modification	FL-269		01-Oct-01	17-Aug-23	1 / IR	4511.50			4602				Complied
27 SB: SB 27-3668	1	Flight Controls - Inspection/Modification of Aileron Outboard Hinge Fitting	FL-269		01-Jun-04	17-Aug-23	1 / 1	4511.50			4602				Complied
27 SB: SB 27-3709	IR	Flight Controls - Addition of Jumper Wire to Stall Warning Lift Computer	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
27 SB: SB 27-3761	1	Flight Controls - Inspection of Flight Control System and Rigging	FL-269		01-Feb-06	23-Oct-23	1 / 1	4551.50			4651				Complied
27 SB: SB 27-4082	IR	Flight Controls - Inspection/Replacement of Improper Hardware on Outboard Aileron Bellcrank	FL-269		01-Dec-11	23-Oct-23	1 / IR	4551.50			4651				Complied
28 AD: 2022-03-15	IR	Garmin G3X Touch Electronic Flight Instrument System (FAA STC SA01899WI) or Garmin GI 275 Multi-Function Display (FAA STC SA02658SE) - Fuel Probe Interface - Modification	FL-269		21-Mar-22	20-Oct-22	1 / IR	4394.40			4424				Complied
28 AD: AD/GENERAL/002	IR	Fuel System - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
28 AD: AD/GENERAL/019	IR	Fuel System - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
28 AD: AD/GENERAL/020	IR	Fuel Valve Controls - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
28 AD: AD/GENERAL/031	1	Fuel Tank Filler Caps - Cancelled	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
28 AD: AD/GENERAL/046	IR	Placarding of Fuel Quantity Indicators - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
28 AD: AD/GENERAL/052	IR	Bonding - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
28 AD: AD/GENERAL/077	IR	Suspect Fuel - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
28 AD: AD/GENERAL/078	1	Fuel Contamination - Cancelled	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
28	AD: AD/GENERAL/079	1 Testing for Ethylene Diamine (EDA) Contamination of Fuel Tanks - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
28	AD: AD/GENERAL/080	2 Ethylene Diamine (EDA) Decontamination - Simple Aircraft - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
28	AD: AD/GENERAL/081	2 Ethylene Diamine (EDA) Decontamination - Complex Aircraft - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
28	SL: MTL-28-01	IR Fuel - Microbiological Contamination In Aircraft Fuel Tanks And Fuel Systems	FL-269		10-Jan-25	1 / IR		4740.80			4811				Complied
28	SL: MTL-28-02	IR Fuel - Engine Fuel Shutoff Valve Inspection	FL-269		30-May-25	03-Jun-25	1 / IR	4827.10			4877				Complied
28	SB: SB 2037	1 Fuel - Improvement of the Fuel Quantity System	FL-269		23-Oct-23	1 / 1		4551.50			4651				Complied
28	SB: SB 2092	IR Fuel - Replacement of Drive Couplings On Lear Siegler Fuel Boost Pumps	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
28	SB: SB 2718	2 Fuel - Replacement of MIL-H-6000B Hose Manufactured By Buckeye Rubber Products Inc	FL-269		01-Jan-97	23-Oct-23	1 / 2	4551.50			4651				Complied
28	SB: SB 28-3825	IR Fuel - Inspection/Replacement of P/N 101-389020-1 Float Valves	FL-269		01-Aug-07	23-Oct-23	1 / IR	4551.50			4651				Complied
28	SB: SB 28-3986	IR Fuel - Replacement of Fuel Line Vent Tube Assemblies in Left and Right Main Landing Gear Wheel Wells	FL-269		01-Aug-09	23-Oct-23	1 / IR	4551.50			4651				Complied
28	SB: SB 28-4059	1 Fuel - Introduction of Improved Fuel Cell Gasket	FL-269		01-Dec-01	03-Jun-25	1 / 1	4827.10			4877				Complied
28	SB: SB 28-4128	IR Fuel - Inspection for Condition of Wing Fuel System	FL-269		01-Mar-14	23-Oct-23	1 / IR	4551.50			4651				Complied
29	AD: AD/HYD/001	IR Sprague Engineering Hydraulic Accumulator - Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
30	AD: 2010-26-03	IR Tail Deicing Pneumatic Supply Tubes	FL-269		20-Dec-10	16-Aug-23	1 / IR	4511.50			4602				Complied
30	AD: AD/BEECH 300/015	1 Aircraft Flight Manual, Flight into Icing Conditions	FL-269		13-Jul-00	16-Aug-23	1 / 1	4511.50			4602				Complied
30	AD: AD/BEECH 300/022	IR Tail Deicing Pneumatic Supply Tubes - Cancelled	FL-269		16-Aug-23	1 / IR		4511.50			4602				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
30	AD: AD/ELECT/047	IR Propeller De-Ice Terminal Clamp Assembly - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
30	SL: MTL-30-01	IR Ice And Rain Protection - Inertial Vane Control Journal Verification	FL-269		01-Apr-19	23-Oct-23	1 / IR	4551.50			4651				Complied
30	SB: SB 2234	IR Ice and Rain Protection - Installation of Water Barrier In Nose Avionics Compartment	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
30	SB: SB 30-3889	1 Ice and Rain Protection - Replacement of Tail Deice Boot Pneumatic Supply Tubing	FL-269		01-Mar-08	23-Oct-23	1 / 1	4551.50			4651				Complied
31	AD: 2010-05-10	IR Pitot Heat Annunciation	FL-269		08-Apr-10	16-Aug-23	1 / IR	4511.50			4602				Complied
31	AD: 2010-09-04	IR APEX Flight Management Systems	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: 2012-26-15	1 Honeywell International Incorporated Air Data Pressure Transducers	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
31	AD: 2017-04-06	IR United Instruments Inc 5934 Series Altimeters - Replacement	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: 2018-03-04	IR Rosemount Aerospace Model 851AK Pitot Probes repaired by CSI Aerospace Inc - Incorrect Airspeed Indication	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: 2019-01-02	IR Aspen Avionics Inc Evolution Flight Display Units - Disabling of ADS-B In / AFM Supplement Revision	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: AD/GENERAL/027	IR Warning or Indicator Light Lamps - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: AD/GENERAL/043	IR Power Supply Connections to Hourmeters - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: AD/GENERAL/047	IR 3 Pointer Type Altimeters - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: AD/INST/001	IR Gyro Horizon Indicators Power Failure Warning Flag - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: AD/INST/002	2 Edison and Garwin Engine Gauge Units - Modification	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
31	AD: AD/INST/003	IR Bendix Fuel Flow Transmitters - Inspection	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31	AD: AD/INST/004	1 Vacuum Pump Splined Coupling - Replacement	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
31 AD: AD/INST/005	1	Fuel Contents Gauges - Tank Unit - Inspection and Modification	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
31 AD: AD/INST/006	2	Eddison Engine Gauge Units - Modification - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
31 AD: AD/INST/008	4	Instruments in VFR Aircraft - Cancelled	FL-269		20-Oct-22	1 / 4		4394.40			4424				Complied
31 AD: AD/INST/009	6	Instruments in IFR Aircraft - Cancelled	FL-269		20-Oct-22	1 / 6		4394.40			4424				Complied
31 AD: AD/INST/016	IR	King KG 102 Directional Gyro - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/017	IR	King K1 525 Indicator - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/018	IR	Collins PN-101 Pictorial Navigation System Slaving Accessory 328A-3G - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/022	IR	Airborne Vacuum Pumps - Removal From Service	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/023	1	Edo-Aire Mitchell NSD-360 Compass System - Addition of Nav Flag Adapter	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
31 AD: AD/INST/024	IR	Filotecnica Salmoiraghi Airspeed Indicators - Calibration Tests	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/025	IR	Aerosonic Encoding Altimeters - Replacement - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/027	IR	Airborne Vacuum Pumps - Removal From Service	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/031	IR	Airborne Vacuum Pumps - Removal from Service	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/032	IR	Altimeters	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/038	IR	LITEF GmbH LCR-88 Attitude and Heading Reference System	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/039	IR	Altimeters Manufactured By CATIC - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/040 [Part: 1]	IR	LITEF Attitude Heading Reference System	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/041	IR	RAPCO Inline Pressure Filter	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/043	IR	Parker Hannifin Flexible Coupling	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/045	IR	Honeywell Air Data Inertial Reference Units	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
31 AD: AD/INST/046 [Part: 1 & 2]		IR SVS III Standby Vacuum System	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/048		IR Honeywell Inertial Reference Unit	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/049		1 Rockwell Collins Air Data Computers	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
31 AD: AD/INST/050		IR Adaptive Flight Display	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/051		IR Flight Management Computers	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/052		IR SVS I and IA Standby Vacuum System	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/053		IR Shadin ADC-2000 Units	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/054		IR Aero Advantage Vacuum Pumps	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/055		IR Garmin GSM 85 Servo Gearbox	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 AD: AD/INST/056		2 Avidyne Corporation Primary Flight Displays	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
31 AD: AD/INST/057		IR Harco Labs, Inc. Pitot/Angle of Attack Probes	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
31 SB: MTB-31-02		IR Indicating/Recording Systems - Flight Hour Meter Replacement	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
31 SL: MTL-31-01		1 Indicating/Recording Systems - Collins Environmental Controller (IEC) And Power Supply (PWR) IAPS Modules Inspection/Replacement	FL-269		11-Oct-22	23-Oct-23	1 / 1	4551.50			4651				Complied
31 SL: MTL-31-02		IR Indicating/Recording Systems - Digital Flight Data Recorder (DFDR) Inspection	FL-269		13-Jun-25	22-Oct-25	1 / IR	4915.70			4946				Complied
31 SB: SB 31-3948		IR Indicating/Recording Systems - Inspection/Correction of Pitot Heat Annunciation Wiring	FL-269		01-Apr-09	23-Oct-23	1 / IR	4551.50			4651				Complied
32 AD: 2012-05-01		IR Goodyear Tires - Inspection / Replacement	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
32 AD: 2025-08-01 [Part: (a)]		1 Unapproved Brake Parts Manufactured by H8 ALS	FL-269		04-Aug-25	22-Oct-25	1 / 1	4915.70			4946				Complied
32 AD: AD/BEECH 300/011		IR Main Landing Gear Clevis Assembly	FL-269		28-Jan-99	16-Aug-23	1 / IR	4511.50			4602				Complied
32 AD: AD/BEECH 300/014		IR Landing Gear Emergency Hand Pump - Faulty Component Replacement	FL-269		27-Sep-99	16-Aug-23	1 / IR	4511.50			4602				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
32 AD: AD/GENERAL/017	4	Landing Gear Audible Warning Device - Cancelled	FL-269		20-Oct-22	1 / 4	4394.40				4424				Complied
32 AD: AD/WHE/001	IR	Firestone Tyres - Inspection and Replacement - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
32 AD: AD/WHE/002	IR	B.F. Goodrich Tyres - Removal from Service - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
32 AD: AD/WHE/003	1	Aircraft Tyres - Retreading - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
32 AD: AD/WHE/004	4	Inflation of Tyres with an Inert Gas	FL-269		20-Oct-22	1 / 4	4394.40				4424				Complied
32 AD: AD/WHE/005	IR	Michelin Aircraft Tyres	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
32 AD: AD/WHE/006	IR	Goodyear Flight Eagle Tyres	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
32 AD: AD/WHE/007	IR	Nosewheel Tyres	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
32 SB: MTB-32-01	IR	Landing Gear - Safety Switch Improvement	FL-269		23-Oct-23	1 / IR	4551.50				4651				Complied
32 SB: MTB-32-02	IR	Landing Gear - Main-Landing-Gear Torque-Knee Pins Replacement	FL-269		11-Apr-23	22-Dec-23	1 / IR	4555.70			4654				Complied
32 SL: MTL-32-01	1	Landing Gear - Inspect the Steering Support Bracket for Incorrect Bolts	FL-269		24-Jul-19	23-Oct-23	1 / 1	4551.50			4651				Complied
32 SL: MTL-32-02	1	Landing Gear - Main-Landing-Gear Torque-Knee Pins Replacement - Cancelled	FL-269		11-Apr-23	17-Aug-23	1 / 1	4511.50			4602				Complied
32 SL: MTL-32-03	1	Landing Gear - Landing Gear Control Switch Inspection	FL-269		02-Dec-22	23-Oct-23	1 / 1	4551.50			4651				Complied
32 SL: MTL-32-04	IR	Landing Gear - Power Pack Remote Control Circuit Breaker Wiring Inspection	FL-269		01-Mar-23	23-Oct-23	1 / IR	4551.50			4651				Complied
32 SB: SB 2385	2	Landing Gear - Inspection/Replacement of Landing Gear Drag Leg Components	FL-269		23-Oct-23	1 / 2	4551.50				4651				Complied
32 SB: SB 2386	IR	Landing Gear - Replacement of Allen Aircraft Main Landing Gear Actuators	FL-269		01-Dec-92	23-Oct-23	1 / IR	4551.50			4651				Complied
32 SB: SB 2407	IR	Landing Gear - Replacement of Airight Hydraulic Power Packs	FL-269		23-Oct-23	1 / IR	4551.50				4651				Complied
32 SB: SB 2658	2	Landing Gear - Main Landing Gear Actuator Bearing Support Bracket Replacement	FL-269		01-Jun-97	23-Oct-23	1 / 2	4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
32 SB: SB 2695	IR	Landing Gear - BFGoodrich Main Landing Asbestos Brake Assembly Conversion Kits	FL-269		01-Aug-96	22-Dec-23	1 / IR	4555.70			4654				Complied
32 SB: SB 2728	1	Landing Gear - Main Landing Gear Actuator Clevis Replacement	FL-269		01-Jun-97	23-Oct-23	1 / 1	4551.50			4651				Complied
32 SB: SB 32-3057	IR	Landing Gear - Installation of the Landing Gear Horn Silence Switch to the Left Hand Power Lever	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
32 SB: SB 32-3073	1	Landing Gear - Hand Pump Inlet Filter Installation (RECURRING INSP)	FL-269		01-Jan-00	23-Oct-23	1 / 1	4551.50			4651				Complied
32 SB: SB 32-3340	IR	Landing Gear - Landing Gear Hydraulic Hand Pump Replacement	FL-269		01-Jan-00	23-Oct-23	1 / IR	4551.50			4651				Complied
32 SB: SB 32-3662	IR	Landing Gear - Main Landing Gear (MLG) Piston Assembly Replacement	FL-269		01-Jun-04	23-Oct-23	1 / IR	4551.50			4651				Complied
33 AD: 2013-10-01	IR	Spectrolab Nightsun XP Searchlab (Replaces EASA AD 2010-0237R2)	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
33 AD: AD/ELECT/060	IR	Precise Flight Incorporated Pulselite	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
33 AD: AD/ELECT/067	IR	Aerospace Lighting Corporation Cabin Fluorescent Lighting System Components	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
33 AD: AD/ELECT/072	IR	Fluorescent Light Ballasts	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
33 AD: AD/GENERAL/033	1	Cargo and Baggage Compartment Lighting - Cancelled	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
33 AD: AD/GENERAL/050	IR	Whelen Strobe Light - Modification	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
33 AD: AD/GENERAL/059	IR	Anti-Collision Lights - Installation - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
33 SB: MTB-33-03	2	Lights - Led Tail Strobe Light Installation	FL-269		07-Oct-19	27-Mar-25	1 / 2	4777.20			4839				Complied
33 SB: MTB-33-05	IR	Lights - Led Tail Strobe Light Installation With 130-3070-0001 Kit Installed	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
33 SB: SB 2635	IR	Lights - A125 Annunciator Control Module Assembly Replacement	FL-269		01-Jun-97	23-Oct-23	1 / IR	4551.50			4651				Complied
33 SB: SB 33-3410	IR	Lights - Flashing Beacon Hardware Kit Improvement	FL-269		01-Nov-00	17-Aug-23	1 / IR	4511.50			4602				Complied
33 SB: SB 33-3799	IR	Lights - Cabin Indirect Lighting Modification	FL-269		01-Jul-06	03-Jun-25	1 / IR	4827.10			4877				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
34	AD: 2020-10-05	IR Rockwell Collins Pro Line 4 and Pro Line 21 Flight Management Systems - Flight Management Computer	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
34	AD: 2020-16-08	IR Aspen Avionics EFD1000 Flight Display - AFM Revision / Operating Restrictions	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
34	AD: 2020-18-51	IR Sandia P/N 306171-10 or 306171-20 Attitude Indicators - Airplane Flight Manual Revision	FL-269		29-Aug-20	20-Oct-22	1 / IR	4394.40			4424				Complied
34	AD: 2021-08-07	IR Rockwell Collins GPS-4000S Global Positioning System P/N 822-2189-100 - Replacement	FL-269		12-May-21	20-Oct-22	1 / IR	4394.40			4424				Complied
34	AD: 2021-08-15	IR Garmin International GMN-00962 GTS Processor Units Part Number 011-02571-0( ) - Software Update	FL-269		17-May-21	20-Oct-22	1 / IR	4394.40			4424				Complied
34	AD: 2022-0024	IR ATA 34 - Navigation - Flight Management Computer 2 / Navigation Modules - Operational Limitations / Amendment	FL-269		04-Feb-22	20-Oct-22	1 / IR	4394.40			4424				Complied
34	AD: 2023-10-02 [Part: (i)]	IR Radio Altimeter - 5G Interference - Aircraft Flight Manual Revision	FL-269		16-Aug-23	21-Dec-23	1 / IR	4555.70			4654				Complied
34	AD: 2023-11-07 [Part: (f)]	IR Radio Altimeter - 5G Interference - Rotorcraft Flight Manual Revision	FL-269		22-Jun-23	28-Mar-24	01 / IR	4565.90			4665				Complied
34	AD: 2024-0024	IR Navigation - Digital Air Data Computer - Replacement	FL-269		07-Feb-24	27-Mar-24	01 / IR	4565.90			4665				Complied
34	AD: 2025-0088	IR Rockwell Collins - Navigation - Satellite Based Augmentation Systems / Global Positioning System Receiver - Replacement	FL-269		30-Apr-25	03-Jun-25	1 / IR	4827.10			4877				Complied
34	AD: 2025-07-01	IR AC32 Digital Air Data Computers	FL-269		15-May-25	03-Jun-25	1 / IR	4827.10			4877				Complied
34	AD: AD/FMS/001	IR Honeywell Flight Management Systems - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
34	AD: AD/FMS/002	IR Honeywell IC-600 Integrated Avionics Computers	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
34	AD: AD/FMS/003	1 Honeywell NZ-2000 and IC-800 Navigation Computers	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
34	AD: AD/GENERAL/006	1 Aircraft Alternate Static Systems - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
34	AD: AD/GENERAL/007	5 Airspeed Indicators and Altimeters - Modification - Cancelled	FL-269		20-Oct-22	1 / 5		4394.40			4424				Complied
34	AD: AD/GENERAL/013	1 Yellow Line Altimeter - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
34	AD: AD/GENERAL/041	1 Weston Garwin Curruth Altimeters - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
34	AD: AD/GENERAL/049	3 TKK Altimeter Mechanisms Incorporated in Altimeters of Various Brand Names - Modification	FL-269		20-Oct-22	1 / 3		4394.40			4424				Complied
34	AD: AD/GENERAL/054	IR Magnetic Compasses Fitted in Compliance with ANO 20.18 - Calibration - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
34	AD: AD/GENERAL/055	2 Directional Gyros - Inspection - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
34	AD: AD/GENERAL/057	1 Pitot Heat Inoperative Indicators - Installation - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
34	AD: AD/GENERAL/083	IR Rockwell Collins 621A-3 Transponders - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
34	AD: CF-2024-14	IR Navigation – Aeroplane – Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference	FL-269		15-May-24	01-Jun-24	1 / IR	4599.20			4689				Complied
34	AD: CF-2024-15	IR Navigation – Rotorcraft – Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference	FL-269		15-May-24	01-Jun-24	1 / IR	4599.20			4689				Complied
34	SB: MTB-34-02	IR Navigation - FDSA Software Update	FL-269		13-Sep-19	23-Oct-23	1 / IR	4551.50			4651				Complied
34	SB: MTB-34-03	1 Navigation - TDR-94D ATC Transponder Strapping Change For King Air B300 And B300C Configured For 15,500 Or Greater Max Takeoff Weight	FL-269		12-Dec-22	23-Oct-23	1 / 1	4551.50			4651				Complied
34	SB: MTB-34-04	IR Navigation - Proline Fusion Upgrade To Phase 4 Software	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
34 SB: MTB-34-05		IR Navigation - Field Upgraded Proline Fusion Phase 3 To Phase 4 Software	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
34 SL: MTL-34-01	1	Navigation - GPS-4000S Global Positioning System Software Update	FL-269		14-May-20	23-Oct-23	1 / 1	4551.50			4651				Complied
34 SL: MTL-34-03		IR Navigation - Transmittal Of Collins Aerospace Service Bulletin ATL-4000-34-D, Navigation - ALT-4000 - Evaluation Of Surface Mount Ferrite Bead Used On The Power Supply	FL-269		08-Mar-22	23-Oct-23	1 / IR	4551.50			4651				Complied
34 SL: MTL-34-04		IR Navigation - Transmittal Of Collins Aerospace Service Bulletin Alt-4000-34-14. Navigation - Alt 4000 Power Supply Robustness Improvement	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
34 SB: SB 2043		IR Navigation/Pitot Static - Installation of an Avionics Cooling Blower in the Nose Compartment	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
34 SB: SB 2519		IR Navigation/Pitot Static - Cockpit Voice Recorder Audio Input Interface Standardization	FL-269		23-Oct-23	1 / IR		4551.50			4651				Complied
34 SB: SB 34-3236	3	Navigation - Year 2000 Readiness Software Anomaly	FL-269		01-Apr-02	23-Oct-23	1 / 3	4551.50			4651				Complied
34 SB: SB 34-3355		IR Navigation / Pitot Static - Air Data Flag With Static Source Switching	FL-269		01-May-02	17-Aug-23	1 / IR	4511.50			4602				Complied
34 SB: SB 34-3435		IR Navigation - Modification Of Collins Tdr-94/94D Status -004 Transponder Receiver-Transmitter (Transponder) Sets	FL-269		03-May-02	17-Aug-23	1 / IR	4511.50			4602				Complied
34 SB: SB 34-3507	5	Navigation - Air Data Computer (Collins ADC-85A) Increased Accuracy (RVSM)	FL-269		01-Jun-02	17-Aug-23	1 / 5	4511.50			4602				Complied
34 SB: SB 34-3673		IR Navigation - Flux Valve Mounting Nutplate Inspection / Replacement	FL-269		01-Aug-04	23-Oct-23	1 / IR	4551.50			4651				Complied
34 SB: SB 34-3679	1	Navigation - Maintenance Diagnostics Computer (MDC-3110) Update	FL-269		01-Oct-04	23-Oct-23	1 / 1	4551.50			4651				Complied
34 SB: SB 34-3728		IR Navigation - Avionics Nose Shelf Improvement	FL-269		01-Sep-05	23-Oct-23	1 / IR	4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
34	SB: SB 34-3738	IR Navigation - Electronic Standby Instrument System Circuit Breaker	FL-269		01-Sep-05	23-Oct-23	1 / IR	4551.50			4651				Complied
34	SB: SB 34-4003	IR Navigation - Reinstatement of Reduced Vertical Separation Minimum (RVSM) Compliance	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
34	SB: SB 34-4150	IR Navigation - Introduction of Automatic Dependent Surveillance - Broadcast Out (ADS-B Out) Installation Kit	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
34	SB: SB 34-4170	IR Navigation - Fusion Equipped King Air 200/300 Electronic Standby Instrument System (EFIS) - Magnetometer Relocation Kit	FL-269		01-Mar-17	23-Oct-23	1 / IR	4551.50			4651				Complied
34	SB: SB 34-4171	2 Navigation - Proline Fusion Upgrade To Phase 3 Software	FL-269		12-Jan-21	23-Oct-23	1 / 2	4551.50			4651				Complied
35	AD: 2009-21-10	1 AVOX Systems and B/E Aerospace Oxygen Cylinder Assemblies, as Installed on Various Transport Airplanes	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
35	AD: 2010-0152	IR Equipment and Furnishing - Oxygen Mask Regulator - Modification	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35	AD: 2010-11-05	IR AVOX Systems and B/E Aerospace Oxygen Cylinder rupture	FL-269		06-Jul-10	20-Oct-22	1 / IR	4394.40			4424				Complied
35	AD: 2011-0090	1 Oxygen - Oxygen Mask Regulator Inflatable Harness - Identification / Replacement	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
35	AD: 2011-01-09	IR B/E Aerospace Protective Breathing Equipment (PBE) Part Number 119003-11 Installed on Various Transport Airplanes	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35	AD: 2011-14-08	IR B/E Aerospace Oxygen Masks - Oxygen Mask Assemblies - Broken in-line Flow Indicators	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35	AD: 2012-0254	1 Inter technique Aircraft Systems MC10, MF10 and MF20 Oxygen Mask Regulators	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
35	AD: 2014-0142	1 Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification / Replacement	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
35 AD: 2017-18-12	IR	B/E Aerospace Protective Breathing Equipment (PBE) P/N 119003-11 and 119003-21 - Inspection / Replacement	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
35 AD: 2021-0135	IR	ATA 35 – Oxygen – Low-Pressure Oxygen Flexible Hoses – Replacement	FL-269		16-Jun-21	20-Oct-22	1 / IR	4394.40			4424				Complied
35 AD: 2022-04-09	IR	AVOX System (formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies, and Oxygen Valve Assemblies	FL-269		04-Apr-22	20-Oct-22	1 / IR	4394.40			4424				Complied
35 AD: 2023-13-11	IR	AVOX System (formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies, and Oxygen Valve Assemblies	FL-269		05-Sep-23	16-Aug-23	1 / IR	4511.50			4602				Complied
35 AD: 2024-19-15	IR	AVOX System (formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies, and Oxygen Valve Assemblies - Inspection	FL-269		26-Nov-24	10-Jan-25	1 / IR	4740.80			4811				Complied
35 AD: 2025-0222	IR	Oxygen - Portable Breathing Equipment - Operational Instructions	FL-269		13-Oct-25	04-Nov-25	1 / IR	4915.70			4946				Complied
35 AD: AD/GAS/002	IR	Filament Wound, Fibre-Glass, High Pressure Spherical Vessels - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35 AD: AD/OXY/001	IR	Mask Rebreather Bag Security - Inspection and Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35 AD: AD/OXY/002	IR	Scott Oxygen Mask Filter Retention - Modification - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35 AD: AD/OXY/003	1	Puritan-Bennett Oxygen Regulator Diaphragm - Replacement	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
35 AD: AD/OXY/004	IR	Scott Aviation Oxygen Cylinders - Recharge - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35 AD: AD/OXY/005	IR	Scott Oxygen Mask Connectors	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35 AD: AD/OXY/006	1	Passenger Oxygen Masks	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
35 AD: AD/OXY/007	1	Eros Oxygen Masks	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
35 AD: AD/OXY/008	IR	Eros Full Face Oxygen Masks	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
35 AD: AD/OXY/009	IR	Du Pont Pels Crewmember Protective Breathing Equipment	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
35	AD: AD/OXY/010	1 Eros Full Face Oxygen Masks	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
35	AD: AD/OXY/011	IR Scott Aviation Oxygen Mask Plug-In Connectors PN 289-57	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/012	IR PELS Model 4566M37B Crewmember Protective Breathing Equipment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/013	IR Puritan Bennett Aero Systems Crewmember Protective Breathing Equipment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/014	IR Puritan Bennett Aero Systems Sweep-On Model 200 Crew Oxygen Masks	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/015	IR Puritan Bennett Oxygen Masks Withdrawal From Service	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/016	IR Puritan-Bennett Oxygen Mask	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/017	IR Smoke Hood Inspection	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/018	IR Passenger Emergency Oxygen Generators - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/019	IR Puritan-Bennett Oxygen Masks	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
35	AD: AD/OXY/020 [Part: 15 Year]	2 Oxygen Cylinders	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
35	SB: SB 35-3520	IR Passenger Oxygen Mask Container Door Modification	FL-269		05-Mar-20	23-Oct-23	1 / IR	4551.50			4651				Complied
36	AD: AD/PNEU/001	IR Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
36	AD: AD/PNEU/002	IR Oil and Water Traps - Retirement - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
36	AD: AD/PNEU/003	IR Garrett AiResearch Starters	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
36	SL: MTL-36-02	IR Pneumatic - Flow Control Valve Insulation Inspection	FL-269		17-Apr-24	01-Jun-24	1 / IR	4599.20			4689				Complied
36	SL: MTL-36-03	IR Pneumatic - Bleed Air Flow Control Valve Inspection	FL-269		11-Jun-24	10-Jan-25	1 / IR	4740.80			4811				Complied
36	SB: SB 2655	IR Pneumatic - Bleed Air Warning System Repairs	FL-269		01-Feb-96	22-Dec-23	1 / IR	4555.70			4654				Complied
38	AD: AD/ELECT/061	IR Nordskog Water Heaters and Coffee Makers	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
38	AD: AD/ELECT/062	IR Inventum Water Heaters	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
38	AD: AD/ELECT/064	IR Nordskog Water Heaters and Coffee Makers	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
38	AD: AD/ELECT/073	IR Britax Sell Galley Equipment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
38	AD: AD/ELECT/074	1 Lermer GmbH Water Boilers	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
38	AD: AD/GENERAL/021	IR Waste Water Outlet - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
39	SB: SB 39-3103	IR Placards And Markings - Edgelight/Overhead Light Control Panel Assembly Modification	FL-269		01-Nov-02	23-Oct-23	1 / IR	4551.50			4651				Complied
44	SB: MTB-44-01	IR Cabin Systems - Avance L3 System Wiring Modification To Prevent TCAS Fail Message	FL-269		07-Jun-21	23-Oct-23	1 / IR	4551.50			4651				Complied
44	SB: SB 44-4115	IR Cabin Systems - Venue System Software Upgrade	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
45	AD: AD/GENERAL/032	1 External Spray Tanks - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
46	AD: 2018-0259	Electronic Flight Bag Universal Serial Bus Receptacle - Modification	FL-269		14-Dec-18	20-Oct-22	1 /	4394.40			4424				Complied
49	AD: 2009-21-03	IR Hamilton Sundstrand T-62T-46C12 APU Software Upgrade	FL-269		20-Nov-09	20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: 2010-0079	IR Airborne Auxiliary Power - Auxiliary Power Unit Turbine Wheel Life Limit - Reduction	FL-269		10-May-10	20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: 2010-12-09	IR GTCP36 Series APU - FCU Delta P Sleeve Bore Inspection	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: AD/APU/001	IR Turbine Blade Containment Ring - Installation	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: AD/APU/002	IR Inspection, Placard, Operational Limitations and/or Modification	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: AD/APU/003	IR Incorporation of Back-Up Plate to Improve Turbine Wheel Containment - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: AD/APU/004	IR Fuel Solenoid Shut Off Valve - Inspection - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: AD/APU/005	2 Cooling Fan Assembly	FL-269			20-Oct-22	1 / 2	4394.40			4424				Complied
49	AD: AD/APU/006	1 Augmentation Containment Ring - Cancelled	FL-269			20-Oct-22	1 / 1	4394.40			4424				Complied
49	AD: AD/APU/007	IR High Pressure Turbine Disc	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: AD/APU/008	IR Garrett APU Compressor Rotating Group	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
49	AD: AD/APU/009	IR PW901A APU Idler Gear and Cooling Fan Shaft	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
49 AD: AD/APU/010		IR GTCP 85 Series APU Axial Containment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/011		IR TSCP700 HPT Disc	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/012		IR Compressor Wheel	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/013		IR Augmentation Containment Ring	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/014		IR TSCP700 First Stage LPC Disc	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/015		IR GTCP 36 Series APU Load Compressor Containment	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/016		IR T-62T APU Compressor Wheel Replacement	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/017		1 Saphir 20 Model 095 Female Quill Shaft Cycles Since New	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
49 AD: AD/APU/018		IR Fuel Leaks on Hamilton Sundstrand APU Models T-62T-46C12 and T-62T-40C14	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/019		1 Micorturbo - Overspeed Protection Channel	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
49 AD: AD/APU/020		IR Hamilton Sundstrand Compressor Impeller Assemblies	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/021		IR RE220 Fuel Nozzles	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: AD/APU/022		1 APS 3200 APU Software Upgrade	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
49 AD: AD/APU/023		IR Saphir 2 Exhaust Thermal Insulation	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
49 AD: CF-2011-40		IR Separation of Turbine Exhaust Duct Flanges	FL-269		16-Nov-11	20-Oct-22	1 / IR	4394.40			4424				Complied
50 AD: AD/CARGO/001		IR Ribeco Air Cargo Pallet	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
50 AD: AD/CARGO/002		1 GPI Cargo Nets	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
50 AD: AD/CARGO/003		IR Ribeco Air Cargo Pallets and Air Cargo Nets	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
51 AD: AD/GENERAL/082		2 Repair Assessment of Pressurised Fuselages	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
51 AD: DCA/GEN/36A		IR Parts Manufactured by Croydon Aircraft Company	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
52 AD: AD/BEECH 300/004		IR Cabin Door - Cancelled	FL-269		16-Aug-23	1 / IR		4511.50			4602				Complied
52 AD: AD/BEECH 300/017		IR External Door Operating Instructions	FL-269		17-Apr-03	16-Aug-23	1 / IR	4511.50			4602				Complied
52 AD: AD/ELECT/070		2 Inflatable Door Seal System	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
52 SB: MTB-52-01	1	Doors - Inside Airstair Door Handle Snap Ring Modification	FL-269		12-Apr-18	17-Aug-23	1 / 1	4511.50			4602				Complied
52 SL: MTL-52-01	IR	Doors - Cabin Door Lock Inspection	FL-269		21-Feb-18	23-Oct-23	1 / IR	4551.50			4651				Complied
52 SL: MTL-52-02	1	Doors - Cabin Entry Door Hook Replacement	FL-269		12-Jan-23	23-Oct-23	1 / 1	4551.50			4651				Complied
52 SB: SB 52-3096	1	Placard And Markings - New External Door Operating Instructions Placard	FL-269		01-Aug-00	23-Oct-23	1 / 1	4551.50			4651				Complied
52 SB: SB 52-3701	IR	Doors - Cabin/Airstair Door Hook Switch Installation Inspection/Modification	FL-269		01-Dec-04	17-Aug-23	1 / IR	4511.50			4602				Complied
53 AD: AD/BEECH 300/007 [Part: 1 Initial]	1	Fuselage Stringers 5 Through 11	FL-269		30-Jun-93	16-Aug-23	1 / 1	4511.50			4602				Complied
53 AD: AD/GENERAL/023	IR	Aircraft Break-In Points - Cancelled	FL-269			20-Oct-22	1 / IR	4394.40			4424				Complied
53 SL: MTL-53-01	IR	Fuselage - Inspect The Left And Right Emergency Exit Reinforcements For Removed Material And Retreat If Rough Or Without Finish	FL-269		30-Jun-20	23-Oct-23	1 / IR	4551.50			4651				Complied
53 SL: MTL-53-03	IR	Fuselage - Cross Tie Fastener Inspection At Fuselage Station 158.00	FL-269		31-Jan-23	23-Oct-23	1 / IR	4551.50			4651				Complied
53 SL: MTL-53-04	3	Fuselage - Forward Fuselage Fastener Inspection	FL-269		08-May-23	23-Oct-23	1 / 2	4551.50			4651				Complied
53 SL: MTL-53-05	3	Fuselage - Filler Shim Or Fastener Installation At Fuselage Station 221	FL-269		15-Aug-23	24-Jan-25	1 / 3	4740.80			4811				Complied
53 SL: MTL-53-06	IR	Fuselage - Crosstie Reinforcement Installation at STA 179.525 and STA 201.775	FL-269		08-Nov-24	24-Jan-25	1 / IR	4740.80			4811				Complied
53 SL: MTL-53-07	IR	Fuselage - Forward and Aft Cargo Door Frame Repair	FL-269		25-Jul-25	22-Oct-25	1 / IR	4915.70			4946				Complied
53 SB: SB 53-3400	1	Fuselage - Wing-To-Fuselage Fuel Quantity Wiring Conduit Sealing Modification	FL-269		01-Apr-03	17-Aug-23	1 / 1	4511.50			4602				Complied
53 SB: SB 53-3592	IR	Fuselage - Inspection/Installation of Missing Stringer Clips	FL-269		01-Jul-03	17-Aug-23	1 / IR	4511.50			4602				Complied
53 SB: SB 53-3855	IR	Fuselage - Inspection/Installation of Missing Rivets in Fuselage Nose Section	FL-269		01-Feb-08	23-Oct-23	1 / IR	4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
53 SB: SB 53-4029	IR	Fuselage - Replacement of Fuselage Frame Clips	FL-269		01-Feb-11	23-Oct-23	1 / IR	4551.50			4651				Complied
53 SB: SB 53-4074	IR	Fuselage - Inspection/Installation of Rivets in Main Entry Door Frame	FL-269		01-Jun-11	23-Oct-23	1 / IR	4551.50			4651				Complied
53 SB: SB 53-4173	IR	Fuselage - Brake Master Cylinder Support Tube Inspection	FL-269		28-Jun-17	23-Oct-23	1 / IR	4551.50			4651				Complied
54 SB: SB 2547	IR	Nacelles/Pylons - Announcement of Forward Cowling Attachment Kits	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
54 SB: SB 54-3970	1	Nacelles - Introduction of Fairing Improvement Kit (130-9009)	FL-269		01-Nov-09	23-Oct-23	1 / 1	4551.50			4651				Complied
55 SL: MTL-55-01	IR	Stabilizers - Inspection of the Washer Location in the Elevator Support Assembly	FL-269		18-May-18	23-Oct-23	1 / IR	4551.50			4651				Complied
55 SB: SB 2044	IR	Stabilizers - Inspection and Possible Replacement of Rivets in the Forward and Aft Spars of the Vertical Stabilizer (RECURRING INSP)	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
55 SB: SB 55-3082	IR	Stabilizers - Inspection of the Vertical Stabilizer Rear Spar Assembly	FL-269		01-Feb-98	23-Oct-23	1 / IR	4551.50			4651				Complied
55 SB: SB 55-3403	1	Stabilizers - Horizontal Stabilizer Installation Gap Inspection/repair - Cancelled	FL-269		01-Oct-00	17-Aug-23	1 / 1	4511.50			4602				Complied
55 SB: SB 55-3551	IR	Elevator Trim Tab Assembly Rivet Inspection/Repair	FL-269		01-Feb-03	17-Aug-23	1 / IR	4511.50			4602				Complied
55 SB: SB 55-3552	IR	Rudder Trim Tab Assembly Rivet Inspection/Repair	FL-269		01-Feb-03	17-Aug-23	1 / IR	4511.50			4602				Complied
55 SB: SB 55-3835	IR	Stabilizers - Installation of Empennage Inspection Access Panels	FL-269		01-Jun-08	17-Aug-23	1 / IR	4511.50			4602				Complied
55 SB: SB 55-4004	IR	Stabilizers - Inspection of Rudder Assembly for Proper Drainage	FL-269		01-Nov-09	17-Aug-23	1 / IR	4511.50			4602				Complied
55 SB: SB 55-4106	1	Stabilizers - Inspection/Installation of Rivets on the Vertical Stabilizer Aft Spar Cap (Kit 101-4095)	FL-269		01-Mar-13	23-Oct-23	1 / 1	4551.50			4651				Complied
56 AD: AD/BEECH 300/001	IR	Cockpit D Side Window - Cancelled	FL-269			16-Aug-23	1 / IR	4511.50			4602				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
56 SB: MTB-56-03		IR Windows - Model B300/B300C Coolview Window With Tinted Frost Pane Installation For Cockpit, Cabin, Or Baggage "Area" Windows	FL-269		07-Feb-25	22-Oct-25	1 / IR	4915.70			4946				Complied
56 SB: MTB-56-05		IR Windows - Model B300/B300C Coolview Window With Clear Frost Pane Installation For Passenger (Round) Windows	FL-269		07-Feb-25	22-Oct-25	1 / IR	4915.70			4946				Complied
56 SL: MTL-56-01		IR Windows - Window Shade Dust Pane Bonding Improvement	FL-269		06-Mar-23	23-Oct-23	1 / IR	4551.50			4651				Complied
56 SB: SB 2273		2 Windows - Installation of Replacement Cockpit Side Windows	FL-269		01-Aug-89	23-Oct-23	1 / 2	4551.50			4651				Complied
57 SB: MTB-57-01		1 Wings - Inspect the Aft Upper and Lower Wing Bolts for Correct Washer and Replacement	FL-269		05-Mar-20	23-Oct-23	1 / 1	4551.50			4651				Complied
57 SL: MTL-57-04		1 Wings - Crack Inspection - Wing Attach Fittings And Outboard Wing Spar Caps For Heavyweight Model B300/B300C	FL-269		20-Dec-99	27-Mar-25	1 / IR	4777.20			4839				Complied
57 SL: MTL-57-05		IR Wings - Inboard Aileron Hinge Arm Inspection	FL-269		16-Jul-25	22-Oct-25	1 / IR	4915.70			4946				Complied
57 SB: SB 2105		IR Wings - Inspection/Modification of Hydraulic Line Clearance on Left Inboard Wing Access Panel (RECURRING INSP)	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
57 SB: SB 2143		IR Wings - Part I, Replacement of Battery Access Panel Seal; Part II, Cover Installation	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
57 SB: SB 2295		IR Wings - Installation of Reinforced Leading Edge Skins	FL-269			23-Oct-23	1 / IR	4551.50			4651				Complied
57 SB: SB 57-3553		IR Wings - Aileron Trim Tab Assembly Rivet Inspection/Repair	FL-269		01-Apr-02	23-Oct-23	1 / IR	4551.50			4651				Complied
57 SB: SB 57-3867		2 Wings - Aileron Drain Hole Inspection	FL-269		01-Oct-07	28-Nov-23	1 / 2	4555.70			4654				Complied
57 SB: SB 57-4126		IR Wings - Inspection/Replacement of Incorrect Rivets Installed by Kit P/N 101-4045	FL-269		01-May-13	17-Aug-23	1 / IR	4511.50			4602				Complied
57 SB: SB 57-4144		IR Wings - Aileron Hinge Screw Inspection	FL-269		01-Feb-15	17-Aug-23	1 / IR	4511.50			4602				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
61 SB: 13198	IR	Propeller Governor - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / IR	4483.10	4537							Complied
61 SB: 13198	IR	Propeller Governor - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / IR	4502.40	4547							Complied
61 SB: 13212	IR	Propeller Governor Mounting Gasket - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / IR	4502.40	4547							Complied
61 SB: 13212	IR	Propeller Governor Mounting Gasket - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / IR	4483.10	4537							Complied
61 SB: 13354	1	Propeller Governor - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30	4413							Complied
61 SB: 13354	1	Propeller Governor - Replacement / Modification Of	PCE-PK0278	L/H	12-May-14	1 / 1	4366.00	4403							Complied
61 SB: 13397	IR	Beta Valve Packing Propeller Governor - Replacement Of	PCE-PK0277	R/H	07-Apr-05	27-Jul-23	1 / IR	4385.30	4413						Complied
61 SB: 13397	IR	Beta Valve Packing Propeller Governor - Replacement Of	PCE-PK0278	L/H	07-Apr-05	12-May-14	1 / IR	4366.00	4403						Complied
61 AD: 2010-13-10	IR	Ontic Governors - Pilot Valve Plunger - Inspection / Repair	FL-269		20-Oct-22	1 / IR	4394.40	4424							Complied
61 AD: 2020-19-06	IR	McCauley idler gear bearing (P/N A-20028)	FL-269		03-Nov-20	20-Oct-22	1 / IR	4394.40	4424						Complied
61 AD: AD/GOV/001	1	Retirement Lives - Critical Components - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40	4424							Complied
61 AD: AD/GOV/002	IR	Governor Body - Inspection	FL-269		20-Oct-22	1 / IR	4394.40	4424							Complied
61 AD: AD/GOV/003	IR	Speed Adjusting Lever Retention - Modification - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40	4424							Complied
61 AD: AD/GOV/004	IR	Flyweight Pin Retainer - Modification - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40	4424							Complied
61 AD: AD/GOV/005	IR	Governor Pump Idler Gear Stud - Replacement - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40	4424							Complied
61 AD: AD/GOV/006	IR	Governor Pressure Relief Valve Roll Pin - Modification	FL-269		20-Oct-22	1 / IR	4394.40	4424							Complied
61 AD: AD/GOV/007	1	McCauley Governor Flyweight Assembly - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40	4424							Complied
61 AD: AD/GOV/008	IR	Woodward Combined Power Turbine and Propeller Governor - Feather Check	FL-269		20-Oct-22	1 / IR	4394.40	4424							Complied
61 AD: AD/GOV/009	IR	Governor Control Arm Attachment Cap Screw A-1635-105 - Replacement - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40	4424							Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
61 AD: AD/GOV/010	1	Governor Flyweight Assembly - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
61 AD: AD/PT6A/030		IR Propeller Governor Assembly	PCE-PK0277	R/H	18-Apr-02	16-Aug-23	1 / IR	4502.40			4547				Complied
61 AD: AD/PT6A/030		IR Propeller Governor Assembly	PCE-PK0278	L/H	18-Apr-02	16-Aug-23	1 / IR	4483.10			4537				Complied
61 SB: SB 2115		IR Propellers - Part I, Installation of an Improved Type II Synchrophaser Control Box; Part II, Installation of Improved Synchrophaser Targets	FL-269		23-Oct-23	1 / IR	4551.50				4651				Complied
61 SB: SB 61-3737		IR Propellers - Propeller Mounting Bolt Inspection/Replacement	FL-269		01-Jul-05	17-Aug-23	1 / IR	4511.50			4602				Complied
61 SB: SB 61-3915		IR Propellers - Propeller Mounting Bolt Replacement and Torque Inspection	FL-269		17-Nov-08	23-Oct-23	1 / IR	4551.50			4651				Complied
61 SB: SB 61-3945		IR Propellers - Announcement of Hartzell Service Bulletin, Counterweight Slug Bolt Inspection/Replacement	FL-269		17-Nov-08	23-Oct-23	1 / IR	4551.50			4651				Complied
71 AD: AD/BEECH 300/003		IR Engine Mount Assembly Attachment Bolts	FL-269		17-Sep-92	16-Aug-23	1 / IR	4511.50			4602				Complied
71 AD: AD/BEECH 300/005		IR Aft Cowling Access Door	FL-269		30-May-95	16-Aug-23	1 / IR	4511.50			4602				Complied
71 SB: SB 2432		IR Power Plant - Inspection/Replacement of the Engine Mount Assembly Attachment Bolts	FL-269		01-Feb-92	23-Oct-23	1 / IR	4551.50			4651				Complied
72 SB: 13009		IR Propeller Shaft Oil Seal Improved Support - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13009		IR Propeller Shaft Oil Seal Improved Support - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13010		IR Guide Pin Reversing Lever Bracket Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13010		IR Guide Pin Reversing Lever Bracket Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13018		IR Torquemeter Cylinder - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13018		IR Torquemeter Cylinder - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13019	1	Improved Power Turbine Shroud and No. 2 Bearing Housing Cover Flange - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
72 SB: 13019	1	Improved Power Turbine Shroud and No. 2 Bearing Housing Cover Flange - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13023	IR	Oil Temperature Bulb Adapter - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13023	IR	Oil Temperature Bulb Adapter - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13025	1	Outer Combustion Chamber Liner Assembly - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13025	1	Outer Combustion Chamber Liner Assembly - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13026	IR	New Compressor Bearing Oil Nozzle and Strainer - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13026	IR	New Compressor Bearing Oil Nozzle and Strainer - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13028	1	New No. 3 and No. 4 Bearing Oil Pressure Tube Assembly - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13028	1	New No. 3 and No. 4 Bearing Oil Pressure Tube Assembly - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13031	2	Exhaust Duct Assembly - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13031	2	Exhaust Duct Assembly - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13032	IR	No. 1 Bearing Inner and Outer Housings and Compressor Rear Stator Air Seal Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13032	IR	No. 1 Bearing Inner and Outer Housings and Compressor Rear Stator Air Seal Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13039	1	Reduction Gearbox Housing Assembly (Front) With Improved Torquemeter Boss - Introduction Of	PCE-PK0277	R/H	17-Aug-23	1 / 1	4502.40				4547				Complied
72 SB: 13039	1	Reduction Gearbox Housing Assembly (Front) With Improved Torquemeter Boss - Introduction Of	PCE-PK0278	L/H	17-Aug-23	1 / 1	4483.10				4537				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
72 SB: 13043	IR	Compressor Turbine Stator Assembly - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13043	IR	Compressor Turbine Stator Assembly - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13046	1	Power Turbine Housing Assembly With Floating Grommet - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13046	1	Power Turbine Housing Assembly With Floating Grommet - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13052	2	Compressor Rear Hub With Increased Cyclic Fatigue Life - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13052	2	Compressor Rear Hub With Increased Cyclic Fatigue Life - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13053	IR	Improved First-Stage Compressor Blades - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13053	IR	Improved First-Stage Compressor Blades - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13055	1	Improved Compressor Stator Assembly - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13055	1	Improved Compressor Stator Assembly - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13058	IR	Improved First-Stage Compressor Blades - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13058	IR	Improved First-Stage Compressor Blades - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13059	IR	New Third-Stage Turbine Vane Ring - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13059	IR	New Third-Stage Turbine Vane Ring - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13065	6	Compressor Turbine Shroud Segment Locating Ring - Removal Shroud Housing Assembly and Small Exit Duct Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 6	4385.30				4413				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
72 SB: 13065	6	Compressor Turbine Shroud Segment Locating Ring - Removal Shroud Housing Assembly and Small Exit Duct Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 6	4366.00				4403				Complied
72 SB: 13067	4	Outer Combustion Chamber Liner Assembly With Improved Sealing Feature - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 4	4385.30				4413				Complied
72 SB: 13067	4	Outer Combustion Chamber Liner Assembly With Improved Sealing Feature - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 4	4366.00				4403				Complied
72 SB: 13068	2	Compressor Air Seals - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13068	2	Compressor Air Seals - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13069	1	Improved Accessory Gearbox Housing Assembly - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13069	1	Improved Accessory Gearbox Housing Assembly - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13070	1	Compressor Turbine Stator Air Seal Assembly - Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / 1	4502.40				4547				Complied
72 SB: 13070	1	Compressor Turbine Stator Air Seal Assembly - Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / 1	4483.10				4537				Complied
72 SB: 13071	4	Tachometer Drive Bevel Gearshaft - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 4	4385.30				4413				Complied
72 SB: 13071	4	Tachometer Drive Bevel Gearshaft - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 4	4366.00				4403				Complied
72 SB: 13072	1	Improved Compressor Turbine Disk - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13072	1	Improved Compressor Turbine Disk - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13076	6	Improved First Stage Reduction Planet Gear Sleeve Bearings (Premachined Bronze) - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 6	4385.30				4413				Complied
72 SB: 13076	6	Improved First Stage Reduction Planet Gear Sleeve Bearings (Premachined Bronze) - Introduction Of	PCE-PK0278	L/H	12-May-14	1 / 6	4366.00				4403				Complied
72 SB: 13080	1	No. 3 Bearing Cover Antirotation Feature - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
72 SB: 13080	1	No. 3 Bearing Cover Antirotation Feature - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13086	1	Improved No. 1 Bearing Outer Housing - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13086	1	Improved No. 1 Bearing Outer Housing - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13088	IR	Improved Scavenge Pump Housing Assembly - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13088	IR	Improved Scavenge Pump Housing Assembly - Introduction Of	PCE-PK0278	L/H	12-May-14	1 / IR	4366.00				4403				Complied
72 SB: 13089	1	Improved Compressor Turbine Blades - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13089	1	Improved Compressor Turbine Blades - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13091	1	Celsius Reading Trim Plate - Introduction Of	PCE-PK0277	R/H	17-Aug-23	1 / 1	4502.40				4547				Complied
72 SB: 13091	1	Celsius Reading Trim Plate - Introduction Of	PCE-PK0278	L/H	17-Aug-23	1 / 1	4483.10				4537				Complied
72 SB: 13093	2	Improved Compressor Rotor Balancing Assembly - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13093	2	Improved Compressor Rotor Balancing Assembly - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13096	1	Improved Reduction Gearbox Rear Housing - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13096	1	Improved Reduction Gearbox Rear Housing - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13105	2	Improved Compressor Turbine Shroud Housing and Compressor Turbine Shroud Segments - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13105	2	Improved Compressor Turbine Shroud Housing and Compressor Turbine Shroud Segments - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13108	1	Compressor Turbine Stator Air Seal with Classified Diameter - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
72 SB: 13108	1	Compressor Turbine Stator Air Seal with Classified Diameter - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13109	3	Improved No. 1 Bearing Air Seals - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 3	4385.30				4413				Complied
72 SB: 13109	3	Improved No. 1 Bearing Air Seals - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 3	4366.00				4403				Complied
72 SB: 13114	IR	No. 1 Bearing - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / IR	4483.10				4537				Complied
72 SB: 13114	IR	No. 1 Bearing - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / IR	4502.40				4547				Complied
72 SB: 13115	IR	No. 4 Bearing - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13115	IR	No. 4 Bearing - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13116	3	Propeller Flange Shim - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 3	4385.30				4413				Complied
72 SB: 13116	3	Propeller Flange Shim - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 3	4366.00				4403				Complied
72 SB: 13121	1	Compressor Turbine Shroud Retaining Ring - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13121	1	Compressor Turbine Shroud Retaining Ring - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13123	1	Power Turbine Coupling and Rotor Air Seal - Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / 1	4502.40				4547				Complied
72 SB: 13123	1	Power Turbine Coupling and Rotor Air Seal - Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / 1	4483.10				4537				Complied
72 SB: 13124	2	No. 2 Bearing Housing Cover Flange - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13124	2	No. 2 Bearing Housing Cover Flange - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13126	1	Propeller Shaft Oil Seal Runner - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13126	1	Propeller Shaft Oil Seal Runner - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13128	1	Compressor Turbine Shroud Segment Retaining Ring - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13128	1	Compressor Turbine Shroud Segment Retaining Ring - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13130	IR	No. 3 Bearing Cover Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
72 SB: 13130		IR No. 3 Bearing Cover Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
72 SB: 13134		1 Compressor Turbine Shroud Segment Retaining Ring Stop - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1		4366.00			4403				Complied
72 SB: 13134		1 Compressor Turbine Shroud Segment Retaining Ring Stop - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1		4385.30			4413				Complied
72 SB: 13136		2 New Compressor Turbine Bolt - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied
72 SB: 13136		2 New Compressor Turbine Bolt - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 2		4366.00			4403				Complied
72 SB: 13137		IR New Power Turbine Assembly - Introduction Of	PCE-PK0277	R/H	17-Aug-23	1 / IR		4502.40			4547				Complied
72 SB: 13137		IR New Power Turbine Assembly - Introduction Of	PCE-PK0278	L/H	17-Aug-23	1 / IR		4483.10			4537				Complied
72 SB: 13141		3 New Compressor Turbine Shroud Segments - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 3		4366.00			4403				Complied
72 SB: 13141		3 New Compressor Turbine Shroud Segments - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 3		4385.30			4413				Complied
72 SB: 13144		IR Improved No. 4 Bearing Oil Supply System - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
72 SB: 13144		IR Improved No. 4 Bearing Oil Supply System - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13148		2 New Compressor Rotor Rear Air Seal - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied
72 SB: 13148		2 New Compressor Rotor Rear Air Seal - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 2		4366.00			4403				Complied
72 SB: 13151		1 Power Turbine Stator Housing Assembly - Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / 1		4502.40			4547				Complied
72 SB: 13151		1 Power Turbine Stator Housing Assembly - Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / 1		4483.10			4537				Complied
72 SB: 13152		2 Accessory Gearbox Drive Shaft Coupling Spacer - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 2		4366.00			4403				Complied
72 SB: 13152		2 Accessory Gearbox Drive Shaft Coupling Spacer - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied
72 SB: 13153		4 Turbine Exhaust Duct Assembly - Replacement / Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / 4		4502.40			4547				Complied
72 SB: 13153		4 Turbine Exhaust Duct Assembly - Replacement / Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / 4		4483.10			4537				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
72 SB: 13155	3	Improved Gas Generator Case Assembly - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 3	4366.00				4403				Complied
72 SB: 13155	3	Improved Gas Generator Case Assembly - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 3	4385.30				4413				Complied
72 SB: 13159	1	Propeller Shaft Oil Seal Runner Accessory Drive Gear Spacer and Bearing Retaining Nut - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13159	1	Propeller Shaft Oil Seal Runner Accessory Drive Gear Spacer and Bearing Retaining Nut - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13160	1	No. 1 Bearing Oil Nozzle Strainer Element Assembly - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / 1	4502.40				4547				Complied
72 SB: 13160	1	No. 1 Bearing Oil Nozzle Strainer Element Assembly - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / 1	4483.10				4537				Complied
72 SB: 13161	6	New Accessory Gearbox Coupling Shaft Locking Feature - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 6	4385.30				4413				Complied
72 SB: 13161	6	New Accessory Gearbox Coupling Shaft Locking Feature - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 6	4366.00				4403				Complied
72 SB: 13163	5	Accessory Gearbox Center Bearing Support Sleeve - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 5	4385.30				4413				Complied
72 SB: 13163	5	Accessory Gearbox Center Bearing Support Sleeve - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 5	4366.00				4403				Complied
72 SB: 13164	IR	Front Propeller Reduction Gearbox Housing Assembly - Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / IR	4483.10				4537				Complied
72 SB: 13164	IR	Front Propeller Reduction Gearbox Housing Assembly - Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / IR	4502.40				4547				Complied
72 SB: 13168	5	Compressor Turbine Stator Assembly Compressible Seals - Introduction Of	PCE-PK0277	R/H	17-Aug-23	1 / 5	4502.40				4547				Complied
72 SB: 13168	5	Compressor Turbine Stator Assembly Compressible Seals - Introduction Of	PCE-PK0278	L/H	17-Aug-23	1 / 5	4483.10				4537				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
72 SB: 13170	3	Propeller Shaft Oil Seal - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / 3	4502.40				4547				Complied
72 SB: 13170	3	Propeller Shaft Oil Seal - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / 3	4483.10				4537				Complied
72 SB: 13172	5	Combustion Chamber Liner Assemblies - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 5	4385.30				4413				Complied
72 SB: 13172	5	Combustion Chamber Liner Assemblies - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 5	4366.00				4403				Complied
72 SB: 13173 [Part: 1.D.Part A]	2	Propeller Shaft Oil Seal Dust Seal - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13173 [Part: 1.D.Part A]	2	Propeller Shaft Oil Seal Dust Seal - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13174	IR	Number 3 & 4 Bearing Pressure Oil Tube Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13174	IR	Number 3 & 4 Bearing Pressure Oil Tube Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13177	5	Outer Combustion - Chamber Liner Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 5	4366.00				4403				Complied
72 SB: 13177	5	Outer Combustion - Chamber Liner Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 5	4385.30				4413				Complied
72 SB: 13179	4	Gas Generator Case Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 4	4385.30				4413				Complied
72 SB: 13179	4	Gas Generator Case Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 4	4366.00				4403				Complied
72 SB: 13181	IR	Compressor Turbine Stator Assembly and Shroud Housing - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13181	IR	Compressor Turbine Stator Assembly and Shroud Housing - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13188	2	Compressor Rotor Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13188	2	Compressor Rotor Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
72 SB: 13191	IR	Propeller Gearbox Front Accessory Drive Bevel Gear and Adjusting Spacer With Re-Defined Tolerances - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13191	IR	Propeller Gearbox Front Accessory Drive Bevel Gear and Adjusting Spacer With Re-Defined Tolerances - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13192	1	Accessory Gearbox Housing and Bearing Support Sleeve - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13192	1	Accessory Gearbox Housing and Bearing Support Sleeve - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13197	1	Accessory Gearbox Housing and Diaphragm Assemblies Keywashers And Center Bearing Retaining Bolts - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13197	1	Accessory Gearbox Housing and Diaphragm Assemblies Keywashers And Center Bearing Retaining Bolts - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13201	1	Compressor Rotor Assembly and No. 1 Bearing Oil Nozzle - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13201	1	Compressor Rotor Assembly and No. 1 Bearing Oil Nozzle - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13205	1	Non-Metallic Ring Seal - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13205	1	Non-Metallic Ring Seal - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13208	IR	Compressor Turbine Stator Air Seal and Gasket - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13208	IR	Compressor Turbine Stator Air Seal and Gasket - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13214	IR	Gaskets Containing Asbestos Fibers - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13214	IR	Gaskets Containing Asbestos Fibers - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
72 SB: 13217		IR No. 2 Bearing Housing Cover Flange - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13217		IR No. 2 Bearing Housing Cover Flange - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
72 SB: 13221		IR No. 2 Bearing Housing-Cover Flange Retaining-Bolts - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
72 SB: 13221		IR No. 2 Bearing Housing-Cover Flange Retaining-Bolts - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13223		1 Asbestos Fiber Gaskets - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1		4385.30			4413				Complied
72 SB: 13223		1 Asbestos Fiber Gaskets - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1		4366.00			4403				Complied
72 SB: 13224		IR Asbestos Fiber Gaskets - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13224		IR Asbestos Fiber Gaskets - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
72 SB: 13225		IR Asbestos Fiber Gaskets - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
72 SB: 13225		IR Asbestos Fiber Gaskets - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13226		1 Asbestos Fiber Gaskets - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1		4385.30			4413				Complied
72 SB: 13226		1 Asbestos Fiber Gaskets - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1		4366.00			4403				Complied
72 SB: 13227		IR Asbestos Fiber Insulation and Shields - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
72 SB: 13227		IR Asbestos Fiber Insulation and Shields - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13231		IR Power Turbine Blade (First-Stage) - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / IR		4483.10			4537				Complied
72 SB: 13231		IR Power Turbine Blade (First-Stage) - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / IR		4502.40			4547				Complied
72 SB: 13232		IR Power-Turbine Rotor Balancing Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13232		IR Power-Turbine Rotor Balancing Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
72 SB: 13235		IR Compressor-Turbine Stator Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
72 SB: 13235		IR Compressor-Turbine Stator Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23		1 / IR	4385.30			4413				Complied
72 SB: 13236		IR Alternative Air Inlet Screen - Introduction Of	PCE-PK0278	L/H	17-Aug-23		1 / IR	4483.10			4537				Complied
72 SB: 13236		IR Alternative Air Inlet Screen - Introduction Of	PCE-PK0277	R/H	17-Aug-23		1 / IR	4502.40			4547				Complied
72 SB: 13240		2 Compressor Rotor Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23		1 / 2	4385.30			4413				Complied
72 SB: 13240		2 Compressor Rotor Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23		1 / 2	4366.00			4403				Complied
72 SB: 13241		1 Compressor Stator Assemblies - Replacement Of / Impeller Shroud Spacer - Introduction Of / Gas Generator Case Assemblies - Modification Of	PCE-PK0278	L/H	27-Jul-23		1 / 1	4366.00			4403				Complied
72 SB: 13241		1 Compressor Stator Assemblies - Replacement Of / Impeller Shroud Spacer - Introduction Of / Gas Generator Case Assemblies - Modification Of	PCE-PK0277	R/H	27-Jul-23		1 / 1	4385.30			4413				Complied
72 SB: 13243		IR Scavenge Pump Housing - Replacement Of	PCE-PK0278	L/H	27-Jul-23		1 / IR	4366.00			4403				Complied
72 SB: 13243		IR Scavenge Pump Housing - Replacement Of	PCE-PK0277	R/H	27-Jul-23		1 / IR	4385.30			4413				Complied
72 SB: 13252		2 Second and Third-Stage Compressor Blades - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23		1 / 2	4385.30			4413				Complied
72 SB: 13252		2 Second and Third-Stage Compressor Blades - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23		1 / 2	4366.00			4403				Complied
72 SB: 13256		1 Power Turbine Blades - Replacement Of	PCE-PK0278	L/H	27-Jul-23		1 / 1	4366.00			4403				Complied
72 SB: 13256		1 Power Turbine Blades - Replacement Of	PCE-PK0277	R/H	27-Jul-23		1 / 1	4385.30			4413				Complied
72 SB: 13258		1 Vane-Ring Retaining Ring - Replacement Of	PCE-PK0278	L/H	27-Jul-23		1 / 1	4366.00			4403				Complied
72 SB: 13258		1 Vane-Ring Retaining Ring - Replacement Of	PCE-PK0277	R/H	27-Jul-23		1 / 1	4385.30			4413				Complied
72 SB: 13260		3 First-Stage Power Turbine Blades - Replacement / Modification Of	PCE-PK0278	L/H	17-Aug-23		1 / 3	4483.10			4537				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
72 SB: 13260	3	First-Stage Power Turbine Blades - Replacement / Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / 3	4502.40	4547							Complied
72 SB: 13263	1	Electrical Grounding Provision on AGB Housing, Propeller RGB Front Housing And Inlet Case - Modification / Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00	4403							Complied
72 SB: 13263	1	Electrical Grounding Provision on AGB Housing, Propeller RGB Front Housing And Inlet Case - Modification / Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30	4413							Complied
72 SB: 13265	IR	Accessory Gearbox Housing Assembly - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / IR	4483.10	4537							Complied
72 SB: 13265	IR	Accessory Gearbox Housing Assembly - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / IR	4502.40	4547							Complied
72 SB: 13266	IR	Main Scavenge-Pump Screen Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00	4403							Complied
72 SB: 13266	IR	Main Scavenge-Pump Screen Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30	4413							Complied
72 SB: 13268	1	Compressor-Turbine Shroud-Housing Compressor-Turbine Shroud-Segments and Power-Turbine Sealing-Ring - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00	4403							Complied
72 SB: 13268	1	Compressor-Turbine Shroud-Housing Compressor-Turbine Shroud-Segments and Power-Turbine Sealing-Ring - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30	4413							Complied
72 SB: 13274	2	No. 3 and No. 4 Bearing Oil Pressure Tube Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30	4413							Complied
72 SB: 13274	2	No. 3 and No. 4 Bearing Oil Pressure Tube Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00	4403							Complied
72 SB: 13275	2	Turbine Exhaust Duct - Replacement and Power Turbine Shroud Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00	4403							Complied
72 SB: 13275	2	Turbine Exhaust Duct - Replacement and Power Turbine Shroud Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30	4413							Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
72 SB: 13277	IR	Accessory Drive Plain Cover - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13277	IR	Accessory Drive Plain Cover - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13280	2	Power Turbine Disk Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
72 SB: 13280	2	Power Turbine Disk Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13282	1	No. 1 Bearing - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13282	1	No. 1 Bearing - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13290	IR	Identification Support Plate - Replacement Of Reduction Gearbox Housing Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13290	IR	Identification Support Plate - Replacement Of Reduction Gearbox Housing Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13293	1	No. 4 Bearing - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
72 SB: 13293	1	No. 4 Bearing - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
72 SB: 13297	5	Power Turbine Disk Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 5	4385.30				4413				Complied
72 SB: 13297	5	Power Turbine Disk Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 5	4366.00				4403				Complied
72 SB: 13301	IR	Compressor Disk Balancing Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13301	IR	Compressor Disk Balancing Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13312	IR	Gearshaft Fuel Control Drive and Fuel Pump - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
72 SB: 13312	IR	Gearshaft Fuel Control Drive and Fuel Pump - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
72 SB: 13313	2	Accessory Gearbox Diaphragm Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
72 SB: 13313	2	Accessory Gearbox Diaphragm Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
72 SB: 13320	3	Main Scavenge Pump Housing and Body Assemblies - Replacement / Modification Of	PCE-PK0278	L/H	17-Aug-23		1 / 3	4483.10			4537				Complied
72 SB: 13320	3	Main Scavenge Pump Housing and Body Assemblies - Replacement / Modification Of	PCE-PK0277	R/H	17-Aug-23		1 / 3	4502.40			4547				Complied
72 SB: 13321	4	Scavenge Pump Housing Assembly - Modification Of	PCE-PK0277	R/H	27-Jul-23		1 / 4	4385.30			4413				Complied
72 SB: 13321	4	Scavenge Pump Housing Assembly - Modification Of	PCE-PK0278	L/H	27-Jul-23		1 / 4	4366.00			4403				Complied
72 SB: 13340 [Part: 1.E]	4	Filler Cap and Oil Gage Assembly - Replacement Of	PCE-PK0277	R/H	20-Jul-15	27-Jul-23	1 / 4	4385.30			4413				Complied
72 SB: 13346	1	Outer Liner - Replacement Of And Inner Liner - Inspection Of	PCE-PK0277	R/H	27-Jul-23		1 / 1	4385.30			4413				Complied
72 SB: 13357	1	Protective Caps and Plugs - Replacement Of	PCE-PK0277	R/H	17-Aug-23		1 / 1	4502.40			4547				Complied
72 SB: 13357	1	Protective Caps and Plugs - Replacement Of	PCE-PK0278	L/H	17-Aug-23		1 / 1	4483.10			4537				Complied
72 SB: 13359	1	Shipping Container Skid Base - Replacement / Modification Of	PCE-PK0277	R/H	17-Aug-23		1 / 1	4502.40			4547				Complied
72 SB: 13359	1	Shipping Container Skid Base - Replacement / Modification Of	PCE-PK0278	L/H	17-Aug-23		1 / 1	4483.10			4537				Complied
72 SB: 13388	IR	Compressor Rear-Stator Air-Seal Assembly - Replacement Of	PCE-PK0277	R/H	17-Aug-23		1 / IR	4502.40			4547				Complied
72 SB: 13388	IR	Compressor Rear-Stator Air-Seal Assembly - Replacement Of	PCE-PK0278	L/H	17-Aug-23		1 / IR	4483.10			4537				Complied
72 SB: 13398	1	Oil Tank Filler Cap - Inspection Of	PCE-PK0277	R/H	25-May-05	17-Aug-23	1 / 1	4502.40			4547				Complied
72 SB: 13398	1	Oil Tank Filler Cap - Inspection Of	PCE-PK0278	L/H	25-May-05	17-Aug-23	1 / 1	4483.10			4537				Complied
72 SB: 13399	1	Seal Plain - Replacement Of	PCE-PK0278	L/H	12-May-14		1 / 1	4366.00			4403				Complied
72 SB: 13399	1	Seal Plain - Replacement Of	PCE-PK0277	R/H	27-Jul-23		1 / 1	4385.30			4413				Complied
72 SB: 13400	IR	Main Scavenge Pump Housing and Body Assemblies - Replacement Of	PCE-PK0277	R/H	27-Jul-23		1 / IR	4385.30			4413				Complied
72 SB: 13400	IR	Main Scavenge Pump Housing and Body Assemblies - Replacement Of	PCE-PK0278	L/H	12-May-14		1 / IR	4366.00			4403				Complied
72 SB: 13415 [Part: 1.E]	3	New Oil Tank Filler Cap and Gage Assembly - Replacement Of	PCE-PK0278	L/H	17-Aug-23			4483.10			4537				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
72 SB: 13417		2 Oil Filler-Tube-Valve Assembly - Replacement Of	PCE-PK0278	L/H	12-May-14	1 / 2		4366.00			4403				Complied
72 SB: 13417		2 Oil Filler-Tube-Valve Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied
72 SB: 13422		1 Air Inlet Screen - Replacement Of	PCE-PK0278	L/H	12-May-14	1 / 1		4366.00			4403				Complied
72 SB: 13423		IR The Oil Pressure Tube Of The No.3 & 4 Bearing - Replacement Of	PCE-PK0278	L/H	12-May-14	1 / IR		4366.00			4403				Complied
72 SB: 13423		IR The Oil Pressure Tube Of The No.3 & 4 Bearing - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13425		2 CT Rotor Air-Seal - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied
72 SB: 13454		2 Gas Generator - Inspection Of	PCE-PK0277	R/H	23-Apr-13	17-Aug-23	1 / 2	4502.40			4547				Complied
72 SB: 13454		2 Gas Generator - Inspection Of	PCE-PK0278	L/H	23-Apr-13	17-Aug-23	1 / 2	4483.10			4537				Complied
72 SB: 13457		IR No.2 Bearing Oil Packing - Replacement Of	PCE-PK0278	L/H	12-May-14	1 / IR		4366.00			4403				Complied
72 SB: 13457		IR No.2 Bearing Oil Packing - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
72 SB: 13480		IR Shipping Caps For Shipping Containers - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / IR		4483.10			4537				Complied
72 SB: 13480		IR Shipping Caps For Shipping Containers - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / IR		4502.40			4547				Complied
72 SB: 13487		4 Filler Cap and Oil Gage Assembly - Replacement Of	PCE-PK0277	R/H	16-Sep-15	17-Aug-23	1 / 4	4502.40			4547				Complied
72 SB: 13487		4 Filler Cap and Oil Gage Assembly - Replacement Of	PCE-PK0278	L/H	16-Sep-15	28-Nov-23	1 / 4	4527.30			4589				Complied
72 SB: 13489		1 Power Turbine Stator Assembly - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / 1		4483.10			4537				Complied
72 SB: 13489		1 Power Turbine Stator Assembly - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / 1		4502.40			4547				Complied
72 SB: 13494		IR Specific Turbine Disk - Reidentification Of	PCE-PK0278	L/H	17-Aug-23	1 / IR		4483.10			4537				Complied
72 SB: 13494		IR Specific Turbine Disk - Reidentification Of	PCE-PK0277	R/H	17-Aug-23	1 / IR		4502.40			4547				Complied
72 SB: 13515		3 Second Stage Power Turbine Blades - Inspection / Replacement Of	PCE-PK0277	R/H	05-May-20	17-Aug-23	1 / 3	4502.40			4547				Complied
72 SB: 13515		3 Second Stage Power Turbine Blades - Inspection / Replacement Of	PCE-PK0278	L/H	05-May-20	17-Aug-23	1 / 3	4483.10			4537				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
72 SB: 13520		IR Metal Shipping Container - Modification Of	PCE-PK0278	L/H	27-Mar-24	01 / IR	4537.50	4600							Complied
72 SB: 13520		IR Metal Shipping Container - Modification Of	PCE-PK0277	R/H	27-Mar-24	01 / IR	4556.80	4610							Complied
72 SB: 13527		IR Shipping Container - Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / IR	4483.10	4537							Complied
72 SB: 13527		IR Shipping Container - Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / IR	4502.40	4547							Complied
72 SB: 13542 [Part: 1.E]		IR Power Turbine Blades - Inspection/Replacement Of	PCE-PK0277	R/H	05-Feb-25	27-Mar-25	1 / IR	4768.10	4784						Complied
72 SB: 13542 [Part: 1.E]		IR Power Turbine Blades - Inspection/Replacement Of	PCE-PK0278	L/H	05-Feb-25	27-Mar-25	1 / IR	4748.80	4774						Complied
72 AD: 2011-20-51		IR Failure of First Stage Reduction Sun Gears	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40	4547							Complied
72 AD: 2011-20-51		IR Failure of First Stage Reduction Sun Gears	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10	4537							Complied
72 AD: 2011-25-12		IR Failure of First Stage Reduction Sun Gears	PCE-PK0277	R/H	01-Dec-11	16-Aug-23	1 / IR	4502.40	4547						Complied
72 AD: 2011-25-12		IR Failure of First Stage Reduction Sun Gears	PCE-PK0278	L/H	01-Dec-11	16-Aug-23	1 / IR	4483.10	4537						Complied
72 AD: 2012-09-10		IR Reduction Gearbox - First Stage Sun and Planet Gear - Replacement	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10	4537							Complied
72 AD: 2012-09-10		IR Reduction Gearbox - First Stage Sun and Planet Gear - Replacement	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40	4547							Complied
72 AD: AD/ENG/001		IR Cancelled	PCE-PK0278	L/H	24-Jan-25	1 / IR	4712.40	4746							Complied
72 AD: AD/ENG/001		IR Cancelled	PCE-PK0277	R/H	24-Jan-25	1 / IR	4731.70	4756							Complied
72 AD: AD/ENG/002		IR Cancelled	PCE-PK0277	R/H	24-Jan-25	1 / IR	4731.70	4756							Complied
72 AD: AD/ENG/002		IR Cancelled	PCE-PK0278	L/H	24-Jan-25	1 / IR	4712.40	4746							Complied
72 AD: AD/ENG/003		1 Approved Propeller Installations - Cancelled	PCE-PK0277	R/H	24-Jan-25	1 / 1	4731.70	4756							Complied
72 AD: AD/ENG/003		1 Approved Propeller Installations - Cancelled	PCE-PK0278	L/H	24-Jan-25	1 / 1	4712.40	4746							Complied
72 AD: AD/ENG/004		11 Piston Engine Continuing Airworthiness Requirements	PCE-PK0277	R/H	24-Jan-25	1 / 11	4731.70	4756							Complied
72 AD: AD/ENG/004		11 Piston Engine Continuing Airworthiness Requirements	PCE-PK0278	L/H	24-Jan-25	1 / 11	4712.40	4746							Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
72 AD: AD/ENG/005	9	Turbine Engine Continuing Airworthiness Requirements	PCE-PK0277	R/H	24-Jan-25	1 / 9	4731.70	4756							Complied
72 AD: AD/ENG/005	9	Turbine Engine Continuing Airworthiness Requirements	PCE-PK0278	L/H	24-Jan-25	1 / 9	4712.40	4746							Complied
72 AD: AD/ENG/006	1	Propeller Strike - Cancelled	PCE-PK0277	R/H	24-Jan-25	1 / 1	4731.70	4756							Complied
72 AD: AD/ENG/006	1	Propeller Strike - Cancelled	PCE-PK0278	L/H	24-Jan-25	1 / 1	4712.40	4746							Complied
72 AD: AD/ENG/007	IR	Replacement of Life Limited Turbine Engine Components	PCE-PK0277	R/H	24-Jan-25	1 / IR	4731.70	4756							Complied
72 AD: AD/ENG/007	IR	Replacement of Life Limited Turbine Engine Components	PCE-PK0278	L/H	24-Jan-25	1 / IR	4712.40	4746							Complied
72 AD: AD/PT6A/001	3	Rotor Components - Service Life - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / 3	4483.10	4537							Complied
72 AD: AD/PT6A/001	3	Rotor Components - Service Life - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / 3	4502.40	4547							Complied
72 AD: AD/PT6A/002	3	Rotor Components - Service Life - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / 3	4483.10	4537							Complied
72 AD: AD/PT6A/002	3	Rotor Components - Service Life - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / 3	4502.40	4547							Complied
72 AD: AD/PT6A/003	1	Rotor Components - Service Life - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / 1	4483.10	4537							Complied
72 AD: AD/PT6A/003	1	Rotor Components - Service Life - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / 1	4502.40	4547							Complied
72 AD: AD/PT6A/004	3	Rotor Components - Service Life - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / 3	4483.10	4537							Complied
72 AD: AD/PT6A/004	3	Rotor Components - Service Life - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / 3	4502.40	4547							Complied
72 AD: AD/PT6A/005	2	Life Limits - Engine Rotating Parts - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / 2	4502.40	4547							Complied
72 AD: AD/PT6A/005	2	Life Limits - Engine Rotating Parts - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / 2	4483.10	4537							Complied
72 AD: AD/PT6A/006	4	Rotor Components - Service Life - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / 4	4483.10	4537							Complied
72 AD: AD/PT6A/006	4	Rotor Components - Service Life - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / 4	4502.40	4547							Complied
72 AD: AD/PT6A/007	IR	Re-Routing Of Governor Air Pressure Line - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40	4547							Complied
72 AD: AD/PT6A/007	IR	Re-Routing Of Governor Air Pressure Line - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10	4537							Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
72 AD: AD/PT6A/008		IR Compressor Rear Hub Hardness - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/008		IR Compressor Rear Hub Hardness - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/009		IR Exhaust Duct Reinforcing Ring - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/009		IR Exhaust Duct Reinforcing Ring - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/010		IR Propeller Reversing Teleflex Control Cable Terminals - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/010		IR Propeller Reversing Teleflex Control Cable Terminals - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/011		IR Woodward Primary Propeller Governors and Overspeed Governors - Solenoid Coil Attachment - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/011		IR Woodward Primary Propeller Governors and Overspeed Governors - Solenoid Coil Attachment - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/012		IR Improved Wire Rope Reversing Cable - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/012		IR Improved Wire Rope Reversing Cable - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/013		IR Fuel Pump Drive Coupling - Improved Lubrication - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/013		IR Fuel Pump Drive Coupling - Improved Lubrication - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/014		IR Sungear Coupling Shaft Retaining Rings - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/014		IR Sungear Coupling Shaft Retaining Rings - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/015		IR Reversing Linkage Front End Clevis - Incorporation of Inspection Hole - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/015		IR Reversing Linkage Front End Clevis - Incorporation of Inspection Hole - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
72 AD: AD/PT6A/017		IR Improved Power Turbine Blade Containment - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/017		IR Improved Power Turbine Blade Containment - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/020		IR No. 2 Bearing Cover	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/020		IR No. 2 Bearing Cover	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/021		IR Replacement of Compressor Delivery Heated Air Tube - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/021		IR Replacement of Compressor Delivery Heated Air Tube - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/022		IR Fuel Pump Coupling - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/022		IR Fuel Pump Coupling - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/023		IR Replacement of Compressor Delivery Heated Air Tube by a Non-Metallic Hose - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/023		IR Replacement of Compressor Delivery Heated Air Tube by a Non-Metallic Hose - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/024		1 Rotor Components - Service Life - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / 1	4483.10				4537				Complied
72 AD: AD/PT6A/024		1 Rotor Components - Service Life - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / 1	4502.40				4547				Complied
72 AD: AD/PT6A/025		IR Sundstrand Fuel Pump Drive Wear - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/025		IR Sundstrand Fuel Pump Drive Wear - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/026		IR Power Turbine Containment Ring - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/026		IR Power Turbine Containment Ring - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/027		IR Compressor Bleed Off Valve - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / IR	4483.10				4537				Complied
72 AD: AD/PT6A/027		IR Compressor Bleed Off Valve - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / IR	4502.40				4547				Complied
72 AD: AD/PT6A/028		1 Water Washing - Cancelled	PCE-PK0277	R/H	16-Aug-23	1 / 1	4502.40				4547				Complied
72 AD: AD/PT6A/028		1 Water Washing - Cancelled	PCE-PK0278	L/H	16-Aug-23	1 / 1	4483.10				4537				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
72 AD: AD/PT6A/029		IR Compressor Bleed Valve - Cancelled	PCE-PK0278	L/H	16-Aug-23		1 / IR	4483.10			4537				Complied
72 AD: AD/PT6A/029		IR Compressor Bleed Valve - Cancelled	PCE-PK0277	R/H	16-Aug-23		1 / IR	4502.40			4547				Complied
72 AD: AD/PT6A/033		IR Compressor Rear Hub - Life Limit Review - Cancelled	PCE-PK0278	L/H	16-Aug-23		1 / IR	4483.10			4537				Complied
72 AD: AD/PT6A/033		IR Compressor Rear Hub - Life Limit Review - Cancelled	PCE-PK0277	R/H	16-Aug-23		1 / IR	4502.40			4547				Complied
72 AD: CF-2013-21		1 Compressor Turbine (CT) Blade Failures	PCE-PK0278	L/H	31-Oct-13	16-Aug-23	1 / 1	4483.10			4537				Complied
72 AD: CF-2013-21		1 Compressor Turbine (CT) Blade Failures	PCE-PK0277	R/H	31-Oct-13	16-Aug-23	1 / 1	4502.40			4547				Complied
72 AD: CF-2014-33		IR Power Plant - Power Turbine Containment Ring Failure	PCE-PK0278	L/H	28-Nov-13	16-Aug-23	1 / IR	4483.10			4537				Complied
72 AD: CF-2014-33		IR Power Plant - Power Turbine Containment Ring Failure	PCE-PK0277	R/H	28-Nov-13	16-Aug-23	1 / IR	4502.40			4547				Complied
72 AD: CF-2019-30		1 Compressor Turbine (CT) Blade Fracture due to Non-conforming CT Vane Installation	PCE-PK0278	L/H	02-Sep-19	16-Aug-23	1 / 1	4483.10			4537				Complied
72 AD: CF-2019-30		1 Compressor Turbine (CT) Blade Fracture due to Non-conforming CT Vane Installation	PCE-PK0277	R/H	02-Sep-19	16-Aug-23	1 / 1	4502.40			4547				Complied
72 AD: CF-2024-05		IR Engine - Second-Stage Power Turbine (PT2) Blade Failure	PCE-PK0277	R/H	15-Feb-24	27-Mar-24	01 / IR	4556.80			4610				Complied
72 AD: CF-2024-05		IR Engine - Second-Stage Power Turbine (PT2) Blade Failure	PCE-PK0278	L/H	15-Feb-24	27-Mar-24	01 / IR	4537.50			4600				Complied
72 AD: CF-2024-33		IR Engine - First-Stage Power Turbine (PT1) Blade Failure	PCE-PK0277	R/H	30-Sep-24	10-Jan-25	1 / IR	4731.70			4756				Complied
72 AD: CF-2024-33		IR Engine - First-Stage Power Turbine (PT1) Blade Failure	PCE-PK0278	L/H	30-Sep-24	10-Jan-25	1 / IR	4712.40			4746				Complied
72 SB: SB 72-4117		IR Engine - Engine Truss Inspection/Repair	FL-269		01-Nov-13	23-Oct-23	1 / IR	4551.50			4651				Complied
73 SB: 13034		IR New Fuel Control Unit Incorporating a Smaller Fuel Inlet Filter - Introduction Of	PCE-PK0278	L/H		27-Jul-23	1 / IR	4366.00			4403				Complied
73 SB: 13034		IR New Fuel Control Unit Incorporating a Smaller Fuel Inlet Filter - Introduction Of	PCE-PK0277	R/H		27-Jul-23	1 / IR	4385.30			4413				Complied
73 SB: 13048		2 New Fuel Pump Unit - Introduction Of	PCE-PK0278	L/H		27-Jul-23	1 / 2	4366.00			4403				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
73 SB: 13048	2	New Fuel Pump Unit - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied
73 SB: 13074	3	Fuel Flow Divider and Purge Valve - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / 3		4502.40			4547				Complied
73 SB: 13074	3	Fuel Flow Divider and Purge Valve - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / 3		4483.10			4537				Complied
73 SB: 13094	1	Improved Oil-To-Fuel Heater - Introduction Of	PCE-PK0277	R/H	17-Aug-23	1 / 1		4502.40			4547				Complied
73 SB: 13094	1	Improved Oil-To-Fuel Heater - Introduction Of	PCE-PK0278	L/H	17-Aug-23	1 / 1		4483.10			4537				Complied
73 SB: 13112	1	Auxiliary Power Recovery System with Independent Air Supply - Introduction Of	PCE-PK0277	R/H	17-Aug-23	1 / 1		4502.40			4547				Complied
73 SB: 13112	1	Auxiliary Power Recovery System with Independent Air Supply - Introduction Of	PCE-PK0278	L/H	17-Aug-23	1 / 1		4483.10			4537				Complied
73 SB: 13129	1	Improved Thermostatic By-Pass Valve - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 1		4366.00			4403				Complied
73 SB: 13129	1	Improved Thermostatic By-Pass Valve - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 1		4385.30			4413				Complied
73 SB: 13175	3	P3 Air Filter Housing and Cover With Drain Valve - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 3		4366.00			4403				Complied
73 SB: 13175	3	P3 Air Filter Housing and Cover With Drain Valve - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 3		4385.30			4413				Complied
73 SB: 13189	IR	Fuel Control - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
73 SB: 13189	IR	Fuel Control - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
73 SB: 13190	1	Oil-To-Fuel Heater - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1		4385.30			4413				Complied
73 SB: 13190	1	Oil-To-Fuel Heater - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1		4366.00			4403				Complied
73 SB: 13216	1	Fuel Control Unit (FCU) - Replacement / Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / 1		4483.10			4537				Complied
73 SB: 13216	1	Fuel Control Unit (FCU) - Replacement / Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / 1		4502.40			4547				Complied
73 SB: 13228	IR	Primary Fuel-Pressure-Tube Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
73 SB: 13228	IR	Primary Fuel-Pressure-Tube Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
73 SB: 13246	1	Oil-To-Fuel-Heater Thermal-Element Retaining-Cap - Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / 1	4502.40				4547				Complied
73 SB: 13246	1	Oil-To-Fuel-Heater Thermal-Element Retaining-Cap - Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / 1	4483.10				4537				Complied
73 SB: 13255	IR	Fuel Control Unit (FCU) - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
73 SB: 13255	IR	Fuel Control Unit (FCU) - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
73 SB: 13267	IR	Fuel Nozzle Sheath - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
73 SB: 13267	IR	Fuel Nozzle Sheath - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
73 SB: 13283	IR	Turboprop Fuel Control Unit - Inspection / Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / IR	4502.40				4547				Complied
73 SB: 13283	IR	Turboprop Fuel Control Unit - Inspection / Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / IR	4483.10				4537				Complied
73 SB: 13286	1	Fuel Control Unit - Inspection Of	PCE-PK0278	L/H	17-Aug-23	1 / 1	4483.10				4537				Complied
73 SB: 13286	1	Fuel Control Unit - Inspection Of	PCE-PK0277	R/H	17-Aug-23	1 / 1	4502.40				4547				Complied
73 SB: 13307	7	Fuel Nozzles and Manifold Adapters - Inspection / Replacement Of	PCE-PK0278	L/H	27-Aug-19	12-May-14	1 / 7	4366.00			4403				Complied
73 SB: 13307	7	Fuel Nozzles and Manifold Adapters - Inspection / Replacement Of	PCE-PK0277	R/H	27-Aug-19	17-Aug-23	1 / 7	4502.40			4547				Complied
73 SB: 13310	5	Fuel Nozzles and Manifold Adapters - Inspection / Replacement Of	PCE-PK0278	L/H	27-Aug-19	12-May-14	1 / 5	4366.00			4403				Complied
73 SB: 13310	5	Fuel Nozzles and Manifold Adapters - Inspection / Replacement Of	PCE-PK0277	R/H	27-Aug-19	17-Aug-23	1 / 5	4502.40			4547				Complied
73 SB: 13314	1	Fuel Control Unit - Modification Of	PCE-PK0278	L/H	17-Aug-23	1 / 1	4483.10				4537				Complied
73 SB: 13314	1	Fuel Control Unit - Modification Of	PCE-PK0277	R/H	17-Aug-23	1 / 1	4502.40				4547				Complied
73 SB: 13323	1	Compressor Delivery Air Pressure Insulated Tube Assembly and Clamp - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
73 SB: 13323	1	Compressor Delivery Air Pressure Insulated Tube Assembly and Clamp - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1		4366.00			4403				Complied
73 SB: 13356	1	Oil To Fuel Heater - Modification / Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / 1		4483.10			4537				Complied
73 SB: 13356	1	Oil To Fuel Heater - Modification / Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / 1		4502.40			4547				Complied
73 SB: 13406 [Part: 1.E]	IR	Fuel Pump Coupling Shaft Spline - Inspection Of	PCE-PK0278	L/H	02-Mar-06	17-Aug-23	1 / IR	4483.10			4537				Complied
73 SB: 13406 [Part: 1.E]	IR	Fuel Pump Coupling Shaft Spline - Inspection Of	PCE-PK0277	R/H	02-Mar-06	17-Aug-23	1 / IR	4502.40			4547				Complied
73 SB: 13450	IR	Py And P3 Insulated Air Pressure Tubes - Inspection / Replacement Of	PCE-PK0278	L/H	12-May-14	1 / IR		4366.00			4403				Complied
73 SB: 13465	2	Turboprop Engine With Hamilton Sunstrand Fuel Pump Coupling Shaft Spline - Inspection Of	PCE-PK0277	R/H	17-May-12	17-Aug-23	1 / 2	4502.40			4547				Complied
73 SB: 13465	2	Turboprop Engine With Hamilton Sunstrand Fuel Pump Coupling Shaft Spline - Inspection Of	PCE-PK0278	L/H	17-May-12	17-Aug-23	1 / 2	4483.10			4537				Complied
73 SB: 13485	2	Fuel Pump - Inspection / Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / 2		4483.10			4537				Complied
73 SB: 13485	2	Fuel Pump - Inspection / Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / 2		4502.40			4547				Complied
73 SB: 13505	2	Fuel Control Unit - Inspection Of	PCE-PK0278	L/H	21-Dec-18	17-Aug-23	1 / 2	4483.10			4537				Complied
73 SB: 13505	2	Fuel Control Unit - Inspection Of	PCE-PK0277	R/H	21-Dec-18	17-Aug-23	1 / 2	4502.40			4547				Complied
73 SB: 13506	1	Fuel Nozzle Evaluation	PCE-PK0278	L/H	17-Aug-23	1 / 1		4483.10			4537				Complied
73 SB: 13506	1	Fuel Nozzle Evaluation	PCE-PK0277	R/H	17-Aug-23	1 / 1		4502.40			4547				Complied
73 AD: 2012-03-06	IR	AVStar Fuel Systems (AFS) Fuel Servo Diaphragm	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: 2012-03-07	IR	Carburetor Model HA-6 Mixture Control Sleeve	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/BEECH 300/018	IR	Engine Controls Cross Shaft	FL-269		28-Oct-04	16-Aug-23	1 / IR	4511.50			4602				Complied
73 AD: AD/FSM/001	1	Marvel Schebler Carburettor Venturi - Inspection - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
73 AD: AD/FSM/002	IR	Marvel Schebler Carburettor Throttle Lever P/N 12A341 - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
73 AD: AD/FSM/003		IR Marvel Schebler Carburettor Float - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/004		1 Marvel Schebler Carburettor Float Bracket Attach Screws - Modification - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
73 AD: AD/FSM/005		IR AD/FSM/5 - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/006		IR Fuel Pump Relief Valve - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/007		1 Marvel Schebler Carburettors Bowl Cover Screws Safety Locking - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
73 AD: AD/FSM/008		IR AD/FSM/8 - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/009		1 Marvel Schebler Carburettor - Throttle Shaft Modification - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
73 AD: AD/FSM/010		IR Marvel Schebler Carburettors - Float Valve Assembly - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/011		1 Marvel Schebler Carburettors - Float Valve Assembly - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
73 AD: AD/FSM/012		IR Marvel Schebler Carburettor Float Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/013		IR General Electric Engine Driven Fuel Pump Spline - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/014		IR Marvel Schebler Carburettors - Drain Plug - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/015		2 Marvel Schebler (Facet Aerospace Products Co.) Carburettors - Throttle Arm Screw - Retorque and Locking - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
73 AD: AD/FSM/016		IR Vickers Vane Pump Drive Shaft - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/017		IR Bendix Fuel Injector - Air Diaphragm P/N 2529470 - Inspections - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/018		IR Marvel Schebler Carburettor - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/019		2 Bendix Fuel Injection System Regulator Stem Nut - Inspection - Crimp Locking - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
73 AD: AD/FSM/020		IR Bendix Injector Mixture Control Shaft - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/021		IR Trw Inc. (Thompson Products) Engine Driven Fuel Pump (Model TF 1900) - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/022		IR POSA Carburettor - Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/023		IR AD/FSM/23 - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/024		IR Metering Sleeve - MA-3PA Carburettors - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/025		4 Lear Romec Fuel Pumps - Cancelled	FL-269		20-Oct-22	1 / 4		4394.40			4424				Complied
73 AD: AD/FSM/026		IR Air Metering Stop Pin P/N 62-226 Fitted to MA4-5, MA-5 and MA-6 Series Carburettors	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/027		IR O-Ring Damage on Bendix RSA-7AA Servo Fuel Injector - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/028		IR Hamilton Standard JFC118 Fuel Leak Inspection	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/030		IR Mixture Control Shaft Retention Screw	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
73 AD: AD/FSM/031		3 Fuel Injection Servo Plugs	FL-269		20-Oct-22	1 / 3		4394.40			4424				Complied
73 AD: AD/PT6A/019		IR Fuel Control Bypass Valve Diaphragm	PCE-PK0278	L/H	16-Aug-23	1 / IR		4483.10			4537				Complied
73 AD: AD/PT6A/019		IR Fuel Control Bypass Valve Diaphragm	PCE-PK0277	R/H	16-Aug-23	1 / IR		4502.40			4547				Complied
73 AD: AD/PT6A/031		IR Fuel Control Unit	PCE-PK0277	R/H	18-Apr-02	16-Aug-23	1 / IR	4502.40			4547				Complied
73 AD: AD/PT6A/031		IR Fuel Control Unit	PCE-PK0278	L/H	18-Apr-02	16-Aug-23	1 / IR	4483.10			4537				Complied
73 AD: CF-2015-23		IR Fuel Control - Fuel Control Unit Bellow Leak	PCE-PK0277	R/H	06-Aug-15	16-Aug-23	1 / IR	4502.40			4547				Complied
73 AD: CF-2015-23		IR Fuel Control - Fuel Control Unit Bellow Leak	PCE-PK0278	L/H	06-Aug-15	16-Aug-23	1 / IR	4483.10			4537				Complied
73 SL: MTL-73-02		IR Engine Fuel and Control - Inspection Of Fuel Pressure Switch O-Ring	FL-269		02-May-24	01-Jun-24	1 / IR	4599.20			4689				Complied
74 SB: 13082		IR Improved Spark Igniters - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
74 SB: 13082		IR Improved Spark Igniters - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
74 SB: 13154	2	Improved Igniter Plugs - Introduction Of (For Information Only)	PCE-PK0278	L/H	17-Aug-23	1 / 2		4483.10			4537				Complied
74 SB: 13154	2	Improved Igniter Plugs - Introduction Of (For Information Only)	PCE-PK0277	R/H	17-Aug-23	1 / 2		4502.40			4547				Complied
74 SB: 13234	IR	Ignition Cable Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
74 SB: 13234	IR	Ignition Cable Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
74 SB: 13270	IR	Ignition Cable Bracket - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
74 SB: 13270	IR	Ignition Cable Bracket - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
74 SB: 13424	1	Spark Igniters - Inspection Of	PCE-PK0278	L/H	20-Sep-07	17-Aug-23	1 / 1	4483.10			4537				Complied
74 SB: 13424	1	Spark Igniters - Inspection Of	PCE-PK0277	R/H	20-Sep-07	17-Aug-23	1 / 1	4502.40			4547				Complied
74 SB: 13531	IR	Ignition Cable Assembly - Inspection / Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
74 SB: 13531	IR	Ignition Cable Assembly - Inspection / Replacement Of	PCE-PK0278	L/H	27-Mar-24	01 / IR		4537.50			4600				Complied
74 AD: 2011-26-07	IR	Champion Aerospace (formerly Unison Industries) (Slick) Magneto	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74 AD: 2022-16-03	IR	Potential Improperly Lubricated Roller Bearing in S-1200 Series Magnetos	FL-269		15-Aug-22	31-May-24	1 / IR	4599.20			4689				Complied
74 AD: AD/ELECT/002	IR	Ignition Switches - Briggs and Stratton - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74 AD: AD/ELECT/004	IR	Magnetos BTH - Earthing Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74 AD: AD/ELECT/005	IR	Magneto - Impulse Starters - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74 AD: AD/ELECT/006	IR	Magneto - BTH - Contact Breakers Assembly - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74 AD: AD/ELECT/007	IR	Magneto - BTH Gear - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74 AD: AD/ELECT/008	IR	Magneto Bosch Cam Bearing - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74 AD: AD/ELECT/009	IR	Magneto Bendix Scintilla - Lubrication - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
74	AD: AD/ELECT/010	1 Magneto Bendix Scintilla - Lubrication and Modification - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
74	AD: AD/ELECT/012	IR Briggs and Stratton AAF Type B5 Ignition Switches - Modification - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
74	AD: AD/ELECT/013	2 Magneto - BTH - Slow Speed Wheel - Inspection	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
74	AD: AD/ELECT/014	IR Magneto Bendix Scintilla - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
74	AD: AD/ELECT/015	IR Engine Starter - Bendix - Modification - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
74	AD: AD/ELECT/016	IR Magneto - Bendix Scintilla Distributor Gear - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
74	AD: AD/ELECT/017	IR Magneto - Bendix Scintilla Distributor Block - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
74	AD: AD/ELECT/018	3 Slick 4000/4100 Series Sealed Non-Repairable Magnets - Retirement Life - Cancelled	FL-269		20-Oct-22	1 / 3	4394.40				4424				Complied
74	AD: AD/ELECT/019	1 Slick Magneto Impulse Coupling - Replacement - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
74	AD: AD/ELECT/020	IR Eisemann Magneto Coils P/N H27-958 - Inspection and Replacement	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
74	AD: AD/ELECT/021	6 Slick Magnets - 447 and 600 Series - Cancelled	FL-269		20-Oct-22	1 / 6	4394.40				4424				Complied
74	AD: AD/ELECT/025	1 Slick Magneto Hub - Impulse Coupling Replacement - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
74	AD: AD/ELECT/027	6 Bendix Impulse Coupling - Flyweight Clearance Inspection - Cancelled	FL-269		20-Oct-22	1 / 6	4394.40				4424				Complied
74	AD: AD/ELECT/029	IR Bendix Magneto Rear Bearing Overheating Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
74	AD: AD/ELECT/030	2 Bendix Magneto Coil Retainer Plug Inspection - Cancelled	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
74	AD: AD/ELECT/031	IR Bendix Magneto Capacitor Malfunction Inspection - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
74	AD: AD/ELECT/032	IR Bendix Magneto - Housing Distortion - Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/ELECT/033	IR Bendix Magneto Rear Bearing Overheating Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/ELECT/034	IR Bendix D2000/D2200 Series Magnetos Using Green Distributor Blocks - Inspection and Replacement - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/ELECT/035	1 Bendix Magneto - Housing Distortion - Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
74	AD: AD/ELECT/036	IR Slick Magneto Impulse Coupling - Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/ELECT/039	IR Bendix Starting Vibrator - Inspection and Modification	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/ELECT/040	IR Slick Magneto Coil	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/ELECT/041	IR Bendix Distributor Gear Electrode - Inspection/Replacement - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/ELECT/042	2 Bendix Impulse Couplings	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
74	AD: AD/ELECT/044	1 Slick Magnetos - Bearing Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
74	AD: AD/ELECT/046	6 Slick Magnetos - Cancelled	FL-269		20-Oct-22	1 / 6		4394.40			4424				Complied
74	AD: AD/ELECT/049	IR Bendix Magneto Distributor Block - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/ELECT/053	2 Bendix Magneto Clear Case Coils - Cancelled	FL-269		20-Oct-22	1 / 2		4394.40			4424				Complied
74	AD: AD/ELECT/063	1 TCM (Bendix) Magneto Capacitor	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
74	AD: AD/ELECT/066	1 Bendix Magneto Coils and Rotating Magnets	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
74	AD: AD/ELECT/068	IR Bendix Impulse Coupling Inspection - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
74	AD: AD/GENERAL/011	IR Briggs and Stratton AAF Type B5 Ignition Switch - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
75	SB: 13062	2 New Improved Swing Check Valve Assembly - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
75 SB: 13062	2	New Improved Swing Check Valve Assembly - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
75 SB: 13131	IR	New Bleed Air Case Assembly - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
75 SB: 13131	IR	New Bleed Air Case Assembly - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
75 SB: 13206	7	Accessory Gearbox Assembly With Separate Coupling Shaft And Drive Gearshaft - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / 7	4385.30				4413				Complied
75 SB: 13206	7	Accessory Gearbox Assembly With Separate Coupling Shaft And Drive Gearshaft - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / 7	4366.00				4403				Complied
75 SB: 13207	2	Gaskets Containing Asbestos Fibers and Bleed Valve Assembly - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 2	4366.00				4403				Complied
75 SB: 13207	2	Gaskets Containing Asbestos Fibers and Bleed Valve Assembly - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 2	4385.30				4413				Complied
75 SB: 13242	IR	Compressor Bleed-Valve Assembly - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
75 SB: 13242	IR	Compressor Bleed-Valve Assembly - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
75 SB: 13287	3	Bleed Off Valve (BOV) Cover - Inspection / Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 3	4385.30				4413				Complied
75 SB: 13287	3	Bleed Off Valve (BOV) Cover - Inspection / Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 3	4366.00				4403				Complied
75 SB: 13518	1	Parts Kit - Introduction Of	PCE-PK0278	L/H	27-Mar-24	01 / 01	4537.50				4600				Complied
75 SB: 13518	1	Parts Kit - Introduction Of	PCE-PK0277	R/H	27-Mar-24	01 / 01	4556.80				4610				Complied
75 AD: AD/AIRIND/002	2	Brackett Air Filter Gasket	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied
76 SB: 13021	1	Propeller Reversing Lever - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 1	4385.30				4413				Complied
76 SB: 13021	1	Propeller Reversing Lever - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 1	4366.00				4403				Complied
76 SB: 13302	IR	Propeller Reversing Lever - Replacement / Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / IR	4385.30				4413				Complied
76 SB: 13302	IR	Propeller Reversing Lever - Replacement / Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / IR	4366.00				4403				Complied
76 SB: 13361	IR	Interconnect Rod - Inspection Of	PCE-PK0278	L/H	02-Aug-04	12-May-14	1 / IR	4366.00			4403				Complied
76 SB: 13361	IR	Interconnect Rod - Inspection Of	PCE-PK0277	R/H	02-Aug-04	27-Jul-23	1 / IR	4385.30			4413				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<b>ATA/Ref No:</b>	<b>Rev:</b>	<b>Description:</b>	<b>Applies to:</b>	<b>Pos:</b>	<b>Eff From:</b>	<b>Last Comp'd:</b>	<b>Project/ Iss/Rev:</b>	<b>Comp. Hours:</b>	<b>Due Hours:</b>	<b>Hrs. Rem.:</b>	<b>Comp. Ldgs:</b>	<b>Ldg Rem.:</b>	<b>Due Ldgs:</b>	<b>Due Date:</b>	<b>Status</b>
76 SB: 13370	1	Propeller Reversing Lever - Inspection Of	PCE-PK0278	L/H	06-Jan-09	17-Aug-23	1 / 1	4483.10			4537				Complied
76 SB: 13370	1	Propeller Reversing Lever - Inspection Of	PCE-PK0277	R/H	06-Jan-09	27-Jul-23	1 / 1	4385.30			4413				Complied
76 SB: 13416	IR	Bolts And Nuts Of The FCU Connector Rod - Replacement Of	PCE-PK0277	R/H		27-Jul-23	1 / IR	4385.30			4413				Complied
76 SB: 13416	IR	Bolts And Nuts Of The FCU Connector Rod - Replacement Of	PCE-PK0278	L/H		12-May-14	1 / IR	4366.00			4403				Complied
76 SB: 13426	1	Bolt Of The FCU Connector Rod - Replacement Of	PCE-PK0277	R/H	27-Sep-07	27-Jul-23	1 / 1	4385.30			4413				Complied
76 SB: 13426	1	Bolt Of The FCU Connector Rod - Replacement Of	PCE-PK0278	L/H	27-Sep-07	12-May-14	1 / 1	4366.00			4403				Complied
76 SL: MTL-76-01	IR	Engine Controls - Power Control Cable Inspection	FL-269		02-May-19	23-Oct-23	1 / IR	4551.50			4651				Complied
76 SL: MTL-76-02	IR	Engine Controls - Transmittal Of Innovative Solutions And Support Service Bulletin SB2124 And Recall Notice RN2111	FL-269		14-Oct-21	23-Oct-23	1 / IR	4551.50			4651				Complied
76 SB: SB 73-3634 [Part: Part II]	IR	Engine Fuel Systems - Engine Controls Cross Shaft/Pedestal Modification	FL-269			17-Aug-23	MI11123	4511.50			4602				Complied
77 SB: 13011	2	Oil Pressure Indicator Restrictor - Replacement Of	PCE-PK0278	L/H		27-Jul-23	1 / 2	4366.00			4403				Complied
77 SB: 13011	2	Oil Pressure Indicator Restrictor - Replacement Of	PCE-PK0277	R/H		27-Jul-23	1 / 2	4385.30			4413				Complied
77 SB: 13038	2	T5 Single Thermocouple and Dual Bus Bar - Replacement / Modification Of	PCE-PK0277	R/H		27-Jul-23	1 / 2	4385.30			4413				Complied
77 SB: 13038	2	T5 Single Thermocouple and Dual Bus Bar - Replacement / Modification Of	PCE-PK0278	L/H		27-Jul-23	1 / 2	4366.00			4403				Complied
77 SB: 13135	IR	Locking Washers For ITT Terminal Bolts - Introduction Of	PCE-PK0277	R/H		27-Jul-23	1 / IR	4385.30			4413				Complied
77 SB: 13135	IR	Locking Washers For ITT Terminal Bolts - Introduction Of	PCE-PK0278	L/H		27-Jul-23	1 / IR	4366.00			4403				Complied
77 SB: 13193	1	T5 Immersion Thermocouples - Replacement Of	PCE-PK0277	R/H		27-Jul-23	1 / 1	4385.30			4413				Complied
77 SB: 13193	1	T5 Immersion Thermocouples - Replacement Of	PCE-PK0278	L/H		27-Jul-23	1 / 1	4366.00			4403				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 | Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
77 SB: 13249	2	Thermocouple Wiring - Harness Terminal - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied
77 SB: 13249	2	Thermocouple Wiring - Harness Terminal - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 2		4366.00			4403				Complied
79 SB: 13006	1	Oil Filter Housing Check Valve - Modification Of	PCE-PK0278	L/H	27-Jul-23	1 / 1		4366.00			4403				Complied
79 SB: 13006	1	Oil Filter Housing Check Valve - Modification Of	PCE-PK0277	R/H	27-Jul-23	1 / 1		4385.30			4413				Complied
79 SB: 13050	IR	Oil Transfer Pressure Tube Assembly - Introduction Of	PCE-PK0278	L/H	27-Jul-23	1 / IR		4366.00			4403				Complied
79 SB: 13050	IR	Oil Transfer Pressure Tube Assembly - Introduction Of	PCE-PK0277	R/H	27-Jul-23	1 / IR		4385.30			4413				Complied
79 SB: 13066	1	Fine Mesh Oil Filter Element - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 1		4385.30			4413				Complied
79 SB: 13066	1	Fine Mesh Oil Filter Element - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 1		4366.00			4403				Complied
79 SB: 13319	2	No.2 Bearing Scavenge-Tube Seal-Retaining-Plate - Replacement Of	PCE-PK0277	R/H	27-Jul-23	1 / 2		4385.30			4413				Complied
79 SB: 13319	2	No.2 Bearing Scavenge-Tube Seal-Retaining-Plate - Replacement Of	PCE-PK0278	L/H	27-Jul-23	1 / 2		4366.00			4403				Complied
79 SB: 13411	1	Oil Filter Element - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / 1		4502.40			4547				Complied
79 SB: 13411	1	Oil Filter Element - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / 1		4483.10			4537				Complied
79 SB: 13452	IR	Oil Pressure Transfer Coupling - Replacement Of	PCE-PK0278	L/H	17-Aug-23	1 / IR		4483.10			4537				Complied
79 SB: 13452	IR	Oil Pressure Transfer Coupling - Replacement Of	PCE-PK0277	R/H	17-Aug-23	1 / IR		4502.40			4547				Complied
79 AD: AD/COOL/001	IR	Stewart Warner Oil Coolers - Inspection and Replacement	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
79 AD: AD/COOL/002	IR	Stewart Warner Oil Coolers - Inspection and Replacement	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
79 AD: AD/GENERAL/022	IR	Engine Oil Tank - Modification - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
79 AD: AD/LUB/001	IR	Facet Scavenge Oil Filter Placards	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
79 AD: AD/PT6A/018	IR	No. 2 Bearing Oil Pressure Tube	PCE-PK0277	R/H	16-Aug-23	1 / IR		4502.40			4547				Complied
79 AD: AD/PT6A/018	IR	No. 2 Bearing Oil Pressure Tube	PCE-PK0278	L/H	16-Aug-23	1 / IR		4483.10			4537				Complied
79 SB: SB 2159	2	Oil - Replacement of Engine Oil Pressure Transducers and Electrical Connectors	FL-269		23-Oct-23	1 / 2		4551.50			4651				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

ATA/Ref No:	Rev:	Description:	Applies to:	Pos:	Eff From:	Last Comp'd:	Project/ Iss/Rev:	Comp. Hours:	Due Hours:	Hrs. Rem.:	Comp. Ldgs:	Ldg Rem.:	Due Ldgs:	Due Date:	Status
81	AD: 2010-07-08	IR Rebuilt Kelly Aerospace Turbochargers	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
81	AD: 2011-13-03	IR Hartzell Engine Technologies Turbochargers	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
81	AD: 2012-10-52	IR Hartzell Engine Technologies (HET) Turbochargers - Insufficient Oil Flow to the Bearings	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
81	AD: 2013-21-02	IR Hartzell Turbocharger Turbine Wheel Removal	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
81	AD: 2018-02-04	IR FAA PMA Aerospace Welding Minneapolis Mufflers P/N A1754001-23 and A1754001-25 - Inspection / Replacement	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
81	AD: AD/TURBO/002	IR Kelly Aerospace Turbochargers	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
91	AD: 2011-15-05	IR FAA Approved Flight Manual - Correction to Takeoff Speeds and Field Length	FL-269		19-Aug-11	16-Aug-23	1 / IR	4511.50			4602				Complied
95	AD: 2009-0122	1 Equipment / Furnishings - Load Release Units - Inspection / Modification / Limitation	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
95	AD: 2010-03-02	IR Lifesaving Systems D-Lok Hook	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
95	AD: 2013-06-51	IR Equipment / Furnishing - Hoist - Inspection / Replacement (Mandatory for FAA (US) Rotorcraft only. Refer individual Rotorcraft AD series')	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
95	AD: 2022-05-10	IR Goodrich Externally-Mounted Hoist Assemblies (Mandatory for FAA (US) Rotorcraft only. Refer individual Rotorcraft AD series')	FL-269		20-Apr-22	20-Oct-22	1 / IR	4394.40			4424				Complied
95	AD: AD/SUPP/002	1 Breeze Hoists - Deactivation - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
95	AD: AD/SUPP/004 [Part: 1 & 2]	IR Air Equipment Rescue Hoist - Inspection and Modification of Squib	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied
95	AD: AD/SUPP/005	1 Air Equipment Hoists - "Up Limit" Micro Switches - Inspection and Modification - Cancelled	FL-269		20-Oct-22	1 / 1		4394.40			4424				Complied
95	AD: AD/SUPP/006	IR Air Equipment Hoists - Cancelled	FL-269		20-Oct-22	1 / IR		4394.40			4424				Complied

# Aircraft Management Status

Pulse Aero Pty Ltd

01-Jan-26 Ian Williams

**A/C Reg No:** VH-UVH      **Type:** Aircraft, Beechcraft, B300 Series      **A/C Serial No:** FL-269      **DoM:** 20-Dec-99  
**Posted TSN:** 4952.8      **Posted LSN:** 4980      **Last Flight:** 24-Dec-25      **Owner:** Flight One

## Publication - Complied With

<i>ATA/Ref No:</i>	<i>Rev:</i>	<i>Description:</i>	<i>Applies to:</i>	<i>Pos:</i>	<i>Eff From:</i>	<i>Last Comp'd:</i>	<i>Project/ Iss/Rev:</i>	<i>Comp. Hours:</i>	<i>Due Hours:</i>	<i>Hrs. Rem.:</i>	<i>Comp. Ldgs:</i>	<i>Ldg Rem.:</i>	<i>Due Ldgs:</i>	<i>Due Date:</i>	<i>Status</i>
95 AD: AD/SUPP/007	1	Conversion of Breeze Hoist P/N BL-16600 to P/N BL-16600-110 or -120 - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
95 AD: AD/SUPP/009	1	Air Equipment Rescue Hoists	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
95 AD: AD/SUPP/010	IR	Breeze-Eastern Hoists	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
95 AD: AD/SUPP/012	IR	Rescue Hoists - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
95 AD: AD/SUPP/013	1	Air Equipment Hoists - Earth Bonding	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
95 AD: AD/SUPP/014	IR	Lucas-Air Equipment Rescue Hoist Guide Pin	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
95 AD: AD/SUPP/015	IR	Air-Equipment Hoists - Earth Bonding - Cancelled	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
95 AD: AD/SUPP/017 [Part: 1]	1	Lucas Air Equipment Rescue Hoists - Up Limit Position Security	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
95 AD: AD/SUPP/018	1	SIREN Load Release Units - Cancelled	FL-269		20-Oct-22	1 / 1	4394.40				4424				Complied
95 AD: AD/SUPP/019	IR	Breeze Eastern Aerospace Rescue Hoist	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
95 AD: AD/SUPP/020	IR	Rope Down Device	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
95 AD: AD/SUPP/021	IR	Helicopter External Rescue Systems	FL-269		20-Oct-22	1 / IR	4394.40				4424				Complied
95 AD: AD/SUPP/022	2	Lifesaving Systems D-Lok Hook - Cancelled	FL-269		20-Oct-22	1 / 2	4394.40				4424				Complied