



CESCOM 20 - Projected Maintenance Due

Owner: **SKYLINE AVIATION LTD**
 Aircraft Model: **510 - CITATION MUSTANG**
 Aircraft Serial: **510-0070**
 Unit: **0070** Reg No: **ZK-YDZ**
 Airworthiness: **18-Apr-2008**
 Print Date: **26-Aug-2025 4:07PM**
 MSG-3 Program Applied Date: **01-Jan-2001**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	3109.5	3994	19-Aug-2025	.38	0.55	200	200	365	12
ENG 1	3109.5	3994	19-Aug-2025	.38	0.55	200	200	365	12
ENG 2	3109.5	3994	19-Aug-2025	.38	0.55	200	200	365	12
AIR COND	1000.5		19-Aug-2025	.9	0.55	200		365	12

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B243000 051224B	CONCORDE (RG-390E) LEAD-ACID BATTERY FUNCTIONALCHECK (CAPACITY CHECK)			RG-380E/30 41405592	MTH 11-Oct-2024 HRS 2989.1 LDG 3820		12		11-Oct-2025	1 m 15 d
059003	MAINTENANCE REVIEW NZCAR 135.415				MTH 20-Oct-2024 HRS 2992.3 LDG 3825		12		20-Oct-2025	1 m 24 d
5-12-05 051205	INSPECTION DOCUMENT 05 *CF				MTH 18-Apr-2008 HRS 0		3150		3150	40.5
052020	PERFORM REDUCED VERTICAL SEPARATION MINIMUM (RVSM) HEIGHT MONITORING REQUIREMENTS				MTH 06-Nov-2023 HRS 2765 LDG 3478		24 1000		30-Nov-2025 3765	3 m 4 d 655.5
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE				MTH		12 MTH		07-Mar-2026	6 m 9 d
				MANDATORY						
5-12-35	INSPECTION DOCUMENT 35				MTH 07-Mar-2025		6		07-Mar-2026	6 m 9 d
052300	INSPECT DZM INSTALLATION				MTH 13-May-2024 HRS 2889.4 LDG 3664		24 600		13-May-2026 3489.4	8 m 17 d 379.9
CAA NZ DCA/GEN/19A	EMERGENCY EXITS				MTH 20-May-2025 HRS 3070.4 LDG 3936		12		20-May-2026	8 m 24 d Complete
35-00-00-960 051210 : OXY	RESTORATION OXYGEN BOTTLE HYDROSTATIC TEST			4441073-040 777211801	MTH 30-Jun-2021		60		30-Jun-2026	10 m 4 d

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB 510-76-02	ENGINE CONTROLS - ANTI-ICE FADEC WIRING IMPROVEMENT				MTH RECOMMENDED MSC		-			
SL 510-21-04	AIR CONDITIONING - CABIN PRESSURIZATION CONTROLLER IMPROVEMENT				MTH RECOMMENDED MSC		-			

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
CAA NZ DCA/RAD/43	MODE S ADDRESS CODE - INSPECTION				MTH 27-May-2025 HRS 3077.4 LDG 3944		24		27-May-2027	21 m 1 d Complete
				AIRWORTHINESS DIRECTIVE	MSC		DUE			